Figuration Con		Word or	IGNMENT (Office) MSIG Bill to:	Datef	Curse:	31/10/2018
	TTP RES / OD	RESTEVATION SLB:	7428R	Impred:	SLW	6483L
st Workshoo p	n/s	Khek	100 Motor	Tel: 96	1666	58/678554=
Policy No	2908913	6 MCY	Claim No:	56778	2	
Sun Insured			Excess			
Make of Veh.				D.O./	18	108/18
See Transport		1			- Car 12	
Date/Time: 0	REP. / REV 2	RIE Person Co			IN OI	
	REP. / REV 2		MMCCMI.			
Date/Time: 0	REP. / REV 2	on () Ex	MMCCMI.		IN) OI	

n ...

D-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239. Fax: 6315 3298. Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no

: 351M0818.KJM

Vehicle no

: SLB7428B

1 REFERENCE

Date of inspection

: 20 August 2018

Requested by

: Hoo Sio Fooi

28 Flora Drive

#01-53

Singapore 506951

Type of survey

: Independent

Repairer

: Khek Joo Motor Workshop

Blk 9004 Tampines St 93, #01-94, Singapore 528838

Date of accident

: 18 August 2018

Type of Collison

: Head to Rear

2 VEHICLE DATA

Make/model

: BMW 5231 2.5 AT ABS D/AB 2WD 4DR GAS/D

Chassis no Engine no

: WBAFP32070C866195 : 08977745N52B25AF

Date of registration

: 28 June 2011

Engine capacity

: 2497 cc : Silver

Colour

Odometer reading

: 160673 km

3 STATIC CONDITION CHECK

Steering

: Serviceable

Foot brakes

: Serviceable

Hand brakes

: Serviceable

Paintwork

: Good

General

: Good

:

4 TIRE CONDITION CHECK RH/MAKE

LH/MAKE

SIZE

Front tread Rear tread

: 7 mm/Michelin : 7 mm/Michelin

7 mm/Michelin 7 mm/Michelin 225/55R17 225/55R17

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper dented/bulged/cracked, rear end panel bent, rear bumper reinforcement bent/fractured, rear boot lid dented, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and we have not authorized any repairs.

7 RECOMMENDATION

Final cost of repairs

\$4,800.00 (lump sum basis)

No. of days taken

Four (4)

ASSESSMENT OF DAMAGE AND COSTS

Report no:

351M0818.KJM

Vehicle no:

SLB7428B

A SPARE PARTS

			Assessed	Re	pairer's	Revised
Descr	ription	Qty	Condition		mount	Amount
Rear bumper	15.32	1	dented/top bulged/cracked	TO/ac	1,600.00	1,600.00
Rear bumper side reta	ining bracket	2	to reuse	41	300.00	0.00
Rear bumper reinforce	ement 7/10	1	bent/fractured	50	730.00	730.00
Rear bumper centre p	lastic retaining beam	1	bent/warped	one	75.00	75.00 _
Rear bumper clip	60	10	necessary	zje	100.00	100.00
Reverse sensor (set)	205×2=410	4	dented/shorted	4	1,000.00	1,000.00 72
Tow cover		1	scraped	11	55.00	55.00 X
Rear bumper side refle	ector LH	1	to reuse	17	45.00	0.00
Rear bumper side refle	ector RH	1	to reuse	17	45.00	0.00
Rear end panel		1	to repair	1	850.00	0.00
Rear end panel garnisi	h	1	to reuse	10	130.00	0.00 🐰
Rear end panel garnish	h clip	4	to reuse	12	40.00	0.00
LH taillamp assy		1	casing distorted/lens split	11	600.00	600.00
RH taillamp assy		1	casing distorted/lens split	11	600.00	600.00
Rear boot lid		1	to repair	1	1,650.00	0.00 🗴
Rear boot lid inner loc	k assy	1	to repair	11	240.00	0.00
Rear boot li d'BMW' lo	ogo	1	necessary	11	75.00	75.00 >
Rear boot lid '523!' en	nblem	1	necessary	11	70.00	70.00
			Subtotal of the above		8,205.00	4,905.00
			Discount 10%		820.50	490.50
	279	3.8	Total cost of parts:		7,384.50	4,414.50
	28	0				
LABOUR						V
To apply anti-rust und	ercoat for the affected	rearr	ortion		120.00	17 60.00

В	LA	B	O	UR
---	----	---	---	----

To apply anti-rust undercoat for the affected rear portion.	120.00	60.00
To check wiring.	45.00	30.00
To instal reversing sensors and programme ECU to recognise sensors.	150.00	120.00
Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts and body panels.	900.00 400	hearnan
Spray painting of the rear bumper, rear end panel, rear boot lid, spare tyre panel and necessary areas.	1,000.00	750.00

Total cost of labour:	2,215.00	1,560.00

Total cost of repair: 9,599.50 5,974.50 Report no:

351M0818.KJM

Vehicle no:

SLB7428B

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$5,974.50

. (a) The final cost of repair based on lump sum repairs would be

\$4,800.00

(b) The number of days taken by the repairs would be

Four (4)

(1st Reinspection conducted on 21st August 2018)

(Post Repair Inspection conducted on

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its preaccident condition.

Yours faithfully

Liaw Leong San

Licensed Automotive Appraiser

Dated:

3 October 2018

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

Hoo Sio Fooi	
28 Flora Drive	
#01-53	
Singapore 506951	

Invoice no:	POS0351/18
Date:	3 October 2018
Report no:	351M0818.KJM
Vehicle:	SLB7428B

INVOICE

No	Item Description	Qty	Unit Price	Total Amount (\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			649.00
GD(\$)	: Six hundred and Forty-nine only	_	Grand Total:	649.00

[&]quot;Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

Authorised Signature

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby con aforesaid.	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	20/08/2018 10:53
Date Of Accident	18/08/2018 15:50
kact Location Of Accident PIE TOWARDS CHANGI AIRPORT BEFORE EUNOS EXIT	
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLB7428B
Insured/Policyholder	
Name Of Registered Owner	HOO SIO FOOI
NRIC No	S7871269D
Email Address	GLENNLHL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92708298
Alternative Phone No	OFFICE-92708298
Vehicle Particulars	
Manufacturer	BMW
Model	523I-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO

If No, Please state action to be taken

Vehicle Category

THIRD PARTY

PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy

Policy Number A80435798QMX

Cover Note Number

Driver

Name of Driver LIM HOCK LIN NRIC No S7935824Z Date Of Birth 13/11/1979 Occupation INDOOR Date Of Driving Pass 02/12/1998

Driving Experience 19 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97807049

Fax Number

Contact Number

EMail Address GLENNLHL@GMAIL.COM Address

28 FLORA DRIVE #01-53

Postcode

506951

Was driver an employee of the Insured's Company NO

SPOUSE

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: HOO SIO FOOI

GENDER:

FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLW6483L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

	PZE	TOWARDS	CHRAFT	ASTORT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ENTER DE LA COMPANIA DEL COMPANIA DE LA COMPANIA DE LA COMPANIA DEL COMPANIA DE LA COMPANIA DEL COMPANIA DEL COMPANIA DE LA COMPANIA DE LA COMPANIA DE LA COMPANIA DE LA COMPANIA DEL COMPA	
On 18/8/19	
ON 15/5/18 WHILE DRIVING ALONG PLE TOWARDS CHARLE STREDET A	
VEHICLE HELF ME SILL 6483L CORNER NO STILL HUZ 3912(2775) H	GT.
MY ULHICLE SEB 7428B [PRIVER ; ILM HELP LIN 57835824 Z) FROM	BEHZAY
THE LOCATION IN BEFORE EUROS ENTEREDE LAMPTON 437/18/4 GISS	DHKY
TRAFFIC WAS SLOW MOUZALE AT THAT TOME, I WAS WITH MY WIF	15
IN THE CAR DURING THE ACCIDENT NO BODY WAS SNIWED . NOT RE	ENEN!
CLARATION	

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN Na.:

Sketch Plan Pg. 3



and the second second



Dwer: 92708298.

Driver: 97807049

BMW523 i glennth leginail-am

REPUBLIC OF SINGAPORE IDENTITY CARD NO. S7935824Z

S7935824Z

LIM HOCK LIN

林 稿 森 CHINESE

Date of turn. 13-11-1979 CountyPage of both SINGAPORE

13902-

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with <7 passengers, exclusive 18 Oct 2001 of the driver; and other motor solution < 2500kg

NP 426A

Licence No. 578712860

S7871269D

MALAYSIAN

0. 30-11-1898

28 FLORA DRIVE #01-53 SINGAPORE 508851 HRIC No: \$78712680

Date 02/03/2017

1304667

Driver License 1935 dde: 2/12/1993 -- 57935824Z

23-04-2014


28 FLORA DRIVE #01-53 SINGAPORE 508951 NRIC No: 57935824Z

Date 02/03/2017

















Accident Photo
















Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 21/08/2018 10:00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report 21/08/2018 09:54

Date Of Accident 18/08/2018 16:00

Exact Location Of Accident PIE JLN EUNOS EXIT

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

NORMAL USAGE

Vehicle Registration Number SLW6483L

Insured/Policyholder

Name Of Registered Owner BORNEO MOTORS (S) PTE LTD

Co Reg No 196700086Z

Email Address CERIGWEN.NG@INCHCAPE.COM.SG

Mobile Phone No.

Alternative Phone No. Office-81231429

Vehicle Particulars

Manufacturer TOYOTA

Model CAMRY-2.0 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken REPORTING ONLY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number B 29089136 MCY

Cover Note Number

Driver

Name of Driver NG JING HUI CERIGWEN

NRIC No. S9126277J Date Of Birth 29/07/1991 Occupation INDOOR

Date Of Driving Pass 28/11/2014

Driving Experience 3 YEARS AND 8 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-81231429 Fax Number

Contact Number

EMail Address

CERIGWEN.NG@INCHCAPE.COM.SG

Address

BLK 142 SIMEI ST 2 #03-100

Postcode

520142

YES

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLB7428B

Vehicle Make/Model/Colour

BMW/523I/SILVER

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIM HOCK LIN

NRIC/Passport Number

S7935824Z

97807049

Contact Number

28 FLORA DR #01-53

Address Postcode

Insurance Company Name

506951

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- . Rease report <u>sportestly</u> the details of the accident to speed up the claims process.
- 2. This Formmost be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any willul inscrepresentation or withholding of material facts may allow insurance companies to respecting policy liability.
- 4. The issue and acceptance of this Formity insurance companies is not an admission of policy liability on the part of the insurance companies.
- a. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the incurers of the GIA Records Management Carmin established by the General Insurance Association
- of Singapore (GIA) for exchiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the ceisire and to copies of the report being made available aforesaid.
- 5. Consent under the Personal Data Protection Act (PDPA)
- Linderstand, acknowledge, agree and consent that
- (a) My insurer, my workshop and the General historics Association of Singapore ("GIA") may are permitted to collect, use, disclose under process my personal data/personal aformation set out in this [lost) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "linsurers"), the insurers' insurers' law years have from the Monetary Authority of Singapore and any resevant powers and agency faulthority (such as the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the suttainent of the claims and any recessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any anguless by ite.
- [N] administering my chiefs (including the making of correspondence, sightments, invoices, reports or nolices to me, which could involve disclosure of cortise personal data about me to bring about delivery of the same as wiell as no the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling another dealing with my claims.
- (colectively the "Purpeyys")
- (b) all enucer(s) who have insured vehicle(s) involved in the accident and the insurers law yers law firms, may have permeted to called, use, declines and/or process my Personal Informed in the above Purposes, and

. .

(c) my Personal information esystem be disclosed by any of the hausers and/or GM to their third party service providers or agents. Lecturing their lawyers/law firms), which may be seed outside of Singapore, for one or more of the above Purposes.

folloyficktier's Signature / Date & Time	Driver's Signature (# driver is not the policyholder) / Date & Tane	Wheesed by Reporting Centre Personnel
Sketch Plan		
	A 56874	LA IS
	1-1-11-100	
	() Sc ~ 6	1836

while the service of	(BRUFELD) if	William A	W.	(va)	dWMr4	a. (DIMMA I
		44			,		
LU64(3L)							
						_	
				_			
						_	
				_			
						_	
				_			
			_			_	
						_	
				_			
			_	_		_	
				_			
			_		_	_	
						_	
eclaration							
We decide the foregoing particulars are	true in every respect.						
					13	1	
					V	1	
- 1	A.				7	-	

Describe Circumstances of the Accident



Contract Square 12 of

Willia Toward Watapo TaPPT Lil

Certificate of Insurance

THE MALE THE PARTY SEE AND THE SAND THE

40	MOTORWAX PULB-COMMERCIAL
	Comprehensive 1
Ċ	Farme No.
	The West and State of Section of Value
3	Name of Telephones.
- (8	Effective State of the Communication of this Friends but the survivines of the ACC
12	
- 7	See Chiery However
	Parametric Common of Personal and East Top provide
	The control of the street of the control of the control of the street of the control of the cont
	FAMILY AND SECTION
	A STATE OF THE PARTY OF THE PAR
	THE RESERVE OF THE RELATED ASSAULT CAN BE CONSIDER OFF AT ANY REPRESENT OF THE PROJECT OF THE ASSAULT

PLOTE PER LA CONTRACTOR DE LA CONTRACTOR

MBC-running thingspoon for the

tore we

NO STATE SHADOW A COLOR



REPUBLIC OF SINGAPORE





(HUANG JINGHUI)

并 新 里 CHRESE

29-07-1991 P SING APORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES:

INFECTIVE DATE

591262773

18-01-2008

APT BLK (4) NUMBER STREET () PGS-NGG SURGARCOUS \$20544)

MP4201







Accident Photo







...CLAIM SUBFOLDER...(Pending for Survey Report) Paper Survey

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	Submitted	Ins Auth'ed	Status	
Main	20 Aug 2018		21 Aug 2018 09:33 Edit Adj Rpt	5\$2,800.0 Edit Estim	1 00	2,800.00 New Rpt		Pending for Report Cancel Ca	Martin Martin
	Main	R	eference	Clai	im Details		Documents		Show All
CLAIM S	UBFOLDER DE	TAILS				[Created	by insurer]		
Insured:	BORNEO	HOTORS (SING	PORE) PTE LTD,	Co. Reg. No.:	196700088	SZ.			
Main Claimant:	H00 SI0	FOOI, ID: S78	71269D						
Vehicle Re	SLB742	88		D	ate of Loss		3 00:00 - :59 and 21 Days Fro	m LTA Reg Dat	e (Man Yr))
Claim Typ	e: TP / 567	782			olicy/Cover ote No.:	29089136MCY (Comprehensive) Coverage: 01/07/2018 - 30/06/2019			
Vehicle Re No. (Insured):	SLW6483	L			olicy No. Claimant):				
************					xcess:				
Repairer:	Khek Joo	Motor Worksho	p (HQ) BLK 9004 TA	AMPINES STRE	ET 93 #01	-94, 528838	Tampines - Tel: 67	854258	
Handling Insurer:			ore) Pte. Ltd. (HQ)						
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [)	tandled by	MARCUS CHI	UA] [Final R	t due 02/11	/2018]
Adj Asg. Remarks:	Third Party	Pre-Repair Surve	ry. Insured non-repo	orting Contact	: Mr Ng We	e Khiang @ 9	616 6658		
ASSOCIA	TED MAIL RE	CEIVED					Vier	w All Comp	ose Case Mai
 MSIG_ 	SG (31/10/2018); Report Send	Back Alerts - SLB7	428B (TP)					
ALL ASS	OCIATED TAS	KS ⁼				View All	search Tasks C	reate New Task	Complete
Due Da		Type Task	Group Subjec	t Handler	Assig	ned By	Completed On	Created (On Done

Merimen e-Claims Page 1 of 3

Claim Documents

*SLB7428B (567782)

[SLW6483L]

TP

HOO SIO FOOI

Aug 18 2018 12:00AM

[BORNEO MOTORS (SINGAPORE) PTE LTD]

Khek Joo Motor Workshop

Ass	essment Reports		1 per p	age v	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/08/18 14:29	Accident Statement From:SC - Reg. No: SLW6483L, Claimant: BORNEO MOTORS (5) PTE LTD	0	Load HTM	
Pho	otos/Images		3 per p	age V	V
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/08/18 09:31	Chassis Number	0	Load JPG	~
2	22/08/18 09:31	Odometer Reading	0	Load JPG	✓
3	22/08/18 09:32	General View	0	Load JPG	V
4	22/08/18 09:32	General View	0	Load JPG	V
5	22/08/18 09:32	General View	0	Load JPG	V
6	22/08/18 09:32	General View	0	Load JPG	V
7	22/08/18 09:32	General View	0	Load JPG	2
8	22/08/18 09:32	General View	0	Load JPG	V
9	22/08/18 09:32	General View	0	Load JPG	✓
10	22/08/18 09:32	General View	0	Load JPG	V
11	22/08/18 09:32	General View	0	Load JPG	N.
12	22/08/18 09:32	General View	0	Load JPG	V
13	22/08/18 09:32	General View	0	Load JPG	V
14	22/08/18 09:32	General View	0	Load JPG	2
15	22/08/18 09:32	General View	0	Load JPG	V
16	22/08/18 09:32	General View	0	Load JPG	V
17	22/08/18 09:32	General View	0	Load JPG	V
18	22/08/18 09:32	General View	0	Load JPG	₩.
19	22/08/18 09:32	General View	0	Load JPG	V
20	22/08/18 09:32	General View	0	Load JPG	V
21	22/08/18 09:32	General View	0	Load JPG	2
22	22/08/18 09:32	General View	0	Load JPG	V
23	22/08/18 09:32	General View	0	Load JPG	V
24	22/08/18 09:32	General View	0	Load JPG	2
25	22/08/18 09:32	General View	0	Load JPG	2
26	22/08/18 09:32	General View	0	Load JPG	V
27	22/08/18 09:32	General View	0	Load JPG	V
28	22/08/18 09:32	General View	0	Load JPG	2
29	22/08/18 09:32	General View	0	Load JPG	V
30	22/08/18 09:32	General View	0	Load JPG	V
31	22/08/18 09:32	General View	0	Load JPG	V
32	22/08/18 09:32	General View	0	Load JPG	V
33	22/08/18 09:32	General View	0	Load JPG	W

Ass	essment Reports		1 per p	age V	V
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	22/08/18 09:32	General View	0	Load JPG	V
35	22/08/18 09:32	General View	0	Load JPG	V
36	22/08/18 09:32	General View	0	Load JPG	V
37	22/08/18 09:32	General View	0	Load JPG	V
38	22/08/18 09:32	General View	0	Load JPG	V
39	22/08/18 09:32	General View	0	Load JPG	V
40	22/08/18 09:32	General View	0	Load JPG	V
41	22/08/18 09:32	General View	0	Load JPG	V
42	22/08/18 09:32	General View	0	Load JPG	V
110	NAME OF TAXABLE PARTY.	General View	0	Load JPG	V
43	22/08/18 09:32		0	Load JPG	V
44	22/08/18 09:32	General View	0	Load JPG	V
45	22/08/18 09:32	General View	- 172	100 miles	-
46	22/08/18 09:32	General View	0	Load JPG	V
47	22/08/18 09:32	General View	0	Load JPG	Z
48	22/08/18 09:32	General View	0	Load JPG	☑
49	22/08/18 09:32	General View	0	Load 3PG	₹
50	22/08/18 09:32	General View	0	Load 3PG	V
51	22/08/18 09:32	General View	0	Load JPG	✓
52	22/08/18 09:32	General View	0	Load JPG	V
53	22/08/18 09:32	General View	0	Load JPG	2
54	22/08/18 09:32	General View	0	Load JPG	V
55	22/08/18 09:32	General View	0	Load JPG	V
56	22/08/18 09:32	General View	0	Load JPG	2
57	22/08/18 09:32	General View	0	Load JPG	8
58	22/08/18 09:32	General View	0	Load JPG	V
59	22/08/18 09:32	General View	0	Load JPG	V
-		General View	0	Load JPG	V
60	22/08/18 09:32	NOTICE AND DESCRIPTION OF THE PROPERTY OF THE	0	Load JPG	V
51	22/08/18 09:32	General View	0	Load JPG	<u>V</u>
62	22/08/18 09:32	General View	0	Load JPG	V
63	22/08/18 09:32	General View			1000
64	22/08/18 09:32	General View	0	Load JPG	Z
65	22/08/18 09:32	General View	0	Load JPG	V
66	22/08/18 09:32	General View	0	Load JPG	✓
67	22/08/18 09:32	General View	0	Load JPG	2
68	22/08/18 09:32	General View	0	Load JPG	Y
69	22/08/18 09:32	General View	0	Load JPG	V
70	22/08/18 09:32	General View	0	Load JPG	V
71	22/08/18 09:32	General View	0	Load JPG	20
72	22/08/18 09:32	General View	0	Load JPG	V
73	22/08/18 09:32	General View	0	Load JPG	~
		Record of the control			
Doc	cumentation		1 per	page: V	1
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Prin
1	20/08/18 17:15	TP PRI	0	Load PDF	
2	20/08/18 17:15	E-FILE REPORT (SLB74288)	9	Load PDF	
3_	20/08/18 17:58	TP LIST OF SJE & OUR REJECTION REPLY & NOMINATED LKK	0	Load PDF	-
4	30/10/18 19:38	TP SURVEY REPORT	9	Load PDF Thumbnail	Prin
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load PDF	
1_	05/11/18 17:01	Colour Photo Colour Photo	ő	Load PDF	-

Merimen e-Claims Page 3 of 3

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18015190/UVD3E2-1

Date:

05/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29089136MCY

Claimant Vehicle SLB7428B No:

Insured Vehicle No:

SLW6483L

Date of Loss:

18/08/2018

Nature of Claim:

TP

Claim No: 567782

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLB7428B

Make & Model:

BMW 5231, 2.5 (A)

Engine No:

08977745N52B25AF

Reg. Date: Colour:

28/06/2011 (Man. Year: 2011)

Chassis No: Odometer.

WBAFP32070C866195

160673 km

Silver

Engine Capacity: 2497 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

225/55 R17

Rear Tyre Size:

225/55 R17

Front Left Side:

Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

Front Right Side: Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,384.50	2,512.80	4,871.70	65.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,215.00	1,030.00	1,185.00	53.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,599.50	3,542.80	6,056.70	63.09
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	9,599.50	2,800.00	6,799.50	70.83

INSPECTION

Date of Assignment:

21/08/2018

Date Inspected:

21/08/2018 Inspected At:

Khek Joo Motor Workshop (HQ)

BLK 9004 TAMPINES STREET 93 #01-94

Singapore 528838

Estimated Period of Repair.

3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 4

REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2018)
Parts:	143	BMW 523I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, r	no print-code for SLB7428B)
Validity:		es are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented / Deformed	1,600.00 FL	*1,532.00 FL
2	2	*REAR BUMPER SIDE RETAINING BRACKET	Not Necessary	300.00 FL	*-FL
3	1	*REAR BUMPER REINFORCEMENT	Dented	730.00 FL	*715.00 FL
4	1	*REAR BUMPER CENTRE PLASTIC RETAINING BEAM	Cracked	75.00 FL	*75.00 FL
5	10	*REAR BUMPER CLIP	Necessary	100.00 FL	*60.00 FL
6	1	*SET REVERSE SENSOR (4PCS)	Shorted-2pcs only	1,000.00 FL	*410.00 FL
7	1	*TOW COVER	Not Necessary	55.00 FL	*-FL
8	1	*REAR BUMPER SIDE REFLECTOR LH	Not Necessary	45.00 FL	*- FL
9	1	*REAR BUMPER SIDE REFLECTOR RH	Not Necessary	45.00 FL	*- FL
10	1	*REAR END PANEL	Repair	850.00 FL	*-FL
11	1	*REAR END PANEL GARNISH	Not Necessary	130.00 FL	*- FL
12	4	*REAR END PANEL GARNISH CLIP	Not Necessary	40.00 FL	*-FL
13	1	*LH TAILLAMP ASSY	Not Necessary	600.00 FL	*-FL
14	1	*RH TAILLAMP ASSY	Not Necessary	600.00 FL	*-FL
15	1	*REAR BOOT LID	Repair	1,650.00 FL	*-FL
16	1	*REAR BOOT LID INNER LOCK ASSY	Not Necessary	240.00 FL	*- FL
17	1	*REAR BOOT LID BMW LOGO	Not Necessary	75.00 FL	*-Fl
18	1	*REAR BOOT LID 523I EMBLEM	Not Necessary	70.00 FL	*-Fl
F=Fn	anchise	part. L=ListItemDisc.			
			Sub Total (S\$)		2,792.00
		- List Item Discount on L Items	10.00/10.00% (S\$)	820.50	279.20
			Total Parts (S\$)	7,384.50	2,512.80

Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items		~	
1	TO APPLY ANTI-RUST UNDERCOAT FOR THE AFFECTED REAR PORTION	New	120.00	0.00
2	TO CHECK WIRING	New	45.00	30.00
3	TO INSTAL REVERSING SENSORS AND PROGRAMME ECU TO RECOGNISE SENSORS	New	150.00	50.00
4	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS AND BODY PANELS	New	900.00	400.00
5	SPRAY PAINTING OF THE REAR BUMPER, REAR END PANEL, REAR BOOT LID, SPARE TYRE PANEL AND NECESSARY AREAS	New	1,000.00	550.00
	Gross Labou	r Cost (S\$)	2,215.00	1,030.00
	Report was unsubmitted during	this print-out		

< END OF ESTIMATES >