

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 21 Dec 2018

Preliminary Advice

Vehicle No	: SDG6833P	Accident Date	: 29/10/2018
Make	: BMW 520I	Policy No.	: 27530845SMP
Assignment Date	: 01/11/2018	Excess	: S\$750.00
Date of Inspection	: 02/11/2018	Est. Duration of Repair	: 3 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,165.45 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	3,744.95 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,744.95

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	66,272.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,728.00

Remarks

(X) The vehicle is economical for repair. Supplementary amount is \$ 247.00.

() The above survey was conducted on a 'without prejudice' basis.