

ASS. REC. BY:

REF:

CS/FCI180/9876/Krd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 01/11/18 @ 2:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 909M

Insured:

SHA 1608R

at Workshop m/s

Transcab

Tel:

6287 6666

of

No. 2 AMK 84-63

Policy No:

Claim No:

218007866 MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/10/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:31pm @ 1/11/18

Person Contacted:

Candy

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHD 909M - C3 / FCI 74052696 / Kvm3u2	DOA: 21/11/2013
	SHA 1608R - CS / FCI 16000261 / Ftb2	DOA: 01/01/2016
2/11/18	Email preli revised to FCI	
7/11/18	Final fig \$1475.06 (Red 18,809.24, 93M)	

ASS. REC. BY:

REF: FCZ/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHO 909M

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Longitude

c.c

1993

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

84753

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABLI5AUC 283222

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size:

F: Giti

215/60R16

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

27/10/18

D.O.I.

1/11/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rt o/s down mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/11 File pass to Catherine

RECEIVED 07 NOV 2018

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2) File - typist

Days Of Repair:

1

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Fines

Others

TOTAL

10x15=150

130+150

50

50

11

431

Report Format:

Lump Sum / I.B.I. (\$

cws

1475.06



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007866MFSH

Our ref: CS/FCI18019876/Kvd3

Date : 2/11/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 909M


We thank for your instruction on 1/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/11/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$20,284.30
Revised Estimate Amount	: S\$1,475.06
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s door mirror



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	01-11-2018	Our Ref No. D18007866MFSH
Accident Date	27-10-2018	Claim Type. Third Party
Insured Vehicle	SHA1608R	Third Party Vehicle. SHD909M
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 7 November 2018 10:47 AM
To: 'Ng Wai Yin'; 'calvin.er'
Cc: jasminetan@transcab.com.sg; SUR
Subject: SHD 909M-DOA: 27/10/2018 (FCIL TP)
Attachments: MARK EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Please submit \$1475.06 @ 1 working day.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 2 November 2018 3:15 PM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007866MFSH/1, SHD 909M
Attachments: SHD 909M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 909M
Date of survey: 1/11/2018
Number of days : 1 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 1 November 2018 2:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007866MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 1 November 2018 2:21 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007866MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD909M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003181
Chassis No.:	VF1ABL15AUC283222
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,327.00
Total Rebate Amount:	\$42,325.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Oct 2018

OK

Trans-cab Auto Services Pte Ltd

AAD1810-283

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 909M

Not Authorized
Recovery B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 909M ✓

VF1ABL15AUC283222

RENAULT

LATITUDE

27.10.18

FIRST CAPITAL

PART		LIST	
1	BUMPER COVER FRT	\$	<i>N</i> 1,259.42
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08
1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15
1	FENDER PANEL FRT RH	\$	<i>N</i> 783.83
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>N</i> 2,844.66
1	DOOR MIRROR ASSY RH	\$	<i>CM</i> 1,483.40 ✓
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sn</i> 466.51 X
1	ROCKER PANEL INNER RH	\$	<i>N</i> 1,024.79 X
1	ROCKER PANEL CENTER RH	\$	<i>N</i> 990.25 X
TOTAL		\$	13,451.44
10%		\$	1,345.14
		\$	12,106.30

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>nn</i> 80.00 X
1	FRONT DOOR STICKER 'Classic'	\$	<i>nn</i> 50.00 X

Trans-cab Auto Services Pte Ltd

AAD1810-283

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 909M

1	BUMPER CLIP FRT	\$	nn	66.00	X
1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1	WHEELARCH CLIP FRT RH	\$	nn	30.50	X
TOTAL		\$		318.00	

TOTAL PARTS \$ 12,424.30**LABOUR**

Putty and spray painting of the affected portion.	\$	3,000.00	601
To rust-proofing of the affected areas.	\$	nn	170.00 X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn	380.00 X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn	380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	nn	380.00 X

TOTAL \$ 7,860.00**Over All Total \$ 20,284.30****PART BY PART (REPAIR DAY)****10 DAYS**
1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18019876/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1608R	Veh. Inspected	SHD 909M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007866MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	01/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283222	Colour	METALLIC WHITE / RED	
Odometer	84753	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GOODYEAR	8 mm	
L/H Rear Tyre	215/60 R16	GOODYEAR	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2018	Inspection Date	01/11/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 909M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR MIRROR ASSY RH	CRACKED	1,483.40	1,483.40
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
	LESS 10% DISCOUNT		-1,345.14	-148.34
			12,106.29	1,335.06
SPECIAL NETT ITEMS				
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/FCI18019876/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
			318.00	-
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT,BUMPER BEAM FRT,HEADLAMP PANEL FRT RH,FENDER PANEL FRT RH,DOOR PANEL FRT RH,ROCKER PANEL INNER RH AND ROCKER PANEL CENTER RH.		3,000.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			7,860.00	140.00
GRAND TOTAL			20,284.29	1,475.06

RECOMMENDED COST OF REPAIRS			1,475.06
------------------------------------	--	--	-----------------

Report Ref No. CS/FCI18019876/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.