



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 01.11.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLQ7603H TOYOTA AXIO HYBRID

To Supply

1)	1pc	rear bumper		\$ <i>de</i> 700.00
2)	1set	rear bumper clip		\$ <i>ue</i> 30.00
3)	1pc	rear bumpe left side retainer		\$ <i>ue</i> 60.00
4)	1pc	rear bumper right side retainer		\$ <i>ue</i> 60.00
5)	1pc	right tail lamp lower bracket		\$? 70.00
6)	1pc	right tail lamp		\$? 450.00
7)	1pc	left tail lamp lower bracket		\$? 70.00
8)	1pc	left tail lamp housing		\$ <i>Ry</i> 285.60
9)	1pc	left tail lamp		\$ <i>cr</i> 450.00
10)	1pc	rear boot lid		\$ <i>bt</i> 680.00
11)	1pc	rear boot lid "corolla" emblem		\$ <i>ue</i> 59.60
12)	1pc	rear boot lid "Hybrid Synergy Drive" emblem		\$ <i>ue</i> 61.70
13)	1pc	rear boot lid "Axio" emblem		\$ <i>ade</i> 48.60
14)	1pc	rear boot lid weatherstrip		\$ <i>ut</i> 120.00
15)	2pcs	rear boot lid hinges	@\$157.60	\$ <i>Ry</i> 315.20
16)	1pc	rear boot lid lock		\$ <i>bt</i> 90.00
17)	1pc	rear boot lid catch		\$ <i>bt</i> 50.00
18)	1pc	rear end panel		\$ <i>bt</i> 380.00
19)	1pc	rear end panel top garnish		\$ <i>de</i> 180.00
20)	1set	rear end panel top garnish clip		\$ <i>ue</i> 20.00

Sub total parts \$ 4,180.70

Less: 25% discount	\$	(1,045.18)
	\$	3,135.52

To supply S.Nett parts

1) 1set reverse sensor	\$	200.00
-------------------------	----	--------

Sub total S.Nett parts	\$	200.00
------------------------	----	--------

L/charges

1) To tuff kote	\$	150.00
------------------	----	--------

2) To transfer rear boot lid trim board, mechanism parts	\$	50.00
---	----	-------

3) To remove rear bumper, cut / welding rear end panel, knock floor panel, left wheel house panel, left rear fender. Remove & replace rear boot lid, rear bumper & etc. To align rear boot lid & rear bumper	\$	900.00
---	----	--------

4) To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel, floor panel & left rear fender. To polish	\$	900.00
--	----	--------

Sub total L/charges	\$	1,850.00
---------------------	----	----------

Estimated total	\$	5,185.52
-----------------	----	----------

Taufhin 97445749
 01/11/18 @ 1710
 Resurvey after repair.
 05 days
 Sure (Henderson)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: