

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5473A**AAD1810-287***Not Authorised*
6/1/2018

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5473A

VF1ABL15AUC280958

RENAULT

LATITUDE

29.10.18

AXA**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bumper</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Del Div</i> 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>Bro</i> 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Div</i> 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Mis</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>Bz</i> 914.08 ✓
13	1	TOW COVER FRT	\$	<i>Del</i> 28.61 ✓
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Del</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Bz</i> 89.79 ✓
19	1	FRONT BRACE PANEL	\$	<i>Bz</i> 177.22 ✓
20	1	HORN	\$	<i>SL</i> 314.17 X
21	1	HORN BRACKET	\$	<i>N</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>Bz</i> 1,184.43 ✓
23	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43 X
24	1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15 X
26	1	BONNET	\$	<i>Bz</i> 1,941.63 ✓
27	1	BONNET INSULATOR	\$	<i>SL</i> 405.73 X
28	1	BONNET STRUT LH	\$	<i>SL</i> 88.61 X

Trans-cab Auto Services Pte Ltd**AAD1810-287**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5473A

29	1	BONNET STRUT RH	\$	SL 88.61 X
30	1	BONNET HINGE LH	\$	Diy 348.31 ✓
31	1	BONNET HINGE RH	\$	N 3,548.31 X
32	1	BONNET LOCK	\$	Bz 305.48 ✓
33	1	BONNET CABLE	\$	SL 119.19 X
34	1	BONNET CABLE COVER	\$	SL 161.03 X
35	1	BONNET SEAL OUTER	\$	SL 92.36 X
36	1	BONNET SEAL INNER	\$	SL 157.28 X
37	1	FENDER PANEL FRT LH	\$	Bz 783.83 ✓
38	1	WHEELARCH FRT LH	\$	SL 278.84 X
39	1	FENDER BRACKET LOWER LH	\$	SL 15.79 X
40	1	FENDER INSULATOR LH	\$	SL 130.84 X
41	1	FENDER PANEL FRT RH	\$	N 130.84 X
42	1	WHEELARCH FRT RH	\$	SL 278.84 X
43	1	FENDER BRACKET LOWER RH	\$	SL 36.11 X
44	1	FENDER INSULATOR RH	\$	SL 130.84
45	1	WIPER RESERVOIR	\$	SL 348.25
46	1	WIPER RESERVOIR NECK	\$	SL 136.11
47	1	WIPER RESERVOIR MOTOR	\$	SL 270.06
48	1	AIR CLEANER LOWER	\$	SL 271.26
49	1	AIR CLEANER HOSE	\$	SL 76.14
50	1	BASE BATTERY TRAY	\$	SL 363.40
51	1	AIR CLEANER BOX	\$	SL 464.20
52	1	TURBO DUCT	\$	SL 1,027.80
53	1	A/C HEATER VALVE	\$	SL 484.50
54	1	SUBFRAME OUTER FRT	\$	Bz 2,652.45 ✓
55	1	SUBFRAME BRACKET OUTER LH	\$	N 92.36 X
56	1	ENGINE UNDERTRAY	\$	SL 564.98 X
57	1	A/C CONDENSER	\$	2,020.37 ?
58	1	A/C CONDENSER GARNISH LH UPPER	\$	SL 39.67
59	1	A/C CONDENSER GARNISH RH UPPER	\$	SL 39.67
60	1	A/C CONDENSER GARNISH LH	\$	SL 58.81
61	1	A/C CONDENSER GARNISH RH	\$	SL 59.60
62	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SL 208.39
63	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SL 658.72
64	1	A/C PIPE COMPRESSOR	\$	SL 334.29
65	1	A/C PIPE	\$	SL 658.72
66	1	A/C COMRPESSOR	\$	SL 2,684.61

Trans-cab Auto Services Pte Ltd**AAD1810-287**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5473A

67	1	AIR COOLER	\$	S\$ 792.60	X
68	1	AIR INTERCOOLER HOSE (LONG)	\$	S\$ 1,014.13	X
69	1	AIR INTERCOOLER HOSE (Short)	\$	S\$ 375.14	X
70	1	TRANSMISSION COOLER	\$	S\$ 1,219.30	X
71	1	TRANSMISSION COOLER PAD	\$	S\$ 17.96	X
72	1	RADIATOR	\$	1,202.20	?
73	2	RADIATOR STUD UPPER	\$	S\$ 14.41	}
74	2	RADIATOR BUSH UPPER	\$	S\$ 50.12	
75	2	RADIATOR MTG LOWER	\$	S\$ 55.85	
76	1	RADIATOR FAN COWLING	\$	S\$ 820.54	
77	1	RADIATOR FAN MOTOR LH	\$	S\$ 967.36	
78	1	RADIATOR FAN MOTOR RH	\$	S\$ 1,479.46	
79	1	RADIATOR TANK	\$	S\$ 324.62	
80	1	RADIATOR HOSE UPPER	\$	S\$ 240.56	
81	1	RADIATOR HOSE LOWER	\$	S\$ 491.18	
82	1	RADIATOR TANK HOSE	\$	S\$ 61.18	
83	1	AUTO COMPUTER	\$	S\$ 5,032.17	} X
84	1	INJECTION COMPUTER	\$	S\$ 4,706.30	
85	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S\$ 5,154.52	
86	1	STEERING PUMP ELECTRIC L70Y	\$	S\$ 2,306.90	
87	1	STEERING PINION RACK L70Y	\$	S\$ 4,413.11	
88	1	LOWER ARM LH L70Y	\$	S\$ 685.76	
89	1	KNUCKLE ARM LH L70Y	\$	S\$ 846.98	
90	1	ABSORBER FRT LH L70Y	\$	S\$ 360.54	
91	1	DRIVESHAFT LH	\$	S\$ 1,747.45	
92	1	STABILIZER BAR FRT	\$	S\$ 604.65	
93	1	AIR CLEANER BOX	\$	S\$ 464.20	
94	1	AIR CLEANER HOSE	\$	S\$ 175.85	

TOTAL	\$	69,861.98
10%	\$	6,986.20
	\$	62,875.78

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	S\$ 52.00	✓
2	1SET	BUMPER CLIP FRT	\$	S\$ 66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	S\$ 12.00	X

Trans-cab Auto Services Pte Ltd**AAD1810-287**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5473A

4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	} X
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	per	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	per	30.00	}
13	1	Windscreen moulding	\$	na	120.00	
16	1SET	Front licence plate with holder	\$	hit	80.00	4552
17	1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
18	1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	X
19	1	Front left tyre	\$	per	330.00	X
20	1	Front left tyre rim	\$	per	380.00	X

TOTAL	\$	1,353.50
--------------	-----------	-----------------

TOTAL PARTS	\$	64,229.28
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	6,000.00	7001
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	601
----	--------	-----

To apply paint protection system (PPS) maintain and enhancement

\$	na	380.00	X
----	----	--------	---

To transfer of tire, rim and on wheel balancing.

\$	na	170.00	X
----	----	--------	---

Putty and spray painting of the affected portion.

\$	6,000.00	8801
----	----------	------

Trans-cab Auto Services Pte Ltd**AAD1810-287**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5473A

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 100
To replace, refix and top up coolant for radiator	\$	170.00 50
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 50
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20

Trans-cab Auto Services Pte Ltd**AAD1810-287**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5473A

To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	<i>nn</i> 200.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00	X
Towing Fees	\$	120.00	<i>Sc</i>
TOTAL	\$	18,340.00	
Over All Total	\$	82,569.28	

Repair Days (LUMP SUM)**~~20~~ DAYS***5 days*

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
