

CARZ AUTO SERVICES PTE LTD

NO 61, WOODLANDS INDUSTRIAL PARK E9

#04-04 E9 PREMIUM

S(757047)

Tel :90236692 Allan

Email:allan_goh@carzauto.com.sg

Office 69093080

GST : 201409457D

Estimate**LONPAC INSURANCE BHD**

300, Beach Road #17-04/07

The Concourse

Singapore 199555

TEL: 62507388

FAX: 62963767

Date : 31.10.2018

Vehicle No. : SLV6953C

Make/Model : MERCEDES BENZ E250

Chassis WDD2120472A480219

Date of Accident: 24.10.2018

Date of Register: 26.10.2018

No.	Parts (List Price)	QTY	List Price (\$)	Parts Discou	Final price (\$)
1	FRONT BUMPER	1	\$ 1,850.00	10%	\$ 1,665.00
2	FRONT BUMPER REINFORCEMNET	1	\$ 600.00	10%	\$ 540.00
3	FRONT BUMPER SPONGE	3	\$ 250.00	10%	\$ 225.00
4	FRONT BUMPER SENSOR	6	\$ 1,740.00	10%	\$ 1,566.00
5	FRONT BUMPER FOGLAMP MESH	2	\$ 220.00	10%	\$ 198.00
6	FRONT BUMPER FOGLAMP MESH OUTER GARNISH	2	\$ 187.60	10%	\$ 168.84
7	FRONT BUMPER LOWER GRILLE MESH	1	\$ 138.20	10%	\$ 124.38
8	FRONT BUMPER CENTRE LOWER LIP	1	\$ 387.90	10%	\$ 349.11
9	FRONT RADIATOR GRILLE BASE WITH GARNISH	1	\$ 1,287.50	10%	\$ 1,158.75
10	FRONT HEADLAMP	2	\$ 7,000.00	10%	\$ 6,300.00
11	FRONT HEADLAMP BRACKET	2	\$ 540.00	10%	\$ 486.00
12	FRONT BONNET	1	\$ 2,470.00	10%	\$ 2,223.00
13	FRONT BONNET LOGO	1	\$ 110.00	10%	\$ 99.00
Total List Price:			\$16,781.20		\$ 15,103.08

No.	Special Nett Items	QTY	NETT Price		Final price (\$)
1	NUMBER PLATE WITH CASING	1 SET	\$ 50.00		\$ 50.00
2	FRONT BUMPER CLIPS	1 SET	\$ 30.00	-	\$ 30.00
Special Nett Items Total:			\$ 80.00	-	\$ 80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Labour Charges	Price (\$)
1	To renew damaged parts, replace ,beat ,weld realign and align all parts	\$ 250 1,500.00
2	To respray affected areas	\$ 250 1,200.00
3	To tuffcoat affect areas	\$ X 150.00
4	To remove & replace reverse sensor and distance settling	\$ 30 200.00
5	To tuffcoat affect areas	\$ / X 200.00
6	To remove/refit wiring check	\$ 30 80.00
Total:		\$ 3,330.00
GrandTotal		\$ 18,513.08
<u>Estimate Report</u>		
Total Parts Cost	:	\$9494.96
Total Labour Cost	:	\$ 5190
Total Repair Cost	:	\$14684.96
Lumpsum Repair 20%:	:	\$11747.968
Surveyor name	:	
Contact Number	:	
Email	:	
No of Days Awarded	:	
Date	:	
 		
Carz Auto Services Pte Ltd		

Taufik 97495749
 'wp'
 5/11/18 @ 145pm
 2 @ 2 days
 Reasoning before pri
 Reasoning after repair.
 suv@lkhauts.com