

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9365Y

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9

KL1LA6

CHEVR

EPICA

30.10.1

CHINA

1,202. +

239.94 +

68.76 +

623.76 +

973. +

406.56 +

120.62 +

130.84 +

119.84 +

128.4 +

128.4 +

479.3 +

479.3 +

=

5,168.72 *

5,168.72 x

90. %

4,651.85 *

PART

1	1	Rear Bumper	\$	
2	1	Rear Bumper Beam	\$	44. +
3	1	Rear Bumper Centre Absorber	\$	30. +
4	1	Rear Bumper Side Retainer RH	\$	30. +
5	1	Rear Bumper Side Retainer LH	\$	=
6	1	Rear Bumper Reflectors RH	\$	104.00 *
7	1	Rear Bumper Reflectors LH	\$	600. +
8	1	Rear Bumper Tow Hook Cover	\$	60. +
9	1	Rear End Panel Outer	\$	60. +
10	1	Rear End Panel Inner Trim	\$	60. +
11	1	Rear Luggage Floor Panel	\$	60. +
12	1	Rear Luggage Floor Panel Insulator	\$	20. +
13	1	Rear Luggage Floor Panel Trim Board	\$	=
14	1	Bootlid	\$	1,460.00 *
15	1	Bootlid inner trim board	\$	4,651.85 +
16	1	Bootlid Weatherstrip	\$	104. +
17	1	Bootlid Lock - Top	\$	1,460. +
18	1	Bootlid 'CHEVROLET' Badge	\$	=
19	1	Bootlid Logo	\$	6,215.85 *
20	1	Bootlid 'EPICA LT' Badge	\$	6,215.85 x
21	1	Bootlid Reflector Centre	\$	80. %
22	1	Bootlid Reflector RH	\$	4,972.68 *
23	1	Bootlid Reflector LH	\$	
24	1	Rear Tail Lamp RH	\$	
25	1	Rear Tail Lamp LH	\$	
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	
27	1	Rear Fender RH	\$	
28	1	Rear Fender Inner Trim RH	\$	
29	1	Rear Fender LH	\$	

No

112

ASH

45
4.950

103.00 479.30 ✓

CM 479.30 ✓

R 1,110.00 X

R 1,145.00 X

SL 418.44 X

R 1,145.00 X