

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9365Y**AAD1810-301***Not Authorized*
11 Sep @ 4950h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9365Y

KL1LA69RJBB071750

CHEVROLET

EPICA 2.0

30.10.18

CHINA TAIPING**PART****LIST**

1	1	Rear Bumper	\$	<i>B</i> 1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>B</i> 239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>Sm</i> 260.00	X
4	1	Rear Bumper Side Retainer RH	\$	<i>Sm</i> 68.76	X
5	1	Rear Bumper Side Retainer LH	\$	<i>Dis</i> 68.76	✓
6	1	Rear Bumper Reflectors RH	\$	<i>Sm</i> 119.74	X
7	1	Rear Bumper Reflectors LH	\$	<i>Sm</i> 119.74	X
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sm</i> 93.00	X
9	1	Rear End Panel Outer	\$	<i>B</i> 623.76	✓
10	1	Rear End Panel Inner Trim	\$	<i>Sm</i> 263.84	X
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00	X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sm</i> 63.50	X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sm</i> 378.00	X
14	1	Bootlid	\$	<i>B</i> 973.00	✓
15	1	Bootlid inner trim board	\$	<i>Sm</i> 400.00	X
16	1	Bootlid Weatherstrip	\$	<i>Sm</i> 344.28	X
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56	✓
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>R</i> 120.62	✓
19	1	Bootlid Logo	\$	<i>R</i> 138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>R</i> 119.84	✓
21	1	Bootlid Reflector Centre	\$	<i>Sm</i> 217.97	X
22	1	Bootlid Reflector RH	\$	<i>CM</i> 128.40	✓
23	1	Bootlid Reflector LH	\$	<i>CM</i> 128.40	✓
24	1	Rear Tail Lamp RH	\$	<i>ms/cm</i> 479.30	✓
25	1	Rear Tail Lamp LH	\$	<i>CM</i> 479.30	✓
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	X
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00	X
28	1	Rear Fender Inner Trim RH	\$	<i>Sm</i> 418.44	X
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00	X

Trans-cab Auto Services Pte Ltd**AAD1810-301**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9365Y

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44 X
----	---	---------------------------	----	--------------------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 X
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sn</i> 300.00 X
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00 ✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 X
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00 X
6	1	Rear Exhaust Mounting	\$	<i>Sn</i> 300.00 X
7	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00 X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00 X
9	1	Spare Tyre	\$	<i>Sn</i> 180.00 X
10	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74 X
11	1	Rear boot sticker 'Trans-cab'	\$	<i>nn</i> 80.00 <i>30sn</i>
12	1	Rear boot sticker '6555-3333'	\$	<i>nn</i> 80.00 <i>30sn</i>

TOTAL	\$	1,390.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,827.43
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,000.00	<i>600</i>
----	----------	------------

Putty And Spray Painting Of The Affected Portion.

\$	3,000.00	<i>600</i>
----	----------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>60</i>
----	--------	-----------

To reinstall rear bumper parking sensor.

\$	170.00	<i>60</i>
----	--------	-----------

To transfer of end panel fittings and conduct
water seepage test.

\$	170.00	<i>60</i>
----	--------	-----------

Trans-cab Auto Services Pte Ltd**AAD1810-301**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9365Y

To transfer of boot fittings and conduct water seepage test.	\$	170.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X

TOTAL	\$	7,450.00
--------------	-----------	-----------------

OVER ALL TOTAL	\$	20,277.43
-----------------------	-----------	------------------

Repair Days (LUMP SUM)**10 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: