

1/11/18

INS. CASE OWNER:

CC 4/EQ11801

LKK
IDAC

Surveyor:

DOI:

Date/Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

STAGE

DATE/PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PDR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days/Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

(Agreed / Adjusted)

BOLA S/N No.:

IF NO or B 28, Ass. Lia:

Repair Cost:

SS

3852.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

6300.00

x 7 days

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GLA/ATA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost:

SS

Total:

SS

4880.00

Global Sum SS:

4880.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

CONFIDENTIAL

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

cc 1/1/18

cc 1/1/18

2/2

Surrey

Pam

REF: G01

1176N

ASSIGNMENT

From: Date: 01/11/18

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBG 8083 Y
at Workshop m/s: Sin Sheng Engineering
of 3 tech park Crescent

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{rup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBG 8083 Y Yr Regn: 2012 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HILUX DX 3.0 A cc 2982

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 36961 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDH 2010233539

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80R15
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/10/18 D.O.I. 01/11/18

Survey held at: Sin Sheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

US \$ 3600 (Ref \$ 2387.89/40%)

Color/Time, File Pass in?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CT118019831/K1eb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 31-10-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 2995A	Veh. Inspected	SHC 6223Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	31/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/10/2018	Inspection Date	30/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002654

Date : 30/10/2018

Vehicle Num. : GBC8083Y

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH2010233539/1KD2751171

Accident Date : 18/10/2018

Claim No. :

Reference : GY8632J

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BUMPER <i>cut</i>		577.40 ✓
2.	1	BUMPER SIDE BRACKET, LH <i>X 800</i>		123.50 X
3.	1	FRONT DOOR, LHS <i>Bl</i>		1,799.19 ✓
4.	2	DOOR HINGE <i>X 800</i>	101.30	202.60 ✓
5.	1	DOOR LOCK <i>X 800</i>		285.50 X
6.	1	SIDE MIRROR <i>mis</i>		865.20 ✓
7.	1	SIDE SILL PANEL <i>capote Bl</i>		365.20 ✓
8.	1	SIDE SILL PANEL, SEAL <i>Die</i>		95.20 ✓
9.	1	DOOR REGULATOR <i>Bl</i>		485.20 ✓
10.	1	DOOR WEATHERSTRIP <i>neu</i>		214.20 ✓
List Total S\$:				4401.59
25.00% Discount S\$:				1,100.39
				3301.19
NETT ITEMS :				
1.	1	COMPANY REGISTRATION STICKER		20.00 ✓
Nett Total S\$:				20
10.00% Discount S\$:				2.00
				18.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002654

Date : 30/10/2018

Vehicle Num. : GBC8083Y

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH2010233539/1KD2751171

Accident Date : 18/10/2018

Claim No. :

Reference : GY8632J

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO PANEL BEAT/REPAIR LH BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

TO APPLY NEW LOGO

TO APPLY TUFF KOTE

TOWING CHARGES

LOSS OF USE : 7 DAYS @ \$ 120/DAY

Labour Total S\$:

Resue
~~400~~ 500
~~600~~ 750.00
~~600~~ 600
~~200~~ 950.00
~~200~~ 350.00 X X 11
~~60~~ 100.00
~~60.00~~
Reg after repair
 1220
 2,210.00



SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 5,987.89

3301.19

201.00

1220.00

4541.19

20%

3632.95

45-3,600

6 days



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118019892/R1pb3

Date: 02.11.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBG8083Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.11.2018 at the premises of M/s Sin Sheng Engineering Services and have the following to report:-

Workshop Estimate Amount	: S\$	5,987.89
Revised Estimate Amount	: S\$	4,177.29
"Check" Items Amount	: S\$	363.90
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002654

Date : 30/10/2018

Vehicle Num. : GBG8083Y

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH2010233539/1KD2751171

Accident Date : 18/10/2018

Claim No. :

Reference : GY8632J

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BUMPER <i>cut</i> ✓		577.40
2.	1	BUMPER SIDE BRACKET, LH <i>X</i>		123.50
3.	1	FRONT DOOR, LHS <i>Bl</i> ✓		1,799.19
4.	2	DOOR HINGE <i>X</i>	101.30	202.60
5.	1	DOOR LOCK <i>X</i>		285.50
6.	1	SIDE MIRROR <i>mis</i> ✓		865.20
7.	1	SIDE SILL PANEL <i>caput</i> <i>Bl</i> ✓		365.20
8.	1	SIDE SILL PANEL, SEAL <i>dis</i> ✓		95.20
9.	1	DOOR REGULATOR <i>?</i>		485.20
10.	1	DOOR WEATHERSTRIP <i>neu</i> ✓		214.20
List Total S\$:				5,013.19
25.00% Discount S\$:				1,253.30
				3,759.89
NETT ITEMS :				
1.	1	COMPANY REGISTRATION STICKER	<i>neu</i> ✓	20.00
Nett Total S\$:				20.00
10.00% Discount S\$:				2.00
				18.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002654

Date : 30/10/2018

Vehicle Num. : GBC8083Y

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH201023539/1KD2751171

Accident Date : 18/10/2018

Claim No. :

Reference : GY8632J

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

LABOUR :
TO PANEL BEAT/REPAIR LH BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

TO APPLY NEW LOGO

TO APPLY TUFF KOTE

TOWING CHARGES

LOSS OF USE : 7 DAYS @ \$ 120/DAY

Labour Total SS :

Resue
4/1 900/10068
6 days
4/3
01/11/18 @ 1620
Reg after repair

400	500
600	750.00
600	950.00
300	350.00 X
60	100.00
	60.00
	2,210.00

Total SS : 5,987.89

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



YISHUN TOWING PTE LTD

Blk 4015 Ang Mo Kio Industrial Park 1, #01-502, Singapore 569631

Tel: 6458 8480 HP: 9628 8480 Fax: 6288 8480

Website: www.yishuntowing.com

Reg. No. 200106908W GST No. 200106908W

M/s SIN Sengly

WORK ORDER

No. 256434

Order By: 96130558

AT 1541 D/T

Date: 31/10/18

車牌 Vehicle No. G3G 8083Y

車型 Model T. Hiace

From: 13/012 PASIR RES

To: TECH RE CRES

Remarks:

Day/Night

Customer Signature & Company Stamp

Authorised Signature

Tow Truck No.: YK6316X

All business transactions with Yishun Towing Pte Ltd are subject to its Standard Conditions in so far as these Conditions are applicable. Copies of these conditions may be obtained upon request. Note: Please see terms & conditions on the reverse side.



Hsiao Tong (LKKAUTO)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Wednesday, 19 December 2018 3:35 PM
To: Rasul (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO)
Subject: Re: Accident Involving GBG8083Y with GY8632J on 18/10/2018
Attachments: GBG8083Y_ATA.pdf; GBG8083Y_LOC.pdf

Hi Ms Hsiao Tong,

Attached LOC document and ATA for your attention please.

Kindly assist to revert with the offer if direct settlement is in order.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On Wed, 19 Dec 2018 at 15:20, sinsheng engineering services <sinsheng1981@gmail.com> wrote:
Hi Mr Rasul,

We are agreed.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On Wed, 19 Dec 2018 at 14:58, Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Susan,

Finalised amount is \$ 3,600.00 / 6 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]

Sent: Friday, 2 November, 2018 10:47 AM

To: Rasul (LKKAuto); SUR

Cc: Admin A

Subject: Re: Accident Involving GBG8083Y with GY8632J on 18/10/2018

Hi Mr Rasul,

Please find attached.

Thank You

Regards

Susan

Sin Sheng Engineering Services

3 Tech Park Crescent

Tuas Tech Park

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477

On Tue, 30 Oct 2018 at 15:06, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Dear Officer In Charge,

We are repairer of vehicle GBG8083Y. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two(2) workings days upon receipted of this email.

Enclose Accident Statement and LTA search fee for your attention please.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection

Kindly assist to revert the liability issue if direct settlement is in order.

Thank You

Regards

Susan

Sin Sheng Engineering Services

3 Tech Park Crescent

Tuas Tech Park

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 24 December 2018 10:33 AM
To: 'sinsheng engineeringservices'
Cc: Rasul (LKKAuto)
Subject: RE: Accident Involving GBG8083Y with GY8632J on 18/10/2018 *LKK REF: CC4/EQI18019892/R1pb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$4,480.00(all-in).

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineeringservices <sinsheng1981@gmail.com>
Sent: Wednesday, 19 December 2018 3:35 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: Accident Involving GBG8083Y with GY8632J on 18/10/2018

Hi Ms Hsiao Tong,

Attached LOC document and ATA for your attention please.

Kindly assist to revert with the offer if direct settlement is in order.

Thank You
Regards

Hsiao Tong (LKKAUTO)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Monday, 24 December 2018 11:01 AM
To: Hsiao Tong (LKKAUTO)
Cc: Rasul (LKKAUTO)
Subject: Re: Accident Involving GBG8083Y with GY8632J on 18/10/2018 *LKK REF: CC4/EQ118019892/R1pb3

Hi Ms Hsiao Tong,

We are agreed. Please forward us with the Discharge Voucher.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On Mon, 24 Dec 2018 at 10:33, Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$4,480.00(all-in).

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Wednesday, 19 December 2018 3:35 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: Accident Involving GBG8083Y with GY8632J on 18/10/2018

Hi Ms Hsiao Tong,

Attached LOC document and ATA for your attention please.

Kindly assist to revert with the offer if direct settlement is in order.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Wed, 19 Dec 2018 at 15:20, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Hi Mr Rasul,

We are agreed.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On Wed, 19 Dec 2018 at 14:58, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Susan,

Finalised amount is \$ 3,600.00 / 6 days lump sum

Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Friday, 2 November, 2018 10:47 AM
To: Rasul (LKKAuto); SUR
Cc: Admin A
Subject: Re: Accident Involving GBG8083Y with GY8632J on 18/10/2018

Hi Mr Rasul,

Please find attached.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On Tue, 30 Oct 2018 at 15:06, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Dear Officer In Charge,

We are repairer of vehicle GBG8083Y. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two(2) working days upon receipt of this email.

Enclose Accident Statement and LTA search fee for your attention please.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection

Kindly assist to revert the liability issue if direct settlement is in order.

Thank You

Regards

Susan

Sin Sheng Engineering Services

3 Tech Park Crescent

Tuas Tech Park

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477



新盛机械工程服务

SIN SHENG ENGINEERING SERVICES

REGISTRATION NO : 312029/00D

No 3, Tech Park Crescent, Tuas Tech Park, Singapore 638129

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

19-Dec-18

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1, #02-25
Paya Ubi Industrial Park
Singapore 408933

Fax: 6741 4108

Tel: 6256 3561

Our ref: SSES/L2018/0416

Your

Attn: Ms Poh Kin

Dear Sir,

VEHICLE: GBG8083Y (DoA: 18/10/2018)

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill	:	3,852.00
Loss of Use: 8 days @ S\$ 120/day (including 2 day for PRI)	:	960.00
Survey Fee	:	N/A
Third Party Vehicle Insurance Search Fee	:	2.00
Total	:	<u><u>4,814.00</u></u>

Thank You

Yours faithfully

Susan Tan
OPERATIONS EXECUTIVE
Encl



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQ118019892/R1pb3

14 NOV 2018

JT LANDSCAPE PTE LTD

24 JALAN SHAER SEMBAWANG SPRINGS ESTATE

SINGAPORE 769370

ATTN: THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GY 8632J AND GBG 8083Y ON 18/10/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from GBG 8083Y against your insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, GOLDBELL LEASING PTE LTD ("The Third Party Claimant") of
NO 59, SENOKO ROAD, SINGAPORE 758123 (address),
being the owner of GBG8083Y (vehicle no.) hereby authorize
SIN SHENG ENGINEERING SERVICES ("the workshop") to act for me
with respect to my claim for repair cost and / or rental and / or loss of use ("claim") for my
vehicle bearing registration no. GBG8083Y that was damaged pursuant to the accident
which occurred on 18/10/2018 along Open Car Park of Bk 57 New Upper Changi Road
involving vehicle's GBG8083Y / GY8632J ("the
accident")

I further authorize the workshop to settle my above mentioned claim in a manner they deem
fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability in so far as the driver/owner/insurers of
the other vehicle is concerned.

Dated this 18 day of DEC (month) 2018 (year)



Signed by "the Third Party claimant"



Signed by "the workshop"

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Tax Invoice : TI002654

Date : 19/12/2018

Vehicle Num. : GBG8083Y

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH2010233539/1KD2751171

Accident Date : 18/10/2018

Claim No. :

Reference : GY8632J

Policy No. : 29004183

Amount S\$

ACCIDENT LUMP SUM REPAIR

3,600.00



SIN SHENG ENGINEERING SERVICES

M9-0010014-J

Total S\$:	3,600.00
GST @ 7% S\$:	252.00
Amount Due S\$:	3,852.00



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-168244

Date of Request: 30/10/2018

Your Ref No:

Online Purchase

Sin Shang Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129

GBG8083Y (DoA:18/10/2018)

Dear Sir/Madam,

Owner : GBL

Enquiry Date 30/10/2018
Enquiry By Wang Sye Yuen
TP Vehicle No. GY8632J
Accident Date 18/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 31/12/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GY 8632J (Insd Veh)	Your Ref. No. : DMCPHQ18-005723
	GBG 8083Y (TP Veh)	Our Ref. No. : CC4/EQI18019892/R1pb3q2
Date of Accident	18/10/2018	

Liability	100%	
Final Repair Cost	: \$ 3,852.00	
Loss of Use	: \$ 630.00	7 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	4,484.00	
Final Settlement Sum	: \$ 4,480.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	SIN SHENG ENGINEERING SERVICES	: \$ 4,480.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ18019892/R1pb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 31-12-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 8632J	Veh. Inspected	GBG 8083Y
Policy No.	DMCPHQ18-005723	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANET	Assign Date	01/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE DX 3.0 A	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2010233539	Colour	WHITE
Odometer	36961	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/10/2018	Inspection Date	01/11/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8083Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	577.40	577.40
1	BUMPER SIDE BRACKET ,LH	SERVICEABLE	123.50	-
1	FRONT DOOR ,LHS	BENT	1,799.19	1,799.19
2	DOOR HINGE @\$101.30	SERVICEABLE	202.60	-
1	DOOR LOCK	SERVICEABLE	285.50	-
1	SIDE MIRROR	MISSING	865.20	865.20
1	SIDE SILL PANEL	BENT	365.20	365.20
1	SIDE SILL PANEL ,SEAL	DISTORTED	95.20	95.20
1	DOOR REGULATOR	BENT	485.20	485.20
1	DOOR WEATHERSTRIP	NECESSARY	214.20	214.20
	LESS 25% DISCOUNT		-1,253.30	-1,100.40
			3,759.89	3,301.19
<u>SPECIAL NETT ITEMS</u>				
1	COMPANY REGISTRATION STICKER (SN)	NECESSARY	20.00	20.00
			20.00	20.00
<u>LABOUR</u>				
	TO PANEL BEAT /REPAIR LH BODY TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS.		750.00	500.00
	SPRAY PAINTING.		950.00	600.00
	TO APPLY NEW LOGO .	NOT NECESSARY	350.00	-
	TO APPLY TUFF KOTE.		100.00	60.00
	TOWING CHARGES.		60.00	60.00
			2,210.00	1,220.00
GRAND TOTAL			5,989.89	4,541.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC4/EQ118019892/R1pb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.