

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
HENG WAH HENG BLK 102 LENGKONG TIGA #03-397 SINGAPORE 410102 Contact No Mobile: 97392685	Cust No/Name	/HENG WAH HENG
	Reg No/Reg Date	SME102J / 27/07/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AJH001994
	Engine No	3A92UGT7415
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	31/10/2018/ 20:04		465 / Tay Jian Ye	32640		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER , BOOTLID, WELD AND CUT END PANEL, FLOOR , REAR LH FENDER, REAR LH TAILLAMP PANEL, REAR RH FENDER, REAR RH TAILLAMP PANEL							3850 4400.00
E PNT88000 TO TRANSFER BOOTLID TRIMS, MECHANISM TO NEW PARTS							275.00
E PNT88000 TO TRANSFER REAR PARKING SENSOR TO NEW PARTS							60 80.00
E PNT88000 TO REMOVE AND REFIT REAR END PANEL TRIM REAR FENDERTRIM , AND REAR SEAT TO FACILITATE REPAIR							275.00
E PNT88000 TO REMOVE AND REFIT REAR WINDSCREEN							240.00
A 13900099 TO REMOVE AND REFIT FUEL TANK							X 275.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, REAR BOOTLID, END PANEL, FLOOR REAR BOTH FENDER, REAR BOTH TAILLAMP PANEL							2940 3780.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							200.00
M SUNDRY TO APPLY ANTI COROSSION							60 80.00
M SUNDRY TO APPLY BODY SEALANT							150.00
M SUNDRY TO APPLY WINDSCREEN SEALANT							80.00
M SUNDRY TO SUPPLY C&C LOGO							50.00
M SUNDRY TO SUPPLY MIVEC LOGO							50.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
HENG WAH HENG	Cust No/Name	/HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date	SME102J / 27/07/201
#03-397	Date In/Mileage	/ 0
SINGAPORE 410102	Chassis No	MMBSTA13AJH001994
Contact No Mobile: 97392685	Engine No	3A92UGT7415
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	31/10/2018/ 20:04		465 / Tay Jian Ye	32640			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								220.00
TO SUPPLY PARKING SENSOR								50.00
M SUNDRY								20 50.00
TO SUPPLY REAR NUMBER PLATE								
M SUNDRY								
SUNDRIES								
M BRACKET,RR BUMPER,LH	neu				1.00	27.00	00.00	27.00
M BRACKET,RR BUMPER,RH	neu				1.00	27.00	00.00	27.00
M FACE,RR BUMPER	DE				1.00	740.00	00.00	740.00
M CLIP,FR BUMPER	neu				10.00	3.00	00.00	30.00
M REFLECTOR LH	X				1.00	22.00	00.00	22.00
M REFLECTOR RH	X				1.00	22.00	00.00	22.00
M BODY KIT, ATTRAGE, A66	neu CR				1.00	740.00	00.00	740.00
M PANEL,RR END	BT				1.00	421.00	00.00	421.00
M TRIM,RR END	BT				1.00	65.00	00.00	65.00
M BOARD,TRUNK ROOM FLOOR	BT				1.00	193.00	00.00	193.00
M DUCT,RR VENTILATOR	BT				1.00	30.00	00.00	30.00
M COVER,RR VENTILATOR	BT				1.00	40.00	00.00	40.00
M BUZZER,KEYLESS OPERATIO,RR	BT				1.00	90.00	00.00	90.00
M ANT,KEYLESS OPERATION,RR	BT				1.00	84.00	00.00	84.00
M FLOOR,RR	repair				1.00	947.00	00.00	947.00
M HINGE,TRUNK LID,LH	BT				1.00	201.00	00.00	201.00
M HINGE,TRUNK LID,RH	BT				1.00	201.00	00.00	201.00
M WEATHERSTRIP,TRUNK LID	neu				1.00	155.00	00.00	155.00
M PANEL,TRUNK LID	BT				1.00	865.00	00.00	865.00
M LATCH,TRUNK LID	BT				1.00	216.00	00.00	216.00
M MARK,ATTRAGE	neu				1.00	21.00	00.00	21.00
M MARK,THREE-DIA	neu				1.00	45.00	00.00	45.00
M GARNISH,RR END PANEL	DE				1.00	332.00	00.00	332.00
M PANEL,QTR,OTR LH	repair				1.00	748.00	00.00	748.00
M PANEL,RR COMB LAMP HSG,LH	repair				1.00	60.00	00.00	60.00
M LAMP ASSY,COMB,RR LH	CR				1.00	332.00	00.00	332.00
M PANEL,QTR,OTR RH	repair BT				1.00	756.00	00.00	756.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
HENG WAH HENG	Cust No/Name	/HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date	SME102J / 27/07/201
#03-397	Date In/Mileage	/ 0
SINGAPORE 410102	Chassis No	MMBSTA13AJH001994
Contact No Mobile: 97392685	Engine No	3A92UGT7415
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	31/10/2018/ 20:04		465 / Tay Jian Ye	32640			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL,RR COMB LAMP HSG,RH	Repair			1.00	60.00	00.00	60.00
M	LAMP ASSY,COMB,RR RH	Can /			1.00	332.00	00.00	332.00
M	STOPPER,WINDSHIELD GLASS	see /			2.00	3.00	00.00	6.00
M	SPACER,RR WINDOW	A see /			3.00	9.00	00.00	27.00

Estimate

SURVEYOR NAME: Ramon - Hp 90010068SURVEYOR SIGNATURE: [Signature]DATE: 05/11/18 @ 1535REMARKS: 13 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Confirm & accepted by _____

7% GST on	18140.00	1269.80
Nett		18,140.00
Total Payable		19,409.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.