



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info	
HENG WAH HENG	Cust No/Name	/HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date	SME102J / 27/07/201
#03-397	Date In/Mileage	/ 0
SINGAPORE 410102	Chassis No	MMBSTA13AJH001994
Contact No Mobile: 97392685	Engine No	3A92UGT7415
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	31/10/2018/ 20:04		465 / Tay Jian Ye	32640			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3850 4400.00
TO RENEW REAR BUMPER , BOOTLID, WELD AND CUT END PANEL, FLOOR								275.00
, REAR LH FENDER, REAR LH TAILLAMP PANEL, REAR RH FENDER,								60 80.00
REAR RH TAILLAMP PANEL								275.00
E PNT88000								275.00
TO TRANSFER BOOTLID TRIMS, MECHANISM TO NEW PARTS								275.00
E PNT88000								275.00
TO TRANSFER REAR PARKING SENSOR TO NEW PARTS								275.00
E PNT88000								275.00
TO REMOVE AND REFIT REAR END PANEL TRIM REAR FENDERTRIM ,								240.00
AND REAR SEAT TO FACILITATE REPAIR								275.00
E PNT88000								275.00
TO REMOVE AND REFIT REAR WINDSCREEN								275.00
A 13900099								275.00
TO REMOVE AND REFIT FUEL TANK								275.00
E PNT98000								275.00
PAINT WORK SPRAY REAR BUMPER, REAR BOOTLID, END PANEL, FLOOR								275.00
REAR BOTH FENDER, REAR BOTH TAILLAMP PANEL								275.00
A 54900099								275.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								275.00
A 10028901								275.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								275.00
USING HI-SCAN PRO TEST								275.00
M SUNDRY								275.00
TO APPLY ANTI CORROSION								275.00
M SUNDRY								275.00
TO APPLY BODY SEALANT								275.00
M SUNDRY								275.00
TO APPLY WINDSCREEN SEALANT								275.00
M SUNDRY								275.00
TO SUPPLY C&C LOGO								275.00
M SUNDRY								275.00
TO SUPPLY MIVEC LOGO								275.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
HENG WAH HENG	Cust No/Name	/HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date	SME102J / 27/07/201
#03-397	Date In/Mileage	/ 0
SINGAPORE 410102	Chassis No	MMBSTA13AJH001994
Contact No Mobile: 97392685	Engine No	3A92UGT7415
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	31/10/2018/ 20:04		465 / Tay Jian Ye	32640			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								220.00
TO SUPPLY PARKING SENSOR								
M SUNDRY								50.00
TO SUPPLY REAR NUMBER PLATE								
M SUNDRY								20 50.00
SUNDRIES								
M	BRACKET,RR BUMPER,LH	NEA			1.00	27.00	00.00	27.00
M	BRACKET,RR BUMPER,RH	NEA			1.00	27.00	00.00	27.00
M	FACE,RR BUMPER	DE			1.00	740.00	00.00	740.00
M	CLIP,FR BUMPER	NEA			10.00	3.00	00.00	30.00
M	REFLECTOR LH	X SVC			1.00	22.00	00.00	22.00
M	REFLECTOR RH	X SVC			1.00	22.00	00.00	22.00
M	BODY KIT, ATTRAGE, A66	CRA			1.00	740.00	00.00	740.00
M	PANEL,RR END	BT			1.00	421.00	00.00	421.00
M	TRIM,RR END	BT			1.00	65.00	00.00	65.00
M	BOARD,TRUNK ROOM FLOOR	CRA			1.00	193.00	00.00	193.00
M	DUCT,RR VENTILATOR	Cut			1.00	30.00	00.00	30.00
M	COVER,RR VENTILATOR	X SVC			1.00	40.00	00.00	40.00
M	BUZZER,KEYLESS OPERATIO,RR	CRA			1.00	90.00	00.00	90.00
M	ANT,KEYLESS OPERATION,RR	CRA			1.00	84.00	00.00	84.00
M	FLOOR,RR	repair			1.00	947.00	00.00	947.00
M	HINGE,TRUNK LID,LH	BT			1.00	201.00	00.00	201.00
M	HINGE,TRUNK LID,RH	BT			1.00	201.00	00.00	201.00
M	WEATHERSTRIP,TRUNK LID	NEA			1.00	155.00	00.00	155.00
M	PANEL,TRUNK LID	BT			1.00	865.00	00.00	865.00
M	LATCH,TRUNK LID	BT			1.00	216.00	00.00	216.00
M	MARK,ATTRAGE	NEA			1.00	21.00	00.00	21.00
M	MARK,THREE-DIA	NEA			1.00	45.00	00.00	45.00
M	GARNISH,RR END PANEL	DE			1.00	332.00	00.00	332.00
M	PANEL,QTR,OTR LH	repair			1.00	748.00	00.00	748.00
M	PANEL,RR COMB LAMP HSG,LH	repair			1.00	60.00	00.00	60.00
M	LAMP ASSY,COMB,RR LH	CRA			1.00	332.00	00.00	332.00
M	PANEL,QTR,OTR RH	repair			1.00	756.00	00.00	756.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
HENG WAH HENG	Cust No/Name /HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date SME102J / 27/07/201
#03-397	Date In/Mileage / 0
SINGAPORE 410102	Chassis No MMBSTA13AJH001994
Contact No Mobile: 97392685	Engine No 3A92UGT7415
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	31/10/2018/ 20:04		465 / Tay Jian Ye	32640
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M PANEL,RR COMB LAMP HSG,RH bt	1.00	60.00	00.00	60.00	
M LAMP ASSY,COMB,RR RH car	1.00	332.00	00.00	332.00	
M STOPPER,WINDSHIELD GLASS new	2.00	3.00	00.00	6.00	
M SPACER,RR WINDOW new	3.00	9.00	00.00	27.00	

Estimate

SURVEYOR NAME: Poon - Hp 90010068SURVEYOR SIGNATURE: [Signature]DATE: 05/11/18 @ 1535REMARKS: 13 days + 4 = 17 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Confirm & accepted by
Date: _____

Nett	18,140.00
7% GST on	1269.80
Total Payable	19,409.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Surveyor : RASUL - LKK
 Company : TP LONPAC
 Emailed : 15/04/19, 6pm
 Date survey : 05.11.2018

VEHICLE NO : SME 102 J
 MODEL : MIT ATTRAGE 1.2
 WIP : 32640

Material	:	\$	<u>6,824.00</u>
Labour	:	\$	<u>9,925.00</u>
Sub-Total	:	\$	<u>16,749.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>16,749.00</u>
GST 7%	:	\$	<u>1,172.43</u>
Grand Total	:	\$	<u>17,921.43</u>
Finalise By/Date	:	<u>LOI / 15/04/19</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 17 WORKING DAYS + 6 Days (3) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 23

☒ TP claim YM9424L

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
HENG WAH HENG	Cust No/Name	/HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date	SME102J / 27/07/2018
#03-397	Date In/Mileage	07/11/2018/ 7437
SINGAPORE 410102	Chassis/Package	MMBSTA13AJH001994 /CS5P
Contact No Mobile: 97392685	Engine No	3A92UGT7415
07/11/	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	15/04/2019/ 17:51	TLT	260 / AiTing	32640			
Description of Goods/ Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE BOOT LID, REAR END PANEL, REAR BUMPER, RH REAR FENDER, LH REAR FENDER, RH REAR TAILLAMP PANEL, REPAIR LH REAR TAILLAMP PANEL, REAR FLOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 3850.00
E PNT88000 TRANSFER BOOT LID TRIMS, MECHANISMS, AND ALL OTHER ATTACHMENTS TO NEW PANEL								✓ 275.00
E PNT88000 TRANSFER REAR PARKING SENSOR TO NEW PANEL								✓ 60.00
E PNT88000 REMOVE AND REINSTALL REAR END PANEL TRIM, REAR FENDER TRIMS, REAR SEAT, AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR								✓ 275.00
E PNT88000 REMOVE AND REINSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST								✓ 240.00
E PNT98000 RESPRAY REAR BUMPER, REAR BOOT LID, REAR END PANEL, REAR FLOOR, BOTH REAR FENDERS, BOTH REAR TAILLAMP PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2940.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 200.00
M SUNDRY APPLY ANTI COROSSION ON AFFECTED AREAS								✓ 60.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS								✓ 150.00
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT								✓ 80.00
M SUNDRY SUPPLY C&C LOGO								✓ 50.00
M SUNDRY SUPPLY MIVEC LOGO								✓ 50.00



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
HENG WAH HENG	Cust No/Name	/HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date	SME102J / 27/07/2018
#03-397	Date In/Mileage	07/11/2018/ 7437
SINGAPORE 410102	Chassis/Package	MMBSTA13AJH001994 /CS5P
Contact No Mobile: 97392685	Engine No	3A92UGT7415
07/11/	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	15/04/2019/ 17:51	TLT	260 / AiTing	32640			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								✓ 20.00
SUNDRIES								✓ 50.00
S SPECIALISTJOB								X 275.00
SUPPLY & REPLACE REAR LICENSE PLATE WITH PLASTIC FRAME								✓ 220.00
A 13900099								1100.00
REMOVE AND REINSTALL FUEL TANK TO FACILITATE REPAIR								
S SPECIALISTJOB								
SUPPLY ONE SET OF REVERSE SENSOR								
E PNT88000								
REPLACE LH REAR FENDER, LH REAR TAIL LAMP HOUSING PANEL								
X BRACKET,RR BUMPER,LH					1.00	✓ 27.00	00.00	27.00
X BRACKET,RR BUMPER,RH					1.00	✓ 27.00	00.00	27.00
X FACE,RR BUMPER					1.00	✓ 740.00	00.00	740.00
X CLIP,FR BUMPER					10.00	✓ 3.00	00.00	30.00
X BODY KIT, ATTRAGE, A66					1.00	✓ 740.00	00.00	740.00
X PANEL,RR END					1.00	✓ 421.00	00.00	421.00
X TRIM,RR END					1.00	? 65.00	00.00	65.00
X BOARD,TRUNK ROOM FLOOR					1.00	? 193.00	00.00	193.00
X DUCT,RR VENTILATOR					1.00	? 30.00	00.00	30.00
X BUZZER,KEYLESS OPERATIO,RR					1.00	? 90.00	00.00	90.00
X ANT,KEYLESS OPERATION,RR					1.00	? 84.00	00.00	84.00
X HINGE,TRUNK LID,LH					1.00	✓ 201.00	00.00	201.00
X HINGE,TRUNK LID,RH					1.00	✓ 201.00	00.00	201.00
X WEATHERSTRIP,TRUNK LID					1.00	✓ 155.00	00.00	155.00
X PANEL,TRUNK LID					1.00	✓ 865.00	00.00	865.00
X LATCH,TRUNK LID					1.00	? 216.00	00.00	216.00
X MARK,ATTRAGE					1.00	✓ 21.00	00.00	21.00
X MARK,THREE-DIA					1.00	✓ 45.00	00.00	45.00
X GARNISH,RR END PANEL					1.00	✓ 332.00	00.00	332.00
X PANEL,QTR,OTR LH					1.00	R 748.00	00.00	748.00
X PANEL,RR COMB LAMP HSG,LH					1.00	R 60.00	00.00	60.00
X LAMP ASSY,COMB,RR LH					1.00	✓ 332.00	00.00	332.00
X PANEL,QTR,OTR RH					1.00	✓ 756.00	00.00	756.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
HENG WAH HENG	Cust No/Name /HENG WAH HENG
BLK 102 LENGKONG TIGA	Reg No/Reg Date SME102J / 27/07/2018
#03-397	Date In/Mileage 07/11/2018/ 7437
SINGAPORE 410102	Chassis/Package MMBSTA13AJH001994 /CS5P
Contact No Mobile: 97392685	Engine No 3A92UGT7415
07/11/	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim A06 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	15/04/2019/ 17:51	TLT	260 / AiTing	32640

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LAMP ASSY, COMB, RR RH	1.00	✓ 332.00	00.00	332.00
X STOPPER, WINDSHIELD GLASS	2.00	✓ 3.00	00.00	6.00
X SPACER, RR WINDOW	3.00	✓ 9.00	00.00	27.00
X PANEL, RR COMB LAMP HSG, RH	1.00	R 60.00	00.00	60.00
X STRIKER, TRUNK LID LATCH → Supp	1.00	20.00	00.00	20.00

Z TEXT
 TP CLAIM LONPAC YM9424L
 DOA : 30.10.18
 SURVEYOR RASUL LKK 05.11.18
 REPAIR 13 DAYS + 4 days

Pro Forma

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	6,824.00	Nett	16,749.00
Labour	9,245.00	7% GST on	16749.00
Standard Menu	0.00		1172.43
Specialist Job	270.00	Total Payable	17,921.43
Diagnostics Job	0.00		
Sundry/Others	410.00		
Total(w/o GST)	16,749.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : LONPAC

Supplementary Parts For Registration No.:

Materials

1 Striker, trunk lid latch

Cost (\$)

20.00 ✓

Total

20.00

Total Materials

20.00

Labour

1 Replace LH rear fender, LH rear tail lamp housing panel

Cost (\$)

1,100.00 ✓

Total Labour

1,100.00

Taxable amount

1,120.00

7% GST


78.40

Grand total

\$ 1,198.40

Thank You.

Yours faithfully



LOI AI TING
CUSTOMER SERVICE ADVISOR
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6565 1240 / 6567 5258

Car No: Sme 102 J WIP 32610

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	Board Trunk Rear Floor	? /Supp			
2	Trunk RR End	? /Supp			
3	Buzzer Keyless	? /Supp			
4	Ant Keyless	? /Supp			
5	Latch Trunk Lid	? /Supp			
6	Trunk Lid Latch Catcher	? /Supp			
7	Panel Tail Lamp RH	? /Supp			
8	Duct Ventilator	? /Supp			
9	Fender RR LH	? /Supp			
10	Tail Lamp Panel LH	? /Supp			
11	to be removed & refit	? /Supp			\$ 245/-
12	Fuel Tank	? /Supp			
13		? /Supp			
14	Additional Rear Fender	? /Supp			\$ 1100/-
15	LH & Tail Lamp Panel LH	? /Supp			
16		? /Supp			
17		? /Supp			
18	Additional repair dry	? /Supp			\$ 4 days
19		? /Supp			
20		? /Supp			
PHOTO BEFORE PAINT		DATE	TAKEN BY		
PHOTO AFTER PAINT					
PHOTO OF DAMAGED PARTS (DPS)					
PHOTO OF CELESTE BENCH					
REMOVE & INSTALL ENGINE					
REMOVE & INSTALL DASHBOARD					
PHOTO BA SUSP & U/C REMOVE					

Model: PM17 ATW/C1-2
 Surveyor: P. Ram LLC