

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Owner : Ahmad Izwan Bin Mohamed Noor

Accident Date : 23-Oct-18

Vehicle No : JRB 905

Vehicle Model : Yamaha LC135

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front cowling inner bracket	\$ 55.00
2	Front fork tubes assy	\$ 640.00
1	Front wheel rim	\$ 280.00
1	Fork under bracket	\$ 185.00
1	Front rim shaft	\$ 45.00
1	Front rim bearing	\$ 38.00
1	Front brake disc	\$ 155.00
1	Handle bar	\$ 75.00
2	Handle bar ends	\$ 64.00
1	Hand grip (1 set)	\$ 55.00
1	Handle bar inner bracket	\$ 68.00
1	Side mirror (1 set)	\$ 80.00
1	Brake lever	\$ 40.00
2	Front signals	\$ 140.00
1	Front signal lower garnish	\$ 95.00
1	Headlamp	\$ 185.00
1	Meter assy	\$ 385.00
1	Meter cable	\$ 55.00
1	Fairing assy (1 set)	\$ 475.00
1	Front footrest bracket	\$ 65.00
2	Front footrest rubbers	\$ 70.00
1	Gear pedal	\$ 42.00
1	Brake pedal	\$ 42.00
2	Rear footrests	\$ 80.00
2	Rear footrest brackets	\$ 156.00
1	Exhaust assy	\$ 485.00
1	Exhaust protector -Chrome	\$ 60.00
1	Exhaust protector -Black	\$ 45.00
1	Rear handle	\$ 50.00
1	Chain cover	\$ 48.00
1	Seat	\$ 230.00
1	Side stand	\$ 75.00
1	Main stand	\$ 95.00
1	Rear taillamp	\$ 135.00
		\$ 4,793.00

NOT Allowed
2 hr K
L/S
to be ph. after repair
Sdy.
1/1/18

0/5 m r s
0/5 cm

4034

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Ahmad Izwan Bin Mohamed Noor

Accident Date : 23-Oct-18

Vehicle No : JRB 905

Vehicle Model : Yamaha LC135

Estimated Repair Costs

		c/f:	\$ 4,793.00
1	Rear wheel rim		\$ 20/24 280.00 ✓
1	Rear fender	4909	\$ 320 120.00 —
1	Rear fender reflector		\$ 320 40.00 —
1	Basket		\$ cur 50.00 —
1	Swing arm		\$ 20/24 425.00 —
			\$ 5,708.00
		Less 10%	\$ 570.80
			\$ 5,137.20
Special Nett Items			
1	Number plate (1 set)		\$ 1M 28.00 20
2	Fork oils		\$ 11 30.00 x
2	Fork oil seals		\$ 11 56.00 x
1	Steering cone bearing (1 set)		\$ 11 90.00 x
1	Front tyre		\$ 500 120.00 x
1	Sticker (1 set)		\$ 1M 95.00 ✓
			\$ 419.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

Acknowledged by Repairer
Signature:
Date:

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 35 50.00
2	To check wiring and reset headlamp focusing.	\$ 11 80.00 x
3	To provide labour.	\$ 300 380.00
4	To repair body frame.	\$ 300 350.00
		\$ 860.00

Dollars: Six Thousand Four Hundred Sixteen And Twenty Cents Only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Grand Total

Acknowledged by Repairer
Signature:
Date:

\$ 6,416.20

5204.1