

ASS. REC. BY:

REF:

CS/MS618019898/G90n2

Special Instruction:

Surveyor

Mei Men

ASSIGNMENT (Office)

From (Person): Irene Tan

of

MS16

Date/Time: 01-11-2018 3:46pm

Estimated Cost:

Bill to:

OD / HW / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 2046m

Insured:

SLC 9632J

at Workshop m/s

N-51 Automotiv

Tel:

of

2 Koki Bukit Ave 2 #01-17

Policy No:

80453971QMY

Claim No:

574978

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

01-11-2018 3:50pm

Person Contacted:

Hui Xin

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SLS 2046m - CS3/ALH18009965/124d302

DA 26052018

SLC 9632J - x

02/11/18 @ 8pm Informed Irene Tan, we are pending estimate from repairer.

12/11/18 @ 5:03pm revised to Irene Tan via Mei Men.

Surveyor: XAL

REF: MSG

C1909C

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s N-51
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$80k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 11 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GLS2046M Yr Regn: 13 Sep 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Alpha
 Make: Toyota Prius C.C. 1797
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 117658 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZVW4000 25 897
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Ind / Jammed / Leaked / Burnt or
 Brake: Ind / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 205/60 R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or HAB lead
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 01-11-18
 Survey held at W/S 4pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>01/11</u>	<u>Estimate given later</u>
<u>12/9</u>	<u>Finalized \$14K with Kong (Red to 13235.84, 49%)</u>

RECEIVED 12 SEP 2019

12/9/2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 13/9 12:15 ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 11

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

200 S + RS. 11 SI

Photos

Others

TOTAL

211

Report Format: MER-TP

Lump Sum / I.B.I: (\$) 14000

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 12 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLC9632J	Accident Date	: 31/10/2018
TP Vehicle No	: SLS2046M	Assignment Date	: 01/11/2018
Make	: TOYOTA PRIUS ALPHA HYBRID	Est. Duration of Repair	: 11.00
Date of Inspection	: 01/11/2018		
Inspection At	: N-51AUTOMOTIVE PTE LTD (HQ) KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18 SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairster's Estimate (Gross)	:S\$	27,235.84
Revised Amount	:S\$	17,528.84
Check Items (Estimated)	:S\$	0.00
Total	:S\$	17,528.84

Lump Sum Repair	:S\$	14,000.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2018 11:07		01 Nov 2018 15:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	PEACOCK CONTAINER PTE. LTD., Co. Reg. No.: 200201231Z								
Main Claimant:	DARWIN-51 CAR RENTAL PTE LTD, Co. Reg. No.: 201407909C								
Vehicle Reg. No.:	SLS2046M	Date of Loss:	31/10/2018 09:00 - :59 [13 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	80453971QMY Coverage: 05/02/2018 - 30/11/2018						
Vehicle Reg. No. (Insured):	SLC9632J	Policy No. (Claimant):							
		Excess:							
Repairer:	N-51automotive Pte Ltd (HQ) KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel: 6842 0051 / 67440510								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/11/2018]								
Adj Asg. Remarks:	Liability 100% vs OI. TP agree with SJE - Assign any MSIG In-House Surveyor. contact: 6842 0051 / 6744 0510 (Melody)								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 2 November 2018 6:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLS 2046M (YOUR POLICY: 80453971QMY)

This mail is associated with :

***SLS2046M**

[SLC9632J]

TP

DARWIN-51 CAR RENTAL PTE LTD

Oct 31 2018 9:00AM

[PEACOCK CONTAINER PTE. LTD.]

N-51automotive Pte Ltd

Dear Irene,

Please be informed that we have inspected the vehicle SLS 2046M on 01/11/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7909C
Vehicle Details	
Vehicle No.:	SLS2046M
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS ALPHA HYBRID 1.8S CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR1980889
Chassis No.:	ZVW400025897
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,703.00
Original Registration Date:	13 Sep 2017
First Registration Date:	13 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$42,091.00
Total Rebate Amount:	\$45,841.00

The information contained herein is correct as at 02 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2018 11:15
Date Of Accident	31/10/2018 09:15
Exact Location Of Accident	KPE TOWARDS CITY BEFORE TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS2046M
Insured/Policyholder	
Name Of Registered Owner	DARWIN-51 CAR RENTAL PTE LTD
Co Reg No	201407909C
Email Address	SALES@N51.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-90045506

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID-1.8 S CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD18V07071/VPZ/R01
Cover Note Number	

Driver

Name of Driver	WONG YONG FATT
NRIC No	S1724625I
Date Of Birth	11/11/1965
Occupation	OUTDOOR
Date Of Driving Pass	16/07/1988
Driving Experience	30 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98308666
Fax Number	
Contact Number	
Email Address	FUHUA204@GMAIL.COM

Address	BLK 9 RIVERVALE CRESCENT #08-23
Postcode	545086
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC9632J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJH9810J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	WONG YONG FATT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLS2046M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	BLK 9 RIVERBALE CRESCENT #08-23
Postcode	545086

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

- (A) SLR 2046 M
- (B) SLR 9632J
- (C) SJH 9810J



KPE towards City just enter Tunnel 1.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/10/18 at @ 0915 hrs, I was travelling in my vehicle (SLR 2046 M) along KPE towards City just enter into the tunnel on the centre lane. The vehicle (SJH 9810J) in front of me stopped and I slow down and stopped too. Suddenly, I felt a great impact from the rear. The impact was so strong that pushed my vehicle forward and caused my vehicle to collide onto the said vehicle ahead.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LKC QuocQuang

01/11/18

DARWIN-51 CAR RENTAL PTE LTD
1 KAKI BUKIT ROAD 1 #01-09 ENTERPRISE
ONE
SINGAPORE 415934

Contact : 98308666

ESTIMATE

Repair Code : CLM14872

Date in : 31/10/2018

Vehicle Num. : SLS2046M

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025897/2ZR1980889

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER X NN	1	1218.45	1,218.45 X
FRONT BUMPER / re	1	781.10	495.2 781.10 /
FRONT BUMPER 'LOGO' EMBLEM - scr	1	172.10	80 172.10 /
FRONT BUMPER CENTER GRILLE / re	1	758.85	231.2 758.85 /
Δ FRONT BUMPER FOGLAMP L/R / BR	2	258.35 591.60	516.7 1,183.20 X
FRONT BUMPER INNER SPONGE / CRA	1	174.45	174.45 /
FRONT BUMPER LOWER COVER / re	1	280.25	200.9 280.25 /
FRONT BUMPER REINFORCEMENT X NN	1	681.90	X 681.90 X
Δ FRONT BUMPER SIDE LOCK CLIPS X / MC	6	9.50	20 57.00 /
FRONT BUMPER SIDE LOCK CLIPS HOLDER X NN	6	12.90	X 77.40 X
FRONT BUMPER SIDE RETAINER L/R / re	2	132.25	65 264.50 /
FRONT BUMPER TOW HOOK COVER L/R X NN	2	121.45	X 242.90 X
Δ FRONT BUMPER UPPER SEAL RUBBER X / MC	1	174.45	42.2 174.45 /
FRONT GRILLE / CRA	1	426 651.60	651.60 /
FRONT HEADLAMP L/R / CRA	2	2449 271.10	4898 5,422.20 /
FRONT HEADLAMP LOWER BRACKET L/R X NN	2	172.45	X 344.90 /
Δ FRONT NUMBER PLATE BRACKET X / re	1	93.00	30 93.00 /
Δ FRONT PEDESTRIAN SPEAKER X / CRA	1	280.00	225.7 280.00 /

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
1 KAKI BUKIT ROAD 1 #01-09 ENTERPRISE
ONE
SINGAPORE 415934

Contact : 98308666

ESTIMATE

Repair Code : CLM14872

Date in : 31/10/2018

Vehicle Num. : SLS2046M

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025897/2ZR1980889

FRONT SUPPORT PANEL	Repair X	1	972.75	X	972.75	X
FRONT SUPPORT PANEL INNER TOP COVER	X / RL	1	561.60	255.4	561.60	-
FRONT SUPPORT PANEL INNER TOP COVER CLIPS	X NN	3	12.90	X	38.70	-
INVERTER RADIATOR	/ Cut	1	731.35	/	731.35	-
RADIATOR LOWER AIR GUIDE	X / RL	1	176.60	/	176.60	-
RADIATOR SIDE AIR GUIDE L/R	/ RL	2	172.10	/	344.20	-
RADIATOR UPPER BRACKET	X / Rec.	1	140.00	49.6	140.00	-
REAR BUMPER	/ RL	1	523.90	/	523.90	-
REAR BUMPER LH REFLECTOR	X NN	1	58.00	X	58.00	-
REAR BUMPER SIDE RETAINER L/R	/ RL	2	98.00	/	196.00	-
REAR COMPARTMENT TRAY BOX	/ Cut	1	459.70	/	459.70	-
REAR COMPARTMENT TRAY BOX TOP COVER	/ dff	1	655.00	/	655.00	-
REAR END PANEL	/ bue	1	781.45	/	781.45	-
REAR END PANEL ANTENNA SENSOR	/ OM	1	485.00	/	485.00	-
REAR END PANEL INNER TOP GARNISH	/ RL	1	175.00	/	175.00	-
REAR EXHAUST GASKET	X	1	35.00	X	35.00	-
REAR EXHAUST RUBBER MOUNTING	X NN	2	55.00	X	110.00	-
REAR EXHAUST SILENCER BOX	X Repair.	1	1010.70	X	1010.70	-

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 1 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 1 KAKI BUKIT ROAD 1 #01-09 ENTERPRISE
 ONE
 SINGAPORE 415934

Contact : 98308666

ESTIMATE

Repair Code : CLM14872

Date in : 31/10/2018

Vehicle Num. : SLS2046M

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025897/2ZR1980889

REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	LH - De, RH XNN	656.00	/	1,312.00
REAR LH SPARE TYRE INNER TOP SIDE COVER	- CFA	381.10	/	381.10
Δ REAR RH DECK BOX COVER	X NN	481.90	X	481.90
Δ REAR SPARE TYRE PANEL	X Repair / Pmc	972.45	690.3	972.45
REAR TAILGATE	/ Pmc	929.60	/	929.60
REAR TAILGATE 'HYBRID' EMBLEM	/ Pmc	50.00	/	50.00
REAR TAILGATE 'PRIUS' EMBLEM	/ Pmc	52.30	/	52.30
REAR TAILGATE INNER PULL GARNISH	X NN	38.50	X	38.50
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	- CFA	578.00	/	578.00
REAR TAILGATE MECHANISM LOCK	/ BT	425.00	/	425.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R	X NN	29.00	X	58.00
REAR TAILGATE WEATHER STRIP	/ Twi	360.70	/	360.70
REAR TAILGATE WINDSCREEN LOWER SEAL	X	42.00	X	42.00
REAR TAILGATE WINDSCREEN MOULDING L/R	X	65.00	X	130.00
REAR TAILGATE WINDSCREEN UPPER SEAL	X	38.00	X	38.00
REAR TAILLAMP BACK RUBBER SEAL L/R	X	69.50	X	139.00
REAR TAILLAMP L/R	- CFA	630.00	/	1,260.00
Δ REAR TAILLAMP LOWER BRACKET L/R	X / De	68.00	60.2	136.00

*** This is a computer-generated document which requires no signature.***

11

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

18077.85

25%: 13558.39

DARWIN-51 CAR RENTAL PTE LTD
1 KAKI BUKIT ROAD 1 #01-09 ENTERPRISE
ONE
SINGAPORE 415934

Contact: 98308666

ESTIMATE

Repair Code : CLM14872

Date in : 31/10/2018

Vehicle Num. : SLS2046M

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025897/2ZR1980889

REAR TOOL SPONGE TRAY	1	396.70	396.70
Subtotal before discount			28,114.45
Percentage discount 25%			7,028.61
Sub-total 1			21,085.84
FRONT BUMPER CLIPS - SET	1	50.00	50.00
FRONT NUMBER PLATE	1	25.00	25.00
FRONT NUMBER PLATE HOLDER	1	50.00	50.00
RADIATOR COOLANT	1	60.00	60.00
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR BUMPER REVERSE SENSOR	1	250.00	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	20.00	20.00
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	30.00	60.00
REAR NUMBER PLATE	1	25.00	25.00
REAR NUMBER PLATE HOLDER	1	50.00	50.00
REAR SPARE TYRE PANEL INSULATOR MAT	1	350.00	350.00
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	1	80.00	80.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	20.00	20.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00

*** This is a computer-generated document which requires no signature.***

570

DARWIN-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 1 KAKI BUKIT ROAD 1 #01-09 ENTERPRISE
 ONE
 SINGAPORE 415934

Contact : 98308666

ESTIMATE

Repair Code : CLM14872
 Date in : 31/10/2018
 Vehicle Num. : SLS2046M
 Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT
 Chassis/Eng# : ZVW400025897/2ZR1980889

REAR TAILLAMP CLIPS L/R - SET	2	30.00	NNX	60.00
	Subtotal before discount			1,230.00
Percentage discount 0%				0.00
	Sub-total 2			1,230.00
	Parts-total			22,315.84

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	100	60	120.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	60		100.00
To remove, reinstall tailgate windscreen	100		120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60		150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	(Hood)	1200	1,900.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	1400	60	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	(Hood)	1500	2,200.00
To apply anti-rust chemical on repaired and replaced panel.	80		150.00
To remove, reinstall tailgate mechanism and check for function	40		80.00
	3400		4,920.00
	Labour Total		4,920.00
	Parts & Labour Total		27,235.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on the basis of the repairer's report
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated document which requires no signature.***

page 5

17528.39

27,235.84

11 Days

Vehicle No = SLS 2046M

Model = Toyota Prius Alpha Hybrid 1.8s CVT

Chassis = ZVW400025897

Year = 2017

Record purpose 1: -

List Price

- ① Front Bumper Foglamps LH/RH 516.70
- ② Front Bumper Side lock Clips Retainer 9 69.30
- ③ Front Bumper Upper Seal Rubber 42.20
- ④ Front Pedestrian Speaker 225.70
- ⑤ Front Support Panel Inner Top Cover 225.40
- ⑥ Radiator Lower air guide 165.70
- ⑦ Radiator Upper Bracket 49.60
- ⑧ Rear RH neck Box cover Air cleaner Box 9970.10
- ⑨ Rear Spare Tyre Panel 690.30
- ⑩ Rear Taillamps Cover Bracket LH/RH 60.20

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18019898/GQBN2

Date: 16/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80453971QMY
Claimant Vehicle No :	SLS2046M	Insured Vehicle No :	SLC9632J
Date of Loss:	31/10/2018	Nature of Claim:	TP
		Claim No:	574978

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2046M	Engine No:	2ZR1980889
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW400025897
Reg. Date:	13/09/2017 (Man. Year: 2017)	Odometer:	117658 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Bandvulc 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,315.84	14,128.84	8,187.00	36.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,920.00	3,400.00	1,520.00	30.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,235.84	17,528.84	9,707.00	35.64
Approved Total (Overridden) (S\$)		14,000.00		
(S\$)	27,235.84	14,000.00	13,235.84	48.60
+ GST 7.00/7.00% (S\$)	1,906.51	980.00	926.51	48.60
Nett Amount (S\$)	29,142.35	14,980.00	14,162.35	48.60

INSPECTION

Date of Assignment:	01/11/2018	
Date Inspected:	01/11/2018	Inspected At:
		N-51automotive Pte Ltd (HQ) KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18 Singapore 417921
Estimated Period of Repair:	11.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
Parts:	144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS2046M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIRCON CONDENSER	Not Necessary	1,218.45 FL	*- FL
2	1		*FRONT BUMPER	Deformed	781.10 FL	*495.20 FL
3	1		*FRONT BUMPER LOGO EMBLEM	Scratched	172.10 FL	*80.00 FL
4	1		*FRONT BUMPER CENTER GRILLE	Deformed	758.85 FL	*231.20 FL
5	2		*FRONT BUMPER FOGLAMP L/R	Broken	1,183.20 FL	*516.70 FL
6	1		*FRONT BUMPER INNER SPONGE	Cracked	174.45 FL	*174.45 FL
7	1		*FRONT BUMPER LOWER COVER	Deformed	280.25 FL	*200.90 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	681.90 FL	*- FL
9	1		*FRONT BUMPER SIDE LOCK CLIPS	Necessary	57.00 FL	*20.00 FL
			(6 Pcs)			
10	6		*FRONT BUMPER SIDE LOCK CLIPS HOLDER	Not Necessary	77.40 FL	*- FL
11	2		*FRONT BUMPER SIDE RETAINER L/R	Deformed	264.50 FL	*65.00 FL
12	2		*FRONT BUMPER TOW HOOK COVER L/R	Not Necessary	242.90 FL	*- FL
13	1		*FRONT BUMPER UPPER SEAL RUBBER	Necessary	174.45 FL	*42.20 FL
14	1		*FRONT GRILLE	Cracked	651.60 FL	*426.00 FL
15	2		*FRONT HEADLAMP L/R	Cracked	5,442.20 FL	*4,898.00 FL
16	2		*FRONT HEADLAMP LOWER BRACKET L/R	Not Necessary	344.90 FL	*- FL
17	1		*FRONT NUMBER PLATE BRACKET	Deformed	93.00 FL	*30.00 FL
18	1		*FRONT PEDESTRIAN SPEAKER	Cracked	280.00 FL	*225.70 FL
19	1		*FRONT SUPPORT PANEL	Repair	972.75 FL	*- FL
20	1		*FRONT SUPPORT PANEL INNER TOP COVER	Deformed	561.60 FL	*255.40 FL
21	3		*FRONT SUPPORT PANEL INNER TOP COVER CLIPS	Not Necessary	38.70 FL	*- FL
22	1		*INVERTER RADIATOR	Cut	731.35 FL	*731.35 FL
23	1		*RADIATOR LOWER AIR GUIDE	Deformed	176.60 FL	*176.60 FL
24	2		*RADIATOR SIDE AIR GUIDE L/R	Deformed	344.20 FL	*344.20 FL
25	1		*RADIATOR UPPER BRACKET	Necessary	140.00 FL	*49.60 FL
26	1		*REAR BUMPER	Deformed	523.90 FL	*523.90 FL
27	1		*REAR BUMPER LH REFLECTOR	Not Necessary	58.00 FL	*- FL
28	2		*REAR BUMPER SIDE RETAINER L/R	Deformed	196.00 FL	*196.00 FL
29	1		*REAR COMPARTMENT TRAY BOX	Cut	459.70 FL	*459.70 FL
30	1		*REAR COMPARTMENT TRAY BOX TOP COVER	Cracked	655.00 FL	*655.00 FL
31	1		*REAR END PANEL	Buckled	781.45 FL	*781.45 FL
32	1		*REAR END PANEL ANTENNA SENSOR	Damaged	485.00 FL	*485.00 FL
33	1		*REAR END PANEL INNER TOP GARNISH	Deformed	175.00 FL	*175.00 FL
34	1		*REAR EXHAUST GASKET	Not Necessary	35.00 FL	*- FL
35	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	110.00 FL	*- FL
36	1		*REAR EXHAUST SILENCER BOX	Repair	1,010.70 FL	*- FL
37	1		*REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	N/s Deformed/O/s Not Necessary	1,312.00 FL	*656.00 FL
38	1		*REAR LH SPARE TYRE INNER TOP SIDE	Cracked	381.10 FL	*381.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
COVER						
39	1		*REAR RH DECK BOX COVER	Not Necessary	481.90 FL	*- FL
40	1		*REAR SPARE TYRE PANEL	Buckled	972.45 FL	*690.30 FL
41	1		*REAR TAILGATE	Buckled	929.60 FL	*929.60 FL
42	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	50.00 FL	*50.00 FL
43	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	52.30 FL	*52.30 FL
44	1		*REAR TAILGATE INNER PULL GARNISH	Not Necessary	38.50 FL	*- FL
45	1		*REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	Cracked	578.00 FL	*578.00 FL
46	1		*REAR TAILGATE MECHANISM LOCK	Bent	425.00 FL	*425.00 FL
47	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	58.00 FL	*- FL
48	1		*REAR TAILGATE WEATHER STRIP	Twisted	360.70 FL	*360.70 FL
49	1		*REAR TAILGATE WINDSCREEN LOWER SEAL	Not Necessary	42.00 FL	*- FL
50	2		*REAR TAILGATE WINDSCREEN MOULDING L/R	Not Necessary	130.00 FL	*- FL
51	1		*REAR TAILGATE WINDSCREEN UPPER SEAL	Not Necessary	38.00 FL	*- FL
52	2		*REAR TAILLAMP BACK RUBBER SEAL L/R	Not Necessary	139.00 FL	*- FL
53	2		*REAR TAILLAMP L/R	Cracked	1,260.00 FL	*1,260.00 FL
54	2		*REAR TAILLAMP LOWER BRACKET L/R	Deformed	136.00 FL	*60.20 FL
55	1		*REAR TOOL SPONGE TRAY	Cut	396.70 FL	*396.70 FL
56	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
57	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*10.00 FS
58	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
59	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
60	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
61	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
62	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
63	2		*SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R	Necessary	60.00 FS	*40.00 FS
64	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
65	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
66	1		*REAR SPARE TYRE PANEL INSULATOR MAT	Necessary	350.00 FS	*150.00 FS
67	1		*SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
68	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
69	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
70	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	29,344.45	18,648.45
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,028.61	4,519.61
Total Parts (\$\$)	22,315.84	14,128.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHANGE AIR CON PARTS,VACUUMS,REFILL AIR CON GAS	New	120.00	100.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	100.00	60.00
3	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	120.00	100.00
4	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	150.00	60.00
5	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,900.00	1,400.00
6	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	60.00
7	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,200.00	1,500.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	150.00	80.00
9	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	40.00
Gross Labour Cost (\$\$)			4,920.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >