

ESTIMATE TO REPAIR

VEHICLE NO. : GBB 3237 E
 MAKE : TOYOTA
 MODEL : DYNA 150 MANUAL 3 SEATER
 YEAR : 2008
 CHASSIS NO : JTFAT35Y70K200185

SURVEYOR NAME :
 DATE OF SURVEY : 12 NOV 2018
 TIME OF SURVEY :

DATE : 1-Nov-18
 DATE OF ACCIDENT : 29-Oct-18
 THIRD PARTY REF : AIG / SLR 7656 A

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	N/S Rear Conopy Panel	S.Nett			\$ 1,800.00
1 pc	N/S Rear Conopy Sliding Door Lock Catch	S.Nett			\$ 80.00
1 set	DHL Logo	S.Nett			\$ 480.00
					\$ 2,360.00
	To putty and spray painting.				\$ 450.00
	Labour Charges.				\$ 450.00
	<i>Not Authorized</i> <i>11 Sep 8?</i> <i>Assuming After Paint</i> <i>3 days</i>				
TG-RA/-	TOTAL				\$ 3,260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd

Bldg 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Website: www.LTM.sg
 Co.Reg No 199307277D GST Reg No M2-0019086-0