

Insurance Kalvin

REF:

CC3/TML7021435/KS4052-1

ASSIGNMENT

From

Date:

Estimated Cost

CO / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop m/s

of

Insured SJA 1395E

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Rpt

Consistent? Yes or No

GIA PR Seen

Consistent? Yes or No

Est Repairs

3

days

Res

Yes or No

Lump Sum

1-B-1

%

3 Val

Yes or No

CA / REV / REP / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SH 8845J

Yr Regn

25 May, 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Tm / Prime Mover /

Truck / Trailer or

Make

Toyota Pro

cc 1798

Colour

Blue

A/C

Insured / Std / NI / NA

Sp Reading

88397

T/Radio

Insured / Std / NI / NA

Eng/No:

C/No:

J 70K03F450355 6852

Gen. Cond: Good / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

195/65R15

R:

SD/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

2

mm

R/Bal

2

mm

L/Bal

2

mm

L/Bal

2

mm

D.O.A

7/1/12

D.O.A

9/1/12

Survey held at

CDK E (Lany)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

28/1/12 SH 8845J - NA / INS 176015340/bu
SJA 1395E - NA / INC 12014396/SL
Grove 1455015.75/387
(Red: 2688.94, 357.)

DDI 310711

T.K.2

DDI 305711

11P

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee

Transportation

3 S + RS. SI

3 Photos

3 Others

3

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / I.B. (\$ 5015.75

250

10

\$1607



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD			Ref : CC3/TMI17021435/K1gb	
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046			Date : 09-11-2017	
			Code : TMI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJA 1395E	Veh. Inspected	SH 8845J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/11/2017	Inspection Date	09/11/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

COMFORT DELCRO

Date/Time: 09.11.2017 09:19 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JO NO 305086989

CUSTOMER

MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO 7010045

ADDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P)

COUNT CARD NO

REGN NO

SH 8845J

MILEAGE

MAKE

TOYOTA

FUEL

E 1/2 F

MODEL

PRIUS HYBRID(G4)07.11.2017 18:00

DATE TIME IN

YR OF MANU

25.05.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU503556852

COMPLETION DATE/TIME

JOB DESCRIPTION

accident Date: 07.11.2017

NATURE: 3P 07.11.2017

LABOR CODE

DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 8845J

LKE/KALVIN

Vehicle No.: SH 8845J

SH 8845J

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/11/2017 16:28
Date Of Accident 07/11/2017 17:10
Exact Location Of Accident AROOZOO AVE X CHARLTON RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SH8845J
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 199303821R
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768
Vehicle Particulars
Manufacturer TOYOTA
Model PRIUS HYBRID 4G
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number MCOM0016
Cover Note Number
Driver
Name of Driver CHONG HON YUN
NRIC No S1569997C
Date Of Birth 01/11/1962
Occupation OUTDOOR
Date Of Driving Pass 25/11/1980
Driving Experience 36 YEARS AND 11 MONTHS
Gender MALE
Mobile Number
Fax Number
Contact Number
Email Address ICICLEHOME@HOTMAIL.COM

Address BLK 639 PASIR RIS DRIVE 1
 #06-552
 Postcode 510639
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions DRIZZLING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20171108/2087 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJA1395E
 Vehicle Make/Model/Colour TOYOTA
 Details Of Properties
 Name of Driver UNKNOWN
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage LH FRONT DOOR
 No. Of Passenger (Including Driver)
 Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

CHONG HON YUN

Approximate Age

Injuries Sustain

NECK AND BACK

Injured person in which vehicle?

SH8845J

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

BLK 639 PASIR RIS DRIVE 1

Postcode

#06-552

510639

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

03/11/17
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to P/Report T/2017/1108/2087

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG NO. 189303021R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

08/11/17
Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

4500000 Sketch Plan Pg. 2



**SINGAPORE
POLICE FORCE**



T/20171108/2087

1 of 3

Report No. T/20171108/2087

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/11/2017 14:18		Vide Report No.:		Station Diary No.: 97	
Informant's Particulars					
Name of Informant: CHONG HON YUN			Address: APT BLK 639 PASIR RIS DRIVE 1 #06-552 SINGAPORE 510639		
ID Type / ID No.: NRIC NO / S1569997C			Contact No.: Home/Office: Mobile: 90671886		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 55	Date of Birth: 01/11/1962	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3,4,5		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/11/2017 17:10	Type of Location: T-Junction
Location: Along Road 1 AROOZOO AVENUE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SH8845J	Car	TOYOTA		Blue		2
SJA1395E	Car	TOYOTA	VIOS	Silver		0

Details of Person Involved

Any Pedestrian involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE
POLICE FORCE



T/20171108/2087

2 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1600-5852999

Report No: T/20171108/2087

CONTINUATION OF REPORT

Driver Name	CHONG HON YUN	ID No.	S1569997C
Related Vehicle	SH8845J (Car)	Contact No.	90671886
Hospital/Clinic	A LIFE CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	08/11/2017	Date Discharge	08/11/2017
No. of Days granted Medical Leave	05	Degree of Injury	NIL

Brief Details.

On 07/11/2017 at about 1710hrs, I was driving in my taxi (Blue Toyota Prius bearing license plate SH8845J) along Aroozoo Avenue towards the junction of Charlton Rd and Aroozoo Avenue. All of a sudden, another vehicle (Silver Toyota Vios bearing license plate SJA1395E) appeared and drove across Charlton Rd. As such, the front of my taxi collided with the front left passenger door of the Toyota Vios. We alighted from our vehicles and took pictures of the scene. However, we did not exchange particulars as the other driver refused to provide me with his details. We then subsequently left the scene. No police or ambulance arrived. As a result of the accident, the front bumper of my taxi was damaged. I also felt pain at my neck and back area.

I wish to state that I have an in-car camera installed in my vehicle, and it was recording at the time of the accident.



**SINGAPORE
POLICE FORCE**



T/20171108/2087

3 of 3

Report No. T/20171108/2087

Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE

519457

Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G/

Sgt 2 CHAN XIANG DA

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

08/11/2017 14:18

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt LEE SOON LYE

Contact No.: 65476239

Classification Of Case:

Authentication Stamp






NP163

SN 163



Signature:

Singapore Police Force



ComfortDelGro Engineering Pte Ltd (Co.Reg No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL
Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: SH8845J
Party At Fault: UNKNOWN

Ref. No:
Date of Loss: 07/11/2017
Driveable? YES

Make/Model: TOYOTA PRIUS HYBRID, 1.8 (A)
Vehicle Colour: BLUE
Engine No: 2ZRS042749
Odometer: 0 KM

Vehicle Reg. Date: 25/05/2017
Gen Condition: GOOD
Chassis No: JTDKB3FU503556852

Paint Type:
List Item Discount: 25.00 %
Total Loss? NO
Est. Duration of Repair (day) 5

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	5,399.37
Labour	10.00
Paintwork Labour	1,260.00
Towing	0.00

Gross Total (S\$)	6,669.37
+ GST 7.00% (S\$)	466.86
Nett Amount (S\$)	7,136.23

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHIC : SH 8845J

MAKE :

MODEL: TOYOTA PRIUS

9/11/2017 10:43

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRONT BUMPER COVER			\$ 490.50
FRONT BUMPER REINFORCEMENT			\$ 691.50
FRONT BUMPER REINFORCEMENT ABSORBER			\$ 115.70
BRACKET SUB-ASSY, FRONT SIDE MEMBER, RH			\$ 250.40
FRONT BUMPER SPONGE			\$ 78.80
FRONT BUMPER CENTRE GRILLE			\$ 301.90
FRONT BUMPER LOWER GRILLE			\$ 148.60
FRONT BUMPER SIDE RETAINER			\$ 77.00
FRONT UNDER COVER			\$ 178.30
FRONT BUMPER TOP GARNISH			\$ 225.40
COVER, FRONT BUMPER HOLE, RH			\$ 27.80
SUPPORT FR BUMPER, RH			\$ 81.70
BRACKET, FRONT BUMPER SIDE, RH			\$ 56.20
UNIT ASSY, HEADLAMP, RH (LED)			\$ 2,530.60
HEAD LAMP PANEL (RH) / LH			\$ 213.50
BRACKET, HEADLAMP MOUNTING, RH			\$ 25.50
FENDER SUB-ASSY, FRONT RH			\$ 933.10
FRONT FENDER SHIELD, RH			\$ 198.50
FRONT FENDER SHIELD CLIP			\$ 14.90
FRONT FENDER HYBRID EMBLEM, RH			\$ 86.50
Support Sub- Assy Radiator upper			\$ 361.10
Front Bumper Emblem			\$ 87.10
SUB TOTAL			\$ 6,726.40
LESS 25%			\$ 1,681.60
DISCOUNTED TOTAL			\$ 5,044.80
FRONT NO. PLATE GARNISH			\$ 99.00
Front number plate			\$ 35
Labour Charge			\$ 400
Panel Beating			\$ 360
Spray Painting Charge			\$ 20
Wiring Charge			\$ 20
Tuff Kote			\$ 10
Meridian Fee			\$ 1,060.00
TOTAL LABOUR			\$ 1,060.00
ESTIMATE TOTAL			\$ 6,203.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 09 Nov 2017)

Parts: 144

TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH8845J/09/11/2017 17:21

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No. Qty Part No. Particulars

%Disc %Depr Amount

1	1	*FRT BUMPER COVER	25.00	0.00	*490.50 FL
2	1	*FRT BUMPER REINFORCEMENT	25.00	0.00	*694.50 FL
3	1	*FRT BUMPER REINFORCEMENT ABSORBER	25.00	0.00	*115.70 FL
4	1	*BRACKET SUB-ASSY, FRT SIDE MEMBER RH	25.00	0.00	*250.40 FL
5	1	*FRT BUMPER SPONGE	25.00	0.00	*78.80 FL
6	1	*FRT BUMPER CENTRE GRILLE	25.00	0.00	*301.90 FL
7	1	*FRT BUMPER LOWER GRILLE	25.00	0.00	*148.60 FL
8	1	*FRT BUMPER SIDE RETAINER RH	25.00	0.00	*77.00 FL
9	1	*FRT UNDER COVER	25.00	0.00	*178.30 FL
10	1	*FRT UNDER COVER X <i>replaced</i>	25.00	0.00	*178.30 FL
11	1	*FRT BUMPER TOP GARNISH	25.00	0.00	*225.40 FL
12	1	*FRT BUMPER HOLD COVER RH	25.00	0.00	*27.80 FL
13	1	*FRT BUMPER SUPPORT RH	25.00	0.00	*81.70 FL
14	1	*FRT BUMPER SIDE BRACKET RH	25.00	0.00	*56.20 FL
15	1	*HEADLAMP ASSY RH	25.00	0.00	*2,530.60 FL
16	1	*HEADLAMP PANEL RH	25.00	0.00	*213.50 FL
17	1	*HEADLAMP MOUNTING BRACKET RH	25.00	0.00	*25.50 FL
18	1	*FRT FENDER SUB-ASSY RH	25.00	0.00	*933.10 FL
19	1	*FRT FENDER SHIELD RH	25.00	0.00	*198.50 FL
20	1	*FRT FENDER SHIELD CLIP RH	25.00	0.00	*14.90 FL
21	1	*FRT FENDER HYBRID EMBLEM RH	25.00	0.00	*86.50 FL
22	1	*BONNET HINGE RH X <i>repair</i>	25.00	0.00	*56.40 FL
23	1	*BONNET HINGE LH X <i>repair</i>	0.00	0.00	*99.00 F
24	1	*FRT NO. PLATE GARNISH	0.00	0.00	*35.00 F
25	1	*FRT NO. PLATE			

F=Franchise part L=ListItemDisc.

Sub Total (\$\$)

7,154.50

- List Item Discount on L Items (\$\$)

1,755.13

Total Parts (\$\$)

5,399.37

ComfortDelGro Engineering Pte Ltd/SH8845J/09/11/2017 17:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimate Report

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			10.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	560.00
2	SPRAY PAINTING CHARGE	New	600.00
3	WIRING CHARGE	New	50.00
4	TUFF KOTE	New	50.00
Gross Labour Cost (S\$)			1,260.00

ComfortDelGro Engineering Pte Ltd/SH8845J/09/11/2017 17:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048V)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
LIM BOON SIANG
 Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MV010568	Date of Loss:	07/11/2017
Vehicle Reg. No.:	SH8845J	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Vehicle Reg. Date:	25/05/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	1NZX645045	Chassis No:	MR053HY9305035402
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	SJA1395E-ACCIDENT WITH SH8845J - JT - ALONG AROOZOO AVE X CHARLTON ROAD		
Present Location:	**NO ARF-10.11.17(BW) **TIME: 17:10 COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
COST OF CLAIMS	531.27
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	531.27
+ GST 7.00% (S\$)	37.19
Nett Amount (S\$)	568.46
+ Previous Estimates (S\$)	7,136.23
Claim Total (S\$)	7,704.69

Estimate Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2017)
 Parts: 144 TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH8845J/28/12/2017 09:41

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SUPPORT SUB-ASSY RADIATOR LH <i>ra</i>	25.00	0.00	*213.50 FL
2	1		*SUPPORT SUB-ASSY RADIATOR UPPER <i>ra</i>	25.00	0.00	*361.10 FL
3	1		*FRT BUMPER EMBLEM <i>ra</i>	25.00	0.00	*87.10 FL
4	1		*FRT NO PLATE <i>reported</i>	0.00	0.00	*35.00 F
Sub Total (S\$)						696.70
- List Item Discount on L Items (S\$)						165.43
Total Parts (S\$)						531.27

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH8845J/28/12/2017 09:41. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 28.12.2017
Time: 13:59:58
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305086989
REGN NO : SH 8845J
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 25.05.2017
DATE/TIME IN : 07.11.2017 18:00
ACCIDENT DATE : 07.11.201

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2292-G	PRIG4 COVER FRONT BUMPER	1 L	490.50	25.00	367.87
0002	04-01-0302-0635-G	PRIG4 ABSORBER FRONT BUMP	1 L	78.80	25.00	59.10
0003	04-01-0302-2062-G	PRIG4 GRILLE RADIATOR LOW	1 L	148.60	25.00	111.45
0004	04-01-0302-0646-G	PRIG4 COVER RADIATOR SUPP	1 L	225.40	25.00	169.05
0005	04-01-0302-2297-G	PRIG4 EMBLEM SIDE PANEL (	1 L	86.50	25.00	64.87
0006	04-01-0302-2170-G	PRIG4 BRACKET FRT BUMPER	1 N	99.00	2.50	99.00
0007	FNPS	NO PLATE(S)	1 N	35.00	0.25	35.00
0008	04-01-0302-2915-G	PRIG4 UNIT ASSY HEADLAMP	1 L	2,530.60	25.00	1,897.95
0009	04-01-0302-2298-G	PRIG4 REINFORCEMENT SUB-A	1 L	691.50	25.00	518.62
0010	04-01-0302-2875-G	SUPPORT SUB-ASSY RADIATOR	1 L	213.50	25.00	160.12
0011	04-01-0302-2975-G	SUPPORT SUB-ASSY RADIATOR	1 L	213.50	25.00	160.12
0012	04-01-0302-2277-G	SUPPORT SUB-ASSY RADIATOR	1 L	361.10	25.00	270.82
0013	04-01-0302-2164-G	PRIG4 GRILLE SUB-ASSY RAD	1 L	301.90	25.00	226.42

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 28.12.2017
Time: 13:59:58
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305086989
REGN NO : SH 8845J
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 25.05.2017
DATE/TIME IN : 07.11.2017 18:0
ACCIDENT DATE :

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0302-0988-G	PRIG4 EMBLEM ASSY RADIATO	1 L	87.10	25.00	65.32
SUB-TOTAL :					4,205.71

JOB NATURE

0000 L	MERIMEN CHARGE				10.00
0001 L	PANEL BEATING				400.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA				360.00
0003 17-01	CHECK ALL LIGHTING				20.00
0004 20-00	TUFF COAT ON AFFECTED PARTS,				20.00
SUB-TOTAL :					810.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.12.2017

Time: 13:59:58

Page: 3

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305086989
REGN NO : SH 8845J
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 25.05.2017
DATE/TIME IN : 07.11.2017 18:0
ACCIDENT DATE :

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,015.71

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305086989
Date : 25/12/17

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508669
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr KALVIN ANG
Vehicle Reg No. : SH8845J CTPL

Fax :
07.11.17

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJA1395E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$4,205.75
 - (b) Labour Charges \$810.00
 - Total for Part-By-Part Repair Cost \$5,015.75**
 - (c) Lumpsum Repair (if applicable) 20%
 - Total for Lumpsum repair cost after Less:
 - Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature :
Name :
Date : 28/2/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

2017.12.25 (10:42) 287 71717

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TM17021435/K1GBS2
Date: 14/02/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MV010568
 Claimant Vehicle No: SH8845J Insured Vehicle No: SJA1395E
 Date of Loss: 07/11/2017 Nature of Claim: TP Claim No: M1705740

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH8845J
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A) Engine No: 2ZRS042749
 Reg. Date: 25/05/2017 (Man, Year: 2017) Chassis No: JTDKB3FU503556852
 Colour: Blue Odometer: 88397 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,930.64	4,205.75	1,724.89	29.08
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,260.00	800.00	460.00	36.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,200.64	5,015.75	2,184.89	30.34
+ GST 7.00/7.00% (S\$)	504.05	351.10	152.95	30.34
Nett Amount (S\$)	7,704.69	5,366.85	2,337.84	30.34

INSPECTION

Date of Assignment: 10/11/2017 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 09/11/2017 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2018)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SH8845J/14/02/2018 11:47	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER COVER	Deformed	490.50 FL	*490.50 FL
2	1		*FRT BUMPER REINFORCEMENT	Bent	694.50 FL	*691.50 FL
3	1		*FRT BUMPER REINFORCEMENT ABSORBER	Serviceable	115.70 FL	*- FL
4	1		*BRACKET SUB-ASSY, FRT SIDE MEMBER RH	Serviceable	250.40 FL	*- FL
5	1		*FRT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
6	1		*FRT BUMPER CENTRE GRILLE	Cracked	301.90 FL	*301.90 FL
7	1		*FRT BUMPER LOWER GRILLE	Cracked	148.60 FL	*148.60 FL
8	1		*FRT BUMPER SIDE RETAINER RH	Serviceable	77.00 FL	*- FL
9	1		*FRT UNDER COVER	Serviceable	178.30 FL	*- FL
10	1		*FRT UNDER COVER	Repeated	178.30 FL	*- FL
11	1		*FRT BUMPER TOP GARNISH	Cracked	225.40 FL	*225.40 FL
12	1		*FRT BUMPER HOLD COVER RH	Repair	27.80 FL	*- FL
13	1		*FRT BUMPER SUPPORT RH	Serviceable	81.70 FL	*- FL
14	1		*FRT BUMPER SIDE BRACKET RH	Serviceable	56.20 FL	*- FL
15	1		*HEADLAMP ASSY RH	Cracked	2,530.60 FL	*2,530.60 FL
16	1		*HEADLAMP PANEL RH	Cracked	213.50 FL	*213.50 FL
17	1		*HEADLAMP MOUNTING BRACKET RH	Serviceable	25.50 FL	*- FL
18	1		*FRT FENDER SUB-ASSY RH	Repair	933.10 FL	*- FL
19	1		*FRT FENDER SHIELD RH	Serviceable	198.50 FL	*- FL
20	1		*FRT FENDER SHIELD CLIP RH	Not Necessary	14.90 FL	*- FL
21	1		*FRT FENDER HYBRID EMBLEB RH	Necessary	86.50 FL	*86.50 FL
22	1		*BONNET HINGE RH	Repair	56.40 FL	*- FL
23	1		*BONNET HINGE LH	Repair	56.40 FL	*- FL
24	1		*FRT NO. PLATE GARNISH	Cracked	99.00 F	*99.00 F
25	1		*FRT NO. PLATE	Dented	35.00 F	*35.00 F
Supplementary #1						
26	1		*SUPPORT SUB-ASSY RADIATOR LH	Cracked	213.50 FL	*213.50 FL
27	1		*SUPPORT SUB-ASSY RADIATOR UPPER	Cracked	361.10 FL	*361.10 FL
28	1		*FRT BUMPER EMBLEM	Necessary	87.10 FL	*87.10 FL
29	1		*FRT NO PLATE	Repeated	35.00 F	*- F

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	7,851.20	5,563.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,920.56	1,357.25
Total Parts (\$\$)	5,930.64	4,205.75

LKK Auto Consultants Pte Ltd/SH8845J/14/02/2018 11:47. Not valid without Reference section.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	560.00	400.00
2	SPRAY PAINTING CHARGE	New	600.00	360.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
Gross Labour Cost (\$\$)			1,260.00	800.00

LKK Auto Consultants Pte Ltd/SH8845J/14/02/2018 11:47. Not valid without Reference section.

< END OF ESTIMATES >



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

COMFORTDELGRO ENGINEERING PTE LTD

Ref : CC3/TMI17021435/K1cbs2-1

59 LOYANG DRIVESINGAPORE 508969

Date : 01-11-2018



Code : QW007

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SH 8845J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	09/11/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU503556852	Colour	BLUE
Odometer	88397	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	BRIDGESTONE	7 mm
L/H Front Tyre	195/65R15	BRIDGESTONE	7 mm
R/H Rear Tyre	195/65R15	BRIDGESTONE	7 mm
L/H Rear Tyre	195/65R15	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/11/2017	Inspection Date	01/11/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8845J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER COVER	DEFORMED	490.50	490.50
1	FRT BUMPER REINFORCEMENT	BENT	694.50	691.50
1	FRT BUMPER REINFORCEMENT ABSORBER	SERVICEABLE	115.70	-
1	BRACKET SUB-ASSY, FRT SIDE MEMBER RH	SERVICEABLE	250.40	-
1	FRT BUMPER SPONGE	TORN	78.80	78.80
1	FRT BUMPER CENTRE GRILLE	CRACKED	301.90	301.90
1	FRT BUMPER LOWER GRILLE	CRACKED	148.60	148.60
1	FRT BUMPER SIDE RETAINER RH	SERVICEABLE	77.00	-
1	FRT UNDER COVER	SERVICEABLE	178.30	-
1	FRT UNDER COVER	REPEATED	178.30	-
1	FRT BUMPER TOP GARNISH	CRACKED	225.40	225.40
1	FRT BUMPER HOLD COVER RH	TO REPAIR SEE LABOUR	27.80	-
1	FRT BUMPER SUPPORT RH	SERVICEABLE	81.70	-
1	FRT BUMPER SIDE BRACKET RH	SERVICEABLE	56.20	-
1	HEADLAMP ASSY RH	CRACKED	2,530.60	2,530.60
1	HEADLAMP PANEL RH	CRACKED	213.50	213.50
1	HEADLAMP MOUNTING BRACKET RH	SERVICEABLE	25.50	-
1	FRT FENDER SUB-ASSY RH	TO REPAIR SEE LABOUR	933.10	-
1	FRT FENDER SHIELD RH	SERVICEABLE	198.50	-
1	FRT FENDER SHIELD CLIP RH	NOT NECESSARY	14.90	-
1	FRT FENDER HYBRID EMBLEM RH	NECESSARY	86.50	86.50
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	56.40	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	56.40	-
1	SUPPORT SUB-ASSY RADIATOR LH	CRACKED	213.50	213.50
1	SUPPORT SUB-ASSY RADIATOR UPPER	CRACKED	361.10	361.10
1	FRT BUMPER EMBLEM	NECESSARY	87.10	87.10
	LESS 25% DISCOUNT		-1,920.56	-1,357.25
			5,761.64	4,071.75
<u>SPECIAL NETT ITEMS</u>				
1	FRT NO. PLATE GARNISH (SN)	CRACKED	99.00	99.00
1	FRT NO. PLATE (SN)	DENTED	35.00	35.00

Report Ref No. CC3/TMI17021435/K1cbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT NO PLATE (SN)	REPEATED	35.00	-
			169.00	134.00
	LABOUR			
	OD/TP CASE (INSURER)		10.00	10.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER HOLD COVER RH, BONNET HINGE RH AND BONNET HINGE LH.		560.00	400.00
	SPRAY PAINTING CHARGE.		600.00	360.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
			1,270.00	810.00
	GRAND TOTAL		7,200.64	5,015.75
	RECOMMENDED COST OF REPAIRS			5,015.75

Report Ref No. CC3/TMI17021435/K1cbs2-1

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.