

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
СОМ	FORTDELGRO E	NGINEERING PTE LTD	Ref : CC3/TMI17021435/K1cbs2-1		
59 LOYANG DRIVESINGAPORE 508969			Date: 01-11-2018 Code: QW007		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	SH 8845J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	09/11/2017	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JTDKB3FU503556852	Colour	BLUE	
	Odometer	88397	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65R15	BRIDGESTONE	7 mm	
	L/H Front Tyre	195/65R15	BRIDGESTONE	7 mm	
	R/H Rear Tyre	195/65R15	BRIDGESTONE	7 mm	
	L/H Rear Tyre	195/65R15	BRIDGESTONE	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	07/11/2017	Inspection Date	09/11/2018	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			