

ASS. REC. BY:

REF: CS/ICB18019906/Kvbhz

Special Instruction:

SURVIVOR

ASSIGNMENT (Office)

FROM (Person):

Desmond Lee

of ICS

Date/Time: 01-11-2018 1044am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

GBG 554ST

Insured:

GBE 2258K

at Workshop m/s

Cheng Hoe motor.

Tel:

6755 6142.

of

Bik 1019 Yishun Ind Park A #01-374

Policy No:

mcv 18A00062900

Claim No:

Dmcv18 000 84H/DL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30.10.2018

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 01-11-2018 11:23am

Person Contacted:

Efeeda

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

ASS. REC. BY:

REF: 1CS/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

5-6 days

Res.: Yes or No

Lum Sum: _____

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBG 5548T

Yr Regn: _____

09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toy Hiac

c.c.

2982

Colour: _____

White

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

88723

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JT1H702P600215135

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. _____

6

mm

Rear

R/Bal. _____

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

mm

D.O.A. _____

30/10/18

D.O.I. _____

13/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/11

File pass to Catherine

3/12

05046.97 Carfax Check (Red To H.65, 12M)

RECEIVED 31 DEC 2018

31/12/2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

31/12 - typist

Days Of Repair: _____

5

Resurvey No. of Trip: _____

2

Survey Fee:

Transportation:

250

10

Fixtures

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I. (\$

5046.97

TOTAL

260

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) Edit Reg		14 Nov 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	BRANWOOD MARKETING PTE LTD, Co. Reg. No.: 201713478K		
Vehicle Reg. No.:	GBG5548T	Date of Loss:	30/10/2018 14:00 - :59
Claim Type:	TP / DMCV1800084H/DL	Policy/Cover Note No.:	MCV18A00062900
Vehicle Reg. No. (Insured):	GBE2258K	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Nivitha (LKK Auto)

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Thursday, 1 November 2018 10:44 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June); assignments
Cc: ECICS Claims
Subject: RE: Repair Survey (Single Joint Expert) - GBG5548T, doa 30/10/18 (Yr insured GBE2258K)

Importance: High

11:23am @ 1/11/2018
person @ Effenda
UNI

Dear Lkk

Please assist with the PRI.

Thank you.

Best regards,
Desmond Lee
Claims Division
DID: +65 6303 0167
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Center
Singapore 408600

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Thursday, 1 November, 2018 10:42 AM
To: Desmond Lee Ker Wen (ECICS, Claims)
Cc: ECICS Claims
Subject: Re: Repair Survey (Single Joint Expert) - GBG5548T, doa 30/10/18 (Yr insured GBE2258K)

Good morning Desmond,

Our selection as below :-

1. LKK

Pls assist to arrange for survey asap.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd

Tel :67556142
Fax : 67557719

From: Desmond Lee Ker Wen (ECICS, Claims)
Sent: Wednesday, October 31, 2018 4:35 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Cc: ECICS Claims
Subject: RE: Repair Survey (Single Joint Expert) - GBG5548T, doa 30/10/18 (Yr insured GBE2258K)

Dear June

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Best regards,
Desmond Lee
Claims Division
DID: +65 6303 0167
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Center
Singapore 408600

From: ECICS Claims
Sent: Wednesday, 31 October, 2018 2:40 PM
To: Desmond Lee Ker Wen (ECICS, Claims)
Cc: Cheng Hoe Motor Pte Ltd (Yishun-June); ECICS Claims
Subject: RE: Repair Survey (Single Joint Expert) - GBG5548T, doa 30/10/18 (Yr insured GBE2258K)

Hi Desmond

Please assist.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]
Sent: Wednesday, 31 October, 2018 2:32 PM
To: Janice Goh Siew Geok (ECICS, Claims); ECICS Claims
Subject: Repair Survey (Single Joint Expert) - GBG5548T, doa 30/10/18 (Yr insured GBE2258K)

Dear Sir,

OUR CLIENT – GBG5548T
DOA : 30/10/18 @1420hrs
YR INSURED : GBE2258K

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

follow us on  facebook follow us on  twitter visit our website ecics.com.sg 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3478K
Vehicle Details	
Vehicle No.:	GBG5548T
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 4 DR AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2681357
Chassis No.:	JTFHT02P600215135
Maximum Power Output:	-
Open Market Value:	\$29,070.00
Original Registration Date:	04 Sep 2017
First Registration Date:	04 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,454.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$32,617.00
Total Rebate Amount:	\$32,617.00

The information contained herein is correct as at 30 Oct 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBG 5548 T
TP/ECICS

M/S : ECICS LIMITED
10 EUNOS ROAD 8
SINGAPORE POST CENTRE, 09-04A
SINGAPORE 408600
TEL: 63374779 FAX: 63389267
ATTN: Motor Claim Department

Estimate No: ES1891287/YISHUN
Date: 13 Nov 2018
Policy No: 5103180146
Veh Reg No: GBG5548T
Make/Model: TOYOTA HIACE VAN
TURBO 4 DR AUTO
Chassis No: JTFHT02P600215135
Engine No: 1KD2681357
Reg. Date: 04/09/2017

WS Ref: TP/ECICS/YS
Claim Type: Third Party
Accident Date: 30/10/2018
TP Veh Reg No: GBE2258K

Not Notified

Resurvey B4 paint

5 - 6 days

Estimate Repair Cost to Vehicle No :GBG5548T

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR TAILGATE	1,790.50	1 PC	1,790.50	✓
2 TAILGATE LOGO	70.24	1 PC	70.24	✓
3 TAILGATE STICKER (TOYOTA HIACE)	46.05	1 PC	46.05	✓
4 TAILGATE OUTER GARNISH	120.70	1 PC	120.70	✓
5 TAILGATE INNER LOCK	264.70	1 PC	264.70	✓
6 TAILGATE INNER RUBBER	391.20	1 PC	391.20	✓
7 REAR WINDSCREEN GLASS	1,251.90	1 PC	1,251.90	✓
8 REAR WINDSCREEN WIPER ARM	120.70	1 PC	120.70	✓
9 RH TAILLAMP	256.90	1 PC	256.90	✓
10 REAR BUMPER	396.10	1 PC	396.10	✓
11 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
12 REAR END PANEL OUTER	325.50	1 PC	325.50	✓
			5,055.49	
Less 25%			1,263.87	3,791.62
Special Net				
13 STICKER (70KM/H)	10.00	1 PC	10.00	✓
14 REVERSE SENSOR	200.00	1 PC	200.00	✓
15 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
			250.00	250.00
Labour				
16 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
17 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE, REAR LOCK ASSY, REAR WIPER ASSY, TO CUT, WELD & RENEW REAR PANEL OUTER & REALIGN THE SAME	750.00	1 LA	750.00	✓
18 PUTTY & RESPRAY ON REAR END PANEL, REAR BUMPER, TAILGATE & REAR AFFECTED AREAS	750.00	1 LA	750.00	✓
19 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
20 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,710.00	1,710.00

Total S\$ 5,751.62
Add GST @ 7% 402.61
Total Amount Payable S\$ 6,154.23

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18019906/KVBN2

Date: 02/01/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MCV18A00062900
Claimant Vehicle No :	GBG5548T	Insured Vehicle No :	GBE2258K
Date of Loss:	30/10/2018	Nature of Claim:	TP
		Claim No:	DMCV1800084H/DL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG5548T	Engine No:	1KD2681357
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 4DR (A)	Chassis No:	JTFHT02P600215135
Reg. Date:	04/09/2017 (Man. Year: 2016)	Odometer:	88773 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,041.62	3,706.97	334.65	8.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,340.00	370.00	21.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,751.62	5,046.97	704.65	12.25
+ GST 7.00/7.00% (S\$)	402.61	353.29	49.32	12.25
Nett Amount (S\$)	6,154.23	5,400.26	753.97	12.25

INSPECTION

Date of Assignment:	01/11/2018	
Date Inspected:	13/11/2018	Inspected At:
		Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun Industrial
		Park A
		Singapore 768761
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jan 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG5548T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,790.50 FL	*1,790.50 FL
2	1		*TAILGATE LOGO	Necessary	70.24 FL	*70.24 FL
3	1		*TAILGATE STICKER (TOYOTA HIACE)	Necessary	46.05 FL	*46.05 FL
4	1		*TAILGATE OUTER GARNISH	Warped	120.70 FL	*120.70 FL
5	1		*TAILGATE INNER LOCK	Dented	264.70 FL	*264.70 FL
6	1		*TAILGATE INNER RUBBER	Dented/Distorted	391.20 FL	*391.20 FL
7	1		*REAR WINDSCREEN GLASS	Shattered	1,251.90 FL	*1,251.90 FL
8	1		*REAR WINDSCREEN WIPER ARM	Serviceable	120.70 FL	*- FL
9	1		*RH TAILLAMP	Cracked	256.90 FL	*256.90 FL
10	1		*REAR BUMPER	Buckled	396.10 FL	*396.10 FL
11	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
12	1		*REAR END PANEL OUTER	Repair	325.50 FL	*- FL
13	1		*STICKER (70KM/H)	Necessary	10.00 FS	*10.00 FS
14	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
15	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					5,305.49	4,859.29
- List Item Discount on L Items 25.00/25.00% (S\$)					1,263.87	1,152.32
Total Parts (S\$)					4,041.62	3,706.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE, REAR LOCK ASSY, REAR WIPER ASSY, TO CUT, WELD & RENEW REAR PANEL OUTER & REALIGN THE SAME	New	750.00	520.00
3	PUTTY & RESPRAY ON REAR END PANEL, REAR BUMPER, TAILGATE & REAR AFFECTED AREAS	New	750.00	640.00
4	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	50.00	50.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (S\$)			1,710.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >