

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 02 Mar 2019)
Parts: N/A ISUZU NQR75UL5A 5.2 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/YN3312K/02/03/2019 09:41
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

*Supplementary***Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT CABIN SUPPORT BEAM	0.00	0.00	✓ *270.00 F
2	1		*FRT CABIN REAR LOCK MOUNTING RH	0.00	0.00	✓ *38.00 F
Total Parts (S\$)						308.00

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/YN3312K/02/03/2019 09:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS