

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHD 3383J

MAKE :

MODEL : HYUNDAI i40

FWD-cp(p)

TB

DATE 1/11/2018

1620

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <del>X</del> <i>ry-1</i>			\$ 553.00
	SUB TOTAL			\$ 553.00
	LESS 20%			\$ 110.60
	DISCOUNTED TOTAL			\$ 442.40
	Labour Charge			
	Panel Beating			\$ <del>400.00</del> <sup>100</sup>
	Spray Painting Charge			\$ <del>300.00</del> <sup>200</sup>
	Wiring Charge			\$ <del>30.00</del> <sup>X</sup>
	Remove/Refix Reverse Sensor			\$ <del>80.00</del> <sup>X</sup>
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,252.40

*Kalini 1 (K)**2/11/18 1030 L**2 P/L**P/L**Attn Repair p/l*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.