## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

31-Oct-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6161 T

1 pc	Rear bumper & repin		\$ 696.00
1 pc	Rear bumper lower cover		\$ 206.00
1 pc	Rear bumper o/s side bracket @ \$29.00 😕		\$ 29.00
1 pc	Rear bumper o/s reflector @ \$46.00		46.00
1 pc	Rear o/s wheel cover X/4->		\$ 116.00
			\$ 1,093.00
		Less 10%	\$ 109.30
			\$ 983.70
S/NETT			
1 set	Rear bumper clips 🔀		\$ 48.00
1 pc	Rear o/s fender sticker		\$ 60.00
1 pc	Rear bumper top protector 🗯		\$ 80.00
	Sundry		\$ 50.00
	To send/test for rear o/s wheel alignment		\$ 80.00 ×
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, etc.		\$ 650.00 20
	To putty and spray painting on rear bumper, rear o/s fender		\$ 4.00
	To apply rustproofing on the repaired and replaced panels.		\$ 120:00 ×
	Lance notify		\$ 2,651.70
the Repaire To display	onsultants hence notify on sultants hence notify or of the built HE REPAIR COSTS ARE SUBJECTED TO GST ) before latter spray painting resurvey dama THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE		

- To resurvey before after spray panially

  To resurvey before after spray panially

  To display dama THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
- Parts prices ar ANY UNFORESEEN DAMAGES.
- Third party survey is on a No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and Subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Milis 1340ho.
2 Page Alle Regio philo.