

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5019D**AAD1810-302***Not Authorized*
11 Sep 8/2001

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5019D

VF1ABL15AUC275170

RENAULT

LATITUDE

30.10.18

AIG

PART		LIST	
1	FENDER PANEL REAR LH	\$	<i>na</i> 3,299.13 X
1	FENDER PANEL INNER TRIM REAR	\$	<i>sn</i> 671.45 X
1	WHEELARCH REAR LH	\$	<i>sn</i> 543.47 X
1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
1	BUMPER LOWER REAR	\$	<i>sn</i> 768.84
1	BUMPER BRACKET CTR REAR	\$	<i>sn</i> 113.47
1	BUMPER RETAINER LH REAR	\$	<i>sn</i> 44.99
1	BUMPER BEAM REAR	\$	<i>na</i> 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	<i>na</i> 225.95
1	TAILLAMP LH	\$	<i>sn</i> 552.55
1	TAILLAMP PANEL LH	\$	<i>na</i> 986.70
			} X
TOTAL		\$	9,092.54
10%		\$	909.25
		\$	8,183.28

Special Nett			
1SET	BUMPER CLIP REAR	\$	<i>na</i> 66.00 ✓
1	BUMPER BRACKET CLIP REAR LH	\$	<i>na</i> 12.00
1	BUMPER SUPPORT CLIP REAR LH	\$	<i>na</i> 10.50
1SET	WHEELARCH CLIP REAR LH	\$	<i>na</i> 35.00
1	REAR DOOR STICKER '6555 3333'	\$	<i>na</i> 80.00
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00
1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00
1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00
1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00
1	REAR LEFT TYRE	\$	<i>sn</i> 330.00
1	REAR LEFT TYRE RIM	\$	<i>sn</i> 380.00
			} X
TOTAL		\$	1,022.50

Trans-cab Auto Services Pte Ltd

AAD1810-302

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5019D

TOTAL PARTS	\$	9,205.78
--------------------	-----------	-----------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,100.00 <i>2000</i>
Putty and spray painting of the affected portion.	\$	2,100.00 <i>2200</i>
To rust-proofing of the affected areas.	\$	<i>na</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>100</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of rear boot fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
TOTAL	\$	6,450.00

Over All Total	\$	15,655.78
-----------------------	-----------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)**7 DAYS***1 1/2 day*