

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 469R**AAD1810-313***Not Authored**Reserve B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 469R

VF1ABL15AUC283413

RENAULT

LATITUDE

31.10.18

AIG

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Rad/Wt</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56 X
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55 X
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70 X
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55 X
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70 X
19	1 BOOT REAR	\$	<i>Bu</i> 2,872.68 ✓
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06 X
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05 X
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35 X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35 X
24	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36 ✓
25	1 BOOT BADGE	\$	<i>R</i> 225.36 ✓
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08 X
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08 X
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84 X
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84 X

30 1 BOOT INNER TRIM
Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 469R

\$ 586.45
AAD1810-313

31	1 BOOT SWITCH	\$	<i>na</i>	168.13 <i>X</i>
32	1 BOOT LOCK	\$	<i>na</i>	202.67 <i>X</i>
33	1 BOOT LOCK CATCH	\$	<i>na</i>	74.40 <i>X</i>

TOTAL	\$	16,046.87
10%	\$	1,604.69
	\$	14,442.19

Special Nett

1	1SET PARKING AID	\$	<i>Sen</i>	700.00 <i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00 <i>—</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00 <i>—</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00 <i>X</i>
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00 <i>X</i>
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00 <i>X</i>
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00 <i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00 <i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00 <i>✓</i>
10	1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	80.00 <i>30.00</i>
11	1 BOOT STICKER "6555-3333"	\$	<i>na</i>	80.00 <i>30.00</i>
12	1 EXHAUST MOUNTING REAR	\$	<i>na</i>	17.82 <i>X</i>
13	2 REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00 <i>X</i>
14	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00 <i>X</i>
15	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00 <i>X</i>

TOTAL	\$	1,404.82
--------------	-----------	-----------------

TOTAL PARTS	\$	15,847.01
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>4800</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 <i>4000</i>

To transfer of tire, rim and on wheel balancing. \$ 170.00

Trans-cab Auto Services Pte Ltd

AAD1810-313

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 469R

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>3ch</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>6ch</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>6ch</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature

TOTAL \$ 8,720.00

Over All Total \$ 24,567.01

PART BY PART (REPAIR DAY)

10-DAYS

3 days