

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING S,pore 079120

Accident date:30/10/18

Date:31/10/18

Estimate cost to repair vel: SLJ 4575L (Honda Odyssey) claims under vel: SGC 3395S.

1pce tail gate	\$ 1,049.50	DDV	800.00
1pce tail gate top lock ?	189.00	NNX	
1pce tail gate lower lock	35.20	NNX	
2pcs tail gate windscreen side rubber@\$31.60	63.20	NECV	
1pce tail gate windscreen top rubber	41.50	NECV	
1pce tail gate windscreen inner sealant	140.00	80.00	
1pce tail gate windscreen tape from	45.50	NECV	
2pcs tail gate damper@\$165	330.00	NNX	
1pce tail gate reflector	378.60	NNX	
1pce tail gate emblem	30.80	NECV	
1pce tail lamp left ?	821.80	NN	
1pce rear bumper	557.80	DDV	
3pcs rear bumper reverse sensor	400.00	200.00	
1pce tail lamp lower garnish ?	75.30	BRV	
2pcs rear bumper inner brackets@\$108.20 ?	216.40	DDV(LH), RH-SVC	
10pcs rear bumper inner clips@\$4	40.00	NECV	
1pce rear bumper side reflector ?	44.50	NNX	
1pce rear left fender	974.50	RX	
1pce rear panel ?	451.80	DDV	
1pce rear panel lower lock cover	187.50	NNX	
	\$ 6,323.10		
Less 20%	1,264.62		
	\$ 5,058.48		
To rustproof	150.00	60.00	
To dismantle/renew tail gate	150.00	NNX	
To remove/refit rear windscreen	140.00	NNX	
To remove/refit rear interior to effect repair	100.00	NNX	
To dismantle/renew accident portion	1,000.00	NNX	
To spray paint	1,500.00	NNX	

TOTAL \$ 8,898.48

Repair done

9733 0686
Thomas

[Signature]
11/11/18

Consultants hence notify
Repairer of the following:
 • To display damaged part(s) during resurvey
 • Part prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No to gain modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____