

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING S,pore 079120

Accident date:30/10/18

Date:31/10/18

Estimate cost to repair vel: SLJ 4575L (Honda Odyssey) claims under vel: SGC 3395S.

1pce tail gate	\$ 1,049.50 / DD ✓	800.00
1pce tail gate top lock ?	189.00 NN X	
1pce tail gate lower lock	35.20 NN X	
2pcs tail gate windscreen side rubber@\$31.60	63.20 / NEC ✓	
1pce tail gate windscreen top rubber	41.50 / NEC ✓	
1pce tail gate windscreen inner sealant	140.00 / 80.00 ✓	
1pce tail gate windscreen tape from	45.50 / NEC ✓	
2pcs tail gate damper@\$165	330.00 X NN X	
1pce tail gate reflector	378.60 X NN X	
1pce tail gate emblem	30.80 / NEC ✓	
1pce tail lamp left ?	821.80 X NN	
1pce rear bumper	557.80 / DD ✓	
3pcs rear bumper reverse sensor	400.00 200.00	
1pce tail lamp lower garnish ?	75.30 BR ✓	
2pcs rear bumper inner brackets@\$108.20 ?	216.40 DD ✓ (LH), RH-SVC	
10pcs rear bumper inner clips@\$4	40.00 / NEC ✓	
1pce rear bumper side reflector ?	44.50 NN X	
1pce rear left fender	974.50 X R X	
1pce rear panel ?	451.80 ? DD ✓	
1pce rear panel lower lock cover	187.50 X NN X	
	\$ 6,323.10	
Less 20%	1,264.62 /	
	\$ 5,058.48	
To rustproof	150.00 / 60.00	
To dismantle/renew tail gate	150.00 X NN X	
To remove/refit rear windscreen	140.00 / 80.00	
To remove/refit rear interior to effect repair	100.00 / 50.00	
To dismantle/renew accident portion	1,000.00 / 850.00	650.00

To spray paint

TOTAL \$ 8,898.48 850.00 700.00

9733 0686
Thomas

[Signature]
11/11/18

Repair days 5 4