

ASS. REC. BY:

REF: CS/EG718019933/Kthbz Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Yee Pei Li of ETL Date/Time: 02/12/018 11:23am

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SMA 50808 Insured: GBH 20653

at Workshop m/s Esteem Performance Tel: 6424 1221

of 5033 Amk Ind Park 2 #01-259

Policy No: Claim No: GBH 20653 /SL/pl

Sum Insured: Excess:

Make of Veh: D.O.A. 31-10-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 02/12/018 11:40am Person Contacted: Jenny Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 50808 - X
	GBH 20653 - X email.
Thu @ 11:56am	Revised via preli advise
	Part by Part \$4181.12 (Red: 4430.72; 51%)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBH2065J/SL/pl
Our Ref: CS/EG118019933/Ktb

Date: 7/11/2018

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SMA 5080B .

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 02/11/2018 at the premises of M/s Esteem Performance and have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,611.84</u>
Revised Estimate Amount	: S\$ <u>4,181.12</u>
"Check" Items Amount	: S\$ <u>2,100.32</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at n/s body portion.



Repair days: 6 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 2 November 2018 11:23 AM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : GBH2065J / TP : SMA5080B/LKK / DOA : 31/10/2018
Attachments: GBH2065J - SAS.pdf; SMA5080B - SAS.pdf; SMA5080B - ESTIMATE.pdf; SMA5080B - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **ESTEEM PERFORMANCE PTE LTD.**

ADDRESS : 5033 AMK IND. PARK
#01-259
SINGAPORE 569536

PERSON TO CONTACT : JENNY CHONG @ 6424 1221

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimates, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 7 November 2018 11:56 AM
To: Admin-D (LKKAuto); 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; assignments
Subject: RE: GBH2065J / TP : SMA5080B/LKK / DOA : 31/10/2018
Attachments: PRELI ADVISED SMA 5080B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMA 5080B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 2 November 2018 11:43 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: GBH2065J / TP : SMA5080B/LKK / DOA : 31/10/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Friday, 2 November, 2018 11:23 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : GBH2065J / TP : SMA5080B/LKK / DOA : 31/10/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **ESTEEM PERFORMANCE PTE LTD.**

ADDRESS : 5033 AMK IND. PARK

ERGO

Date: 02.11.2018
Our Reference: GBH 2065J/SL/pl
Your Reference: SMA 5080B

Sent via Fax

or

Email

jenny@esteemperf.com.sg

To: ESTEEM PERFORMANCE PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SMA 5080B
Insured's Vehicle: GBH 2065J
Date Of Accident: 31.10.2018

We acknowledge receipt of your request for PRS on: 01.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	☒ LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us todate.
☒	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

REPUBLIC OF SINGAPORE DRIVING LICENCE

APPROVED PERSON S26664341

PENG SHULIN

Exp. Date: 15 Feb 1965

Issue Date: 03 Jul 2009

000001253E

REPUBLIC OF SINGAPORE

IDENTITY CARD NO S26664341

Male

PENG SHULIN

彭曙林

Race
CHINESE

Date of birth
15-02-1965

Sex
M

Country of birth
CHINA

S26664341

Land Transport Authority

VOCATIONAL LICENCE

Licence No: S26664341

Name: PENG SHULIN

Card Issue Date: 29/03/2018

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 01 Motor Cars < 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 03 Jul 2009

Licence No: S26664341

4730744

S26664341

Date of issue
06-06-2011

APT BLK 502B YISHUN STREET 51 #12-428
SINGAPORE 762502

NRIC No: S26664341

Date: 16/05/2017

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	29/03/2018





ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 5080 B

Parts	(a) Cost / List Price Items	\$	6,264.80
	Plus/Less 20%	\$	1,252.96
	Total of Cost / List	\$	5,011.84
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	5,011.84
Labour		\$	3,600.00
Total		\$	8,611.84

The above total will be subjected to 7% G.S.T.

Not Authorize
Henry By paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Hennerth
Company : CKK
Survey conducted on : 2/11/18 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 06 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : Sc Date: 2/11/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMA 5080 B**
Make & Model : **HONDA SHUTTLE**
Chassis No. : **GP71210270**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender <i>R</i>	1	\$435.00		X
2	LHF fender wording "hybrid" <i>~ ~</i>	1	\$58.00		X
3	LH front door <i>R</i>	1	\$1,050.00		✓
4	LH front door hinge top <i>R</i>	1	\$48.60		X
5	LH front door hinge bottom <i>R</i>	1	\$48.60		X
6	LH front door lock	1	\$265.30		?
7	LH front door checker <i>R</i>	1	\$48.50		X
8	LH front door weatherstip <i>CM</i>	1	\$47.10		✓
9	LH front door trim	1	\$580.60		?
10	LHF door outer handle side cover <i>RM/D</i>	1	N/A		X X
11	LHF door outer handle <i>RM/D</i>	1	\$322.70		✓
12	LHF door glass outer moulding <i>Bu</i>	1	\$75.60		✓
13	LHF power window motor	1	\$527.50		?
14	LHF power window regulator	1	\$361.00		?
15	LH rear door <i>R</i>	1	\$703.40		✓
16	LH rear door hinge top	1	\$48.60		?
17	LH rear door hinge bottom	1	\$48.60		?
18	LH rear door lock <i>R</i>	1	\$210.00		X
19	LH rear door checker <i>R</i>	1	\$48.60		X
20	LH rear door weatherstip	1	\$81.20		?
21	LH rear door trim	1	\$560.80		?
22	LHR door outer handle <i>Pu</i>	1	\$108.00		X
23	LHR door outer handle side cover	1	N/A		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMA 5080 B**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71210270**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LHR door glass outer moulding <i>h</i>	1	\$32.70		X
25	LHR power window motor <i>h</i>	1	\$151.80		?
26	LHR power window regulator <i>h</i>	1			
27	LH side skirt <i>ng m</i>	1	\$363.60		✓
28	LH side skirt clip <i>m</i>	10	\$39.00		✓
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 5080 B

Parts	(a) Cost / List Price Items	\$	6,264.80
	Plus/Less 20%	\$	1,252.96
	Total of Cost / List	\$	5,011.84
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	5,011.84
Labour		\$	3,600.00
Total		\$	8,611.84

Finalized.

Not Authorized

7601.40

Henry Bepaint

650.35

1951.05

2081.12

2100

4051.05

4181.12

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

CKIC

Survey conducted on

2/11/18

at

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor

Pe

Date:

2/11/18



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SMA 5080 B
Make & Model : HONDA SHUTTLE
Chassis No : GP71210270

Submit By : Carmen Lim
Year Manufacture : 2018
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender <i>R</i>	1	\$435.00		X
2	LHF fender wording "hybrid" <i>nn</i>	1	\$58.00		X
3	LH front door <i>R</i>	1	\$1,050.00	✓	✓
4	LH front door hinge top <i>R</i>	1	\$48.60		X
5	LH front door hinge bottom <i>R</i>	1	\$48.60		X
6	LH front door lock <i>R</i>	1	\$265.30		X
7	LH front door checker <i>R</i>	1	\$48.50		X
8	LH front door weatherstip <i>CA</i>	1	\$47.10	✓	✓
9	LH front door trim <i>Sn</i>	1	\$580.60		X
10	LHF door outer handle side cover <i>MD</i>	1	N/A	✓	X
11	LHF door outer handle <i>MD</i>	1	\$322.70	✓	✓
12	LHF door glass outer moulding <i>Bu</i>	1	\$75.60	✓	✓
13	LHF power window motor <i>Sn</i>	1	\$527.50		X
14	LHF power window regulator <i>Sn</i>	1	\$361.00		X
15	LH rear door <i>R</i>	1	\$703.40	✓	✓
16	LH rear door hinge top <i>R</i>	1	\$48.60		X
17	LH rear door hinge bottom <i>R</i>	1	\$48.60		X
18	LH rear door lock <i>R</i>	1	\$210.00		X
19	LH rear door checker <i>R</i>	1	\$48.60		X
20	LH rear door weatherstip <i>Sn</i>	1	\$81.20		X
21	LH rear door trim <i>Sn</i>	1	\$560.80		X
22	LHR door outer handle <i>Sn</i>	1	\$108.00		X
23	LHR door outer handle side cover	1	N/A	✓	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

298.80

Spare Parts

Vehicle No. : SMA 5080 B
Make & Model : HONDA SHUTTLE
Chassis No : GP71210270

Submit By : Carmen Lim
Year Manufacture : 2018
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LHR door glass outer moulding <i>in</i>	1	\$32.70		X
25	LHR power window motor <i>in</i>	1	\$151.80		<i>in</i>
26	LHR power window regulator <i>in</i>	1			
27	LH side skirt <i>in</i>	1	\$363.60	✓	✓
28	LH side skirt clip <i>in</i>	10	\$39.00	✓	✓
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

402.60



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6464 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Submit By : Carmen Lim
Year of Manufacture : 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18019933/Klbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 30-11-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 2065J	Veh. Inspected	SMA 5080B	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBH2065J/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	02/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71210270	Colour	METALLIC SILVER	
Odometer	39846	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/10/2018	Inspection Date	02/11/2018	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 5080B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH FRONT FENDER	TO REPAIR SEE LABOUR	435.00	-
1	LHF FENDER WORDING "HYBRID"	NOT NECESSARY	58.00	-
1	LH FRONT DOOR	BENT	1,050.00	1,050.00
1	LH FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	48.60	-
1	LH FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	48.60	-
1	LH FRONT DOOR LOCK	TO REPAIR SEE LABOUR	265.30	-
1	LH FRONT DOOR CHECKER	TO REPAIR SEE LABOUR	48.50	-
1	LH FRONT DOOR WEATHERSTRIP	CUT	47.10	47.10
1	LH FRONT DOOR TRIM	SERVICEABLE	580.60	-
1	LHF DOOR OUTER HANDLE SIDE COVER (NPA)	NOT NECESSARY	-	-
1	LHF DOOR OUTER HANDLE	DENTED / DISTORTED	322.70	322.70
1	LHF DOOR GLASS OUTER MOULDING	BUCKLED	75.60	75.60
1	LHF POWER WINDOW MOTOR	SERVICEABLE	527.50	-
1	LHF POWER WINDOW REGULATOR	SERVICEABLE	361.00	-
1	LH REAR DOOR	BENT	703.40	703.40
1	LH REAR DOOR HINGE TOP	TO REPAIR SEE LABOUR	48.60	-
1	LH REAR DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	48.60	-
1	LH REAR DOOR LOCK	TO REPAIR SEE LABOUR	210.00	-
1	LH REAR DOOR CHECKER	TO REPAIR SEE LABOUR	48.60	-
1	LH REAR DOOR WEATHERSTRIP	SERVICEABLE	81.20	-
1	LH REAR DOOR TRIM	SERVICEABLE	560.80	-
1	LHR DOOR OUTER HANDLE	SERVICEABLE	108.00	-
1	LHR DOOR GLASS OUTER MOULDING	SERVICEABLE	32.70	-
1	LHR POWER WINDOW MOTOR }	SERVICEABLE	151.80	-

Report Ref No. CS/EGI18019933/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LHR POWER WINDOW REGULATOR }	SERVICEABLE	-	-
1	LH SIDE SKIRT	MTG CRACKED	363.60	363.60
10	LH SIDE SKIRT CLIP	NECESSARY	39.00	39.00
	LESS 20% DISCOUNT		-1,252.96	-520.28
			5,011.84	2,081.12
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(LHF FENDER,LHF DOOR,LHR DOOR,LH SIDE SKIRT,LHR FENDER,LH CENTRE PILLAR).INCLUSIVE OF THE REPAIR OF LH FRONT FENDER,LH FRONT DOOR HINGE TOP,LH FRONT DOOR HINGE BOTTOM,LH FRONT DOOR LOCK,LH FRONT DOOR CHECKER,LH REAR DOOR HINGE TOP,LH REAR DOOR HINGE BOTTOM,LH REAR DOOR LOCK AND LH REAR DOOR CHECKER.		1,600.00	800.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(LHF FENDER,LHF DOOR,LHR DOOR,LH SIDE SKIRT,LHR FENDER,LH CENTRE PILLAR).		1,400.00	1,100.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD.		300.00	120.00
	TO TUFF COAT.		250.00	60.00
			3,600.00	2,100.00
	GRAND TOTAL		8,611.84	4,181.12
RECOMMENDED COST OF REPAIRS				4,181.12

Report Ref No. CS/EGI18019933/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.