

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1241/2018/GW
Date : 01-Nov-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Sriram Subramanian
Address : Blk 21 A Simei Street 4,
#04-42, double Bay Residences,
Singapore 528718
Telephone : HP +65 91290934
Type of Claim : Own Damage Claims
Policy No. : 1800094625
Vehicle No : **SMD 2218 B**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Aug-18
Engine No : CHZ 472505
Chassis No : WAUZZZ8V1J1072898
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 01-Nov-18
Place of Accident : Simei St 4 In front of Nodera Condo

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 2218 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$ 360.00	✓
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,000.00	?
3	To dismantle and renew front bumper, bonnet and both headlight. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 4,200.00	1,500.
4	To respray front bumper, bonnet and bonnet hinges.	\$ 1,700.00	1,100
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2218 B .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>reband</i>	\$ 1,739.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 161.00	✗
3	FRONT BUMPER GUIDE SECTION-LH-/RH <i>new</i>	2 \$ 66.00	✗
4	FRONT BUMPER GRILLE <i>new</i>	\$ 140.00	✗
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 460.00	✗
6	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 508.00	✗
7	FRONT BUMPER COVER TRIM-LH/RH	2 \$ 280.00	✗
8	FRONT ADAPTER WHEEL HOSUING LINER-LH/RH	2 \$ 64.00	✗
9	RADIATOR GRILLE <i>could</i>	\$ 1,239.00	✓
11	RADATOR GRILLE CLOSING ELEMENT ?	\$ 167.00	?
12	FRONT BUMPER AIR GUIDE GRILLE-RH/LH <i>new</i>	2 \$ 328.00	✗
13	FOAM FILLER PIECE ?	\$ 162.00	?
14	FRONT BUMPER SIDE REINFORCEMENT ?	\$ 633.00	?
15	FRONT BUMPER COVER ?	\$ 105.00	?
16	SIGN CAUTION <i>new</i>	\$ 12.00	✓
17	BONNET <i>Buckled</i>	\$ 2,755.00	✓
18	BONNET ATTACHMENT PARTS ?	\$ 141.00	?
19	BONNET LID HINGE-LH/RH <i>new</i>	2 \$ 106.00	✗
20	BONNET CATCH HOOK <i>new</i>	\$ 78.00	✗
SUB- TOTAL SPARE PARTS CHARGES		\$ 9,144.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMD 2218 B .**

S/N	Parts Description	<u>Damaged Parts & Prices</u>		Remark
		S/Nett		
21	BONENT STRIKER-LH/RH <i>new</i>	2 \$	192.00	<i>+</i>
22	BONNET EDGE PROTECTION <i>new</i>	\$	24.00	<i>✓</i>
23	BONNET LID LOCK MICRO <i>new</i>	2 \$	353.00	<i>+</i>
24	BONNET CATCH HOOK <i>new</i>	\$	55.00	<i>+</i>
25	LED HEADLIGHT-LH/RH <i>cracked</i>	2 \$	9,776.00	<i>✓</i>
26	LIFT CYLINDER-LH/RH <i>new</i>	2 \$	246.00	<i>+</i>
27	AIR GUIDE-LH/RH <i>new</i>	2 \$	40.00	<i>+</i>
28	AIR GUIDE-UPPER CENTRE	\$	10.00	<i>+</i>
29	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR ?	\$	638.00	?
30	COOLANT CONCENTRATE 1.5 LTR ?	4 \$	133.00	?
31	STICKER FOR AIR CONDITIONER ?	\$	7.00	?
32	FRONT NO. PLATE <i>new</i>	S/N \$	25.00	<i>✓</i>
33	SUNDRIES ?	\$	500.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 21,143.00	
TOTAL LABOUR CHARGES			\$ 7,452.00	
GRAND TOTAL			\$ 28,595.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim.
Surveyed Date : 02/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorised, OS Rep

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant