

REF: AU1

CC3 / AU18019937 / Avbn2

ASSIGNMENT

From: Date: 02.11.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMD 22188

at Workshop n/s: Premium

of: 55 Ubi Rd 1

Insured

Policy No: 1800094625

Claims No:

Sum Insured: Excess: 300

(Client's Record)

Make of Veh:

(Policy Condition)

10:30am

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 122K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 18.5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMD22188 Yr Regn: 2018 August

Type: M.Cm / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan C.C. 999

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 2018 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAU228V1J1072898

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A: 1/11/18 D.O.I: 02/11/18

Survey held at: Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

02 AUG.

2/11/18 Revert via merimen

5/11/18 Rece approved \$18,722 from Victor via merimen

5/11/18 Informed James C/A ex \$300 by email

19/12/18 Final dig \$15,877.08 (Red 12,717.92, 4410) confirmed by email

RECEIVED 10 JAN 2019

Date/Time: File Pass to?

☐

Preli. Report

11

☐

Final Report

Date/Time: File Return to?

23 9/1 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 15,877.08)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + PS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp. (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$200
10

210

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 02 Nov 2018

Preliminary Advice

Vehicle No	: SMD2218B	Accident Date	: 01/11/2018
Make	: AUDI A3	Policy No.	: 1800094625
Assignment Date	: 02/11/2018	Excess	: S\$0.00
Date of Inspection	: 02/11/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,595.00
Revised Amount	:S\$	18,722.00
Check Items (Estimated)	:S\$	3,486.00
Total	:S\$	22,208.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	41,617.00
Salvage Value	:S\$	
Margin for Repair	:S\$	80,383.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 19 December 2018 11:27 AM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SMD2218B - OD AIG - SURVEYED 2 NOV 18

Dear Mr Boo,

Confirm repair cost of \$15,877.08 before excess \$300 and GST @ 5 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 17 December 2018 2:40 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SMD2218B - OD AIG - SURVEYED 2 NOV 18

Hi Adrian and all,

Revised estimate and checked items photographs is attached.

Please confirm repair cost of \$15,877.08 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 5 November 2018 11:37 AM
To: 'Claims'; SUR
Subject: RE: OWN DAMAGE CLAIM FOR SMD 2218 B-DOA: 1/11/2018

Dear James,

As instructed by our client , please proceed to repair the **insured vehicle SMD 2218B (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Monday, 5 November 2018 7:41 AM
To: 'Claims' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OWN DAMAGE CLAIM FOR SMD 2218 B-DOA: 1/11/2018

Dear James,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Saturday, 3 November 2018 11:56 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OWN DAMAGE CLAIM FOR SMD 2218 B-DOA: 1/11/2018

Dear Veron,

Any update on approval and excess?
Kindly advise.

Thank you.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Friday, 2 November, 2018 2:30 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OWN DAMAGE CLAIM FOR SMD 2218 B-DOA: 1/11/2018

Dear James,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, 2 November 2018 12:35 PM
To: SUR <sur@lkkauto.com>

Cc: 'PAL Claim' <claims@premiumauto.com.sg>
Subject: OWN DAMAGE CLAIM FOR SMD 2218 B

Dear All,

Kindly advice on approval and excess for the above mentioned case.
Survey was done earlier this morning.
Thanks.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SMD2218B (8995242175SG)**

OD

Nov 1 2018 8:30AM

[SRIRAM SUBRAMANIAN]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 05/11/2018 11:24 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$18722.00) - SMD2218B - Claim Handler: Dally Amri, Mimi Zarina

Approved:18722.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2025C

Vehicle Details

Vehicle No.: SMD2218B
Vehicle to be Exported: No
Intended Deregistration Date: 02 Nov 2018
Vehicle Make: AUDI
Vehicle Model: A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour: Grey
Manufacturing Year: 2018
Engine No.: CHZ472505
Chassis No.: WAUZZZ8V1J1072898
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$22,104.00
Original Registration Date: 08 Aug 2018
First Registration Date: 08 Aug 2018
Transfer Count: 0
Actual ARF Paid: \$22,946.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Aug 2028
PARF Rebate Amount: \$17,209.00

Intended COE Rebate Details

COE Expiry Date: 07 Aug 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$25,000.00
COE Rebate Amount: \$24,408.00
Total Rebate Amount: \$41,617.00

The information contained herein is correct as at 02 Nov 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7662025C



Name

SRIRAM SUBRAMANIAN

Race

INDIAN

Date of birth

14-05-1976

Sex

M

S7662025C

Country of birth

INDIA

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7662025C

Name

SRIRAM SUBRAMANIAN

Birth Date: 14 May 1976

Issue Date: 29 Aug 2014



002340538G



8758879

NRIC No: S7662025C



Nationality

INDIAN

Date of issue

23-02-2006

Address

APT BLK 21A SIMEI STREET 4 #04-42
SINGAPORE 528718

NRIC No: S7662025C

Date: 10/12/2012

No: 7189278

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 29 Aug 2014



Licence No: S7662025C

NP 428A

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : SRIRAM SUBRAMANIAN
 Period of Insurance : 08 Aug 2018 To 07 Aug 2020
 Engine No. : CHZ 472505
 Chassis No. : WAUZZZ8V1J1072898

Vehicle No. : SMD2218B
 Policy No. : 1800094625
 Endorsement No. :
 Issued Date : 17 Aug 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
 Engine Capacity/Tonnage : 999.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes
 Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

SRIRAM SUBRAMANIAN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125267

PREMIUM LEASING -TUC
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



Manik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Staffany Loh

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1241/2018/GW
Date	:	01-Nov-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Sriram Subramanian
Address	:	Blk 21 A Simei Street 4, #04-42, double Bay Residences, Singapore 528718
Telephone	:	HP +65 91290934
Type of Claim	:	Own Damage Claims
Policy No.	:	1800094625
Vehicle No	:	SMD 2218 B
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Aug-18
Engine No	:	CHZ 472505
Chassis No	:	WAUZZZ8V1J1072898
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	01-Nov-18
Place of Accident	:	Simei St 4 In front of Nodera Condo

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 2218 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$ 360.00	✓ ✓
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,000.00	? ✗
3	To dismantle and renew front bumper, bonnet and both headlight. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 4,200.00	1500. ✓
4	To respray front bumper, bonnet and bonnet hinges.	\$ 1,700.00	1100 ✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 7,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2218 B .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehanded</i>	\$ 1,739.00	✓ 1391.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 161.00	✗
3	FRONT BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 66.00	✗
4	FRONT BUMPER GRILLE <i>new</i>	\$ 140.00	✗
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 460.00	✗
6	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 508.00	✗
7	FRONT BUMPER COVER TRIM-LH/RH	2 \$ 280.00	✗
8	FRONT ADAPTER WHEEL HOUSING LINER-LH/RH	2 \$ 64.00	✗
9	RADIATOR GRILLE <i>cracked</i>	\$ 1,239.00	✓ 991.20
11	RADIATOR GRILLE CLOSING ELEMENT <i>end</i>	\$ 167.00	? 133.00
12	FRONT BUMPER AIR GUIDE GRILLE-RH/LH <i>new</i>	2 \$ 328.00	✗
13	FOAM FILLER PIECE <i>Not new</i>	\$ 162.00	? ✗
14	FRONT BUMPER SIDE REINFORCEMENT <i>new</i>	\$ 633.00	? ✗
15	FRONT BUMPER COVER <i>Rehanded</i>	\$ 105.00	? 83.60
16	SIGN CAUTION <i>new</i>	\$ 12.00	✓ 9.28
17	BONNET <i>Buckled</i>	\$ 2,755.00	✓ 2204
18	BONNET ATTACHMENT PARTS <i>new</i>	\$ 141.00	? ✗
19	BONNET LID HINGE-LH/RH <i>new</i>	2 \$ 106.00	✗
20	BONNET CATCH HOOK <i>new</i>	\$ 78.00	✗
SUB- TOTAL SPARE PARTS CHARGES		\$ 9,144.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2218 B .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONENT STRIKER-LH/RH <i>new</i>	2 \$ 192.00 *	
22	BONNET EDGE PROTECTION <i>new</i>	\$ 24.00 ✓	18.88
23	BONNET LID LOCK MICRO <i>new</i>	2 \$ 353.00 +	
24	BONNET CATCH HOOK <i>new</i>	\$ 55.00 +	
25	LED HEADLIGHT-LH/RH <i>crushed</i>	2 \$ 9,776.00 ✓	7820.80
26	LIFT CYLINDER-LH/RH <i>new</i>	2 \$ 246.00 +	
27	AIR GUIDE-LH/RH <i>new</i>	2 \$ 40.00 +	
28	AIR GUIDE-UPPER CENTRE	\$ 10.00 *	
29	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR <i>new</i>	\$ 638.00 ?	X
30	COOLANT CONCENTRATE 1.5 LTR <i>new</i>	4 \$ 133.00 ?	X
31	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 7.00 ?	X
32	FRONT NO. PLATE <i>new</i>	S/N \$ 25.00 ✓	25
33	SUNDRIES <i>new</i>	\$ 500.00 ?	47.92
TOTAL SPARE PARTS CHARGES		:	\$ 21,143.00
TOTAL LABOUR CHARGES			\$ 7,452.00
GRAND TOTAL			\$ 28,595.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King.
Surveyed Date : 02/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS Rep

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1241/2018/GW
Date	:	1-Nov-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb - 17 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Sriram Subramanian
Address	:	Blk 21 A Simei Street 4, #04-42, double Bay Residences, Singapore 528718
Telephone	:	HP +65 91290934
Type of Claim	:	Own Damage Claims
Policy No.	:	1800094625
Vehicle No	:	SMD 2218 B
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Aug-18
Engine No	:	CHZ 472505
Chassis No	:	WAUZZZ8V1J1072898
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	1-Nov-18
Place of Accident	:	Simei St 4 In front of Nodera Condo

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 2218 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$	360.00	\$ 360.00
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$	1,000.00	
3	To dismantle and renew front bumper, bonnet and both headlight. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$	4,200.00	\$ 1,500.00
4	To respray front bumper, bonnet and bonnet hinges.	\$	1,700.00	\$ 1,100.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,452.00</u>	<u>\$ 3,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2218 B .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,739.00	\$ 1,391.20
2	FRONT BUMPER FIXING PARTS	\$ 161.00	
3	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$ 66.00	
4	FRONT BUMPER GRILLE	\$ 140.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 460.00	
6	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 508.00	
7	FRONT BUMPER COVER TRIM-LH/RH	2 \$ 280.00	
8	FRONT ADAPTER WHEEL HOSUING LINER-LH/RH	2 \$ 64.00	
9	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
11	RADATOR GRILLE CLOSING ELEMENT	\$ 167.00	\$ 133.20
12	FRONT BUMPER AIR GUIDE GRILLE-RH/LH	2 \$ 328.00	
13	FOAM FILLER PIECE	\$ 162.00	
14	FRONT BUMPER SIDE REINFORCEMENT	\$ 633.00	
15	FRONT BUMPER COVER	\$ 105.00	\$ 83.60
16	SIGN CAUTION	\$ 12.00	\$ 9.28
17	BONNET	\$ 2,755.00	\$ 2,204.00
18	BONNET ATTACHMENT PARTS	\$ 141.00	
19	BONNET LID HINGE-LH/RH	2 \$ 106.00	
20	BONNET CATCH HOOK	\$ 78.00	
SUB- TOTAL SPARE PARTS CHARGES		\$ 9,144.00	\$ 4,812.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMD 2218 B .**

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		c/f		\$ 4,812.48
21	BONNET STRIKER-LH/RH	2 \$	192.00	
22	BONNET EDGE PROTECTION	\$	24.00	\$ 18.88
23	BONNET LID LOCK MICRO	2 \$	353.00	
24	BONNET CATCH HOOK	\$	55.00	
25	LED HEADLIGHT-LH/RH	2 \$	9,776.00	\$ 7,820.80
26	LIFT CYLINDER-LH/RH	2 \$	246.00	
27	AIR GUIDE-LH/RH	2 \$	40.00	
28	AIR GUIDE-UPPER CENTRE	\$	10.00	
29	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR	\$	638.00	
30	COOLANT CONCENTRATE 1.5 LTR	4 \$	133.00	
31	STICKER FOR AIR CONDITIONER	\$	7.00	
32	FRONT NO. PLATE	S/N \$	25.00	\$ 25.00
33	SUNDRIES	\$	500.00	\$ 47.92
TOTAL SPARE PARTS CHARGES		:	\$ 21,143.00	\$ 12,725.08
TOTAL LABOUR CHARGES			\$ 7,452.00	\$ 3,152.00
GRAND TOTAL			\$ 28,595.00	\$ 15,877.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles



AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMD 2218 B

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1241/2018/MAS

7 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SMD 2218 B Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SMD 2218 B**, claimant, **Mr. Sriram Subramaniam**, please find the related document per attached.

1. A copy of the Original invoice no. 85013318 – S\$16,667.48
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMD 2218 B

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018 13:55		02 Nov 2018 13:09 Edit Adj Rpt	S\$15,877.08 Edit Estimates	S\$15,877.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS Insured: SRIRAM SUBRAMANIAN, ID: S7662025C, Tel: +6591290934, Email: SRIRAM_SUBRAMANIAN@HOTMAIL.COM Vehicle Reg. No.: SMD2218B Claim Type: OD / 8995242175SG Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911 Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/11/2018] Driver/Custodian: SRIRAM SUBRAMANIAN (42 / Male), NRIC: S7662025C, Tel: +6591290934 [Created by insurer] 01/11/2018 08:00 - :59 [2 Months and 24 Days From LTA Reg Date (Man Yr)] Policy/Cover Note No.: 1800094625 (Comprehensive) Excess: S\$300.00																								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail - AIG_SG (05/11/2018): Alert - Adj Mandate Approved (S\$18722.00) - SMD2218B - Claim Handler: Dally Amri... - AIG_SG (05/11/2018): SMD2218B / OD / 01/11/2018 / Coverage & Excess update																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18019937/AVBN2

Date: 11/01/2019

REFERENCE

Insured/Claimant: SRIRAM SUBRAMANIAN
Date of Loss: 01/11/2018

Policy No: 1800094625
Nature of Claim: OD

Claim No: 8995242175SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2218B	Engine No:	CHZ472505
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8V1J1072898
Reg. Date:	08/08/2018 (Man. Year: 2018)	Odometer:	2018 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,143.00	12,725.08	8,417.92	39.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,452.00	3,152.00	4,300.00	57.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,595.00	15,877.08	12,717.92	44.48
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	28,295.00	15,577.08	12,717.92	44.95
+ GST 7.00/7.00% (S\$)	1,980.65	1,090.40	890.25	44.95
Nett Amount (S\$)	30,275.65	16,667.48	13,608.17	44.95

INSPECTION

Date of Assignment: 02/11/2018

Date Inspected: 02/11/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,739.00 FS	*1,391.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	161.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	66.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE	Not Necessary	140.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	460.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	508.00 FS	*- FS
7	2		*FRONT BUMPER COVER TRIM-LH/RH	Not Necessary	280.00 FS	*- FS
8	2		*FRONT ADAPTER WHEEL HOUSING LINER-LH/RH	Not Necessary	64.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Damaged	167.00 FS	*133.20 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	328.00 FS	*- FS
12	1		*FOAM FILLER PIECE	Not Necessary	162.00 FS	*- FS
13	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	633.00 FS	*- FS
14	1		*FRONT BUMPER COVER	Deformed	105.00 FS	*83.60 FS
15	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
16	1		*BONNET	Buckled	2,755.00 FS	*2,204.00 FS
17	1		*BONNET ATTACHMENT PARTS	Not Necessary	141.00 FS	*- FS
18	2		*BONNET LID HINGE-LH/RH	Not Necessary	106.00 FS	*- FS
19	1		*BONNET CATCH HOOK	Not Necessary	78.00 FS	*- FS
20	2		*BONNET STRIKER-LH/RH	Not Necessary	192.00 FS	*- FS
21	1		*BONNET EDGE PROTECTION	Necessary	24.00 FS	*18.88 FS
22	2		*BONNET LID LOCK MICRO	Not Necessary	353.00 FS	*- FS
23	1		*BONNET CATCH HOOK	Not Necessary	55.00 FS	*- FS
24	2		*LED HEADLIGHT-LH/RH	Cracked	9,776.00 FS	*7,820.80 FS
25	2		*LIFT CYLINDER-LH/RH	Not Necessary	246.00 FS	*- FS
26	2		*AIR GUIDE-LH/RH	Not Necessary	40.00 FS	*- FS
27	1		*AIR GUIDE-UPPER CENTRE	Not Necessary	10.00 FS	*- FS
28	1		*LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR	Not Necessary	638.00 FS	*- FS
29	4		*COOLANT CONCENTRATE 1.5 LTR	Not Necessary	133.00 FS	*- FS
30	1		*STICKER FOR AIR CONDITIONER	Not Necessary	7.00 FS	*- FS
31	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
32	1		*SUNDRIES	Necessary	500.00 FS	*47.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$S) 21,143.00 12,725.08

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	-------------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHTS WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER,RADIATOR,ADDITIONAL RADIATOR,ELECTRICAL FANS CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,000.00	-
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHT.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,200.00	1,500.00
4	TO RESPRAY FRONT BUMPER,BONNET AND BONNET HINGES	New	1,700.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,452.00	3,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Claim Documents

***SMD2218B (8995242175SG)**
OD
Nov 1 2018 8:00AM
[SRIRAM SUBRAMANIAN]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer ▼		
Video															1 per page ▼		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail		Print			
1	01/11/18 11:48	Video - Accident [Linked Accident Report Documents]										1	Load MP4				
Assessment Reports															1 per page ▼		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	02/11/18 14:20	Adjuster Immediate Advice										1	Load HTM				
Photos/Images															3 per page ▼		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	02/11/18 14:21	General View										1	Load JPG		☒		
2	02/11/18 14:21	General View										1	Load JPG		☒		
3	02/11/18 14:21	General View										1	Load JPG		☒		
4	02/11/18 14:21	General View										1	Load JPG		☒		
5	02/11/18 14:21	General View										1	Load JPG		☒		
6	02/11/18 14:21	General View										1	Load JPG		☒		
7	02/11/18 14:21	General View										1	Load JPG		☒		
8	02/11/18 14:21	General View										1	Load JPG		☒		
9	02/11/18 14:21	General View										1	Load JPG		☒		
10	02/11/18 14:21	General View										1	Load JPG		☒		
11	02/11/18 14:21	General View										1	Load JPG		☒		
12	02/11/18 14:21	General View										1	Load JPG		☒		
13	02/11/18 14:21	General View										1	Load JPG		☒		
14	02/11/18 14:21	General View										1	Load JPG		☒		
15	02/11/18 14:21	General View										1	Load JPG		☒		
16	02/11/18 14:21	General View										1	Load JPG		☒		
17	02/11/18 14:21	General View										1	Load JPG		☒		
18	02/11/18 14:21	General View										1	Load JPG		☒		
19	02/11/18 14:21	General View										1	Load JPG		☒		
20	02/11/18 14:21	General View										1	Load JPG		☒		
21	02/11/18 14:21	General View										1	Load JPG		☒		
22	02/11/18 14:21	General View										1	Load JPG		☒		
23	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
24	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
25	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
26	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
27	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
28	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
29	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
30	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
31	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
32	18/12/18 18:28	Reinspection Photo										1	Load JPG		☒		
Documentation															1 per page ▼		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	02/11/18 14:23	Singapore Accident Statement										1	Load PDF				
2	02/11/18 14:24	Certificate of Insurance										1	Load PDF				

3	02/11/18 14:24	Driver's Driving License	1	Load PDF	
4	02/11/18 14:24	MARK ESTIMATE	1	Load PDF	
5	11/01/19 09:10	WORKSHOP INVOICE	1	Load PDF	
6	11/01/19 09:10	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

				View	Use Viewer
Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	01/11/18 11:48	Video - Accident	1 Load MP4		
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	01/11/18 12:13	Accident Statement	1 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
2	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
3	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
4	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
5	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
6	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
7	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
8	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
9	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
10	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
11	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
12	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
13	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
14	01/11/18 12:06	Accident Photo	1 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	01/11/18 11:41	Sketch Plan	1 Load JPG	☒	
2	01/11/18 11:41	Sketch Plan #2	1 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				