

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9926P

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

AAD1810-303*Not Notarized**61 Sep @ 2450h***SHB 9926P**

VF1ABL15AUC273379

RENAULT

LATITUDE

30.10.18

CHINA TAIPING**PART****LIST**

- | | |
|----|------------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMPER BRACKET SIDE RH REAR |
| 5 | 1 BUMPER RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMPER BRACKET SIDE LH REAR |
| 8 | 1 BUMPER RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 OUTER PANEL REAR (End Panel) |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM |
| 15 | 1 TAILLAMP RH |
| 16 | 1 TAILLAMP PANEL RH |
| 17 | 1 TAILLAMP LH |
| 18 | 1 TAILLAMP PANEL LH |
| 19 | 1 BOOT REAR |
| 20 | 1 BOOT FINISHER |
| 21 | 1 BOOT WHEATERSTRIP |
| 22 | 1 BOOT REFLECTOR LAMP LH |
| 23 | 1 BOOT REFLECTOR LAMP RH |
| 24 | 1 BOOT BADGE 'RENAULT' |
| 25 | 1 BOOT BADGE |
| 26 | 1 BOOT STRUT LH |
| 27 | 1 BOOT STRUT RH |
| 28 | 1 BOOT HINGE LH |
| 29 | 1 BOOT HINGE RH |

\$	<i>nd/cm</i>	1,108.46	—
\$	<i>nd/cm</i>	768.84	—
\$	<i>SL</i>	113.47	} X
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	
\$	<i>SL</i>	43.61	
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	} X
\$	<i>SL</i>	43.61	
\$	<i>BN</i>	777.52	
\$	<i>N</i>	225.95	} X
\$	<i>N</i>	225.95	
\$	<i>N</i>	1,471.77	
\$	<i>SL</i>	404.56	
\$	<i>SL</i>	552.55	
\$	<i>N</i>	986.70	
\$	<i>SL</i>	552.55	
\$	<i>N</i>	986.70	
\$	<i>N</i>	2,872.68	
\$	<i>SL</i>	470.06	
\$	<i>SL</i>	323.05	
\$	<i>SL</i>	493.35	
\$	<i>SL</i>	493.35	
\$	<i>na</i>	225.36	
\$	<i>na</i>	225.36	
\$	<i>SL</i>	276.08	
\$	<i>SL</i>	276.08	
\$	<i>N</i>	367.84	
\$	<i>N</i>	367.84	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9926P

- 30 1 BOOT INNER TRIM
- 31 1 BOOT SWITCH
- 32 1 BOOT LOCK
- 33 1 BOOT LOCK CATCH
- 34 1 EXHAUST REAR
- 35 1 EXHAUST CAP REAR

\$	Sn	586.45	}	X
\$	Sn	168.13		
\$	n	202.67		
\$	n	74.40		
\$	n	7,489.05		
\$	n	230.49		
TOTAL	\$	23,766.42		
10%	\$	2,376.64		
	\$	21,389.78		

Special Nett

- 1 1SET PARKING AID
- 2 1SET REAR BUMPER CLIP
- 3 1SET BUMPER BRACKET CTR CLIP
- 4 1SET BUMPER BRACKET SIDE CLIP RH RR
- 5 1SET BUMPER RETAINER RH CLIP RR
- 6 1SET BUMPER BRACKET SIDE CLIP LH RR
- 7 1SET BUMPER RETAINER CLIP LH RR
- 8 1SET BUMPER LOWER REAR RIVET
- 9 1SET BUMPER LOWER REAR CLIP
- 10 1 BOOT STICKER "Trans-cab"
- 11 1 BOOT STICKER "6555-3333"
- 12 1 EXHAUST MOUNTING REAR
- 13 2 REAR WINDSCREEN SEALANT
- 14 1 WINDSCREEN MOULDING
- 15 1 REAR WINDSCREEN INNER SPONGE SEAL
- 16 1 BOOT INNER TRIM CLIP

\$	Sn	700.00	X
\$	nn	66.00	—
\$	nn	33.00	—
\$	nn	10.00	X
\$	nn	20.00	X
\$	nn	10.00	X
\$	na	20.00	X
\$	nn	22.00	X
\$	nn	66.00	—
\$	nn	80.00	} X
\$	nn	80.00	
\$	Sn	17.82	
\$	nn	80.00	
\$	nn	100.00	
\$	nn	100.00	
\$	nn	45.00	
TOTAL	\$	1,449.82	

TOTAL PARTS \$ 22,839.60

LABOUR

Putty And Spray Painting Of The Affected Portion. \$

2200
3,000.00

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$

2000
3,000.00

AAD1810-303

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9926P

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>↪</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>↪</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>↪</i> 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>↪</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00 X

TOTAL \$ 8,720.00

Over All Total \$ 31,559.60

LUMP SUM (REPAIR DAY)

~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by LKK is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: