

# EUROSPORTS AUTO PTE LTD

24 Leng Kee Road. #01-03, Singapore 159  
TEL : (65) 6565 5995 FAX : (65) 6567 551



Attn. Motor Claims  
AIG Asia Pacific Insurance

## Repair Quotation

30-10-18

### Lamborghini Aventador SV - LP750 - Reg No. SF10P

(3rd Party Claim against SKT 3947M)

#### Parts

Qty Price

1	470854960L	LINING FOR FENDER RH <i>CRA</i>	Broken	1	\$	8,476
2	470853252B	TURN SIGNAL RH <i>PAO</i>	Broken	1	\$	145
3	470807728	REAR BUMPER EXTENSION RH LP750 <i>SCA</i>	Scratch	1	\$	13,808
4	470601017AG	REAR ALUMINIUM RIM <i>SCA</i>	Chipped	1	\$	13,548
5		Rivets, clips, and other fasteners <i>new</i>	Nec		\$	300

#### Labour (4 days)

1	To dismantle and ReFit all Parts	1400	4	\$	<del>4200</del> 5,600
2	To do Respray Paint on Front Bumper and Spoiler Kit	1000	4	\$	<del>1000</del> 4,000

Sub-Total \$ 45,877  
GST \$ 3,211  
**TOTAL \$ 49,088**

- 1 This is only an estimate, should any additional job be found necessary in the course of work, extra material and labour, cost will be charged accordingly for which you will be informed prior to action taken.
- 2 All materials prices quoted are subject to change without notification
- 3 All repairs are subject to spare parts availability
- 4 Quotation valid for one month from date of issue.

**Lamborghini Singapore**  
**Workshop Contact:**  
Lee Wai Sing  
Service Advisor  
68820865 / 97999596



*by 2/11/18  
5:09pm*

*Resue  
HP 90010068*

*5 days*

*P/P*

*02/11/18 @ 1110*

*Resue b/c paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer