

22/03/2002

ASS REC BY:

REF:

CS/CT118019958 / Ksber2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTL

Date/Time:

02.11.2018 3:59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFE 5757U

Insured:

SKW 629K

at Workshop m/s

Lian Hong Song

Tel:

6484 3683

of

Bik 5035 Amk Ind Park 2 # 01-345

Policy No:

DMPCSN 1649891802

Claim No:

JNM18DD5189 (02)

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

05.11.2018

H.O.D. Endorsement:

Date/Time:

02.11.2018 4:11pm

Person Contacted:

Apple

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFE 5757U - CA / AXA 12019578 / Aedg2

DUA: 03-10-12

SKW 629K - CS/CT118012417 / Gvd302

DUA: 300618

4/12

1/1 Ly @ 8600/ enail & confirmed

05/12/18

Confirmed HS \$8,600/- @ 5 days with Kenneth
(\$ 12,966.42 Red - 60%)

REF:

C71

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFE 5757U
 at Workshop m/s Lian Hong Seng
 of Blk 5035 AMK # 01-345

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4-5 days Res.: Yes or NoLum Sum: 1.5 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFE 5757U Yr Regn: 12 '17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 520D cc 1995Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 20297 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJC 32000NB 92964Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18R: 275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 31/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/11 File pass to Catherine

RECEIVED 05 DEC 2018

Date/Time, File Pass to?

05/12/181) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS St

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I: (\$ 8,600/- 4/5)

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Nov 2018		02 Nov 2018 15:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NG DJONI, ID: S7276554J		
Main Claimant:	LIM LYE HUAT, ID: S1762122Z		
Vehicle Reg. No.:	SFE5757U	Date of Loss:	31/10/2018 10:00 - :59
Claim Type:	TP / SNM18D05189C02	Policy/Cover Note No.:	DMPCSN1669891802 (Comprehensive)
Vehicle Reg. No. (Insured):	SKW629K	Policy No. (Claimant):	MP306641
		Excess:	S\$0.00
Repairer:	Lian Hong Seng Motor Works - Ang Mo Kio (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345, 569537 Ang Mo Kio - Tel: 64843683 96159830 96754083		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	HL Assurance Pte Ltd (HQ) - Tel: 69226030		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/11/2018]		
Driver/Custodian (Insured):	NG DJONI (46 / Male), NRIC: S7276554J		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	31/10/2018 16:20
Date Of Accident	31/10/2018 10:45
Exact Location Of Accident	YISHUN AVE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFE5757U
Insured/Policyholder	
Name Of Registered Owner	LIM LYE HUAT
NRIC No	S1762122Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90112133
Alternative Phone No	OTHERS-90112133
Vehicle Particulars	
Manufacturer	BMW
Model	520D-2.0 M SPORT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP306641
Cover Note Number	08/12/2017 - 07/12/2018
Driver	
Name of Driver	LIM LYE HUAT
NRIC No	S1762122Z
Date Of Birth	22/06/1966
Occupation	INDOOR
Date Of Driving Pass	10/01/1990
Driving Experience	28 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90112133
Fax Number	
Contact Number	OTHERS-90112133
Email Address	NOEMAIL

Address	BLK 445B FERNVALE ROAD #13-385
Postcode	792445
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : YANG HUI RU GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN - MAID GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO OWN WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW629K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Sketch Plan Pg. 2

Date of accident: 31/10/18 Time: 1045am Location: Ate Yishun Ave 1
 My Vehicle A: SFE5T5U Vehicle B: SLW629K Vehicle C: —
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight on my lane when I felt an impact on my rear. Vehicle B has hit onto my rear portion.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :
 Email address :
 & myself :
 Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

AH LIM MOTOR COMPANY



THE SCHEDULE

Insured Name and Address:
 LIM, LYE HUAT
 445B FERNVALE ROAD
 #13-385 FERNVALE VISTA
 SINGAPORE 792445

Policy No.: MP306641
Period of Insurance
From : 08 Dec 2017
To : 07 Dec 2018
(Both Dates Inclusive)
Date of Issue : 08 Dec 2017

Name of Product	:	Car Protect360		
Scope of Cover	:	Comprehensive		
Registration No.	:	SFE5757U		
Make & Model	:	BMW 520d		
Engine No.	:	77959973B47D20A		
Chassis No.	:	WBAJC32000WB92964		
Engine Capacity	:	1995 c.c		
Year of Registration	:	2017		
Sum Insured	:	Market Value	Windscreen	: Unlimited
No Claim Discount	:	40%	Off-Peak Car	: No
Offence Free Dis.	:	Yes	Vehicle Usage	: Private + Work
NCD Protector	:	No	Approved Workshop	: Yes
Own Damage Excess	:	SGD750.00	Windscreen Excess	: SGD100.00
Y/I Driver Excess (if applicable)	:	SGD3,000.00		
Hire Purchase	:	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD		
Authorized Drivers	:	LIM, LYE HUAT		
		N/A		
		N/A		
		N/A		
Limitation as to Use	:	As specified in the Certificate of Insurance		
Subject to Endorsement(s)	:	MAE, M02, M06, M09, M11, M03, M14		
Premium Payable	:	SGD 1,044.22 (Inclusive of GST)		

Signed for and on behalf of
 HL Assurance Pte. Ltd.

Authorized Signature

20160602

HL Assurance Pte. Ltd. A Member of the Hong Leong Group

11 Keppel Road, #11-01 ABI Plaza, Singapore 089057 Tel: 65 6702 0202 Fax: 65 6221 3782 UEN/GST Regn No. 201229558W www.hlas.com.sg



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form X1

CERTIFICATE NUMBER : MP306641

Type of Coverage : Comprehensive Own Damage Excess : SGD750.00

Sum Insured : **Market Value** Windscreen Excess : SGD100.00

- | | |
|--|-------------------|
| 1. Index Mark and Registration Number of Vehicle | SFE5757U |
| Chassis Number of Vehicle | WBAJC32000WB92964 |
| 2. Name of Policyholder | LIM, LYE HUAT |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 08 Dec 2017 |
| 4. Date of Expiry of Insurance | 07 Dec 2018 |
| 5. Persons or Classes of Persons entitled to drive* | |
| 01. LIM, LYE HUAT | 02. N/A |
| 03. N/A | 04. N/A |
| 05. N/A | 06. N/A |

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business or profession. The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Please note that the Own Damage Excess will be halved if claims related repairs are done at HL Assurance Approved Workshops listed in the attached.

This Certificate is not transferable to a new owner of the Motor Vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to HL Assurance Pte. Ltd. Within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

Hire Purchase Company : TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HL ASSURANCE PTE. LTD.

Authorized Signature

Issue on: 08 Dec 2017

The owner and vehicle particulars for Vehicle No. SFE5757U as at 08 Dec 2017 are as follows:

1.	Name	: LIM LYE HUAT
2.	Identification No. Type	: Singapore NRIC
3.	Identification No.	: S1762122Z
4.	Place Of Passport Issue	: -
5.	Registered Address	: APT BLK 445B FERNVALE ROAD #13-385 SINGAPORE 792445
6.	Mailing Address	: -
7.	Vehicle No.	: SFE5757U
8.	Effective Date of Ownership	: 08 Dec 2017
9.	Original Registration Date	: 08 Dec 2017
10.	First Registration Date	: 08 Dec 2017
11.	Vehicle Type	: P10 - Passenger Motor Car
12.	Vehicle Scheme	: Normal
13.	Attachment 1	: No Attachment
14.	Attachment 2	: -
15.	Attachment 3	: -
16.	Vehicle Make	: B.M.W.
17.	Vehicle Model	: 520D M SPORT
18.	Year of Manufacture	: 2017
19.	Primary Colour	: Blue
20.	Secondary Colour	: -
21.	Passenger Capacity	: 4
22.	Chassis/Trailer Chassis No.	: WBAJC32000WB92964 / -
23.	Propellant/Emission Standard	: Diesel / Euro VI
24.	Engine No./Motor No.	: 77959973B47D20A / -
25.	Engine Capacity(cc)/Power Rating(kW)	: 1995 / -
26.	Maximum Power Output(kW/bhp)	: 140.0 / 187
27.	Unladen Weight(kg)	: 1635
28.	Maximum Laden Weight(kg)	: 2245
29.	Open Market Value	: \$57,809.00
30.	PARF Eligibility	: Yes
31.	PARF Eligibility Expiry Date	: 07 Dec 2027
32.	Minimum PARF Benefit	: \$33,028.00
33.	IU Label No.	: -
34.	COE No.	: 2017120103001417K
35.	COE Expiry Date	: 07 Dec 2027
36.	COE Category	: B - Car above 1600cc or 97kW (130bhp)
37.	Quota Premium/Prevailing Quota Premium	: \$57,390.00
38.	Actual Quota Premium/PQP Paid	: \$57,390.00
39.	Actual ARF Paid	: \$66,057.00
40.	CO2 Emission(g/km)	: 114.00
41.	Actual CEVS Rebate Utilised	: \$10,000.00
42.	CEVS Surcharge Paid	: -
43.	Actual Green Vehicle Rebate Utilised	: -
44.	Vehicle Lifespan Expiry Date	: -
45.	Road Tax Amount	: \$1,906.00
46.	Road Tax Start Date	: 08 Dec 2017
47.	Road Tax End Date	: 07 Dec 2018
48.	Remarks	: This vehicle is eligible for PARF. To renew the COE, the Prevailing Quota Premium payable is that of Category B.

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2

#01-345 SINGAPORE 569538

DATE: 31/10/2018

VEHICLE NO: SF5757U

MODEL: BMW 520D

ESTIMATE

ATTN:

Not Authorised

Resurvey B4 paint

5 days

TP

ACCIDENT DATE:

TYPE OF CLAIM:

CLAIM ADVISOR:

1 Bsp @ 8600/yr

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	<i>By</i> \$2,564.50
REAR EMBLEM	1	<i>re</i> \$76.50
REAR LOGO – 520D	1	<i>re</i> \$68.40
BOOTLID LOCK	1	<i>R</i> \$378.50
BOOTLID LOCK SWITCH BUTTON	1	<i>re</i> \$298.40
BOOTLID LAMP	2	<i>re</i> \$849.60
REAR BUMPER CLIPS	10	<i>re</i> \$50.00
REAR BUMPER RETAINER	2	<i>re</i> \$266.20
REAR BUMPER CENTRE BRACKET	1	<i>re</i> \$195.80
REAR BUMPER REFLECTOR	2	<i>re</i> \$298.60
REAR REINFORCEMENT	1	<i>By</i> \$665.40
END PANEL	1	<i>re</i> \$776.50
SPARE TYRE PANEL – FIBRE	1	<i>re</i> \$648.10
SPARE TYRE SIDE PANEL	2	REPAIR
END PANEL TOP GARNISH	1	<i>re</i> \$289.60
REAR WEATHER STRIP	1	<i>re</i> \$255.70
TAILLAMP	2	<i>re</i> \$1,684.60
REAR EXHAUST PIPE MUFFLER	1	<i>re</i> \$2,351.10
REAR EXHAUST PIPE FINISHER	2	<i>re</i> \$448.60
REAR EXHAUST PIPE MOUNTING	2	<i>re</i> \$188.60
REAR EXHAUST HEAT SHIELD	1	<i>re</i> \$345.10
REVERSE SENSOR	4	<i>shot</i> \$1,024.80
REVERSE SENSOR HOLDER	4	<i>re</i> \$248.40
REAR BUMPER SENSOR –	2	<i>re</i> \$346.60
SMART OPENER		
TOTAL:		\$14,319.60
DISCOUNT 5%:		\$715.98
		\$13,603.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

C

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 31/10/2018
VEHICLE NO: SFE5757U
MODEL: BMW 520D

S/NET

REAR BUMPER – M SPORT	1	<i>Ph</i>	\$2,589.40	✓
REAR BUMPER DIFFUSER	1	<i>Del/dit</i>	\$893.40	✓
END PANEL SEALANT	1	<i>nn</i>	\$100.00	X
REAR NUMBER PLATE	1	<i>Del</i>	\$50.00	<i>455n</i>
TOTAL			\$3,632.80	

LABOUR

PRICE

LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$1,800.00	<i>500l</i>
TO RESPRAY AFFECTED AREAS - REAR PORTION	\$1,400.00	<i>800l</i>
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$50.00	<i>20l</i>
TO REMOVE AND REFIT BOOTLID COMPONENT	\$250.00	<i>80l</i>
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$250.00	<i>50l</i>
TO REMOVE AND REFIT REAR EXHAUST PIPE	<i>nn</i> \$300.00	X
TO REMOVE AND REFIT REVERSE SENSOR	<i>nn</i> \$100.00	<i>60l</i>
SUNDARIES	\$80.00	X
RUST PROOFING	\$100.00	<i>30l</i>
TOTAL:	\$4,330.00	
TOTAL:	\$21,566.42	

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Nov 2018		02 Nov 2018 15:59 Edit Adj Rpt	S\$8,600.00 Edit Estimates	S\$8,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG DJONI , ID: S7276554J								
Main Claimant:	LIM LYE HUAT , ID: S1762122Z								
Vehicle Reg. No.:	SFE5757U	Date of Loss:	31/10/2018 10:00 - :59 [10 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05189C02	Policy/Cover Note No.:	DMPCSN1669891802 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKW629K	Policy No. (Claimant):	MP306641						
		Excess:	S\$0.00						
Repairer:	Lian Hong Seng Motor Works - Ang Mo Kio (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345, 569537 Ang Mo Kio - Tel: 64843683 96159830 96754083								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Claimant's Insurer:	HL Assurance Pte Ltd (HQ) - Tel: 69226030								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/11/2018]								
Driver/Custodian (Insured):	NG DJONI (46 / Male), NRIC: S7276554J								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFE5757U (SNM18D05189C02)

[SKW629K]































TP

LIM LYE HUAT

Oct 31 2018 10:00AM

[NG DJONI]

Lian Hong Seng Motor Works - Ang Mo Kio

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	31/10/18 16:57	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	31/10/18 16:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
2	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
3	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/12/18 09:33	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
15	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/12/18 09:33	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
17	05/12/18 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/12/18 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
19	05/12/18 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
20	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	05/12/18 09:34	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/11/18 15:58	PRS		Load PDF	
2	02/11/18 15:58	TP GIA		Load PDF	
3	02/11/18 15:59	OI GIA		Load PDF	
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	31/10/18 16:57	Sketch Plan [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	31/10/18 16:57	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	31/10/18 16:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	31/10/18 16:57	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019958/KSBE2

Date: 10/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1669891802

Claimant Vehicle
No : SFE5757UInsured Vehicle
No : SKW629K

Date of Loss: 31/10/2018

Nature of Claim: TP

Claim
No: SNM18D05189C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFE5757U

Make & Model: BMW 520D, 2.0 M SPORT (A)

Engine No: 77959973B47D20A

Reg. Date: 08/12/2017 (Man. Year: 2017)

Chassis No: WBAJC32000WB92964

Colour: Metallic Blue

Odometer: 20297 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 275/40 R18

Front Left Side: Goodyear 7 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 7 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,316.42	9,380.65	7,935.77	45.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,550.00	2,700.00	63.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,566.42	10,930.65	10,635.77	49.32
Approved Total (Overridden) (S\$)		8,600.00		
Nett Amount (S\$)	21,566.42	8,600.00	12,966.42	60.12

INSPECTION

Date of Assignment: 02/11/2018

Date Inspected: 05/11/2018 Inspected At:

Lian Hong Seng Motor Works - Ang Mo
Kio (HQ)
BLK 5035 ANG MO KIO IND.PARK 2 #01-
345
Singapore 569537

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2018)
Parts:	143	BMW 520D 2.0 M SPORT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFE5757U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,564.50 FL	*2,564.50 FL
2	1		*REAR EMBLEM	Necessary	76.50 FL	*76.50 FL
3	1		*REAR LOGO - 520D	Necessary	68.40 FL	*68.40 FL
4	1		*BOOTLID LOCK	Repair	378.50 FL	*- FL
5	1		*BOOTLID LOCK SWITCH BUTTON	Serviceable	298.40 FL	*- FL
6	1		*BOOTLID LAMP	N/S Cracked	849.60 FL	*424.80 FL
7	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
8	2		*REAR BUMPER RETAINER	Serviceable	266.20 FL	*- FL
9	1		*REAR BUMPER CENTRE BRACKET	Cracked	195.80 FL	*195.80 FL
10	2		*REAR BUMPER REFLECTOR	Serviceable	298.60 FL	*- FL
11	1		*REAR REINFORCEMENT	Bent	665.40 FL	*665.40 FL
12	1		*END PANEL	Repair	776.50 FL	*- FL
13	1		*SPARE TYRE PANEL - FIBRE	Serviceable	648.10 FL	*- FL
14	2		*SPARE TYRE SIDE PANEL (NPA)	Repair	0.00 FL	*- FL
15	1		*END PANEL TOP GARNISH	Serviceable	289.60 FL	*- FL
16	1		*REAR WEATHER STRIP	Serviceable	255.70 FL	*- FL
17	1		*TAILLAMP	N/S Cracked	1,684.60 FL	*842.30 FL
18	1		*REAR EXHAUST PIPE MUFFLER	Repair	2,351.10 FL	*- FL
19	2		*REAR EXHAUST PIPE FINISHER	Serviceable	448.60 FL	*- FL
20	2		*REAR EXHAUST PIPE MOUNTING	Serviceable	188.60 FL	*- FL
21	1		*REAR EXHAUST HEAT SHIELD	Repair	345.10 FL	*- FL
22	4		*REVERSE SENSOR	Shorted	1,024.80 FL	*1,024.80 FL
23	4		*REVERSE SENSOR HOLDER	Necessary	248.40 FL	*248.40 FL
24	2		*REAR BUMPER SENSOR-SMART OPENER	Serviceable	346.60 FL	*- FL
25	1		*REAR BUMPER - M SPORT	Bent	2,589.40 FS	*2,589.40 FS
26	1		*REAR BUMPER DIFFUSER	Dented / Distorted	893.40 FS	*893.40 FS
27	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
28	1		*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
29	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,032.40	9,688.70
- List Item Discount on L Items 5.00/5.00% (\$\$)	715.98	308.05
Total Parts (\$\$)	17,316.42	9,380.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR - REAR PORTION	New	1,800.00	500.00
2	TO RESPRAY AFFECTED AREAS - REAR PORTION	New	1,400.00	800.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	50.00	20.00
4	TO REMOVE AND REFIT BOOTLID COMPONENT	New	250.00	80.00
5	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	New	250.00	60.00
6	TO REMOVE AND REFIT REAR EXHAUST PIPE	New	300.00	0.00
7	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	60.00
8	RUST PROOFING	New	100.00	30.00
Gross Labour Cost (\$\$)			4,250.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >