

Barney Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: 2 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6842L Yr Regd: 20 Aug 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1600

Colour: Silver A/C: Ins / Std / NI / NA

Sp. Reading: 188904 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KNAH 414 MK 5 612257

Gen. Cond: Good / 6 / Poor / Burnt

Steering: Inord / 6 / Jammed / Leaked / Burnt or

Brake: Inord / 6 / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / 6 / Rim or

Tyre Size: F: 205 / 65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / CHITSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 3/10/18

D.O.A. 1/11/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/3 \$1,450

(Red: \$1,831.10 / 52%)

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

\$ + RS, \$1

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

31-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6842 L

1 pc	Rear bumper	\$ 696.00
1 pc	Rear bumper lower cover	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$ 58.00
1 pc	Rear bumper inner sponge	\$ 114.00
1 pc	Rear bumper reinforcement	\$ 607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00	\$ 106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$ 36.00
		\$ 1,859.00
Less 10%		\$ 185.90
		\$ 1,673.10

S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Reverse sensor	\$ 280.00 280
	Sundry	\$ 50.00 X 2
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X 2
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc	\$ 650.00 200
	To putty and spray painting on rear bumper, end panel	\$ 400.00 180
	To apply rustproofing on the repaired and replaced panels.	\$ 80.00 X 2

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify 3,481.10
the Repairer of the following:

- resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin 11/11/18
11/11/18
2 days
After Repair & LK

7/11/18
up \$1650/207

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

31-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6842 L

1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00 ✕	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✕	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✕	\$	36.00
		\$	1,859.00
Less 10%		\$	185.90
		\$	1,673.10

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Reverse sensor ✓	\$	280.00 200
	Sundry	\$	50.00 ✕
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ✕
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc	\$	650.00 200
	To putty and spray painting on rear bumper, end panel ✕	\$	400.00 180
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 ✕
		\$	3,481.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kalvin 11/10/18
11/11/18 133.6
2 days
Alvin Raza & Loh

LKK Auto Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- A third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	20 Aug 2015 / 07:24:48	Receipt No.:	AACCK001-AX239-150820-000007
Asset Type:	Vehicle	Transaction Amount:	\$72,145.00
Asset ID:	SHC6842L	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150820072448845571		
Vehicle No.:	SHC6842L		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	20 Aug 2015		
Original Registration Date:	20 Aug 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5603257		
Engine No.:	D4FDEH313389		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$21,263.00		
Minimum PARF Benefit:	\$13,061.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	20 Aug 2015 07:24:48		
COE No.:	2015082001003023H		
COE Expiry Date:	19 Aug 2023		
COE Bid Category:	-		
Actual QP/POP Paid Amount:	\$50,235.00		
Lifespan Expiry Date:	19 Aug 2023		

Print Received Message

This mail is associated with :

***SHC6842L (MCT18100984)
[SHB4282X]**

TP

PREMIER TAXIS PTE LTD

Oct 31 2018 1:00PM

[-]

Premier Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/07/2019 08:41 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2212.29) - SHC6842L - Claim Handler: Sherini Pillai

Approved:2212.29.

PREMIER TAXIS	HIRER / RELIEF / SUPER RELIEF
VEHICLE NO.	SHC 6842L
CONTACT NO.	9653 0961
NEW MAILING ADDRESS (if any)	/

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S1230979A**

Name: **ELANKOVAN S/O MARIMUTHU**

Birth Date: **04 Jan 1957**

Issue Date: **15 Jul 2003**

10006639678

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1230979A**



ELANKOVAN S/O MARIMUTHU

இலங்கோவன்

Race:

INDIAN

Date of Birth:

04-01-1957

Sex:

M

Country of Birth:

SINGAPORE



Land Transport Authority

VOCATIONAL LICENCE

License No: **S1230979A**

Name: **ELANKOVAN S/O MARIMUTHU**

Issue Date: **15/2/2011**

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

19 Apr 1982

OR10624

10006639678

License No: **S1230979A**

Biased Group: **O+** Date of issue: **05-03-1993**

Address: **APT BLK 287C JURONG EAST STREET 21 #04-330 SINGAPORE 603287**

NRIC No: **S1230979A** Date: **29-04-1998** No: **2593904**

NP 426A



This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
03	BUS VL	20/08/1999
02	TAXI VL	30/11/2001
04	BUS ATTENDANT	20/08/1999



Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	20 Aug 2015 / 07:24:48	Receipt No.:	AACCK001-AX239-150820-000007
Asset Type:	Vehicle	Transaction Amount:	\$72,145.00
Asset ID:	SHC6842L	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150820072448845571		

Vehicle No.:	SHC6842L
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	20 Aug 2015
Original Registration Date:	20 Aug 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MP5603257
Engine No.:	D4FDEH313389
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,263.00
Minimum PARF Benefit:	\$13,061.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	20 Aug 2015 07:24:48
COE No.:	2015082001003023H
COE Expiry Date:	19 Aug 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$50,236.00
Lifespan Expiry Date:	19 Aug 2023

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893 **Cover** : Third Party

1. Index mark and Registration Number of Vehicle : **5HC6842L**
Chassis Number : KNAGM414MF5603257

2. Name of Policyholder : PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance : 20 Oct 2017

4. Expiry Date of Insurance : 31 Jan 2019

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I) : N/A
EXCESS (SECTION II) : S\$3,500
INSURE WITH COE : N/A
HIRE PURCHASE COMPANY : N/A
SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

To: Joy

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6842L/GS

WITHOUT PREJUDICE

6th December 2018

(By Email Only)

Attn: The Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Dear Sir/Madam

ACCIDENT INVOLVING SHC6842L, SHB4282X & SGM994E ALONG CTE – CITY ON 31.10.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHC6842L, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SHB4282X at the material time of the accident with the driver of our client's vehicle, Mr Elankovan S/o Marimuthu

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SHB4282X, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 1765.50 (Incl. GST)
(2) Loss of Rental - 3Days @\$108.93per day	\$ 326.79
(3) Loss of Income – 3Days @\$100.00per day	\$ 300.00
	<u>\$ 2392.29</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHC6842L
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6842L/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,



Claims Department – Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd

AUTHORISATION TO ACT

I/We, PREMIER TAXIS PTE LTD ("the third party claimant") of 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443 (address), owner of SHC 6842L (vehicle no.) hereby authorize PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SHC 6842L that was damaged pursuant to the accident which occurred on 31/10/2018 (date) along CTE TOWARDS CITY (location) involving vehicle no/s SHB 4282X ("the accident").

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of "the workshop".

I/We further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 3 (day) of 7 (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18100984
Claimant Ref: SHC 6842L

This Settlement excludes any
bodily injuries arising out of the
above said accident and pertains
to property damage only

We/I, PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 2,210.00 GLOBAL SUM (repair cost), S\$ - (loss of use/rental), S\$ 0.00 (search fee), vehicle no. SHC 6842L that was damaged pursuant to the accident which occurred on 31.01.2018 (date) at CTE TOWARDS CITY (location) involving vehicle no. SHB 4282X (insured vehicle). This is pursuant to the inspection conducted on 01/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PREMIER TAXIS PTE LTD ("the third party claimant") of vehicle no. SHC 6842L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHC 6842L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,210.00 to PREMIER AUTOMOTIVE SERVICES PTE LTD

Dated this 03 day of July 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

SHAFWATI MD RABU

NRIC:

S83093246

Address:

Nationality:

SINGAPOREAN

Occupation:

CLAIMS

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R


Address:

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

Nationality:

Occupation:



TAX INVOICE

 DATE 3-Jul-2019
 PAGE 1 OF 1

 INDIA INTERNATIONAL INSURANCE PTE LTD
 64 Cecil Street #04/#05
 IOB Building
 Singapore 049711

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6842 L			\$ 1,650.00
TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 1,650.00
GST @ 7%				\$ 115.50
GRAND TOTAL				\$ 1,765.50



for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

Premier Automotive Services Pte Ltd

23 Changi South Avenue 2

#04-02

Singapore 486443

GST: 200707743D ROC: 200707743D

Phone: (65) 6214 8880

Fax: (65) 6214 4498

Tax Invoice



Date

Jul 04, 2019

Page

1

Invoice Number

IV1907010369

Sold To:

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street #04/#05
IOB Building
Singapore 049711
049711

Ship To:

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street #04/#05
IOB Building
Singapore 049711
049711

Shipment / DO No.	Order Date	Vehicle No.	Case ID	PO Number	Terms
SM1907013244		SHC6842L	TP/181031/SHC6842L		30D

S/N	Item Number	Description	Qty. Shp.	Unit Price	Total Discount	Total Amount
1	ICGST1	Cost of Repair (subject to GST)			0.00	1,650.00
2	ICGST2	Loss of Rental (subject to GST)			0.00	305.41
3	ICGIA	GIA Search Fee (subject to GST)			0.00	1.87
4	ICNGST	Misc Charges (not subject to GST)			0.00	115.71

Comments:

Accident involving SGM904E on 31/10/18

Authorised By:

Subtotal

2,072.99

Less discount

0.00

Total amount

2,072.99

GST 7%

137.01

Grand total

2,210.00



02 November 2018

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Elankovan S/O Marimuthu of NRIC Number S1230979A is a registered driver of SHC6842L. Elankovan S/O Marimuthu is paying daily rental rate of \$108.93 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

A handwritten signature in black ink, appearing to be "Kellie Poh", written over a circular stamp.

Kellie Poh
Administration Manager

Prepared By: Hasnah

PREMIER TAXIS PTE LTD
23 Changi South Avenue 2
#03-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 0330
www.premiertaxi.com
Co. Reg. No. 200304975H



REPLACEMENT VEH GIVEN YES / NO

VEH NO. _____


JOB NO. _____

CHECK IN / OUT VOUCHER

| | | | | | | |

DRIVER'S NAME <u>Eldonkovan</u>	
NRIC <u>S 1230979A</u>	HANDPHONE <u>96530961</u>
TAXI REGN NO. <u>S H C6842L</u>	MAKE / MODEL <u>KU2</u>
DATE IN <u>30/10/18</u> TIME IN <u>1400</u>	DATE OUT <u>02/11/18</u> TIME OUT <u>1500</u>
KILOMETRES IN _____ FUEL IN _____	KILOMETRES OUT _____ FUEL OUT _____
<input type="checkbox"/> E <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> F	<input type="checkbox"/> E <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> F

INDICATE AREA OF DAMAGE HERE:



TAXI METER DOWNLOADED

YES

NO

DATE / TIME TOWED IN TO WORKSHOP

D O M M Y Y H H M M

DATE / TIME CALL TO DRIVER FOR VEHICLE COLLECTION

D O M M Y Y H H M M

I ACKNOWLEDGE AND CONFIRM THAT I HAVE EXAMINED THE ABOVE SAID VEHICLE AND THAT THE SAME IS IN GOOD CONDITION AND TO MY SATISFACTION IN EVERY RESPECT TOGETHER WITH THE ACCESSORIES / ITEMS LIST ABOVE. THIS VOUCHER IS USED IN CONJUNCTION WITH THE TERM RENTAL AGREEMENT.

CHECK IN

Eldonkovan

DRIVER'S NAME

DRIVER'S SIGNATURE / DATE / TIME

CHECKED IN BY
(PREMIER'S AUTHORISED WORKSHOP)

CHECK OUT

Eldonkovan

DRIVER'S NAME

DRIVER'S SIGNATURE / DATE / TIME

CHECKED OUT BY
(PREMIER'S AUTHORISED WORKSHOP)

BODY MARKINGS

- | | |
|---------------------|-------------|
| 1 - Light Dent | 5 - Damaged |
| 2 - Serious Dent | 6 - Chip |
| 3 - Light Scratch | 7 - Crack |
| 4 - Serious Scratch | 8 - Peeling |

SERVICE / REPAIRS DONE	DRIVER'S REMARKS
<input type="checkbox"/> SERVICING <input type="checkbox"/> OTHERS: <input type="checkbox"/> T / BELT <input type="checkbox"/> AIRCON SYSTEM <input type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT: <input type="checkbox"/> TURBO <u>31/10/18</u> <u>Y H H H H H</u> <input type="checkbox"/> BRAKE SYSTEM <u>TPW</u> <input type="checkbox"/> CLUTCH SYSTEM <input type="checkbox"/> BULB <input type="checkbox"/> UNDER CARRIAGE <input type="checkbox"/> CPF <input type="checkbox"/> BATTERY	

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

































CLAIM SUBFOLDER TRACKING


Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2018 Edit Reg		01 Nov 2018 00:00 Edit Adj Rpt	S\$1,650.00 Edit Estimates	S\$1,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHC6842L	Date of Loss:	31/10/2018 13:00 - :59 [38 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18100984	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHB4282X	Policy No. (Claimant):	S095103893						
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 14/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (02/07/2019): Alert - Adj Mandate Approved (S\$2212.29) - SHC6842L - Claim Handler: Sherini Pillai III_SG (19/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SHC6842L - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC6842L (MCT18100984)
[SHB4282X]
TP
PREMIER TAXIS PTE LTD
Oct 31 2018 1:00PM
[COMFORT TRANSPORTATION PTE LTD]
Premier Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
2	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
3	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
6	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	02/11/18 17:38	General View							 Load JPG	<input checked="" type="checkbox"/>	
22	07/11/18 08:55	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
23	07/11/18 08:55	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
24	07/11/18 08:55	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
25	07/11/18 08:55	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
26	07/11/18 08:55	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
27	07/11/18 08:55	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
28	07/11/18 08:55	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	02/11/18 17:55	TP ESTIMATE - MARKED							 Load PDF		
2	02/11/18 17:55	TP GIA REPORT							 Load PDF		
3	01/07/19 17:25	LETTER OF DEMAND							 Load PDF		
4	30/07/19 10:51	WORKSHOP INVOICE							 Load PDF		
5	30/07/19 10:51	AUTHORISATION TO ACT FORM							 Load PDF		
6	30/07/19 10:51	DISCHARGE VOUCHER							 Load PDF		
7	30/07/19 10:51	RENTAL RECEIPT							Load PDF		
8	30/07/19 10:51	RENTAL MILEAGE							Load PDF		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
9	30/07/19 10:51	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/11/18 10:04	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18019959/K1HA3Q2

Date: 30/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SHC6842L

Insured Vehicle No : SHB4282X

Date of Loss: 31/10/2018

Nature of Claim:

TP

Claim No: MCT18100984

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6842L

Make & Model: KIA OPTIMA, 1.7 D (A)

Reg. Date: 20/08/2015 (Man. Year: 2015)

Colour: Silver

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: D4FDEH313389

Chassis No: KNAGM414MF5603257

Odometer: 188904 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Front Left Side: Maxxis 7 mm

Front Right Side: Maxxis 7 mm

Rear Tyre Size: 205/65 R16

Rear Left Side: Maxxis 7 mm

Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,051.10	1,708.70	342.40	16.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	410.00	1,020.00	71.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,481.10	2,118.70	1,362.40	39.14
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	3,481.10	1,650.00	1,831.10	52.60
+ GST 7.00/7.00% (S\$)	243.68	115.50	128.18	52.60
Nett Amount (S\$)	3,724.78	1,765.50	1,959.28	52.60
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$108.93/day) (S\$)		326.79		
Nett Liability (S\$)		2,212.29		
Global Sum Settlement (S\$)		2,210.00		

INSPECTION

Date of Assignment: 01/11/2018

Date Inspected: 01/11/2018 Inspected At:

Premier Automotive Services Pte Ltd (HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2018)
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6842L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
2	1		*REAR BUMPER LOWER COVER	Cut	206.00 FL	*206.00 FL
3	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Serviceable	58.00 FL	*- FL
4	1		*REAR BUMPER INNER SPONGE	Torn	114.00 FL	*114.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Cracked	607.00 FL	*607.00 FL
6	2		*REAR BUMPER N/S & O/S STAY	Serviceable	106.00 FL	*- FL
7	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Serviceable	36.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Serviceable	36.00 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
10	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
11	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	2,237.00 1,871.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	185.90 162.30
					Total Parts (\$\$)	2,051.10 1,708.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /REPLACE REVERSE SENSOT TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION ,SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE END PANEL ,ETC	New	650.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL	New	400.00	180.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (S\$)			1,430.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >