

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

30-Oct-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1350 S

1 pc	n/s head lamp @ \$1028.00	X	\$	1,028.00
1 pc	Front bumper		\$	531.00
1 pc	Front bumper emblem @ \$44.00		\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	n/s - o/s X	\$	32.00
1 pc	Front n/s wheel cover @ \$116.00	X repl	\$	116.00
1 pc	Front n/s fender @ \$384.00	X repl	\$	384.00
1 pc	Front n/s fender inner shield @ \$120.00	X	\$	120.00
			\$	2,255.00
		Less 10%	\$	225.50
			\$	2,029.50

### S/NETT

1 set	Front bumper clips		\$	48.00
1 pc	Front n/s fender sticker	X	\$	30.00
1 set	Front n/s fender inner shield clips		\$	28.00
	Sundry		\$	20
	To check/focus n/s head lamp		\$	50.00
	To check front n/s wheel alignment		\$	30.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	80.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	180.00 X
	To putty and spray painting on front bumper, front n/s fender		\$	400
	To apply rustproofing on the repaired and replaced panels.		\$	650.00
			\$	360
			\$	400.00
			\$	120.00 X
			\$	3,645.50

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

Kalin Uky  
1/18/18 1320 L.  
3 hrs  
4s  
After Repair photo