

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 8/11/2018

Reference: SLQ5364K
CHEVROLET
CRUZE NB 1.6D
Make: 6AT

TP III

Xiao Tang

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLQ5364K
CHASSIS NO.:KL1JA69E9GK350997
ENGINE NO.F16D4161690328

Name of insured :Kumar Amit Agarwal
Date of accident.: 29/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	RHR Tail lamp	\$ 606.00	+
2	1	LHR Tail lamp	\$ 606.00	+
3	1	RHR Fender Liner	\$ 115.00	+
4	1	LHR Fender Liner	\$ 115.00	+
5	1	Rear bumper	\$ 1,536.00	+
6	1	Rear bumper tow hook cover	\$ 30.00	+
7	1	LHR Bumper Chrome Moulding	\$ 150.00	✓
8	1	RHR Bumper Chrome Moulding	\$ 75.00	✓
9	1	Centre Bumper Chrome Moulding	\$ 75.00	✓
10	1	Centre Bumper Guide	\$ 75.00	+
11	1	RHRC Bumper Guide	\$ 65.00	+
12	1	LHRC Bumper Guide	\$ 65.00	+
13	1	RHR Bumper Guide	\$ 60.00	+
14	1	LHR Bumper Guide	\$ 60.00	+
15	1	Rear bumper absorber	\$ 189.00	+
16	1	Rear bumper reinforcement	\$ 736.00	+

300

270

Parts Total: \$ 4,558.00
Less 10%: \$ 455.80
Total : \$ 4,102.20

Labour

Labour Description

No. **Price (SGD)**

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 1,650.00	550.
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 1,350.00	450.
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 110.00	*
4	To remove and refix reverse sensor and conduct test	\$ 110.00	50
5	To conduct water leakage test after repairs of vehicle	\$ 110.00	*

1050

Labour Total : \$ 3,330.00

Others**Other Description****No. Qty****Price (SGD)****Front portion**

30

1	1	Rear number plate <i>Not ne</i>	\$ 45.00	*
2	10	Rear bumper clip <i>Not</i>	\$ 65.00	30
3	6	Rear Fender Liner Clip <i>Not ne</i>	\$ 39.00	*
4	1	Reverse sensor (4pcs) <i>Not ne</i>	\$ 320.00	*

Other Total: \$ 469.00

GRAND TOTAL: \$ 7,901.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Suhaimi Ong

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax: 6844 5185

Adrian King
P/P 08/11/18Total: 1350
(P/P)

02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: