

INS. CASE OWNER

CC 4,111 180 19968, 11/18/18

LXX
EDAC

Surveyor: NWA

ASSIGNMENT
DOI: 2/10/18

Date / Time: 1-11-18

Registered in Merimen: 2-11-18

Pre-assign / CCU / FTE: GBF 7612H



Insured Vehicle No.:
Name of Insured: Catholic Welfare Soc. Inc.
Insured Tel No.:
Excess Sec II :SS
Is driver the owner? (YES/NO) (NO) Nature of Accident:

Claim No.:
Policy No.:
Make / Model:
Place of Accident:

If NO, Driver Name / Age:
Driver Tel No.: 516 3666C (V/L-YES/NO)

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO
Insured Liability: % Final? Yes/No



INSRS:
WSP: Stuttgart
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
8/11/18	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final):	
08/11/18	Notification Itr (if non-pickup): Call OI: After call Itr to OI: Documentation Check List: Handler Typist	
01/04/19	Notification Itr (if non-pickup): After call Itr to OI: Authorisation To Act:	
22/05/19	Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice:	
15/8/19	LTA / GIA: Medical Bill: PIR: Migrate/Reject Instruction:	
28/8/19	LOD: Payment Breakdown Form: Post-Repair Photos: Others:	
PRELIMINARY ADVICE	Date/Time: Sent By:	Confirm with:
FINALIZATION	Date/Time: Confirm with:	Confirm by:
Repair Cost: P/P \$19,524.56 (8 days) Reduction: 43 %	Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT	Date/Time: 2/8/19 Confirm with: JAMES	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % 100 (Assesed / Assesed) BCLA S/N No.:	27	
Repair Cost: (w/SS) \$20,891.28		(Old rate-based TP)
Loss of Rental (LOR): \$ (days)		
Loss of Use (LOU): \$ 1,600.00/40 x 10 days		
Loss of Income (LOI): \$ (3 x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR+LOU <input type="checkbox"/> LOR+LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search \$		
Medical: \$		
Disbursement: \$ (e.g. Tow/ Independent)		
Legal Cost \$		
Total: \$22,491.28 Global Sum \$:		
FINAL PAYMENT	Date/Time: Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1: \$22,491.28 Name 1: STUTTGART AUTO PTB LEO		
Payee 2: (Strike if N.A.) \$ Name 2:		
Payee 3: (Strike if N.A.) \$ Name 3:		

COPIES SENT
28/8/19



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 10B BUILDING SINGAPORE 049711 ATTN : FAX :		NAME : Mr Zhao Xumao ADDRESS : 487A Dunman Road Singapore 439242 TEL : 91122186	WIP : 39104 EXCESS : DATE: 30-Oct-18
VEH NO :	SKE3666C	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1Z2Z92ZCLA04579	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	Cayenne Tiptronic	DATE REG.:	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	HEAT SHIELD, REAR EXHASUT P958-504-711-00-	X UN	\$ 416.20
2	8	SPEED NUT, HEAT SHIELD PN -907-088-02-	X UN	\$ 10.40
3	1	ORNAMENT, PORSCHE P958-559-687-00-0C1	NE	\$ 195.40
4	1	ORNAMENT, CAYENNE P958-559-675-00-0C1	NE	\$ 107.80
5	1	CRHOME FINISHER LOWER, TAILGATE P958-512-955-01-GV9	de	\$ 246.20
6	1	REAR REINFORCEMENT P958-505-309-01-	X UN	\$ 1,137.50
7	1	ADAPTER CENTER, REAR BUMPER P958-505-863-00-	? de	\$ 154.20
8	1	REAR BUMPER INNER SPOILER P958-505-521-00-9B9	? de	\$ 775.60
9	1	REAR BUMPER P958-505-411-11-G2X	de	\$ 1,005.70
10	4	EXPANDER NUT, REAR BUMPER PWHT-004-935- -	NE	\$ 4.80
11	1	SENSOR, PARKASSIST P150-919-275-C-G2L AN	? 256.70	\$ 1,027.60
12	4	SEAL, SENSOR P7PP-919-133- -	NE	\$ 17.20
13	6	BLIND RIVET, REAR BUMPER PN -908-550-01-	NE	\$ 9.00
14	4	SPEED NUT, REAR BUMPER PN -904-559-02-	NE	\$ 7.20
15	4	SPECIAL NUT, REAR BUMPER PN -105-168-01-	NE	\$ 4.40
16	4	OVAL HEAD SCREW, REAR BUMPER PN -106-847-01-	NE	\$ 3.20
17	1	TRIM LOWER, REAR BUMPER P958-505-834-01-9B9	X UN	\$ 333.20
18	1	TOWING COVER LHS P958-505-449-00-G2X	X UN	\$ 74.50
19	1	TOWING COVER RHS P958-505-450-00-G2X	de	\$ 74.50
20	1	TAILGATE P958-512-011-04-GRV	bt	\$ 3,029.60
21	8	BLIND RIVET, TAILGATE PN -016-206-1 -	NE	NEC \$ 41.60
22	2	SEALING RUBBER, TAILGATE P958-545-359-00-	NE	NEC \$ 4.80
23	1	CAVITY PRESERVATION P000-043-305-51-	NE	NEC \$ 80.30
24	8	BLIND RIVET, TAILGATE PN -906-481-02-	NE	NEC \$ 32.80
25	2	CLAMP, TAILGATE P958-731-633-00-	de	NEC \$ 12.40
26	1	VELCRO STRIP, TAILGATE P958-612-852-00-	NE	NEC \$ 8.10
27	2	SUPPORT, TAILGATE P958-612-890-00-	NE	NEC \$ 14.80
28	1	WEATHERSTRIP, TAILGATE P958-512-705-01-	X UN	\$ 300.60
29	1	REAR WINDSCREEN MOULDING P958-545-260-00-	NE	\$ 157.40
30	2	SEALING RUBBER, REAR WINDSCREEN P958-545-359-00-	NE	\$ 4.80

31	SET MIXING TUBE, REAR WINDSCREEN	1	P000-043-205-37-	net	\$ 224.60
32	ADHESIVE SET, REAR WINDSCREEN	1	P000-043-305-35-	net	\$ 346.90
33	EXHAUST SILENCER	1	P958-111-910-00-	X m	\$ 2,777.60
34	REAR MUFFLER TIP RHS	1	P958-111-252-00-	net	\$ 643.00
35	SUPPORT WITH RUBBER REAR M	1	P958-111-150-00-	net	\$ 75.10
36	HEXAGON HEAD BOLT, EXHAUST	2	PN -909-210-02-	net	\$ 3.60
37	CLAMP, MUFFLER TIP	2	P958-111-240-00-	net	\$ 80.20
38	CLAMP, EXHAUST SILENCER	2	P958-111-220-20-	X m	\$ 171.20
39	TAILLAMP RHS	1	P958-631-096-04-	X m	\$ 910.60
40	CLIP, TAILLAMP	1	P955-631-471-02-	X net	\$ 3.00
41	REAR REFLECTOR RHS	1	P958-631-106-00-	net	\$ 33.30
+ GUPP					
TOTAL PARTS					\$ 14,560.90
LESS 10%					\$ 1,456.09
TOTAL PARTS COST					\$ 13,104.81

Labour Description

1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	1560.	3900	\$ 8,580.00
2	TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.	1300 ? 1100	2400	\$ 4,050.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		NETT ✓	\$ 560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		NETT ✓	\$ 195.00
5	TO TRANSFER TAILGATE MECHANISM.		NETT ✓	\$ 780.00
6	TO TRANSFER REVERSE SENSORS.		380.	\$ 500.00
7	TO TRANSFER REVERSE CAMERA.		380.	\$ 500.00
8	TO REMOVE AND INSTALL REAR EXHAUST ASSY.		NETT ✓	\$ 2,340.00
9	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		NETT X m	\$ 1,560.00
10	TO CARRY-OUT BODY CAVITY PRESERVATION.		150.	\$ 250.00
11	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150.	\$ 250.00
12	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT ✓	\$ 600.00
13	TO SUPPLY SPECIAL COATING.	sales agreement	NETT	TBA

14	SUNDRIES. <i>Net</i>	50 NETT	\$ 100.00
		TOTAL LABOUR	\$ - \$ 20,265.00
		TOTAL PARTS	\$ - \$ 13,104.81
		TOTAL	\$ - \$ 33,369.81
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
 CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
 WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
 PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

34,116.81

 Authorised Signature

Taylor 97495749
'wp'
02/11/15 @ 4:5pm
Resurvey before paint
su@lkkauto.com
6 days.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : FAX :		NAME : Mr Zhao Xumao ADDRESS : 487A Dunman Road Singapore 439242 TEL : 91122186	WIP : 39104 EXCESS : DATE: 30-Oct-18
VEH NO :	SKE3666C	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZ292ZCLA04579	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	Cayenne Tiptronic	DATE REG.:	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	HEAT SHIELD, REAR EXHASUT 1	P958-504-711-00-	\$ - \$ 416.20
2	SPEED NUT, HEAT SHIELD 8	PN -907-088-02-	\$ - \$ 10.40
3	ORNAMENT, PORSCHE 1	P958-559-687-00-0C1	\$ 195.40 \$ 195.40
4	ORNAMENT, CAYENNE 1	P958-559-675-00-0C1	\$ 107.80 \$ 107.80
5	CRHOME FINISHER LOWER, TAILGATE 1	P958-512-955-01-GV9	\$ 246.20 \$ 246.20
6	REAR REINFORCEMENT 1	P958-505-309-01-	\$ - \$ 1,137.50
7	ADAPTER CENTER, REAR BUMPER 1	P958-505-863-00-	\$ 154.20 \$ 154.20
8	REAR BUMPER INNER SPOILER 1	P958-505-521-00-9B9	\$ 775.60 \$ 775.60
9	REAR BUMPER 1	P958-505-411-11-G2X	\$ 1,005.70 \$ 1,005.70
10	EXPANDER NUT, REAR BUMPER 4	PWHT-004-935- -	\$ 4.80 \$ 4.80
11	SENSOR, PARKASSIST 1	P150-919-275-C -G2L	\$ 256.90 \$ 1,027.60
12	SEAL, SENSOR 4	P7PP-919-133- -	\$ 17.20 \$ 17.20
13	BLIND RIVET, REAR BUMPER 6	PN -908-550-01-	\$ 9.00 \$ 9.00
14	SPEED NUT, REAR BUMPER 4	PN -904-559-02-	\$ 7.20 \$ 7.20
15	SPECIAL NUT, REAR BUMPER 4	PN -105-168-01-	\$ 4.40 \$ 4.40
16	OVAL HEAD SCREW, REAR BUMPER 4	PN -106-847-01-	\$ 3.20 \$ 3.20
17	TRIM LOWER, REAR BUMPER 1	P958-505-834-01-9B9	\$ - \$ 333.20
18	TOWING COVER LHS 1	P958-505-449-00-G2X	\$ - \$ 74.50
19	TOWING COVER RHS 1	P958-505-450-00-G2X	\$ 74.50 \$ 74.50
20	TAILGATE 1	P958-512-011-04-GRV	\$ 3,029.60 \$ 3,029.60
21	BLIND RIVET, TAILGATE 8	PN -016-206-1 -	\$ 41.60 \$ 41.60
22	SEALING RUBBER, TAILGATE 2	P958-545-359-00-	\$ 4.80 \$ 4.80
23	CAVITY PRESERVATION 1	P000-043-305-51-	\$ 80.30 \$ 80.30
24	BLIND RIVET, TAILGATE 8	PN -906-481-02-	\$ 32.80 \$ 32.80
25	CLAMP, TAILGATE 2	P958-731-633-00-	\$ 12.40 \$ 12.40
26	VELCRO STRIP, TAILGATE 1	P958-612-852-00-	\$ 8.10 \$ 8.10
27	SUPPORT, TAILGATE 2	P958-612-890-00-	\$ 14.80 \$ 14.80
28	WEATHERSTRIP, TAILGATE 1	P958-512-705-01-	\$ - \$ 300.60
29	REAR WINDSCREEN MOULDING 1	P958-545-260-00-	\$ 157.40 \$ 157.40
30	SEALING RUBBER, REAR WINDSCREEN 2	P958-545-359-00-	\$ 4.80 \$ 4.80

11		TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
12		TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
13		TO SUPPLY SPECIAL COATING.	\$ -	TBA
14		SUNDRIES.	\$ 50.00	\$ 100.00

TOTAL LABOUR	\$ 11,885.00	\$ 20,265.00
TOTAL PARTS	\$ 7,639.56	\$ 13,851.81
TOTAL	\$ 19,524.56	\$ 34,116.81
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 19,524.56	
GST 7%	\$ 1,366.72	\$ -
GRAND TOTAL	\$ 20,891.28	\$ -

NUMBER OF DAYS: 8 WORKING DAYS(EXCLUDE WAITING FOR LIABILITY,SURVEY,AUTHORIZATION,PARTS,SATURDAY,SUNDAY AND PH)



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : FAX :		NAME : Mr Zhao Xumao ADDRESS : 487A Dunman Road Singapore 439242 TEL : 91122186	WIP : 39104 EXCESS : DATE: 30-Oct-18
VEH NO :	SKE3666C	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZZ92ZCLA04579	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	Cayenne Tiptronic	DATE REG.:	POLICY NO. :

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	HEAT SHIELD, REAR EXHASUT	1	P958-504-711-00-	\$ -	\$ 416.20
2	SPEED NUT, HEAT SHIELD	8	PN -907-088-02-	\$ -	\$ 10.40
3	ORNAMENT, PORSCHE	1	P958-559-687-00-0C1	\$ 195.40	\$ 195.40
4	ORNAMENT, CAYENNE	1	P958-559-675-00-0C1	\$ 107.80	\$ 107.80
5	CRHOME FINISHER LOWER, TAILGATE	1	P958-512-955-01-GV9	\$ 246.20	\$ 246.20
6	REAR REINFORCEMENT	1	P958-505-309-01-	\$ -	\$ 1,137.50
7	ADAPTER CENTER, REAR BUMPER	1	P958-505-863-00-	\$ 154.20	\$ 154.20
8	REAR BUMPER INNER SPOILER	1	P958-505-521-00-989	\$ 775.60	\$ 775.60
9	REAR BUMPER	1	P958-505-411-11-G2X	\$ 1,005.70	\$ 1,005.70
10	EXPANDER NUT, REAR BUMPER	4	PWHT-004-935- -	\$ 4.80	\$ 4.80
11	SENSOR, PARKASSIST	1	P150-919-275-C -G2L	\$ 256.90	\$ 1,027.60
12	SEAL, SENSOR	4	P7PP-919-133- -	\$ 17.20	\$ 17.20
13	BLIND RIVET, REAR BUMPER	6	PN -908-550-01-	\$ 9.00	\$ 9.00
14	SPEED NUT, REAR BUMPER	4	PN -904-559-02-	\$ 7.20	\$ 7.20
15	SPECIAL NUT, REAR BUMPER	4	PN -105-168-01-	\$ 4.40	\$ 4.40
16	OVAL HEAD SCREW, REAR BUMPER	4	PN -106-847-01-	\$ 3.20	\$ 3.20
17	TRIM LOWER, REAR BUMPER	1	P958-505-834-01-989	\$ -	\$ 333.20
18	TOWING COVER LHS	1	P958-505-449-00-G2X	\$ -	\$ 74.50
19	TOWING COVER RHS	1	P958-505-450-00-G2X	\$ 74.50	\$ 74.50
20	TAILGATE	1	P958-512-011-04-GRV	\$ 3,029.60	\$ 3,029.60
21	BLIND RIVET, TAILGATE	8	PN -016-206-1 -	\$ 41.60	\$ 41.60
22	SEALING RUBBER, TAILGATE	2	P958-545-359-00-	\$ 4.80	\$ 4.80
23	CAVITY PRESERVATION	1	P000-043-305-51-	\$ 80.30	\$ 80.30
24	BLIND RIVET, TAILGATE	8	PN -906-481-02-	\$ 32.80	\$ 32.80
25	CLAMP, TAILGATE	2	P958-731-633-00-	\$ 12.40	\$ 12.40
26	VELCRO STRIP, TAILGATE	1	P958-612-852-00-	\$ 8.10	\$ 8.10
27	SUPPORT, TAILGATE	2	P958-612-890-00-	\$ 14.80	\$ 14.80
28	WEATHERSTRIP, TAILGATE	1	P958-512-705-01-	\$ -	\$ 300.60
29	REAR WINDSCREEN MOULDING	1	P958-545-260-00-	\$ 157.40	\$ 157.40
30	SEALING RUBBER, REAR WINDSCREEN	2	P958-545-359-00-	\$ 4.80	\$ 4.80

11		TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
12		TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
13		TO SUPPLY SPECIAL COATING.	\$ -	TBA
14		SUNDRIES.	\$ 50.00	\$ 100.00
			TOTAL LABOUR	\$ 11,885.00
			TOTAL PARTS	\$ 7,639.56
			TOTAL	\$ 19,524.56
			LESS EXCESS	\$ -
			TOTAL AFTER EXCESS	\$ 19,524.56
			GST 7%	\$ 1,366.72
			GRAND TOTAL	\$ 20,891.28

NUMBER OF DAYS: 8 WORKING DAYS(EXCLUDE WAITING FOR LIABILITY,SURVEY,AUTHORIZATION,PARTS,SATURDAY,SUNDAY AND PH)



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : FAX :	NAME : Mr Zhao Xumao ADDRESS : 487A Dunman Road Singapore 439242 TEL : 91122186	WIP : 39104 EXCESS : DATE: 30-Oct-18
---	---	--

VEH NO :	SKE3666C	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZ2922CLA04579	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	Cayenne Tiptronic	DATE REG.:		POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	HEAT SHIELD, REAR EXHASUT	1	P958-504-711-00- 7 \$ 416.20
2	SPEED NUT, HEAT SHIELD	8	PN -907-088-02- ? \$ 10.40
3	ORNAMENT, PORSCHE	1	P958-559-687-00-0C1 ne ✓ \$ 195.40
4	ORNAMENT, CAYENNE	1	P958-559-675-00-0C1 ne ✓ \$ 107.80
5	CRHOME FINISHER LOWER, TAILGATE	1	P958-512-955-01-GV9 de ✓ \$ 246.20
6	REAR REINFORCEMENT	1	P958-505-309-01- ? \$ 1,137.50
7	ADAPTER CENTER, REAR BUMPER	1	P958-505-863-00- ? \$ 154.20
8	REAR BUMPER INNER SPOILER	1	P958-505-521-00-9B9 ? \$ 775.60
9	REAR BUMPER	1	P958-505-411-11-G2X de ✓ \$ 1,005.70
10	EXPANDER NUT, REAR BUMPER	4	PWHT-004-935- - ne ✓ \$ 4.80
11	SENSOR, PARKASSIST	4	P150-919-275-C -G2L ? 266.90 \$ 1,027.60
12	SEAL, SENSOR	4	P7PP-919-133- - ne ✓ \$ 17.20
13	BLIND RIVET, REAR BUMPER	6	PN -908-550-01- ne ✓ \$ 9.00
14	SPEED NUT, REAR BUMPER	4	PN -904-559-02- ne ✓ \$ 7.20
15	SPECIAL NUT, REAR BUMPER	4	PN -105-168-01- ne ✓ \$ 4.40
16	OVAL HEAD SCREW, REAR BUMPER	4	PN -106-847-01- ne ✓ \$ 3.20
17	TRIM LOWER, REAR BUMPER	1	P958-505-834-01-9B9 ? \$ 333.20
18	TOWING COVER LHS	1	P958-505-449-00-G2X x \$ 74.50
19	TOWING COVER RHS	1	P958-505-450-00-G2X de ✓ \$ 74.50
20	TAILGATE	1	P958-512-011-04-GRV bt ✓ \$ 3,029.60
21	BLIND RIVET, TAILGATE	8	PN -016-206-1- ne ✓ NEC \$ 41.60
22	SEALING RUBBER, TAILGATE	2	P958-545-359-00- ne ✓ NEC \$ 4.80
23	CAVITY PRESERVATION	1	P000-043-305-51- ne ✓ NEC \$ 80.30
24	BLIND RIVET, TAILGATE	8	PN -906-481-02- ne ✓ NEC \$ 32.80
25	CLAMP, TAILGATE	2	P958-731-633-00- de ✓ NEC \$ 12.40
26	VELCRO STRIP, TAILGATE	1	P958-612-852-00- ne ✓ NEC \$ 8.10
27	SUPPORT, TAILGATE	2	P958-612-890-00- ne ✓ NEC \$ 14.80
28	WEATHERSTRIP, TAILGATE	1	P958-512-705-01- ? \$ 300.60
29	REAR WINDSCREEN MOULDING	1	P958-545-260-00- ne ✓ \$ 157.40
30	SEALING RUBBER, REAR WINDSCREEN	2	P958-545-359-00- ne ✓ \$ 4.80

31	SET MIXING TUBE, REAR WINDSCREEN	1	P000-043-205-37-	all ✓	\$ 224.60
32	ADHESIVE SET, REAR WINDSCREEN	1	P000-043-305-35-	all ✓	\$ 346.90
33	EXHAUST SILENCER	1	P958-111-910-00-	?	\$ 2,777.60
34	REAR MUFFLER TIP RHS	1	P958-111-252-00-	all ✓	\$ 643.00
35	SUPPORT WITH RUBBER REAR M	1	P958-111-150-00-	all ✓	\$ 75.10
36	HEXAGON HEAD BOLT, EXHAUST	2	PN -909-210-02-	all ✓	\$ 3.60
37	CLAMP, MUFFLER TIP	2	P958-111-240-00-	all ✓	\$ 80.20
38	CLAMP, EXHAUST SILENCER	2	P958-111-220-20-	X	\$ 171.20
39	TAILLAMP RHS	1	P958-631-096-04-	X	\$ 910.60
40	CLIP, TAILLAMP	1	P955-631-471-02-	X	\$ 3.00
41	REAR REFLECTOR RHS	1	P958-631-106-00-	all ✓ X	\$ 33.30
TOTAL PARTS					\$ 14,560.90
LESS 10%					\$ 1,456.09
TOTAL PARTS COST					\$ 13,104.81

Labour Description

1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	1560.	3900	\$ 8,580.00
2	TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.	1340 ? 1100	2400	\$ 4,050.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		NETT ✓	\$ 560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		NETT ✓	\$ 195.00
5	TO TRANSFER TAILGATE MECHANISM.		NETT ✓	\$ 780.00
6	TO TRANSFER REVERSE SENSORS.		380.	\$ 500.00
7	TO TRANSFER REVERSE CAMERA.		380.	\$ 500.00
8	TO REMOVE AND INSTALL REAR EXHAUST ASSY.		NETT ✓	\$ 2,340.00
9	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		NETT X	\$ 1,560.00
10	TO CARRY-OUT BODY CAVITY PRESERVATION.		150.	\$ 250.00
11	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150.	\$ 250.00
12	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT ✓	\$ 600.00
13	TO SUPPLY SPECIAL COATING.	sales agreement	NETT	TBA

14	SUNDRIES.	SU NETT	\$ 100.00
		TOTAL LABOUR	\$ - \$ 20,265.00
		TOTAL PARTS	\$ - \$ 13,104.81
		TOTAL	\$ - \$ 33,369.81
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

Taylor 97495744
 'wp'
 02/11/18 @ 4:15pm
 * Resurvey before paint
 suv@lkkauto.com
 6 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 1 November 2018 4:43 PM
To: eva.kok@eurokars.com.sg; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: janice.syn@porsche.com.sg; jobithomas@eurokars.com.sg;
samuel.ng@eurokars.com.sg; C Meenachi - III
Subject: RE: TP CLAIMS- ACCIDENT INVOLVING - SKE3666C & GBF7612H DOA 22/10/2018
Attachments: SKE3666C TP INDIA.PDF; GIA.PDF

5:07pm @ 1/11/18

VNI

Person @ Eva

Arrange on 02/11/18

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKE3666C and let us have your report urgently.

This claim will be handled by Ms Meena.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]

Sent: 01 November, 2018 2:45 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: janice.syn@porsche.com.sg; jobithomas@eurokars.com.sg; samuel.ng@eurokars.com.sg

Subject: RE: TP CLAIMS- ACCIDENT INVOLVING - SKE3666C & GBF7612H DOA 22/10/2018

Hi,

Please assist assign LKK.

Thank you

Regards,



Eva Kok

Insurance Claims Officer

27A Tanjong Penjuru

Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690

E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: 01 November 2018 11:58 AM

To: Eva Kok <eva.kok@eurokars.com.sg>

Cc: Janice Syn <janice.syn@porsche.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>; Samuel Ng <samuel.ng@eurokars.com.sg>

Subject: RE: TP CLAIMS- ACCIDENT INVOLVING - SKE3666C & GBF7612H DOA 22/10/2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- Autoprobe Consultants
- VP Appraisal
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]

Sent: 01 November, 2018 10:14 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: janice.syn@porsche.com.sg; jobithomas@eurokars.com.sg; samuel.ng@eurokars.com.sg

Subject: TP CLAIMS- ACCIDENT INVOLVING - SKE3666C & GBF7612H DOA 22/10/2018

YOUR REF: GBF7612H / OUR REF: SKE3666C THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle.

Kindly revert Officer In Charge for the case above.

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal

Thank you

Regards,



Eva Kok

Insurance Claims Officer

27A Tanjong Penjuru

Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690

E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SKE3666C (MC20182870)**
[GBF7612H]

TP

ZHAO XU MAO

Oct 22 2018 4:00PM

[CATHOLIC WELFARE SERVICES SINGAPORE]

Stuttgart Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/07/2019 17:48 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$22491.28) - SKE3666C - Claim Handler: C. Meenachi

Approved:22491.28.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 9 August 2019 2:04 PM
To: janice.syn@porsche.com.sg
Subject: Your Ref: SKE3666C **Our Ref: CC4/III18019968/T1pa3 [ACCIDENT INVOLVING GBF 7612H(III) & SKE 3666C ON 22/10/2018]

Your Ref: **SKE3666C**
Our Ref: CC4/III18019968/T1pa3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBF 7612H(III) & SKE 3666C ON 22/10/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$20,891.28
2. Loss of Use (10days x \$160.00)	\$ 1,600.00
TOTAL	\$22,491.28

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



PORSCHE

Salf

Date: 21 August 2019

Aftersales Centre

**c/o LKK AUTO CONSULTANTS PTE LTD
INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attn: Motor Claims Department**

27A Tanjong Penjur
Singapore 609042
Telephone: (65) 6331 0700

Claim No : **MC20182870**

Our Ref : **SKE3666C**

RE: Accident involving SKE3666C & GBF7612H on 22/10/2018

Enclosed is the duly signed **Express Settlement Discharge Voucher** for your perusal.

Please pay **Stuttgart Auto Pte Ltd** the sum of **S22,491.28** as soon as possible and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648.**

Yours faithfully,

Stephanie Loke
Manager – Service & Development
DID: 63310686
FAX: 63310690
e-mail: Stephanie.loke@eurokars.com.sg

LETTER OF AUTHORIZATION

To: Name: Stuttgart Auto Pte Ltd
From: Name: Zhao Xu Mao
Address: 487A Dunman Road
S(439247)

In the matter of an accident involving motor vehicles SKE 3666 C of BBF 7612H on
21/10/2018 along Bencoolen street

I/We Zhao Xu Mao the owner of vehicle registration no: SKE 3666 C
hereby authorize you to commence repairs to my above-mentioned vehicle.

I/We confirm that you are hereby authorized to handle the repair and /or to negotiate and settle any claims relating to the above accident which I/we may have against other third party /parties or insurers and /or to instruct lawyer on my /our behalf to facilitate the third party claim for me /us.

You are hereby authorized as my attorney to execute and /or sign any documents /discharge vouchers /discharge agreement regarding my /our claim for my convenience.

I confirm that in the event of an unsuccessful claim against the negligent party and /or my own insurer for the damages caused to my vehicle, I agree to pay for all repair cost and /or any incidental expenses incurred by you.

Dated the 04 day of 12 20 18



Owner (name /signature)

NRIC No. S857281DE



Witness (name /signature)

NRIC No. _____





PORSCHE

X

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
 Repairers my/our vehicle No: 9PE 3666C which has been
 repaired to my satisfaction and I/we admit that the payment for such repairs
 by **Stuttgart Auto Pte Ltd** is in full and final discharge of my claim under
 policy number: _____ in respect of damage
 caused to the said vehicle as a result of an accident that occurred on
20/10/2018 at Bencoolen Street

Janice Sym 

Witnessed by Repairers

17/12/2018

Date:

[Signature]

Signature by Insured

17/12/2018

Date:

Porsche Centre Singapore
 Stuttgart Auto Pte Ltd
 Brokers Group of Companies
 Company Reg. No. 198403740N

Corporate Head Office & Porsche AG
 Eurokars Centre
 17 Selegie Road, Singapore 229648
 Tel: (65) 6363 0911
 Fax: (65) 6363 3911
 Website: www.porsche.com.sg

City Centre
 29 Leong Kee Road, Singapore 159099
 Tel: (65) 6472 4433
 Fax: (65) 6474 3101



PORSCHE

INDIA INT'L INSURANCE PTE LTD

64 Cecil Street
#04-05 IOB Building
Singapore 049711

Attn : Motor Claims Department

DATE : 08/03/2019

Your Ref : **GBF7612H**

Car Regn No: **SKE3666C**

Accident involving SKE3666C & GBF7612H on 22/10/2018

Direct Settlement Claim

Dear Sirs

The repairs have been completed for **SKE3666C**. We submit the following documents for your perusal :

1) Invoice No: 13204923	\$ 20,891.28
2) Loss of Use (\$180.00 x 14 days)	\$ 2,520.00
3) PRI (\$180.00 x 2 days)	\$ 360.00
4) Letter of Authority	
5) Discharge voucher signed by client	
TOTAL	<u>\$ 23,771.28</u>

Please pay **Stuttgart Auto Pte Ltd** the sum of **\$23,771.28** as soon as possible and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648.**

Yours faithfully,

Stanley Ngu
Manager - Body & Paint Division
DID: 63602845 FAX: 63602899
e-mail: stanley@eurokars.com.sg

Eurokars Centre

12 Sungei Kadut Avenue
Singapore 729648
Telephone: (65) 6363 0911
Fax: (65) 6363 3911

Zhao Xu Mao (Owner's Name)
H&P Dunman Road (Address)
3 (H392H2)

India International Insurance P.L (Ins Co)
44 Cecil Street (Address)
#04-05 10B Building
9049711

Attn : Motor Claims Dept

Your ref : GBF 7612H
Our ref : SRE 366C

Date : 2/11/18

Dear Sirs,

RE : Accident involving vehicle nos. SRE 366C and GBF 7612H on 22/10/18.

I refer to the above accident.

My car has been repaired by Stuttgart Auto Pte Ltd. As they are submitting a 3rd Party claim against India International Insurance P.L on my behalf, please pay to **Stuttgart Auto Pte Ltd** for the whole claim due to them.

Yours faithfully,



(ZHAO XU MAO)

IC No: 88572810E

Cc. Stuttgart Auto Pte Ltd
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648

EXPRESS SETTLEMENT

DISCHARGE VOUCHER Ill-Direct Settlement (PODS)

Without Prejudice
 to Injury Claim

India Ref: MC20182870
 Claimant Ref: SKE 3666C

We/I, STUTTGART AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 20,891.28 (repair cost), S\$ 1,600.00 (loss of use/rental), S\$ — (search fee), vehicle no. SKE 3666C that was damaged pursuant to the accident which occurred on 22/10/2018 (date) at BENCOOLEN STREET (location) involving vehicle no. GBF 7612H (insured vehicle). This is pursuant to the inspection conducted on 02/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ZHAO XU MAO ("the third party claimant") of vehicle no. SKE 3666C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKE 3666C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 22,491.28 to STUTTGART AUTO PTE LTD

Dated this 21 day of 08 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Stuttgart Auto Pte Ltd
 Eurocars Aftersales Centre
 27A Tanjong Penjuru, Singapore 609042
 After Sales : +65 6331 0718
 +65 6331 0701

Nationality:

Occupation:

WITNESS:

Signature:

MTH

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

51 Ubi Avenue 1

#01-25 Paya Ubi Ind. Park S(408933)

Nationality:

Occupation:





PORSCHE

INSURANCE INVOICE

NO. 001 11/11/2008 001000

Customer details including name, address, and contact information.

Vehicle details including make, model, year, and engine information.

Table with 4 columns: Item No., Description, Unit, and Price. Lists various repair items such as 'REPLACE REAR BUMPER', 'REPAIR FRONT AND REAR AIR BAG', etc.

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handlings.

STUTTGART AUTO PTE LTD

Handwritten signature of an authorized representative.

CASH / NETS / AMEX / VISA / MASTER NO:

Customer Signature

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
Eurokars Group
Company Reg. No. 198403740N

Porsche Centre Singapore
29 Leng Kee Road, Singapore 159099
Tel: (65) 6472 4433
www.porsche.com.sg

Aftersales Centre
27A Tanjong Penjuru, Singapore 609042
Tel: (65) 6331 0700

Corporate Head Office
12 Sungai Kadut Avenue, Singapore 729648
Tel: (65) 6363 0911 Fax: (65) 6363 3911



PORSCHE

INSURANCE INVOICE

STUTTGART AUTO PTE LTD

DATE: 15/01/2011
POLICY NO: 101
INSURANCE: ...

Customer details: Name, Address, Contact info

Table with 5 columns: Item No, Description, Qty, Unit Price, Total Price

STUTTGART AUTO PTE LTD
12 SUNGAI KADUT AVENUE, SINGAPORE 729648

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handlings.

STUTTGART AUTO PTE LTD

Handwritten signature of authorized person

CASH / NETS / AMEX / VISA / MASTER NO:

Customer Signature

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
Eurocars Group
Company Reg. No. 198403740N

Porsche Centre Singapore
29 Leng Kee Road, Singapore 159099
Tel: (65) 6472 4433
www.porsche.com.sg

After-sales Centre
27A Tanjong Penjuru, Singapore 609042
Tel: (65) 6331 0700

Corporate Head Office
12 Sungai Kadut Avenue, Singapore 729648
Tel: (65) 6363 0911 Fax: (65) 6363 3911

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2018 Edit Reg		01 Nov 2018 00:00 Edit Adj Rpt	S\$19,524.56 Edit Estimates	S\$19,524.56 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CATHOLIC WELFARE SERVICES SINGAPORE, Co. Reg. No.: -								
Main Claimant:	ZHAO XU MAO, ID: S8572810E								
Vehicle Reg. No.:	SKE3666C	Date of Loss:	22/10/2018 16:00 - :59 [80 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MC20182870	Policy/Cover Note No.:	M495117 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF7612H	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Stuttgart Auto Pte Ltd () 27A Tanjong Penjuru, 609042 West Coast - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (29/07/2019): Alert - Adj Mandate Approved (S\$22491.28) - SKE3666C - Claim Handler: C. Meenach... III_SG (27/05/2019): Alert - Adj Mandate Approved (S\$0.00) - SKE3666C - Claim Handler: C. Meenachi III_SG (12/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SKE3666C - Claim Handler: C. Meenachi III_SG (08/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SKE3666C - Claim Handler: C. Meenachi 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE3666C (MC20182870)
[GBF7612H]

TP

ZHAO XU MAO

Oct 22 2018 4:00PM

[CATHOLIC WELFARE SERVICES SINGAPORE]

Stuttgart Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/04/19 16:36	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	01/04/19 16:36	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
31	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
32	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
34	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/04/19 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
39	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
40	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
41	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
42	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
43	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
44	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
45	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
46	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
47	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
48	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
49	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
50	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
51	01/04/19 16:37	General View		<input checked="" type="checkbox"/>
52	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
53	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
54	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
55	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
56	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
57	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
58	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
59	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
60	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
61	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
62	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
63	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
64	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
65	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
66	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
67	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
68	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
69	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
70	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
71	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
72	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
73	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
74	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
75	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
76	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
77	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
78	01/04/19 16:37	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/11/18 17:08	TP ESTIMATE		<input type="checkbox"/>
2	02/11/18 17:08	TP GIA REPORT		<input type="checkbox"/>
3	02/11/18 17:08	ACKNOWLEDGEMENT EMAIL TO III DD 01.11.2018		<input type="checkbox"/>
4	07/11/18 20:01	TP ESTIMATE - MARKED		<input type="checkbox"/>
5	21/05/19 11:06	WORKSHOP INVOICE		<input type="checkbox"/>
6	21/05/19 11:06	LOD		<input type="checkbox"/>
7	30/08/19 10:02	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
8	30/08/19 10:02	DISCHARGE VOUCHER		<input type="checkbox"/>

Photos/Images			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	05/11/18 09:34	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; padding: 5px;"> <div style="border-bottom: 1px solid black; height: 30px;"></div> <div style="text-align: right;"> ^ v </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18019968/T1PA3Q2

Date: 30/08/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M495117
Claimant Vehicle No: SKE3666C	Insured Vehicle No:	GBF7612H
Date of Loss: 22/10/2018	Nature of Claim:	TP
	Claim No:	MC20182870

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE3666C	Engine No:	C05717
Make & Model:	PORSCHE CAYENNE, 3.6 V6 E5 TIPTRONIC (A)	Chassis No:	WP1ZZZ92ZCLA04579
Reg. Date:	26/01/2012 (Man. Year: 2011)	Odometer:	109962 km
Colour:	Grey		
Engine Capacity:	3598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/50 R19	Rear Tyre Size:	265/50 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,951.81	7,689.56	6,262.25	44.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,165.00	11,835.00	8,330.00	41.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,116.81	19,524.56	14,592.25	42.77
+ GST 7.00/7.00% (S\$)	2,388.18	1,366.72	1,021.46	42.77
Nett Amount (S\$)	36,504.99	20,891.28	15,613.71	42.77
+ Loss of Use (10.0 x S\$160.00/day) (S\$)		1,600.00		
	Nett Liability (S\$)	22,491.28		

INSPECTION

Date of Assignment:	01/11/2018	Inspected At:	Stuttgart Auto Pte Ltd
Date Inspected:	02/11/2018		27A Tanjong Penjuru
			Singapore 609042
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2019)
Parts: M1-SUV	PORSCHE CAYENNE 3.6 V6 E5 TIPTRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE3666C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*HEAT SHIELD ,REAR EXHAUST	Not Necessary	416.20 FL	*- FL
2	8	*SPEED NUT ,HEAT SHIELD	Not Necessary	10.40 FL	*- FL
3	1	*ORNAMENT ,PORSCHE	Necessary	195.40 FL	*195.40 FL
4	1	*ORNAMENT ,CAYENNE	Necessary	107.80 FL	*107.80 FL
5	1	*CHROME FINISHER LOWER ,TAILGATE	Deformed	246.20 FL	*246.20 FL
6	1	*REAR REINFORCEMENT	Not Necessary	1,137.50 FL	*- FL
7	1	*ADAPTER CENTER ,REAR BUMPER	Deformed	154.20 FL	*154.20 FL
8	1	*REAR BUMPER INNER SPOILER	Deformed	775.60 FL	*775.60 FL
9	1	*REAR BUMPER	Deformed	1,005.70 FL	*1,005.70 FL
10	4	*EXPANDER NUT ,REAR BUMPER	Necessary	4.80 FL	*4.80 FL
11	1	*SENSOR ,PARKASSIST (4 PCS)	Not Working (1 PCS ONLY)	1,027.60 FL	*256.90 FL
12	4	*SEAL ,SENSOR	Necessary	17.20 FL	*17.20 FL
13	6	*BLIND RIVET ,REAR BUMPER	Necessary	9.00 FL	*9.00 FL
14	4	*SPPED NUT,REAR BUMPER	Necessary	7.20 FL	*7.20 FL
15	4	*SPECIAL NUT ,REAR BUMPER	Necessary	4.40 FL	*4.40 FL
16	4	*OVAL HEAD SCREW ,REAR BUMPER	Necessary	3.20 FL	*3.20 FL
17	1	*TRIM LOWER ,REAR BUMPER	Not Necessary	333.20 FL	*- FL
18	1	*TOWING COVER LHS	Not Necessary	74.50 FL	*- FL
19	1	*TOWING COVER RHS	Deformed	74.50 FL	*74.50 FL
20	1	*TAILGATE	Bent	3,029.60 FL	*3,029.60 FL
21	8	*BLIND RIVET ,TAILGATE	Necessary	41.60 FL	*41.60 FL
22	2	*SEALING RUBBER ,TAILGATE	Necessary	4.80 FL	*4.80 FL
23	1	*CAVITY PRESERVATION	Necessary	80.30 FL	*80.30 FL
24	8	*BLIND RIVET,TAILGATE	Necessary	32.80 FL	*32.80 FL
25	2	*CLAMP ,TAILGATE	Necessary	12.40 FL	*12.40 FL
26	1	*VELCRO ,STRIP ,TAILGATE	Necessary	8.10 FL	*8.10 FL
27	2	*SUPPORT ,TAILGATE	Necessary	14.80 FL	*14.80 FL
28	1	*WEATHERSTRIP ,TAILGATE	Not Necessary	300.60 FL	*- FL
29	1	*REAR WINDSCREEN MOULDING	Necessary	157.40 FL	*157.40 FL
30	2	*SEALING RUBBER ,REAR WINDSCREEN	Necessary	4.80 FL	*4.80 FL
31	1	*SET MIXING TUBE ,REAR WINDSCREEN	Necessary	224.60 FL	*224.60 FL
32	1	*ADHESIVE SET ,REAR WINDSCREEN	Necessary	346.90 FL	*346.90 FL
33	1	*EXHAUST SILENCER	Not Necessary	2,777.60 FL	*- FL
34	1	*REAR MUFFLER TIP RHS	Dented	643.00 FL	*643.00 FL
35	1	*SUPPORT WITH RUBBER REAR M	Necessary	75.10 FL	*75.10 FL
36	2	*HEXAGON HEAD BOLT ,EXHAUST	Necessary	3.60 FL	*3.60 FL
37	2	*CLAMP ,MUFFLER TIP	Necessary	80.20 FL	*80.20 FL
38	2	*CLAMP ,EXHAUST SILENCER	Not Necessary	171.20 FL	*- FL
39	1	*TAILLAMP RHS	Not Necessary	910.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*CLIP, TAILLAMP	Necessary	3.00 FL	*3.00 FL
41	1		*REAR REFLECTOR RHS	Cut	33.30 FL	*33.30 FL
42	1		*COVER ,LHS ,TAILPIPE	Deformed	79.20 FL	*79.20 FL
43	1		*COVER ,RHS ,TAILPIPE	Deformed	79.20 FL	*79.20 FL
44	2		*NUT	Necessary	2.20 FL	*2.20 FL
45	1		*TAILGATE FINISHER	Deformed	594.30 FL	*594.30 FL
46	1		*SPEAKER ,TAILGATE	Distorted	75.10 FL	*75.10 FL
47	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,490.90	8,538.40
- List Item Discount on L Items 10.00/10.00% (S\$)	1,539.09	848.84

Total Parts (S\$)	13,951.81	7,689.56
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,REAR REINFORCEMENT AND TAILGATE .TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	8,580.00	3,900.00
2	TO RESPRAY REAR BUMPER,REAR END PANEL AND TAILGATE	New	4,050.00	2,400.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	195.00	195.00
5	TO TRANSFER TAILGATE MECHANISM	New	780.00	780.00
6	TO TRANSFER REVERSE SENSORS	New	500.00	380.00
7	TO TRANSFER REVERSE CAMERA	New	500.00	380.00
8	TO REMOVE AND INSTALL REAR EXHAUST ASSY	New	2,340.00	2,340.00
9	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	1,560.00	0.00
10	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
11	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
12	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
13	TO SUPPLY SPECIAL COATING (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			20,165.00	11,835.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >