



STUTT GART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

INDIA INTERNATIONAL INSURANCE P/L		NAME : Mr Zhao Xumao	WIP : 39104
64 CECIL STREET		ADDRESS : 487A Dunman Road	EXCESS :
#04-#05 IOB BUILDING		Singapore 439242	DATE: 30-Oct-18
SINGAPORE 049711		TEL : 91122186	
ATTN. :			
FAX :			
VEH NO :	SKE3666C	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZZ92ZCLA04579	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	Cayenne Tiptronic	DATE REG.:	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	P958-504-711-00-		\$ 416.20
2	8	PN -907-088-02-		\$ 10.40
3	1	P958-559-687-00-0C1		\$ 195.40
4	1	P958-559-675-00-0C1		\$ 107.80
5	1	P958-512-955-01-GV9		\$ 246.20
6	1	P958-505-309-01-		\$ 1,137.50
7	1	P958-505-863-00-		\$ 154.20
8	1	P958-505-521-00-9B9		\$ 775.60
9	1	P958-505-411-11-G2X		\$ 1,005.70
10	4	PWHT-004-935- -		\$ 4.80
11	4	P1S0-919-275-C -G2L		\$ 1,027.60
12	4	P7PP-919-133- -		\$ 17.20
13	6	PN -908-550-01-		\$ 9.00
14	4	PN -904-559-02-		\$ 7.20
15	4	PN -105-168-01-		\$ 4.40
16	4	PN -106-847-01-		\$ 3.20
17	1	P958-505-834-01-9B9		\$ 333.20
18	1	P958-505-449-00-G2X		\$ 74.50
19	1	P958-505-450-00-G2X		\$ 74.50
20	1	P958-512-011-04-GRV		\$ 3,029.60
21	8	PN -016-206-1 -	NEC	\$ 41.60
22	2	P958-545-359-00-	NEC	\$ 4.80
23	1	P000-043-305-51-	NEC	\$ 80.30
24	8	PN -906-481-02-	NEC	\$ 32.80
25	2	P958-731-633-00-	NEC	\$ 12.40
26	1	P958-612-852-00-	NEC	\$ 8.10
27	2	P958-612-890-00-	NEC	\$ 14.80
28	1	P958-512-705-01-		\$ 300.60
29	1	P958-545-260-00-		\$ 157.40
30	2	P958-545-359-00-		\$ 4.80

31	SET MIXING TUBE, REAR WINDSCREEN	1	P000-043-205-37-		\$ 224.60
32	ADHESIVE SET, REAR WINDSCREEN	1	P000-043-305-35-		\$ 346.90
33	EXHAUST SILENCER	1	P958-111-910-00-		\$ 2,777.60
34	REAR MUFFLER TIP RHS	1	P958-111-252-00-		\$ 643.00
35	SUPPORT WITH RUBBER REAR M	1	P958-111-150-00-		\$ 75.10
36	HEXAGON HEAD BOLT, EXHAUST	2	PN -909-210-02-		\$ 3.60
37	CLAMP, MUFFLER TIP	2	P958-111-240-00-		\$ 80.20
38	CLAMP, EXHAUST SILENCER	2	P958-111-220-20-		\$ 171.20
39	TAILLAMP RHS	1	P958-631-096-04-		\$ 910.60
40	CLIP, TAILLAMP	1	P955-631-471-02-		\$ 3.00
41	REAR REFLECTOR RHS	1	P958-631-106-00-		\$ 33.30
			TOTAL PARTS		\$ 14,560.90
			LESS 10%		\$ 1,456.09
			TOTAL PARTS COST		\$ 13,104.81

Labour Description					
1		TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 8,580.00
2		TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.			\$ 4,050.00
3		TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			NETT \$ 560.00
4		TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			NETT \$ 195.00
5		TO TRANSFER TAILGATE MECHANISM.			NETT \$ 780.00
6		TO TRANSFER REVERSE SENSORS.			\$ 500.00
7		TO TRANSFER REVERSE CAMERA.			\$ 500.00
8		TO REMOVE AND INSTALL REAR EXHAUST ASSY.			NETT \$ 2,340.00
9		TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.			NETT \$ 1,560.00
10		TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
11		TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00
12		TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT \$ 600.00
13		TO SUPPLY SPECIAL COATING.			NETT TBA

14	SUNDRIES.	NETT	\$ 100.00
		TOTAL LABOUR	\$ - \$ 20,265.00
		TOTAL PARTS	\$ - \$ 13,104.81
		TOTAL	\$ - \$ 33,369.81
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature