

cc4, LPC 180 19969, T193m

LKK:
IDAC:

Survey:

MTH

DOI:

2.11.18

Date/Time:

2.11.18

Pre-assign / CCU / FTE

SKA 9112R

Registered in Merimen:

18/18/18/vpas 104089



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKE 3846A



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

8/11/18
CHT

SKE 3846 A - X;

SKA 9112R - NA/LPC18019818/24 : 000-30/10/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☐ Call ☐

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

(days)

Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

FNO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

Loss of Use (LOU):

SS

Loss of Income (LOI):

SS

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS

Global Sum SS:

4335.50

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payer 1:

SS

Name 1:

Moya Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$450.00

uh 4/5/19

Taufik

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY _____

To Inspect Vehicle No: _____ SEE 3846A

at Workshop m/s _____ Nova

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:	Consistent? : Yes or No
--------------------	-------------------------

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: **SKE 3846A** Yr Regn: **2012 / Feb**

Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **Hyundai Accent** C.C. **1591**

Colour: **Red** A/C: **Insured / Std / NI / NA**

Sp. Reading: **201356** T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: **ICM HDM 41CMC 444 746**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: **F: 205/55R16**
R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Hanako*

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	2/4/80/64

Survey held at: Mona Fari Yang
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

13/2/17 L/S \$ 3350 Cool \$ 1058.41 24th

Date/Time File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

1)
Date/Time, File Return to?

3

Add Fee: ☐ Site Insp (\$
☐ Interview (\$
☐ Tech Invs (\$
☐ Weekend (\$

Survey Fee

Transportation

$$1 \quad S + P \rightleftharpoons S_1$$

10 Photos

1. Cancers

TOTAL

Report Format :

Lump Sum / I.B.B.: (3.-



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

01/11/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SKE3846A

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK418223

Claim # :-

ACC. Date :- 30/10/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	BOOT LID	1 PC	1,188.00	1,188.00
2.	BOOT LID LOGO	1 PC	26.00	26.00
3.	BOOT LID EMBLEM - HYUNDAI	1 PC	29.00	29.00
4.	BOOT LID EMBLEM - ELANTRA	1 PC	48.00	48.00
5.	BOOT LID EMBLEM - ELITE	1 PC	48.00	48.00
6.	BOOT LID REFLECTOR RH & LH - CHECK	1 PC		
7.	BOOT LID LOCK STICKER	1 PC	19.00	19.00
8.	BOOT LID LOCK	1 PC	159.00	159.00
9.	BOOT LID WEATHERSTRIP	1 PC	80.00	80.00
10.	BOOT LID KEYLESS CONTROL - CHECK	1 PC		
11.	TAILLAMP ASSY LH - CHECK	1 PC		
12.	REAR BUMPER	1 PC	459.00	459.00
13.	REAR BUMPER REINFORCEMENT	1 PC	303.00	303.00
14.	REAR BUMPER REINFORCEMENT BRACKET RH & LH	2 PC	41.00	82.00
15.	REAR BUMPER RETAINER RH & LH	2 PC	28.00	56.00
16.	REAR BUMPER REFLECTOR LH	1 PC	33.00	33.00
17.	REAR BUMPER CLIPS	10 PC	3.50	35.00
18.	REAR END PANEL	1 PC	385.00	385.00
19.	REAR END PANEL TOP GARNISH	1 PC	55.00	55.00
20.	REAR BUMPER BRACKET - BOTTOM	3 PC	12.00	36.00
21.	REAR BUMPER BRACKET - TOP	2 PC	16.00	32.00

LIST TOTAL S\$

3,073.00

20% DISCOUNT S\$

-614.60

2,458.40

SPECIAL NET ITEMS :

1.	REVERSE SENSOR	1 PC	200.00	200.00
----	----------------	------	--------	--------

SPECIAL NET TOTAL S\$

200.00

LABOUR :

TO CUT/WELD REAR END PANEL, KNOCK AND
STRAIGHTEN REAR BODY MEMBER. REMOVE & REPLACE
ACCIDENT DAMAGED PARTS. REALIGN ALL
CONNECTION

600 700.00

SPRAY PAINT BOOT LID, REAR FENDER, REAR END
PANEL, SPARE WHEEL PANEL, REAR BUMPER

600 800.00

REMOVE & REPLACE LUGGAGE COMPARTMENT
INNER TRIM, COVERING, GARNISH

40 60.00

REMOVE & REPLACE REVERSE SENSOR AND CHECK
FUNCTION

30 50.00

TO APPLY SEAL ON WELDING JOINT

30 80.00

RUST PROOF AFFECTED AREAS

30 60.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

01/11/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 133123

Veh # :- SKE3846A

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK418223

Claim # :-

ACC. Date :- 30/10/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			1,750.00

E. & O.E

NON-TAX AMOUNT S	4728.40
AMOUNT S\$	4,408.40
GST @ 7 %	308.59
AMOUNT DUE S\$	4,716.99

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tarfin 97495749
WP
2/4/18 @ 1645
To check p/p or 4/s.
Resurvey before or after paint
05 days
sure@lkkauto.com



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1006,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY

LONPAC INSURANCE BHD
300 BEACH ROAD
17-04/07 THE CONCOURSE
SINGAPORE 199555

Page : 1
Veh No : SKE3846A
Model : HYUNDAI ELANTRA
Acc Date : 30-Oct-18
Incharge : BILLY

No	Description	Qty	U.Price	Amt \$
<u>SPECIAL NET ITEMS:</u>				
1	REAR NUMBER PLATE	1	\$ 40.00	\$ 40.00
	SPECIAL NETS TOTAL S\$			\$40.00
	0% DISCOUNT S\$			\$0.00
				<u>\$40.00</u>

NON-TAX AMOUNTS	\$40.00
GST @ 7%	\$2.80
AMOUNT DUE	<u>\$42.80</u>

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

01/11/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SKE3846A

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK418223

Claim # :-

ACC. Date :- 30/10/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID	1 PC	1,188.00	1,188.00 ✓
2.	BOOT LID LOGO	1 PC	26.00	26.00 ✓
3.	BOOT LID EMBLEM - HYUNDAI	1 PC	29.00	29.00 ✓
4.	BOOT LID EMBLEM - ELANTRA	1 PC	48.00	48.00 ✓
5.	BOOT LID EMBLEM - ELITE	1 PC	48.00	48.00 ✓
6.	BOOT LID REFLECTOR RH & LH - CHECK	1 PC		
7.	BOOT LID LOCK STICKER	1 PC	19.00	19.00 ✓
8.	BOOT LID LOCK	1 PC	159.00	159.00 ✓
9.	BOOT LID WEATHERSTRIP	1 PC	80.00	80.00 ✓
10.	BOOT LID KEYLESS CONTROL - CHECK	1 PC		
11.	TAILLAMP ASSY LH - CHECK - 250.00 ✓	1 PC		
12.	REAR BUMPER	1 PC	459.00	459.00 ✓
13.	REAR BUMPER REINFORCEMENT	1 PC	303.00	303.00 ✓
14.	REAR BUMPER REINFORCEMENT BRACKET RH & LH	2 PC	41.00	82.00 ✓
15.	REAR BUMPER RETAINER RH & LH	2 PC	28.00	56.00 ✓
16.	REAR BUMPER REFLECTOR LH	1 PC	33.00	33.00 ✓
17.	REAR BUMPER CLIPS	10 PC	3.50	35.00 ✓
18.	REAR END PANEL - photo.	1 PC	385.00	385.00 ✓
19.	REAR END PANEL TOP GARNISH	1 PC	55.00	55.00 ✓
20.	REAR BUMPER BRACKET - BOTTOM	3 PC	12.00	36.00 ✓
21.	REAR BUMPER BRACKET - TOP	2 PC	16.00	32.00 ✓
LIST TOTAL S\$			3572.00	3,073.00
20% DISCOUNT S\$			654.40	-614.60
			1) 2617.60	2,458.40
SPECIAL NET ITEMS :				
1.	REVERSE SENSOR	1 PC	200.00	200.00 ✓
SPECIAL NET TOTAL S\$			2) 240.00	200.00
LABOUR :				
TO CUT/WELD REAR END PANEL, KNOCK AND STRAIGHTEN REAR BODY MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				
			600	700.00 ✓
SPRAY PAINT BOOT LID, REAR FENDER, REAR END PANEL, SPARE WHEEL PANEL, REAR BUMPER				
			600	800.00 ✓
REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, COVERING, GARNISH				
			40	60.00 ✓
REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION				
			30	50.00 ✓
TO APPLY SEAL ON WELDING JOINT				
			30	80.00 ✓
RUST PROOF AFFECTED AREAS				
			30	60.00 ✓



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

01/11/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 133123

Veh # :- SKE3846A

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK418223

Claim # :-

ACC. Date :- 30/10/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LABOUR TOTAL S\$

1330.00 1,750.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

4,408.40

GST @ 7 %

308.59

AMOUNT DUE S\$

4,716.99

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

1) PARTS 2617.60

2) S/NRT 240.00

3) LABOUR 1330.00

4187.60

- 837.52 less 20%

3350.08

Lump Sum \$ 3350.00

Please advice.

Thank You

BUT UAW.

Tayfun 97493749

2/4/18 @ 1645

To check p/p or 4/s.

H Resing before or after print

05 days

Surp (khauf.com)

Hsiao Tong (LKKAUTO)

From: Billy <billy@movas.com.sg>
Sent: Friday, 30 November 2018 10:39 AM
To: Taufikh (LKKAUTO)
Cc: SUR; CS A Team
Subject: FW: Re:SKE3846A
Attachments: SKE3846A Hyundai Elantra 2012.pdf; SAM_4762.JPG; SAM_4763.JPG; SAM_4764.JPG; SAM_4765.JPG; SAM_4766.JPG; SAM_4767.JPG; SAM_4768.JPG; SAM_4769.JPG; SAM_4772.JPG; SAM_4773.JPG; SAM_4774.JPG; SAM_4775.JPG; SAM_4776.JPG; SAM_4777.JPG; SAM_4778.JPG; SAM_4826.JPG; 20181109_161422.jpg; 20181109_161428.jpg; 20181109_161435.jpg

Hi Sir,

Attach with Finalization Report, Please advice. Thank You.

Best Regard's
Billy Liaw

MOVA Automotive Pte Ltd
Tel: +65 62623377
Fax: +65 62643151

From: Billy [mailto:billy@movas.com.sg]
Sent: 17 November 2018 12:28
To: 'Taufikh (LKK Auto)'
Subject: Re:SKE3846A

Hi Sir,

Attach with Finalization Report, Please advice. Thank You.

Best Regard's
Billy Liaw

MOVA Automotive Pte Ltd
Tel: +65 62623377
Fax: +65 62643151



Connect with us on  

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 2 November 2018 9:34 AM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: FW: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG
Attachments: RPT.PDF; EST.pdf

9.48am @ 2/11/18
person @ Nitha
vehicle in
sup @ Taekleh

Our Ref : 18/18/18/VP05/021089

Dear Catherine,

Kindly proceed to survey and revert to them on liability.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Nitha [mailto:nitha@moval.com.sg]

Sent: Friday, 2 November, 2018 9:20 AM

To: MT_Claim_SG

Cc: 'Billy'

Subject: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG

Dear Sir/Madam,

Good day

REF : SKA9112R

Kindly assist revert officer in charge and liability and arrange survey for the above mention case.

Vehicle lying at our workshop Fan Yoong.

Thank you.

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 8 November 2018 11:58 AM
To: 'Nitha'
Cc: Admin A; assignments
Subject: RE: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG *LKK REF: CC4/LPC18019969/T1pa3

Without Prejudice

Dear Sirs/ Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 8 November 2018 11:41 AM
To: 'Nitha' <nitha@nova.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG *LKK REF: CC4/LPC18019969/T1pa3

Without Prejudice

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 8 November, 2018 9:20 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG
Attachments: 08112018091727.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 7 November, 2018 7:02 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Hsiao Tong (LKKAUTO); Admin A
Subject: RE: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/18/18/VP05/021089
LKK REF: CC4/LPC18019969/T1pa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SKE 3846A

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly let us have a copy of insured's accident report for our necessary action.

Cc: 'Billy'

Subject: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG

Dear Sir/Madam,
Good day

REF : SKA9112R

Kindly assist revert officer in charge and liability and arrange survey for the above mention case.
Vehicle lying at our workshop Fan Yoong.

Thank you.

Best Regards,

Nitha

Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Hi Nitha,

We are pending for our insured accident report from Lonpac.

Hi Mei Kwan,

Kindly assist to follow up on OI GIA. CC4/LPC18019969/T1pa3

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nitha <nitha@moval.com.sg>

Sent: Thursday, 8 November 2018 10:00 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG

Importance: High

Dear Hsiao Tong,

Please assist to revert liability for the above mention case.

Thank You,

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



From: Nitha [<mailto:nitha@moval.com.sg>]

Sent: Monday, 5 November 2018 2:22 PM

To: 'mt_claim@lonpac.com'

Cc: 'Billy'; 'AVRIL@MOVA.COM.SG'

Subject: RE: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG

Dear Sir/Mdm,

Please kindly revert the liability for direct settlement.

Best Regards,

Nitha

Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



From: Nitha [<mailto:nitha@mova.com.sg>]

Sent: Friday, 2 November 2018 9:20 AM

To: 'mt_claim@lonpac.com'

Cc: 'Billy'

Subject: TP CLAIMS - SKE3846A AGAINST SKA9112R DOA 30/10/2018 AT BUKIT MERAH TOWARDS BUKIT PANJANG

Dear Sir/Madam,
Good day

REF : SKA9112R

Kindly assist revert officer in charge and liability and arrange survey for the above mention case.
Vehicle lying at our workshop Fan Yoong.

Thank you.

Best Regards,

Nitha

Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



Hsiao Tong (LKKAuto)

From: Taufikh (LKKAuto)
Sent: Wednesday, 13 February 2019 12:56 PM
To: 'Billy'
Cc: CS A Team; Hsiao Tong (LKKAuto)
Subject: RE: Re:SKE3846A
Attachments: SKE3846A Hyundai Elantra 2012.pdf

Hi Billy,

COR I/s\$3350 , 5 days.

Regards
Taufikh
Lkk AUTO

From: Billy [mailto:billy@movva.com.sg]
Sent: Friday, 11 January 2019 10:38 AM
To: 'Taufikh (LKK Auto)'
Cc: cs-a@lkkauto.com; sur@lkkauto.com
Subject: FW: Re:SKE3846A

Hi Sir,

Please help to Finalize above mention case. Thank You.

Best Regard's
Billy Liaw

From: Billy [mailto:billy@movva.com.sg]
Sent: 30 November 2018 10:39
To: 'Taufikh (LKK Auto)'
Cc: 'sur@lkkauto.com'; 'cs-a@lkkauto.com'
Subject: FW: Re:SKE3846A

Hi Sir,

Attach with Finalization Report, Please advice. Thank You.

Best Regard's
Billy Liaw

MOVA Automotive Pte Ltd
Tel: +65 62623377
Fax: +65 62643151

From: Billy [mailto:billy@movva.com.sg]
Sent: 17 November 2018 12:28
To: 'Taufikh (LKK Auto)'
Subject: Re:SKE3846A

Hi Sir,

Attach with Finalization Report, Please advice. Thank You.

Best Regard's
Billy Liaw

MOVA Automotive Pte Ltd

Tel: +65 62623377

Fax: +65 62643151



Connect with us on  



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18019969/T1ga3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 08-05-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 9112R	Veh. Inspected	SKE 3846A	
Policy No.	Z18VP05017976	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/021089	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	02/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHDH41CMCU441746	Colour	RED	
Odometer	201356	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	6 mm	
L/H Front Tyre	205/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2018	Inspection Date	02/11/2018	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 3846A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	BENT	1,188.00	1,188.00
1	BOOT LID LOGO	NECESSARY	26.00	26.00
1	BOOT LID EMBLEM -HYUNDAI	NECESSARY	29.00	29.00
1	BOOT LID EMBLEM -ELANTRA	NECESSARY	48.00	48.00
1	BOOT LID EMBLEM -ELITE	NECESSARY	48.00	48.00
2	BOOT LID REFLECTOR RH & LH (NPA)	NOT NECESSARY	-	-
1	BOOT LID LOCK STICKER	TO REPAIR SEE LABOUR	19.00	-
1	BOOT LID LOCK	BENT	159.00	159.00
1	BOOT LID WEATHERSTRIP	CUT	80.00	80.00
1	BOOT LID KEYLESS CONTROL (NPA)	NOT NECESSARY	-	-
1	TAILLAMP ASSY LH	CUT	350.00	350.00
1	REAR BUMPER	DEFORMED	459.00	459.00
1	REAR BUMPER REINFORCEMENT	CRACKED	303.00	303.00
2	REAR BUMPER REINFORCEMENT BRACKET RH & LH @\$41.00	NECESSARY (1 PCS ONLY)	82.00	41.00
2	REAR BUMPER RETAINER RH & LH @\$28.00	NECESSARY	56.00	56.00
1	REAR BUMPER REFLECTOR LH	CUT	33.00	33.00
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	REAR END PANEL	BENT	385.00	385.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	55.00	-
3	REAR BUMPER BRACKET -BOTTOM @\$12.00	NOT NECESSARY	36.00	-
2	REAR BUMPER BRACKET -TOP @\$16.00	NECESSARY	32.00	32.00
	LESS 20% DISCOUNT		-684.60	-654.40
			2,738.40	2,617.60
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
1	REAR NUMBER PLATE (SN) (ADDITIONAL)	BENT	40.00	40.00
			240.00	240.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CUT /WELD REAR END PANEL ,KNOCK AND STRAIGHTEN REAR BODY MEMBER REMOVE & REPLACE ACCIDENT DAMAGED PARTS,REALIGN ALL CONNECTION.INCLUSIVE OF THE REPAIR OF BOOT LID LOCK STICKER .		700.00	600.00
	SPRAY PAINT BOOT LID ,REAR FENDER ,REAR END PANEL,SPARE WHEEL PANEL,REAR BUMPER.		800.00	600.00
	REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM ,COVERING ,GARNISH .		60.00	40.00
	REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION.		50.00	30.00
	TO APPLY SEAL ON WELDING JOINT.		80.00	30.00
	RUST PROOF AFFECTED AREAS.		60.00	30.00
			1,750.00	1,330.00
	GRAND TOTAL		4,728.40	4,187.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,350.00

Report Ref No. CC4/LPC18019969/T1ga3n2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.