

DATE

Taufik

REF:

Independent

CS/TP18020003/TLsbn2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 9195 H

Yr Regn:

2016 Jct.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Fluence

cc 1461

Colour:

Blue

A/C Insured / Std / NI / NA

Sp. Reading

129395

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1L2LF0E54530948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

2/11/18 0330pm

Survey held at

Vooranger

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

13/11/18

Confirmed LS \$3,350/- @ 5 days with Taufik
(\$11,927.80 Red - 78%)

independent report

RECEIVED 14 NOV 2018

[Signature]

14/11/2018

5X15-75

Date/Time File Pass to:

14/11/18

11

Taufik

Date/Time File Return to:

12

Report Format:

Lump Sum / I.B.B. (\$) - 3,350/- 45

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee

Transportation

1 \$ + RS \$

Photos

Others

TOTAL

170+75

50

50+50

45

80

520

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLG9195H
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	RENAULT
Vehicle Model:	FLUENCE 1.5 DCI 110 A/T
Chassis No.:	VF1LZLFOE54530948
Propellant:	Diesel
Engine No.:	K9KN837R000230
Engine Capacity:	1461 cc
Maximum Power Output:	81.0 kW (108 bhp)
Maximum Laden Weight:	1828 kg
Unladen Weight:	1314 kg
Year Of Manufacture:	2015
Original Registration Date:	18 Oct 2016
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$51,507.00
COE Expiry Date:	17 Oct 2026
Road Tax Expiry Date:	17 Oct 2019
PARF Eligibility Expiry Date:	17 Oct 2026
Inspection Due Date:	17 Oct 2019
Intended Transfer Date:	31 Oct 2018
CO2 Emission:	114.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Shirley Hiew (LKK Auto)

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Sent: Monday, 19 November 2018 3:05 PM
To: Shirley Hiew (LKK Auto)
Cc: Taufikh (LKKAuto); Asher Sng (LKKAuto); Admin-D (LKKAuto); Janice Lee (LKKAuto); Hsiao Tong (LKKAuto); Veron Chen (LKKAuto); Vmg admin; Glorioso Eric Paul Patambang; Tejano Exequiel Dawal; Minoko Chan; Pila Ng; Desmond Kor; Edmond Lim; Lina Rosli; Yira Rahman; Luis Tan; Paul Tan
Subject: Re: SLG9195H DOA: 23/10/2017 TO FINALISE (AXA TP)

Dear Shirley,

We confirmed COR @ \$3,350 bef gst (lump sum) 5 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz
Vermogen Ace Pte Ltd
Operation Address:
6 Benoi Sector Singapore 629904
Tel: 6358 3031
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Wcega Plaza Singapore 658064

On Mon, Nov 19, 2018 at 2:51 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Paulo Baldoz,

Please re-confirm final fig of \$ 3,350.00 (lump sum) @ 5 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [mailto:paulo.b@vermogen-group.com]

Sent: Monday, 12 November 2018 10:46 AM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>; Desmond Kor <desmond@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Yira Rahman <yira@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>

Subject: Re: SLG9195H DOA: 23/10/2017 TO FINALISE (AXA TP)

Hi Taufikh,

Attached check item photos.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

On Mon, Nov 12, 2018 at 10:40 AM Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com> wrote:

Dear Taufikh,

Please check and confirm finalize COR @ \$4,250 bef gst (lump sum) 5 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2018 12:55
Date Of Accident	23/10/2018 17:10
Exact Location Of Accident	TPE TOWARDS SLE (BEFORE LOYANG AVE EXIT 2)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG9195H
Insured/Policyholder	
Name Of Registered Owner	ZI EN INTERIOR
Co Reg No	53238529B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98522578
Vehicle Particulars	
Manufacturer	RENAULT
Model	FLUENCE 1.5 DCI 110 A/T
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094744416-01 PREMIUM
Cover Note Number	
Driver	
Name of Driver	SEAH KIAN HOCK
NRIC No	S1773836D
Date Of Birth	24/03/1966
Occupation	OUTDOOR
Date Of Driving Pass	03/06/2008
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98522578
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 178 WOODLANDS STREET 13 #11-287
Postcode	730178
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SOLE PROPRIETOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : KOH YANG KING GENDER: : FEMALE
Passenger 2	NAME: : DOVAN SEAH KAI JUN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XB6957E
Vehicle Make/Model/Colour	MITSUBISHI FUSO FV519J
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SEAH KIAN HOCK

Approximate Age

Injuries Sustain BODY PAIN

Injured person in which vehicle? SLG9195H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Reporting Centre Person's Signature
Name: _____
NRIC/ID No: _____
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN

A = SLG 9795 A
 B = XB 6957 E
 TP# 400000 SL#
 (Before 1/3/00, Area 2)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Singapore 415933

Tel: 67416697 Fax: 67492305

NRIC/Fin No.:

Email: vackb@singnet.com.sg



SLG9195H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : NTUC
CLAIM TYPE : TP
Date of Accident : 23/10/2018

Vehicle Reg. No. : SLG9195H
Vehicle Reg. Date: 18-Oct-2016
Make / Model : RENAULT FLUENCE 1.5 DC
Engine No. : K9KN837R000230
Chassis No. : VF1LZLF0E54530948

COST OF CLAIMS

Parts Cost / List Items :	\$	11,642.00
Plus/Less <u>10%</u>	\$	1,164.20
Total Cost / List :	\$	10,477.80
Special Nett Items :	\$	350.00
Total Parts Amount :	\$	10,827.80
Total Labour Amount :	\$	4,450.00
Gross Total :	\$	15,277.80
GST % : <u>7%</u>	\$	1,069.45
Nett Amount :	\$	16,347.25

Surveyor Name and Company :

Tan Jiah 97495749
Date of survey : 02/11/18 @ 330 PM
Part by Part / Lump Sum : 5 days
Resurvey Before Paint / After Paint After
Authorize/Not Authorize/Without Prejudice Without
Email : sur@lkk.com
Fax No : _____
HP No : _____

This claim is handled by : PAULO BALDOZ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9195H**
 Vehicle Reg. Date: **18/10/2016**
 Make / Model : **RENAULT FLUENCE 1.5 DCI 110 A/T**
 Engine No. : **K9KN837R000230**
 Chassis No. : **VF1LZLFOE54530948**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT DOOR RH	X nn	\$ 1,600.00		
2	1	REAR DOOR RH	bt ✓	\$ 1,600.00	1471.30	
3	1	REAR DOOR STRIKER RH	Ry	\$ 225.00		
4	1	REAR DOOR HINGE TOP RH	Ry	\$ 235.00		
5	1	REAR DOOR HINGE BOTTOM RH	Ry	\$ 235.00		
6	1	REAR DOOR CHECKER RH	X nn	\$ 195.00		
7	1	REAR DOOR WEATHERSTRIP RH	nn ✓	\$ 400.00		
8	1	REAR DOOR STOPPER RH	X nn	\$ 97.00		
9	1	REAR DOOR RUBBER TOP RH	X nn	\$ 90.00		
10	1	REAR DOOR RUBBER LOWER RH	X nn	\$ 135.00		
11	1	REAR DOOR RUBBER FRT RH	X nn	\$ 110.00		
12	1	REAR DOOR POWER WINDOW MOTOR RH	7 bt ✓	\$ 705.00	350	
13	1	REAR DOOR POWER WINDOW MECHANISM RH	7 bt ✓	\$ 600.00	300	
14	1	REAR DOOR TRIM RH	X nn	\$ 650.00		
15	1set	REAR DOOR TRIM CLIPS	X nn	\$ 60.00		
16	1	REAR DOOR SPEAKER RH	X nn	\$ 160.00		
17	1	REAR DOOR OUTER HANDLE RH	cut ✓	\$ 240.00	67-68	
18	1	REAR DOOR INNER HANDLE RH	X nn	\$ 150.00		
19	1	REAR DOOR MOULDING CHROME RH	X nn	\$ 120.00		
20	1	REAR DOOR CLADDING RH	X nn	\$ 300.00		
21	1	REAR FENDER RH	Ry	\$ 1,850.00		
22	1	REAR FENDER INNER SHIELD RH	X nn	\$ 300.00		
23	1set	REAR FENDER INNER SHIELD CLIPS	X nn	\$ 60.00		
24	1	REAR SHOCK ABSORBER RH	X nn	\$ 260.00		
25	1	REAR WHEEL HUB RH	X nn	\$ 565.00	\$	
26	1	REAR RIM RH	cut ✓	\$ 600.00	300	
27	1	REAR RIM WHEEL CAP	X nn	\$ 100.00		
28	1	REAR TYRE RH	X nn		\$ 350.00	
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SLG9195H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : NTUC
CLAIM TYPE : TP
Date of Accident : 23/10/2018

Vehicle Reg. No. : SLG9195H
Vehicle Reg. Date: 18-Oct-2016
Make / Model : RENAULT FLUENCE 1.5 DCI
Engine No. : K9KN837R000230
Chassis No. : VF1LZLFOE54530948

COST OF CLAIMS

Parts Cost / List Items :	\$	11,642.00
Plus/Less <u>10%</u>	\$	1,164.20
Total Cost / List :	\$	10,477.80
Special Nett Items :	\$	350.00
Total Parts Amount :	\$	10,827.80
Total Labour Amount :	\$	4,450.00
Gross Total :	\$	15,277.80
GST % : <u>7%</u>	\$	1,069.45
Nett Amount :	\$	16,347.25

Surveyor Name and Company :

Tan Jun 97495749
Date of survey : 02/11/18 @ 330pm
Part by Part / Lump Sum : 5 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@khanh.com
Fax No :
HP No :

This claim is handled by : PAULO BALDOZ

P = 4145
- 10%
3730.50
L = 1605
5335.50
- 20%
4268.40
L/S = 4250

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLG9195H
 Vehicle Reg. Date: 18/10/2016
 Make / Model : RENAULT FLUENCE 1.5 DCI 110 A/T
 Engine No. : K9KN837R000230
 Chassis No. : VF1LZLF0E54530948

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT DOOR RH	X	\$ 1,600.00		
2	1	REAR DOOR RH	bt ✓	\$ 1,600.00		
3	1	REAR DOOR STRIKER RH	Ry	\$ 225.00		
4	1	REAR DOOR HINGE TOP RH	Ry	\$ 235.00		
5	1	REAR DOOR HINGE BOTTOM RH	Ry	\$ 235.00		
6	1	REAR DOOR CHECKER RH	X	\$ 195.00		
7	1	REAR DOOR WEATHERSTRIP RH	not ✓	\$ 400.00		
8	1	REAR DOOR STOPPER RH	X	\$ 97.00		
9	1	REAR DOOR RUBBER TOP RH	X	\$ 90.00		
10	1	REAR DOOR RUBBER LOWER RH	X	\$ 135.00		
11	1	REAR DOOR RUBBER FRT RH	X	\$ 110.00		
12	1	REAR DOOR POWER WINDOW MOTOR RH * ✓	?	\$ 705.00		
13	1	REAR DOOR POWER WINDOW MECHANISM RH * ✓	?	\$ 600.00		
14	1	REAR DOOR TRIM RH	X	\$ 650.00		
15	1set	REAR DOOR TRIM CLIPS	X	\$ 60.00		
16	1	REAR DOOR SPEAKER RH	X	\$ 160.00		
17	1	REAR DOOR OUTER HANDLE RH	cut ✓	\$ 240.00		
18	1	REAR DOOR INNER HANDLE RH	X	\$ 150.00		
19	1	REAR DOOR MOULDING CHROME RH	X	\$ 120.00		
20	1	REAR DOOR CLADDING RH	X	\$ 300.00		
21	1	REAR FENDER RH	Ry	\$ 1,850.00		
22	1	REAR FENDER INNER SHIELD RH	X	\$ 300.00		
23	1set	REAR FENDER INNER SHIELD CLIPS	X	\$ 60.00		
24	1	REAR SHOCK ABSORBER RH	X	\$ 260.00		
25	1	REAR WHEEL HUB RH	X	\$ 565.00		
26	1	REAR RIM RH	cut ✓	\$ 600.00		
27	1	REAR RIM WHEEL CAP	X	\$ 100.00		
28	1	REAR TYRE RH	X		\$ 350.00	
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

P= 4145

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]
$$L = 1605$$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
VERMOGEN ACE PTE LTD		Ref : CS/TP18020003/T1sbn2		
6 BENOI SECTORSINGAPORE 629904		Date : 21-11-2018		
ON BEHALF OF ZI EN INTERIOR		Code : TP500		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SLG 9195H	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		02/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT FLUENCE	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1LZLF0E54530948	Colour	BLUE	
Odometer	129395	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2018	Inspection Date	02/11/2018	
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9195H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH	NOT NECESSARY	1,600.00	-
1	REAR DOOR RH	BENT	1,600.00	1,471.30
1	REAR DOOR STRIKER RH	TO REPAIR SEE LABOUR	225.00	-
1	REAR DOOR HINGE TOP RH	TO REPAIR SEE LABOUR	235.00	-
1	REAR DOOR HINGE BOTTOM RH	TO REPAIR SEE LABOUR	235.00	-
1	REAR DOOR CHECKER RH	NOT NECESSARY	195.00	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	400.00	400.00
1	REAR DOOR STOPPER RH	NOT NECESSARY	97.00	-
1	REAR DOOR RUBBER TOP RH	NOT NECESSARY	90.00	-
1	REAR DOOR RUBBER LOWER RH	NOT NECESSARY	135.00	-
1	REAR DOOR RUBBER FRT RH	NOT NECESSARY	110.00	-
1	REAR DOOR POWER WINDOW MOTOR RH	BENT	705.00	350.00
1	REAR DOOR POWER WINDOW MECHANISM RH	BENT	600.00	300.00
1	REAR DOOR TRIM RH	NOT NECESSARY	650.00	-
1	SET REAR DOOR TRIM CLIPS	NOT NECESSARY	60.00	-
1	REAR DOOR SPEAKER RH	NOT NECESSARY	160.00	-
1	REAR DOOR OUTER HANDLE RH	CUT	240.00	67.68
1	REAR DOOR INNER HANDLE RH	NOT NECESSARY	150.00	-
1	REAR DOOR MOULDING CHROME RH	NOT NECESSARY	120.00	-
1	REAR DOOR CLADDING RH	NOT NECESSARY	300.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,850.00	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	300.00	-
1	SET REAR FENDER INNER SHIELD CLIPS	NOT NECESSARY	60.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	260.00	-
1	REAR WHEEL HUB RH	NOT NECESSARY	565.00	-
1	REAR RIM RH	CUT	600.00	300.00
1	REAR RIM WHEEL CAP	NOT NECESSARY	100.00	-
	LESS 10% DISCOUNT		-1,164.20	-288.90
			10,477.80	2,600.08
<u>SPECIAL NETT ITEMS</u>				
1	REAR TYRE RH (SN)	NOT NECESSARY	350.00	-

Report Ref No. CS/TP18020003/T1sbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			350.00	-
	LABOUR			
	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA.FRT DOOR RH,REAR DOOR RH,ROCKER PANEL RH,REAR FENDER RH.INCLUSIVE OF THE REPAIR OF REAR DOOR STRIKER RH,REAR DOOR HINGE TOP RH,REAR DOOR HINGE BOTTOM RH AND REAR FENDER RH.		1,500.00	625.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		150.00	30.00
	TO REMOVE AND REFIT INNER TRIM,INNER SEAT,TRIM BOARD,TO ASSIST REPAIR.	NOT NECESSARY	200.00	-
	TO RUSTPROOF ACCIDENT REPAIR AREA.		150.00	30.00
	TO REMOVE AND TRANSFER DOOR COMPONENTS FRONT RH.	NOT NECESSARY	200.00	-
	TO REMOVE AND TRANSFER DOOR COMPONENTS REAR RH.		200.00	60.00
	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA.FRT DOOR RH,REAR DOOR RH,ROCKER PANEL RH,REAR FENDER RH.		1,500.00	750.00
	TO REMOVE AND REPLACE REAR TYRE & BALANCE.		100.00	30.00
	TO PERFORM COMPUTER WHEEL ALIGNMENT.		150.00	80.00
	TO REMOVE AND REPLACE REAR SUSPENSION.	NOT NECESSARY	300.00	-
			4,450.00	1,605.00
	GRAND TOTAL		15,277.80	4,205.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,350.00

Report Ref No. CS/TP18020003/T1sbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.