

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

William Goh
68418434 Catherine LKE Auto

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004676	Page	1
	3 ANSON ROAD #16-00	Date	: 31. Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 31. Oct 2018 3:58:36 PM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: NG DJONI	Survey Date	: HP : +65 8100 6306		
Ins Policy No.	: DMPCSN1669891802	Authorisation Date	: Email : arychua@honda.com.sg		
Date of Accident	: 31/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 71526						
	POLICY/CLAIMS NO: DMPCSN1669891802						
	OWNER: NG DJONI						
	ACC DATE: 31/10/2018@10.30AM						
	SURVEYED BY: Marcus Chua@lkkauto.com 10/14 pm						
	AUTHORIZED ON:						
	REF NO:						
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60
60400-T6A-310ZZ	BULKHEAD COMPFR.	Self/Sec 1	451.70	✓ 25	338.77	23.71	362.48
60433-T6A-300ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE	1	33.60	? 25	25.20	1.76	26.96
60483-T6A-300ZZ	SUPPORT,L.FR.BULKHEAD UPP SIDE	1	35.30	? 25	26.47	1.85	28.32
60210-T6A-300ZZ	FENDER COMPR.FR.	Self/Sec 1	537.80	✓ 25	403.35	28.23	431.58
60260-T6A-300ZZ	FENDER COMPL.FR.	Self/Sec 1	537.80	✓ 25	403.35	28.23	431.58
74150-T6A-000	FENDER ASSYL.FR.INNER	11 1	118.30	X 25	88.72	6.21	94.93
60100-T6A-000ZZ	HOOD COMP	Sec 1	658.20	✓ 25	493.65	34.56	528.21
60120-T6A-000ZZ	HINGE COMPR.HOOD	Self 1	46.50	✓ 25	34.87	2.44	37.31
60170-T6A-000ZZ	HINGE COMPL.HOOD	Self 1	46.50	✓ 25	34.87	2.44	37.31
74120-T6A-003	LOCK ASSYHOOD	Self 1	104.10	✓ 25	78.07	5.46	83.53
74141-T6A-010	INSULATORHOOD	Self 1	92.50	✓ 25	69.37	4.86	74.23
80111-T6A-003	CONDENSER COMP	1	668.50	? 25	501.37	35.10	536.47
80341-T6A-003	PIPE COMPRECEIVER	1	173.20	? 25	129.90	9.09	138.99
19010-5X6-J02	RADIATOR COMP	1	1320.90	? 25	990.67	69.35	1060.02
38611-5A4-H02	FAN COMPCOOLING	1	53.10	? 25	39.82	2.79	42.61
38615-5X6-J01	SHROUD COMP	1	82.10	? 25	61.57	4.31	65.88
38616-5X6-J01	MOTORCOOLING FAN	1	316.30	? 25	237.22	16.61	253.83
38619-5X6-J01	HEAT PROTECTORFAN MOTOR	1	8.40	? 25	6.30	0.44	6.74
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	eng 1	2237.20	✓ 25	1677.90	117.45	1795.35
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED	eng 1	2237.20	✓ 25	1677.90	117.45	1795.35



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004676	Page	2
	3 ANSON ROAD #16-00	Date	: 31. Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 31. Oct 2018 3:58:36 PM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	:		
Owner's Name	: NG DJONI	Survey Date	:		
Ins Policy No.	: DMPCSN1669891802	Authorisation Date	:		
Date of Accident	: 31/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71104-T6A-921	GARNISHR.FR.BUMPER	1	45.20	25	33.90	2.37	36.27
71109-T6A-921	GARNISHL.FR.BUMPER	1	45.20	25	33.90	2.37	36.27
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J	1	897.00	25	672.75	47.09	719.84
72415-T6A-003	MOLDING ASSYR.FR.CORNER	1	86.00	25	64.50	4.52	69.02
71121-T6A-003	BASEFR.GRILLE	1	165.60	25	124.20	8.69	132.89
71122-T6A-003	MOLDINGFR.GRILLE	1	258.10	25	193.57	13.55	207.12
75700-TA0-A00	EMBLEMFR.	1	25.90	25	19.42	1.36	20.78
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
36560-T6A-J01	CAMERA ASSY,MVC FR.	1	509.80	25	382.35	26.76	409.11
36561-T6A-N01	COVERMVC FR.CAMERA	1	8.10	25	6.07	0.42	6.49
04711-T6A-900ZZ	FACE,FR.BUMPER	1	686.20	25	514.65	36.03	550.68
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	65.80	25	49.35	3.45	52.80
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER	1	286.10	25	214.57	15.02	229.59
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71151-T6A-911	BASEMID GRILLE	1	182.80	25	137.10	9.60	146.70
71152-T6A-921	UPPER MOLDINGMID GRILLE	1	150.60	25	112.95	7.91	120.86
71153-T6A-921	MID MOLDINGMID GRILLE	1	144.20	25	108.15	7.57	115.72
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71159-T6A-921	LOWER MOLDINGL.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
91505-TM8-003	CLIP,BUMPER	10	2.00	25	15.00	1.05	16.05
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
Sum Item					10228.56	715.98	10,944.54

BOSUN	SUNDRIES	1	40.00	20	40.00	2.80	42.80
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	120	180.00	12.60	192.60

Printed on 31/10/2018 5:56:29 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMRC1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. : DMPCSN1669891802

Date of Accident : 31/10/2018

Document No. : SQT18004676 **Page** 3

Date : 31. Oct 2018

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 31. Oct 2018 3:58:36 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	11 X	250.00	17.50	267.50
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	280.00	250	280.00	19.60	299.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	350.00	280	350.00	24.50	374.50
BOMISC1	REMOVE,INSTALL & CALIBRATE FRONT CAR VIEW CAMERA(N)	1	350.00	300	350.00	24.50	374.50
BKBH12B	CUT OFF & RENEW BULKHEAD FR R HOUSING COMP.	1	2800.00	1960	2800.00	196.00	2996.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00	2400	2800.00	196.00	2996.00
Sum Labor					7250.00	507.50	7,757.50

Survey By Margus LheDate & Time 5/11/18Excess 1000Status Not AuthorizedSignature Whe phs before party.7dy.**Total Amount** 17,658.56 1,236.08 18,894.64**Total (Inclusive of GST)** 18,894.64

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To spray damaged part(s) during resurvey
 - Part prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 31/10/2018 5:56:29 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)