

ASS. REC. BY:

REF: CS/CTU8020011/R14602

Special Instruction:

SURVEYOR

Rasul

ASSIGNMENT (Office)

McMinn

From (Person):

Elaine Cheong

of

C11

Date/Time: 02/11/2018 4:43pm

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 7606U

Insured:

SJT 9363U

at Workshop in/s

Mova

Tel:

6772 3897.

of

81k 1008 Buldt March Lane 3 # 01-04

Policy No:

DMPCSN3048661801

Claim No:

SNM180 05174602

Sum Insured:

Excess:

Make of Veh:

D.O.A.

J5102018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

05-11-2018 11:17am

Person Contacted:

Avril

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKF 7606U - X

SJT 9363U - NBA / CTU18019798/Y

DA: J510-18

Rasul finalised final fig @ 1752.80, 3 days.

Cred to 806.60, 32%.)

no heap sum

Form

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKF 76064**
at Workshop n/s: **MORA Automotive**
of **Black work, 8t MTRAH L3 # 01-04**
Insured: **CTI**

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: **SKF 76064** Yr Regn: **2012 Jun**

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: **MINICOOPER 1.6 AT** c.c. **1598**

Colour: **RED** A/C: Insured / Std / NI / NA

Sp. Reading: **027359** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **WMW SU32000T3/4772**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: **205/50R16**
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **FALKEN**

Front Rear

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **25/10/18** D.O.I. **27/11/18**

Survey held at **MORA (b.m.)**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 06 DEC 2018

6/12/2018

Date/Time. File Pass to?

☐

: Preli. Report

1) **06/12 12:00**

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

) \$ + RS. \$

) Phone

) Other

)

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

MER-TP

1752.80

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2018		02 Nov 2018 16:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MOREWOOD RICHARD GEOFFREY, ID: -								
Main Claimant:	BOWYER NICOLA JANE, ID: S7088033D								
Vehicle Reg. No.:	SKF7606U	Date of Loss:	25/10/2018 14:00 - :59						
Claim Type:	TP / SNM18D05174C02	Policy/Cover Note No.:	DMPCSN3048661801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJT9363U	Policy No. (Claimant):	5099433981						
		Excess:	S\$0.00						
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/11/2018]								
Driver/Custodian (Insured):	MOREWOOD TAMARA FAITH (45 / Female), NRIC: F5552634Q, Tel: +6592456495								
Adj Asg. Remarks:	EST \$2738.56, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/10/2018 16:25
Date Of Accident	25/10/2018 14:45
Exact Location Of Accident	GRANGE ROAD SLIP ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKF7606U
Insured/Policyholder	
Name Of Registered Owner	BOWYER NICOLA JANE
NRIC No	S7088033D
Email Address	NICKY.BOWYER@ME.COM
Mobile Phone No	(LOCAL) +65-91846959
Alternative Phone No	OTHERS-91846959
Vehicle Particulars	
Manufacturer	MINI
Model	COOPER-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099433981
Cover Note Number	DRIVO CLASSIC
Driver	
Name of Driver	BOWYER NICOLA JANE
NRIC No	S7088033D
Date Of Birth	04/10/1970
Occupation	INDOOR
Date Of Driving Pass	09/11/2010
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91846959
Fax Number	
Contact Number	OTHERS-91846959
Email Address	NICKY.BOWYER@ME.COM

Address	235 ARCADIA ROAD #08-08
Postcode	289843
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOPPED MY VEHICLE AT THE SLIP ROAD WHEN VEHICLE B HIT INTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT9363U
Vehicle Make/Model/Colour	SILVER
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	MOREWOOD TAMARA FAITH
NRIC/Passport Number	F5552634Q
Contact Number	92456495
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No. MI

D.O.A

251018

Vehicle No.

Make/Model

SKF 70614
Honda Super

Report Date: 10/26/2018 Start Time: 4:24 PM

Reporting Type

End Time:

TP

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers; lawyers/law firms; the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.



10/26/2018 16:24

Policyholder's Signature
Date & Time:

Driver's Signature (If driver is not the policyholder)
Date & Time:


10/26/2018 16:24



Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: 5992753

Sketch Plan Pg. 2

SKETCH PLAN



GRANGE ROAD SLIP ROAD

Vehicle A: SKF7606L	Vehicle B: SJJ9363M		
---------------------	---------------------	--	--

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I STOPPED MY VEHICLE AT THE SLIP ROAD WHEN VEHICLE B HIT INTO THE REAR PORTION OF MY VEHICLE

DECLARATION

I/We declare the foregoing particulars are true in every respect

10/26/2018 16:24

Policyholder's Signature
Date & Time



Driver's Signature (If driver is not the policyholder)
Date & Time

10/26/2018 16:24



Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

31/10/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SKF7606U

Veh Model :- MINI COOPER

Estimate# :- CK418219

Claim # :- TP/CK 133081

ACC. Date :- 25/10/18

Terms :- C.O.D Days

Remarks :- MFG 29 JUN 2012 (2011)

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID LOGO <i>ne</i>	1	PC 60.00	60.00
2.	BOOT LID EMBLEM - COOPER <i>ne</i>	1	PC 55.00	55.00
3.	REAR BUMPER <i>cut</i>	1	PC 628.00	628.00
4.	REAR BUMPER LOWER (ROUGH BLACK) ? <i>/ sch / de</i>	1	PC 195.00	195.00
5.	REAR BUMPER FOG LAMP ? <i>Xan</i>	1	PC 125.00	125.00
6.	REAR BUMPER FOGLAMP CHROME FRAME ? <i>Xan</i>	1	PC 48.00	48.00
7.	REVERSE SENSOR O-RING <i>ne</i>	4	PC 6.00	24.00
8.	REAR BUMPER RIVET <i>ne</i>	16	PC 5.00	80.00
9.	REAR BUMPER CLIPS <i>ne</i>	10	PC 5.00	50.00
10.	REAR BUMPER SIDE RETAINER LH <i>X</i>	1	PC 18.00	18.00
11.	REAR BUMPER SIDE RETAINER RH <i>X</i>	1	PC 18.00	18.00
12.	REAR BUMPER CENTRE BRACKET <i>X</i>	1	PC 27.00	27.00
13.	REAR BUMPER SPONGE <i>X</i>	1	PC 38.00	38.00
14.	REAR BUMPER REINFORCEMENT - CHECK <i>X</i>	1	PC	
15.	REVERSE SENSOR LH INNER - CHECK <i>X</i>	1	PC	
16.	REVERSE SENSOR LH OUTER - CHECK <i>X</i>	1	PC	
17.	REVERSE SENSOR RH INNER - CHECK <i>X</i>	1	PC	
18.	REVERSE SENSOR RH OUTER - CHECK <i>X</i>	1	PC	
19.	BOOT LID - REPAIR	1	PC	
20.	REAR FENDER LH -REPAIR	1	PC	
LIST TOTAL S\$				1,366.00
10% DISCOUNT S\$				-136.60
				1,229.40

LABOUR :

TO INSPECT REAR LIGHTING MECHANISM

30 ~~50.00~~

TO REMOVE & INSTALL REVERSE SENSOR &
DIAGNOSE FUNCTION

40 ~~80.00~~

TO KNOCK & STRAIGHTEN ON BOOTLID REAR FENDER
LH. TO REPLACE DAMAGED ITEMS, REALIGN
CONNECTION

300 ~~500.00~~

TO SPRAY PAINT ON REPAIRED AREAS

400 ~~700.00~~

LABOUR TOTAL S\$

1,330.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

31/10/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 133081

Veh # :- SKF7606U

Veh Model :- MINI COOPER

Estimate# :- CK418219

Claim # :-

ACC. Date :- 25/10/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,559.40

GST @ 7 % 179.16

AMOUNT DUE S\$ 2,738.56

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
3 days
4/5
27/11/18 @ 1530
Resuy after repair

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

31/10/2018

CHINA TAIHING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SKF7606U

Veh Model :- MINI COOPER

Estimate# :- CK418219

Claim # :- TP/CK 133081

ACC. Date :- 25/10/18

Terms :- C.O.D Days

Remarks :- MFR 29 JUN 2012 (2011)

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	✓ BOOT LID LOGO <i>na</i>	1	PC	60.00	60.00
2.	✓ BOOT LID EMBLEM - COOPER <i>na</i>	1	PC	55.00	55.00
3.	✓ REAR BUMPER <i>cut</i>	1	PC	628.00	628.00
4.	✓ REAR BUMPER LOWER (ROUGH BLACK) <i>?/- Scratched & Baffirmed</i>	1	PC	195.00	195.00
5.	✓ REAR BUMPER FOG LAMP <i>?/- X na</i>	1	PC	125.00	125.00
6.	✓ REAR BUMPER FOG LAMP CHROME FRAME <i>X na</i>	1	PC	48.00	48.00
7.	✓ REVERSE SENSOR O-RING <i>na</i>	4	PC	6.00	24.00
8.	✓ REAR BUMPER RIVET <i>na</i>	16	PC	5.00	80.00
9.	✓ REAR BUMPER CLIPS <i>na</i>	10	PC	5.00	50.00
10.	✓ REAR BUMPER SIDE RETAINER LH <i>X</i>	1	PC	18.00	18.00
11.	✓ REAR BUMPER SIDE RETAINER RH <i>X</i>	1	PC	18.00	18.00
12.	✓ REAR BUMPER CENTRE BRACKET <i>na</i>	1	PC	27.00	27.00
13.	✓ REAR BUMPER SPONGE <i>na</i>	1	PC	38.00	38.00
14.	✓ REAR BUMPER REINFORCEMENT - CHECK <i>X</i>	1	PC		
15.	✓ REVERSE SENSOR LH INNER - CHECK <i>na</i>	1	PC		
16.	✓ REVERSE SENSOR LH OUTER - CHECK	1	PC		
17.	✓ REVERSE SENSOR RH INNER - CHECK	1	PC		
18.	✓ REVERSE SENSOR RH OUTER - CHECK	1	PC		
19.	✓ BOOT LID - REPAIR	1	PC		
20.	✓ REAR FENDER LH - REPAIR	1	PC		

LIST TOTAL S\$

10% DISCOUNT S\$

1092.00 1,366.00
- 10% -136.60

982.80 1,229.40

LABOUR :

TO INSPECT REAR LIGHTING MECHANISM

30 50.00

TO REMOVE & INSTALL REVERSE SENSOR &
DIAGNOSE FUNCTION

40 80.00

TO KNOCK & STRAIGHTEN ON BOOTLID REAR FENDER
LH. TO REPLACE DAMAGED ITEMS, REALIGN
CONNECTION

300 500.00

TO SPRAY PAINT ON REPAIRED AREAS

400 700.00

LABOUR TOTAL S\$

770.00 1,330.00

Estimate

31/10/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 133081

Veh # :- SKF7606U

Veh Model :- MINI COOPER

Estimate# :- CK418219

Claim # :-

ACC. Date :- 25/10/18

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,559.40

GST @ 7 % 179.16

AMOUNT DUE S\$ 2,738.56

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Part = \$ 982-80
lab = \$ 770-00
\$1752-80

Resue
Hp 90010068

3 days

4/5 → PBP

25/11/18 @ 1530

Resue after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18020011/R1QBN2

Date: 12/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3048661801
Claimant Vehicle No :	SKF7606U	Insured Vehicle No :	SJT9363U
Date of Loss:	25/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05174C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF7606U	Engine No:	B138J109N16B16A
Make & Model:	MINI COOPER, 1.6 (A)	Chassis No:	WMWSU32000T314772
Reg. Date:	29/06/2012 (Man. Year: 2011)	Odometer:	77359 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50R16	Rear Tyre Size:	205/50R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,229.40	982.80	246.60	20.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	770.00	560.00	42.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,559.40	1,752.80	806.60	31.52
+ GST 7.00/7.00% (S\$)	179.16	122.70	56.46	31.51
Nett Amount (S\$)	2,738.56	1,875.50	863.06	31.52

INSPECTION

Date of Assignment:	02/11/2018	
Date Inspected:	27/11/2018	Inspected At:
		Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2018)
Parts: M1-COUPE	MINI COOPER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKF7606U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID LOGO	Necessary	60.00 FL	*60.00 FL
2	1	*BOOT LID EMBLEM-COOPER	Necessary	55.00 FL	*55.00 FL
3	1	*REAR BUMPER	Cut	628.00 FL	*628.00 FL
4	1	*REAR BUMPER LOWER (ROUGH BLACK)	Scratched/Deformed	195.00 FL	*195.00 FL
5	1	*REAR BUMPER FOG LAMP	Not Necessary	125.00 FL	*- FL
6	1	*REAR BUMPER FOG LAMP CHROME FRAME	Not Necessary	48.00 FL	*- FL
7	4	*REVERSE SENSOR O-RING	Necessary	24.00 FL	*24.00 FL
8	16	*REAR BUMPER RIVET	Necessary	80.00 FL	*80.00 FL
9	10	*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
10	1	*REAR BUMPER SIDE RETAINER LH	Not Necessary	18.00 FL	*- FL
11	1	*REAR BUMPER SIDE RETAINER RH	Not Necessary	18.00 FL	*- FL
12	1	*REAR BUMPER CENTRE BRACKET	Not Necessary	27.00 FL	*- FL
13	1	*REAR BUMPER SPONGE	Not Necessary	38.00 FL	*- FL
14	1	*REAR BUMPER REINFORCEMENT (NPA)	Not Necessary	0.00 FL	*- FL
15	1	*REVERSE SENSOR LH INNER (NPA)	Not Necessary	0.00 FL	*- FL
16	1	*REVERSE SENSOR LH OUTER (NPA)	Not Necessary	0.00 FL	*- FL
17	1	*REVERSE SENSOR RH INNER (NPA)	Not Necessary	0.00 FL	*- FL
18	1	*REVERSE SENSOR RH OUTER (NPA)	Not Necessary	0.00 FL	*- FL
19	1	*BOOT LID (NPA)	Repair	0.00 FL	*- FL
20	1	*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,366.00	1,092.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	136.60	109.20
Total Parts (\$\$)	1,229.40	982.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSPECT REAR LIGHTING MECHANISM	New	50.00	30.00
2	TO REMOVE & INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION	New	80.00	40.00
3	TO KNOCK & STRAIGHTEN ON BOOTLID REAR FENDER LH.TO REPLACE DAMAGED ITEMS,REALIGN CONNECTION	New	500.00	300.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	700.00	400.00
Gross Labour Cost (S\$)			1,330.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >