

ASS. REC BY:

REF: CS/FCL18020014 / Uvb2 | Special Instruction:

Surveyor: MUGIS ASSIGNMENT (Office)

From (Person): CS Lurene Jaw of FCL Date/Time: 02/11/2018 5:46pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKQ 7539Y Insured: SHA 8497Y

at Workshop m/s Automobile Hub Tel: 9786 4483

of Blk 1 Kaki Bukit Ave 6 #02-11

Policy No: _____ Claim No: D18007892MFST

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02/11/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi H.O.D. Endorsement: _____

Date/Time: 05/11/2018 10:44am Person Contacted: Ansiung Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKQ 7539Y - x
	SHA 8497Y - CS/TM17014086/K1rbn2 PLA 200717
<u>9/11/18</u>	Email preli revised to FCL

Surveyor Name


REF:

10/1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKQ 75394
 at Workshop m/s Delonchi
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKQ 75394 Yr Regn: 12/14
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Honda used c.c. 1496
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 89493 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU 110 13993
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215-160R16
 R: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 60k.
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 15 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS LTA
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 4/1/18 D.O.I. 5/1/18
 Survey held at _____
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
Rear & H.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
8/11/18 6yrs later.
confirm m/s \$13,000 with AIA Xing (Red 26, 198-80, 67M)

RECEIVED 12 NOV 2018

Date/Time. File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time. File Return to?
 2) 9/11 - typist
 Report Format: aws
 Lump Sum / I.B.I: (\$) 13,000

Days Of Repair: 15
 Resurvey No. of Trip: 21
 Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$) S + R5 (\$) Photos (\$) Others (\$)
 Survey Fee: 170 + 435
 Transportation: 50
50
298
 TOTAL 1003



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007892MFSH

Our ref: CS/FCH18020014/Uvb

DATE: 9/11/2018

The Motor Claims Department
M/s: MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SKQ 7539Y


We thank for your instruction on 2/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 5/11/2018 at the premises of M/s AUTOMOBILE HUB ENTERPRISE and have the following to report:-

Workshop Estimate Amount	: S\$39,198.80
Revised Estimate Amount	: S\$13,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion and front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	02-11-2018	Our Ref No. D18007892MFSH
Accident Date	02-11-2018	Claim Type. Third Party
Insured Vehicle	SHA8497Y	Third Party Vehicle. SKQ7539Y
Survey Location	1 KAKI BUKIT AVE 6 #02-11 AUTOBAY @KAKI BUKIT	
Contact Person.	AH SIONG	
Contact No.	97864483/ 97864483	Fax No. 65365368
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOMOBILE HUB ENTERPRISE	Attention. NIL
Cc : TP Solicitor	JUSEQUITY LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 9 November 2018 2:09 PM
To: 'CWS Motor Claims'
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007892MFSH/1, SKQ 7539Y
Attachments: SKQ 7539Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKQ 7539Y
Date of survey: 5/11/2018
Number of days : 15 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 5 November 2018 10:46 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007892MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 2 November, 2018 5:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007892MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



VEZEL Price Range Depreciation 2015 Vehicle Type

Home » Used Cars » Carro » Honda Vezel 1.5A S

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Leasing

CL LEASING
YOUR PREFERRED CAR LEASING OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Standard Chartered

Enjoy **0.05%** brokerage fees on your online trades in the SG, USA, HK, UK and Australia markets

Honda Vezel 1.5A S

Overview Financial Accessories Similar Research Photos Map

CONSIGNMENT



THE BETTER AUTOMOTIVE EXPERIENCE FOR EVERYBODY

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$65,000	<input button"="" data-bbox="954 864 975 893" type="button" value="?"/>
Reg Date	22-Jun-2015 <small>(6yrs 7mths 14days COE left)</small>	<input data-bbox="954 999 975 1028" type="button" value="?"/>
Manufactured	2015	<input data-bbox="954 1111 975 1140" type="button" value="?"/>
Mileage	75,000 km (22.2k /yr)	<input data-bbox="954 1223 975 1252" type="button" value="?"/>
Transmission	Auto	<input data-bbox="954 1335 975 1364" type="button" value="?"/>
Engine Cap	1,496 cc	<input data-bbox="954 1447 975 1476" type="button" value="?"/>
Road Tax	\$682 /yr	<input data-bbox="954 1559 975 1588" type="button" value="?"/>
Power	96.0 kW (128 bhp) <small>View specs of the Honda Vezel (2014)</small>	<input data-bbox="954 1671 975 1700" type="button" value="?"/>
Curb Weight	1,210 kg	<input data-bbox="954 1783 975 1812" type="button" value="?"/>
Features	A Rare Silver Vezel 1.5 S With Higher Specifications And 2k Worth Of Accessories As Followed.	<input data-bbox="954 1895 975 1924" type="button" value="?"/>
Accessories	AVH-X8750BT Pioneer Touchscreen DVD With Bluetooth, USB, SDcard, CarPlay And Mirrorlink Underseat Subwoofer Integrated Reverse Camera Reverse Sensor.	<input data-bbox="954 2007 975 2036" type="button" value="?"/>
Description	Customized 3D Floor Mat And Window Sunshade Dual Tone Leather Seats HDMI/USB Plug Paddle Shift Blackvue Camera Scuff Plate With LED (Blue Light) Tonneau Cover (Hard) Auto Folding Mirror Mugen Door Visor Customized Boot Tray 17"Sports Rims Gunmetal Grey Paint Body Cladding Heated Front Seats Original Aluminum Sports Pedal Original Steering Audio Control Switch Viewing Is Strictly By Appointment.	<input data-bbox="954 2119 975 2148" type="button" value="?"/>
COE	\$61,000	<input data-bbox="954 2231 975 2240" type="button" value="?"/>
OMV	\$19,200	<input data-bbox="954 2343 975 2240" type="button" value="?"/>
ARF	\$9,200	<input data-bbox="954 2455 975 2240" type="button" value="?"/>
Dereg Value	\$47,310 as of today (change)	<input data-bbox="954 2567 975 2240" type="button" value="?"/>
No. of Owners	1	<input data-bbox="954 2679 975 2240" type="button" value="?"/>
Type of Veh	SUV	
Category	PARF Car, Consignment Car	
Availability	Available	<input type="button" value="CONSIGNMENT"/>

Add to Shortlist Add to Compare Add a Note

Posted on: 29-Oct-2018 | Last Updated on: 29-Oct-2018

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » List of owner consignment cars
- » List of consignment agents



Seller Information

Company	Carro » dealer's pricelist » 218 vehs sold 167 vehs available
Address	26 Sin Ming Lane #01-111 <small>Search cars nearby this location</small>
Location	Midview City
Office No	67146652
Contact Person(s)	Joce 81394200 Betty 96215746

- Apple Event '18: iPhones XS, XS Max, XR, Apple Wat...
- Confusing Signals
- Lornie Road

VEZEL Price Range Depreciation 2015 Vehicle Type

Advanced Search

Home » Used Cars » Car Buyers Automotive Pte Ltd » Honda Vezel 1.5A S

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle



Village Hotel Bugis



\$136 \$194

Hotels.com

Honda Vezel 1.5A S

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

CAR BUYERS CLUB BY CAR BUYERS AUTOMOTIVE PTE LTD

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$63,500	?
Depreciation	\$8,840 /yr <small>View models with similar depreciation</small>	?
Reg Date	25-Jun-2015 <small>(6yrs 7mths 17days COE left)</small>	?
Manufactured	2015	?
Mileage	49,000 km (14.5k /yr)	?
Transmission	Auto	?
Engine Cap	1,496 cc	?
Road Tax	\$682 /yr	?
Power	96.0 kW (128 bhp) <small>View specs of the Honda Vezel</small>	?
Curb Weight	1,210 kg	?
Features	Reliable And Fuel Efficient 1.5L 4 Cylinder Inline DOHC I-VTEC Engine, Mated With Smooth CVT Gearbox, Airbags, ABS, Traction Control.	?
Accessories	Keyless Entry/Start/Stop, Stylish 17" Sports Rims, Roof Rails, Heated Front Seats, Paddle Shift, Aluminium Pedals, Bluetooth, Anti Glare Mirrors, GPS.	?
Description	Only \$6k Down, \$960/Mth To Drive Away This High Specs Ever Reliable Signature Honda Vezel Crossover! S Model Comes With Extra Goodies Including Sporty Rims, Paddle Shift, Roof Rails. Classy White Exterior Against Black Fabric/Leather Interior Finish! Not To Be Missed At This Competitive Price! Accident Free With Absolutely No Repairs Needed! Evaluation Welcome! Viewing By Appointment Only.	?
COE	\$61,000	?
OMV	\$19,791	?
ARF	\$9,791	?
Dereg Value	\$47,804 as of today (change)	?
No. of Owners	1	?
Type of Veh	SUV	?
Category	PARF Car, Premium Ad Car	?
Availability	Available	?



Seller Information

Company	Car Buyers Automotive Pte Ltd <small>» dealer's pricelist » 42 vehs sold 71 vehs available</small>	
Address	10 Kaki Bukit Road 2 #01-13 <small>Search cars nearby this location</small>	
Location	First East Centre	
Office No	68481200	
Contact Person(s)	Adrian Tan Gin Lim	82221375 96870081

Add to Shortlist Add to Compare Add a Note

Posted on: 04-Oct-2018 | Last Updated on: 05-Nov-2018

Compare

Inchcape **FREE SERVICE & TYRE CREDITS** WHEN YOU PURCHASE A CAR FROM INCHCAPE-PREOWNED
 6303 6303

PIT & GO FREE SERVICE & TYRE CREDITS VALUE \$1,500 FOR PURCHASES BELOW \$20K

PIT & GO FREE SERVICE & TYRE CREDITS VALUE \$3,000 FOR PURCHASES ABOVE \$20K

LEARN MORE

Post an Advertisement
 Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Aug 12 Lexus IS250C. Hard top Convertible.



Low Maintenance Sport Car, V6 Engine, High ARI \$57,733, Call Now To View! Shine Connect StarAd

ABWIN **ONE-STOP** MOTORHIRE SOLUTIONS

VIEW OUR PROFILE

Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

21 vehicles

VEZEL

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	VEZEL	Any	Any	2015	Any	Any	Any	Available
	Honda VezeL 1.5A X	\$64,800	\$8,810 /yr	29-Sep-2015	1,496 cc	48,900 km	SUV	Available
Most Popular Hatchback For Sale In Henly Enterprises! Contact Sale Person To View And Believe IT'S Well Maintained Condition! Henly Enterprises Co Posted: 06-Nov-2018 Tags: 2015 Honda VezeL, 2015 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda								
	Honda VezeL 1.5A X	\$59,800	\$8,730 /yr	24-Mar-2015	1,496 cc	42,000 km	SUV	Available
1 Owner, End User Car, Not Private Hire Usage, Genuine Mileage. Meticulously Maintain, High Loan Available. High Trade In Valuation Welcome. Sms/Call/Whatsapp To Arrange Appointment Now! Posted: 04-Nov-2018 Tags: 2015 Honda VezeL, 2015 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda								
	Honda VezeL 1.5A X	\$62,800	\$8,570 /yr	17-Sep-2015	1,496 cc	36,013 km	SUV	Available
90% Loan Available! Low Mileage! 1 Owner Only! Well Maintained, 100% Accident Free! Guaranteed Not A PHV Unit! Vehicle In Excellent Condition! Minimum Down Payment With Bank Or In House Loan Available... Autobrust Traders Pte Ltd Posted: 04-Nov-2018 Tags: 2015 Honda VezeL, 2015 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda								
	Honda VezeL 1.5A X	\$59,800	\$8,750 /yr	12-Mar-2015	1,496 cc	-	SUV	Available
3 Months Warranty From Our In-house Workshop, Promo Interest Rate 2.18% Or 2.28%, Black In Black Colour, Excellent Condition, Accident Free, No Repair Needed. Bank Loan In-house Loan Available, Trade ... Posted: 02-Nov-2018 Tags: 2015 Honda VezeL, 2015 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda								
	Audio Panel (HA-2093T)	1+1 / 2 DIN Audio Panel for VezeL / HR-V (2014)						
More info about this product								
	Honda VezeL 1.5A X	\$64,800	\$8,570 /yr	17-Nov-2015	1,496 cc	51,000 km	SUV	Available
100% Loan Available! High Approval Rate! 1 Owner! Not From Uber/Grab Car! Low Depreciation! Low Fuel Consumption! Low Maintenance! Call The Assign Sales Person To Find Out More! AL Autocar Pte Ltd Posted: 01-Nov-2018 Tags: 2015 Honda VezeL, 2015 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda								
	Honda VezeL 1.5A X	\$66,800	\$9,050 /yr	02-Oct-2015	1,496 cc	31,000 km	SUV	Available
Pearl White Unit! Well Maintained By Previous Owner, Accident Free. Most Popular Compact SUV, Low Mileage, One Owner, 1 Year Warranty And 1 Free Servicing! Buy With A Peace Of Mind. Trade In Welcome, ... AL Autocar Pte Ltd Posted: 01-Nov-2018 Tags: 2015 Honda VezeL, 2015 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda								
	Honda VezeL 1.5A X	\$66,000	\$8,980 /yr	02-Oct-2015	1,496 cc	53,000 km	SUV	Available
Posted: 01-Nov-2018 Tags: 2015 Honda VezeL, 2015 honda vezeL, Honda VezeL, honda vezeL, Honda, VezeL, vezeL, Used Honda								

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1875B
Vehicle Details	
Vehicle No.:	SKQ7539Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	L15B3514008
Chassis No.:	RU11013993
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,949.00
Original Registration Date:	24 Dec 2014
First Registration Date:	24 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$8,949.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2024
PARF Rebate Amount:	\$6,711.00
Intended COE Rebate Details	
COE Expiry Date:	23 Dec 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,889.00
COE Rebate Amount:	\$40,277.00
Total Rebate Amount:	\$46,988.00

The information contained herein is correct as at 09 Nov 2018

OK

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1875B
Vehicle Details	
Vehicle No.:	SKQ7539Y
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	L15B3514008
Chassis No.:	RU11013993
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,949.00
Original Registration Date:	24 Dec 2014
First Registration Date:	24 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$8,949.00 4474
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2024
PARF Rebate Amount:	\$6,711.00
Intended COE Rebate Details	
COE Expiry Date:	23 Dec 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,889.00
COE Rebate Amount:	\$40,401.00
Total Rebate Amount:	\$47,112.00

The information contained herein is correct as at 05 Nov 2018

OK

AUTOMOBILE HUB ENTERPRISE

51 Defu Lane 9
Singapore 539291

1 Kaki Bukit Avenue 6
#02-11 Autobay @ Kaki Bukit
Singapore 417883

H/P: 9786 4483
FAX: 6758 3325
Email: autohub325@gmail.com

*not allowed
N/A
5/11/18
1/5 = 13.000/-
15dy.*

Vehicle No: SKW 7539Y

Model: HONDA VEZEL

Qty	List Price		Price
1	Tailgate	953	1287.00
1	Tailgate outer garnish		220.00 X
1 set	Tailgate outer garnish clips		40.00 X
1	Tailgate centre emblem		25.00 X
1	Tailgate 'Vezel' emblem		56.00
1	Tailgate windscreen glass rubber moulding		122.00
1	Tailgate RH lamp	260	570.00
1	Tailgate LH lamp		570.00 X
1	Tailgate number plate RH lamp		25.00 X
1	Tailgate number plate LH lamp		25.00 X
1	Tailgate inner trim board		197.00
1	Tailgate inner trim board clips		40.00 X
1	Tailgate inner pull garnish		27.00 X
1	Tailgate open button sensor		175.00 X
1	Tailgate lock	195	269.00
1	Tailgate lock catch		27.00 X
1	Tailgate RH damper		180.00 X
1	Tailgate LH damper		180.00 X
1	Tailgate RH hinge		50.00 X
1	Tailgate LH hinge		50.00 X
1	Tailgate weatherstrip		96.00
1	Rear bumper	721	950.00
1 set	Rear bumper clips		50.00
1	Rear bumper RH side cover		195.00
1	Rear bumper LH side cover		195.00 X
1	Rear bumper lower cover		250.00
1	Rear bumper RH side reflector		141.00
1	Rear bumper LH side reflector		141.00 X
1	Rear bumper RH side retainer		23.00
1	Rear bumper LH side retainer		23.00 X
1	End panel	514	585.00
1	End panel inner garnish		145.00
1 set	End panel inner garnish clips		30.00 X
1	End panel antenna sensor		60.00
1	End panel buzzer sensor		85.00
1	RH taillamp	480.60	1360.00
1 set	RH taillamp clips		24.00 X
1	LH taillamp		1360.00 X

9248

Vehicle No: SKW 7539Y

Model: HONDA VEZEL

1 set	LH taillamp clips		11	24.00	X
1	Rear RH fender arch garnish		11	195.00	X
1	Rear RH fender arch garnish clips		11	30.00	X
1 set	Rear RH inner shield		Torn	147.00	/
1	Rear RH inner shield clips		11	30.00	X
1	Rear RH fender inner trim board		DE/scr	295.00	—
1	Rear RH fender inner trim board clips		scr	35.00	—
1	Rear LH fender arch garnish		11	195.00	X
1	Rear LH fender arch garnish clips		11	30.00	X
1 set	Rear LH inner shield		11	147.00	X
1	Rear LH inner shield clips		11	30.00	X
1	Rear LH fender inner trim board		11	295.00	X
1	Rear LH fender inner trim board clips		11	35.00	X
1	Floor jack panel		11	1146.00	X
1	Floor panel		crushed/scr	662.00	—
1	Floor panel compartment tray garnish		Torn	485.00	—
1	Floor panel inner top board cover		wegak	430.00	—
1	Exhaust silencer gasket		11	48.00	X
1	Exhaust silencer	645	scr/scr	845.00	—
1	Exhaust silencer aluminum heat shield		scr	85.00	—
2	Exhaust silencer rubber mountings		scr	33.00	—
1	Central exhaust pipe		11	985.00	X
1	Central exhaust pipe gasket		11	48.00	X
1	Front windscreen glass		CR	1003.00	—
1	Front windscreen glass rubber moulding		scr	142.00	—
1	Bonnet	892.30	scr	1200.00	—
1	Bonnet RH hinge		scr	88.00	—
1	Bonnet LH hinge		scr	88.00	—
1	Bonnet lock	105	scr	209.00	—
1	Bonnet insulator heat shield		scr	133.00	—
1 set	Bonnet insulator heat shield clips		scr	40.00	—
1	Front bumper	801.70	scr	988.00	—
1 set	Front bumper clips		scr	40.00	—
1	Front bumper RH side retainer		scr	25.00	—
1	Front bumper LH side retainer		scr	25.00	—
1	Front bumper lower grille		Torn	145.00	—
1	Front bumper lower lip		11	588.00	X
1	Front bumper reinforcement	321	scr	498.00	—
1	Front bumper reinforcement top garnish		NT	54.00	X
1	Front bumper tow cover		scr	86.00	—
1	Front bumper RH fog lamp		11	367.00	X
1	Front bumper RH fog lamp bracket		CR	125.00	—
1	Front bumper RH fog lamp garnish		scr	45.00	—
1	Front bumper LH fog lamp		11	367.00	X
1	Front bumper LH fog lamp bracket		CR	125.00	—
1	Front bumper LH fog lamp garnish		scr	45.00	—
1	RH headlamp LED	1784	CR	1795.00	—
1	RH headlamp lower bracket		CR	35.00	—
1	LH headlamp LED	1784	CR	1795.00	—
1	LH headlamp lower bracket		CR	35.00	—
1	Front grille	385	CR	589.00	—
1	Front grille centre emblem		scr	45.00	—
1 set	Front grille clips		11	30.00	X
1	Front grille RH chrome moulding		scr	35.00	—

17040

Vehicle No: SKW 7539Y

Model: HONDA VEZEL

- 1 Front grille LH chrome moulding
- 1 Front grille centre bracket
- 1 Front grille outer garnish
- 1 Front grille RH side bracket
- 1 Front grille LH side bracket
- 1 Front grille top garnish
- 1 set Front grille top garnish clips
- 1 Support panel 576.20
- 1 Front RH fender
- 1 Front RH fender arch garnish
- 1 set Front RH fender arch garnish clips
- 1 Front RH fender inner shield
- 1 set Front RH fender inner shield clips
- 1 Front LH fender
- 1 Front LH fender arch garnish
- 1 set Front LH fender arch garnish clips
- 1 Front LH fender inner shield
- 1 set Front LH fender inner shield clips
- 1 Horn
- 1 Washer tank
- 1 Radiator
- 1 Radiator RH top bracket
- 1 Radiator LH top bracket
- 1 Radiator spare tank
- 1 Radiator fan cowling
- 1 Radiator fan blade
- 1 Radiator fan motor
- 1 Radiator top hose
- 1 Radiator lower hose
- 1 Aircon condenser
- 1 Aircon fan cowling
- 1 Aircon fan blade
- 1 Aircon fan motor
- 1 Aircon discharge pipe
- 1 Aircon suction pipe
- 1 Engine RH under cover
- 1 Engine RH under cover clips
- 1 Engine LH under cover
- 1 Engine LH under cover clips

SCA	45.00	—
CRU	86.00	—
CHE	421.00	—
TRM	35.00	—
TRM	35.00	—
TRM	85.00	—
TR	30.00	X
SEL	680.00	—
R	780.00	X
TRM	220.00	—
TR	35.00	X
TR	130.00	X
TR	28.00	X
R	780.00	X
TRM	220.00	—
TR	35.00	X
TR	130.00	X
TR	28.00	X
TR	59.00	X
TR	87.00	X
TRM/TRM	1226.00	—
TR	22.00	X
TR	22.00	X
TR	65.00	X
TR	117.00	X
TR	89.00	X
TR	355.00	X
TR	78.00	X
TR	93.00	X
TR/TRM	1001.00	—
TR	117.00	X
TR	89.00	X
TR	355.00	X
TR	458.00	X
TR	437.00	X
TR	103.00	X
TR	30.00	X
TR	103.00	X
TR	30.00	X

Less 20%

Total \$ 35,626.00

(\$ 7,125.20)

Subtotal: \$ 28,500.80

28501.60

19688.8
 15757.04
 20721.04
 16576.

Special Nett items:

- 1 Tailgate windscreen glass sealant
- 1 Tailgate windscreen glass inner seal

TR 70.00 40
 TR 60.00 30

Vehicle No: SKW 7539Y

Model: HONDA VEZEL

- 1 set Rear bumper reverse sensor
- 1 Rear reverse camera
- 1 Rear number plate
- 1 Front windscreen glass sealant
- 1 Front windscreen glass inner seal
- 1 Front windscreen glass ERP bracket
- 1 Front number plate
- 1 Radiator coolant

subtotal
 11 350.00 200
 11 550.00 X
 11 70.00 X
 11 70.00 40
 11 60.00 30
 11 28.00 20
 11 60.00 40
 11 70.00 30

Subtotal \$ 1,388.00
 430

Labour Charges:

- Labour charges on affected areas (Front portion)
- Spray painting on affected areas
- Remove and replace aircon condenser, pipes and fan assy. To refill aircon gas
- Remove and replace radiator, hoses and fan assy. To refill radiator coolant
- Remove and replace front windscreen glass
- Check electrical and lighting system (Front and Rear)
- Reprogram, diagnose and reset headlamp position
- Apply body panels ~~paint coating and protection~~ rust proofing
- Labour charges on affected areas (Rear portion)
- Spray painting on affected areas (Rear portion)
- Remove and replace tailgate inner components to new tailgate
- Remove and refix tailgate windscreen glass
- Remove and replace rear inner trims, garnish and boards
- Remove and replace exhaust silencer and centre pipe
- Remove, replace and adjust rear bumper reverse sensor and camera
- Mount vehicle on chassis alignment bench

1400.00 700
 1200.00 900
 200.00 100
 200.00 120
 200.00 30
 11 250.00 X
 1200.00 120
 1800.00 1200
 1500.00 1000
 100.00 60
 200.00 120
 350.00 80
 180.00 60
 150.00 50
 11 300.00 X

Subtotal: \$ 10,698.00
 9310

9310 4540

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 39,198.80

39199.6

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118020014/Uvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8497Y	Veh. Inspected	SKQ 7539Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18007892MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	02/11/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	RU11013993	Colour	BLUE
Odometer	89493	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GOODYEAR	7 mm
L/H Front Tyre	215/60 R16	GOODYEAR	7 mm
R/H Rear Tyre	215/60 R16	GOODYEAR	7 mm
L/H Rear Tyre	215/60 R16	GOODYEAR	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/11/2018	Inspection Date	05/11/2018
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7539Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BADLY DENTED	1,287.00	953.00
1	TAILGATE OUTER GARNISH	NOT NECESSARY	220.00	-
1	SET TAILGATE OUTER GARNISH CLIPS	NOT NECESSARY	40.00	-
1	TAILGATE CENTRE EMBLEM	NOT NECESSARY	25.00	-
1	TAILGATE "VEZEL" EMBLEM	NECESSARY	56.00	56.00 ✓
1	TAILGATE WINDSCREEN GLASS RUBBER MOULDING	NECESSARY	122.00	122.00 ✓
1	TAILGATE RH LAMP	CRACKED	570.00	260.00 ✓
1	TAILGATE LH LAMP	NOT NECESSARY	570.00	-
1	TAILGATE NUMBER PLATE RH LAMP	NOT NECESSARY	25.00	-
1	TAILGATE NUMBER PLATE LH LAMP	NOT NECESSARY	25.00	-
1	TAILGATE INNER TRIM BOARD	CRACKED / TWISTED	197.00	197.00 ✓
1	TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	40.00	-
1	TAILGATE INNER PULL GARNISH	NOT NECESSARY	27.00	-
1	TAILGATE OPEN BUTTON SENSOR	NOT NECESSARY	175.00	-
1	TAILGATE LOCK	TWISTED	269.00	195.00 ✓
1	TAILGATE LOCK CATCH	NOT NECESSARY	27.00	-
1	TAILGATE RH DAMPER	NOT NECESSARY	180.00	-
1	TAILGATE LH DAMPER	NOT NECESSARY	180.00	-
1	TAILGATE RH HINGE	NOT NECESSARY	50.00	-
1	TAILGATE LH HINGE	NOT NECESSARY	50.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	96.00	96.00 ✓
1	REAR BUMPER	DENTED	950.00	721.00 ✓
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00 ✓
1	REAR BUMPER RH SIDE COVER	TWISTED	195.00	195.00 ✓
1	REAR BUMPER LH SIDE COVER	TO REPAIR SEE LABOUR ✓	195.00	-
1	REAR BUMPER LOWER COVER	DISTORTED	250.00	250.00 ✓
1	REAR BUMPER RH SIDE REFLECTOR	CRACKED	141.00	141.00 ✓
1	REAR BUMPER LH SIDE REFLECTOR	NOT NECESSARY	141.00	-
1	REAR BUMPER RH SIDE RETAINER	BENT	23.00	23.00 ✓



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER LH SIDE RETAINER	NOT NECESSARY	23.00	-
1	END PANEL	BADLY DENTED	585.00	514.00 ✓
1	END PANEL INNER GARNISH	TWISTED	145.00	145.00 ✓
1	SET END PANEL INNER GARNISH CLIPS	NOT NECESSARY	30.00	-
1	END PANEL ANTENNA SENSOR	CRACKED	60.00	60.00 ✓
1	END PANEL BUZZLE SENSOR	DAMAGED	85.00	85.00 ✓
1	RH TAILLAMP	CRACKED	1,360.00	480.60 ✓
1	SET RH TAILLAMP CLIPS	NOT NECESSARY	24.00	-
1	LH TAILLAMP	NOT NECESSARY	1,360.00	-
1	SET LH TAILLAMP CLIPS	NOT NECESSARY	24.00	-
1	REAR RH FENDER ARCH GARNISH	NOT NECESSARY	195.00	-
1	REAR RH FENDER ARCH GARNISH CLIPS	NOT NECESSARY	30.00	-
1	SET REAR RH INNER SHIELD	TORN	147.00	147.00 ✓
1	REAR RH INNER SHIELD CLIPS	NOT NECESSARY	30.00	-
1	REAR RH FENDER INNER TRIM BOARD	DEFORMED / TWISTED	295.00	295.00 ✓
1	REAR RH FENDER INNER TRIM BOARD CLIPS	NECESSARY	35.00	35.00 ✓
1	REAR LH FENDER ARCH GARNISH	NOT NECESSARY	195.00	-
1	REAR LH FENDER ARCH GARNISH CLIPS	NOT NECESSARY	30.00	-
1	SET REAR LH INNER SHIELD	NOT NECESSARY	147.00	-
1	REAR LH INNER SHIELD CLIPS	NOT NECESSARY	30.00	-
1	REAR LH FENDER INNER TRIM BOARD	NOT NECESSARY	295.00	-
1	REAR LH FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	35.00	-
1	FLOOR JACK PANEL	NO SUCH PARTS	1,146.00	-
1	FLOOR PANEL	CRUMPLED / BUCKLED	662.00	662.00 ✓
1	FLOOR PANEL COMPARTMENT TRAY GARNISH	TORN	485.00	485.00 ✓
1	FLOOR PANEL INNER TOP BOARD COVER	WARPED	430.00	430.00 ✓
1	EXHAUST SILNCER GASKET	NOT NECESSARY	48.00	-
1	EXHAUST SILNCER	BENT / TWISTED	845.00	645.00 ✓
1	EXHAUST SILNCER ALUMINUM HEAT SHIELD	BENT	85.00	85.00 ✓
2	EXHAUST SILNCER RUBBER MOUNTINGS	NECESSARY	33.00	33.00 ✓
1	CENTRAL EXHAUST PIPE	TO REPAIR SEE LABOUR	985.00	-

Report Ref No. CS/FC118020014/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CENTRAL EXHAUST PIPE GASKET	NOT NECESSARY	48.00	-
1	FRONT WINDSCREEN GLASS	CRACKED	1,003.00	1,003.00
1	FRONT WINDSCREEN GLASS RUBBER MOULDING	NECESSARY	142.00	142.00
1	BONNET	BUCKLED	1,200.00	892.30
1	BONNET RH HINGE	TWISTED	88.00	88.00
1	BONNET LH HINGE	TWISTED	88.00	88.00
1	BONNET LOCK	TWISTED	209.00	105.00
1	BONNET INSULATOR HEAT SHIELD	DEFORMED	133.00	133.00
1	SET BONNET INSULATOR HEAT SHIELD CLIPS	NECESSARY	40.00	40.00
1	FRONT BUMPER	DENTED	988.00	801.70
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT BUMPER RH SIDE RETAINER	BENT	25.00	25.00
1	FRONT BUMPER LH SIDE RETAINER	BENT	25.00	25.00
1	FRONT BUMPER LOWER GRILLE	TORN	145.00	145.00
1	FRONT BUMPER LOWER LIP	TO REPAIR SEE LABOUR	588.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	498.00	321.00
1	FRONT BUMPER REINFORCEMENT TOP GARNISH	NOT FITTED	54.00	-
1	FRONT BUMPER TOW COVER	TWISTED	86.00	86.00
1	FRONT BUMPER RH FOG LAMP	NOT NECESSARY	367.00	-
1	FRONT BUMPER RH FOG LAMP BRACKET	CRACKED	125.00	125.00
1	FRONT BUMPER RH FOG LAMP GARNISH	TWISTED	45.00	45.00
1	FRONT BUMPER LH FOG LAMP	NOT NECESSARY	367.00	-
1	FRONT BUMPER LH FOG LAMP BRACKET	CRACKED	125.00	125.00
1	FRONT BUMPER LH FOG LAMP GARNISH	TWISTED	45.00	45.00
1	RH HEADLAMP LED	CRACKED	1,795.00	1,784.00
1	RH HEADLAMP LOWER BRACKET	CRACKED	35.00	35.00
1	LH HEADLAMP LED	CRACKED	1,795.00	1,784.00
1	LH HEADLAMP LOWER BRACKET	CRACKED	35.00	35.00
1	FRONT GRILLE	CRACKED	589.00	385.00
1	FRONT GRILLE CENTRE EMBLEM	NECESSARY	45.00	45.00
1	SET FRONT GRILLE CLIPS	NOT NECESSARY	30.00	-
1	FRONT GRILLE RH CHROME MOULDING	SCRATCHED	35.00	35.00

Report Ref No. CS/FCI18020014/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT GRILLE LH CHROME MOULDING	SCRATCHED	45.00	45.00
1	FRONT GRILLE CENTRE BRACKET	CRACKED	86.00	86.00
1	FRONT GRILLE OUTER GARNISH	CRACKED	421.00	421.00
1	FRONT GRILLE RH SIDE BRACKET	TWISTED	35.00	35.00
1	FRONT GRILLE LH SIDE BRACKET	TWISTED	35.00	35.00
1	FRONT GRILLE TOP GARNISH	TWISTED	85.00	85.00 ✓
1	SET FRONT GRILLE TOP GARNISH CLIPS	NOT NECESSARY	30.00	-
1	SUPPORT PANEL	BENT	680.00	576.20 ✓
1	FRONT RH FENDER	TO REPAIR SEE LABOUR ↓	780.00	-
1	FRONT RH FENDER ARCH GARNISH	TORN	220.00	220.00 ✓
1	SET FRONT RH FENDER ARCH GARNISH CLIPS	NOT NECESSARY	35.00	-
1	FRONT RH FENDER INNER SHIELD	NOT NECESSARY	130.00	-
1	SET FRONT RH FENDER INNER SHIELD CLIPS	NOT NECESSARY	28.00	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR ↓	780.00	-
1	FRONT LH FENDER ARCH GARNISH	TORN	220.00	220.00 ✓
1	SET FRONT LH FENDER ARCH GARNISH CLIPS	NOT NECESSARY	35.00	-
1	FRONT LH FENDER INNER SHIELD	NOT NECESSARY	130.00	-
1	SET FRONT LH FENDER INNER SHIELD CLIPS	NOT NECESSARY	28.00	-
1	HORN	NOT NECESSARY	59.00	-
1	WASHER TANK	NOT NECESSARY	87.00	-
1	RADIATOR	BENT / TWISTED	1,226.00	1,226.00 ✓
1	RADIATOR RH TOP BRACKET	NOT NECESSARY	22.00	-
1	RADIATOR LH TOP BRACKET	NOT NECESSARY	22.00	-
1	RADIATOR SPARE TANK	NOT NECESSARY	65.00	-
1	RADIATOR FAN COWLING	NOT NECESSARY	117.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	89.00	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	355.00	-
1	RADIATOR TOP HOSE	NOT NECESSARY	78.00	-
1	RADIATOR LOWER HOSE	NOT NECESSARY	93.00	-
1	AIRCON CONDENSER	BENT / PUNCTURE	1,001.00	1,001.00 ✓
1	AIRCON FAN COWLING	NOT NECESSARY	117.00	-
1	AIRCON FAN BLADE	NOT NECESSARY	89.00	-

Report Ref No. CS/FC118020014/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON FAN MOTOR	NOT NECESSARY	355.00	-
1	AIRCON DISCHARGE PIPE	NOT NECESSARY	458.00	-
1	AIRCON SUCTION PIPE	NOT NECESSARY	437.00	-
1	ENGINE RH UNDER COVER	NOT NECESSARY	103.00	-
1	ENGINE RH UNDER COVER CLIPS	NOT NECESSARY	30.00	-
1	ENGINE LH UNDER COVER	NOT NECESSARY	103.00	-
1	ENGINE LH UNDER COVER CLIPS	NOT NECESSARY	30.00	-
	LESS 20% DISCOUNT		-7,125.40	-3,937.76
			28,501.60	15,751.04
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	70.00	40.00 ✓
1	TAILGATE WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	60.00	30.00 ✓
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	200.00 ✓
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	550.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	70.00	40.00
1	FRONT WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	60.00	30.00
1	FRONT WINDSCREEN GLASS ERP BRACKET (SN)	NECESSARY	28.00	20.00
1	FRONT NUMBER PLATE (SN)	BENT	60.00	40.00
1	RADIATOR COOLANT (SN)	NECESSARY	70.00	30.00 ✓
			1,388.00	430.00
	<u>LABOUR</u>			
	LABOUR CHARGES ON AFFECTED AREAS (FRONT PORTION). INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER LIP, FRONT RH FENDER AND FRONT LH FENDER.		1,400.00	700.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	900.00
	REMOVE AND REPLACE AIRCON CONDENSER, PIPES AND FAN ASSY, TO REFILL AIRCON GAS. }		200.00	100.00 ✓
	REMOVE AND REPLACE RADIATOR, HOSES AND FAN ASSY. TO REFILL RADIATOR COOLANT. }		200.00	-
	REMOVE AND REPLACE FRONT WINDSCREEN GLASS.		200.00	120.00
	CHECK ELECTRICAL AND LIGHTING SYSTEM (FRONT AND REAR).		80.00	30.00 ✓

Report Ref No. CS/FCI18020014/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPROGRAM,DIAGNOSE AND RESET HEADLAMP POSITION.	NOT NECESSARY	250.00	-
	APPLY BODY PANELS RUST PROOFING.		1,200.00	120.00
	LABOUR CHARGES ON AFFECTED AREAS (REAR PORTION).INCLUSIVE OF THE REPAIR OF REAR BUMPER LH SIDE COVER AND CENTRAL EXHAUST PIPE.		1,800.00	1,200.00
	SPRAY PAINTING ON AFFECTED AREAS (REAR PORTION).		1,500.00	1,000.00
	REMOVE AND REPLACE TAILGATE INNER COMPONENTS TO NEW TAILGATE.		100.00	60.00
	REMOVE AND REFIX TAILGATE WINDSCREEN GLASS.		200.00	120.00
	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND BOARDS.		350.00	80.00
	REMOVE AND REPLACE EXHAUST SILENCER AND CENTRE PIPE.		180.00	60.00
	REMOVE,REPLACE AND ADJUST REAR BUMPER REVERSES ENSOR AND CAMERA.		150.00	50.00
	MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH.	NOT NECESSARY	300.00	-
			9,310.00	4,540.00
GRAND TOTAL			39,199.60	20,721.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/FCI18020014/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.