

### SERVICE ESTIMATE

69688 - C00001 SL: SERVICE SALES - PC

Adamas Bathroom Pte Ltd

Mr Lim

201 Jalan Besar

Singapore 208887

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 02/11/2018

WIP No. : 36366

Veh.In/Out:

\*Tel.No. : Mobile: 96589815

Reg.No. : SCN666U

Reg.date : 29/09/2017

Mileage : 0

Chassis No: SADCA2AN0HA053369

Closed by .... : Paul Ong Qing Yong

Svc Consultant :

Remarks ..... : Adamas Bathroom Pte

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-------------|----------|-------|-------|-----|--------|---|
|-------|-------------|----------|-------|-------|-----|--------|---|

|     |                                                   |   |         |   |  |            |      |
|-----|---------------------------------------------------|---|---------|---|--|------------|------|
| 802 | TO REPLACE REAR BUMPER,<br>REAR EXHAUST ASSY, ETC | 0 | 3600.00 | 0 |  | 3,600.00 S | 1800 |
|-----|---------------------------------------------------|---|---------|---|--|------------|------|

|     |                                                          |   |         |   |  |            |     |
|-----|----------------------------------------------------------|---|---------|---|--|------------|-----|
| 800 | TO PUTTY SPRAYPAINT ON<br>REAR BUMPER, REAR BOOTLID, ETC | 0 | 2400.00 | 0 |  | 2,400.00 S | 800 |
|-----|----------------------------------------------------------|---|---------|---|--|------------|-----|

|     |                                                                  |   |        |   |  |          |   |
|-----|------------------------------------------------------------------|---|--------|---|--|----------|---|
| 280 | TO CHECK WIRING INCLUDE<br>RESETING OF ALL ELECTRICAL<br>MODULES | 0 | 486.00 | 0 |  | 486.00 S | ✓ |
|-----|------------------------------------------------------------------|---|--------|---|--|----------|---|

COVER-BUMPER

1.0 EA 1436.20

1,436.20 S de

BRACKET-BUMPER

1.0 EA 96.50

96.50 S ?

BRACKET-BUMPER

1.0 EA 96.50

96.50 S ?

MOUNTING-BRACKET

1.0 EA 129.90

129.90 S ?

MOUNTING-BRACKET

1.0 EA 129.90

129.90 S ?

MOUNTING-BRACKET

1.0 EA 190.80

190.80 S ?

SENSOR

4.0 EA 248.20

992.80 S ?

SILENCER-EXH RR ASSY

1.0 EA 1258.10

1,258.10 S ?

BADGE

1.0 EA 171.60

171.60 SX

BADGE

1.0 EA 175.30

175.30 SX

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

WP  
14/11/18 2pm

4 days

sure/like to in  
Resurvey before paint.

### SERVICE ESTIMATE

69688 - C00001      SL: SERVICE SALES - PC

Adamas Bathroom Pte Ltd

Mr Lim

201 Jalan Besar

Singapore 208887

GST Reg.No:M28920628X

Inv.No. . : B&P      0    Page 2

Inv.date. : 02/11/2018

WIP No. . : 36366

Veh.In/Out:

\*Tel.No. . : Mobile: 96589815

Reg.No. . : SCN666U

Reg.date. : 29/09/2017

Mileage . : 0

Chassis No: SADCA2AN0HA053369

Closed by .... : Paul Ong Qing Yong

Svc Consultant :

Remarks ..... : Adamas Bathroom Pte

| Op.No | Description         | Mech Qty | Price  | Disc% | Pkg | Amount | G  |
|-------|---------------------|----------|--------|-------|-----|--------|----|
|       | BADGE               | 1.0 EA   | 119.80 |       |     | 119.80 | Sx |
|       | ADHESIVE SEALER FL2 | 1.0 EA   | 549.10 |       |     | 549.10 | Sx |

Gross Total.      11,832.50

Labour Total      6,486.00  
 Parts Total      5,346.50  
 Package Total      0.00

Net.....      11,832.50  
 GST @ 7.0%      828.28  
 Total.....      12,660.80  
 Paid.....      0.00  
 Please Pay..      12,660.80

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated