

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
105 CECIL STREET
#19-00 THE OCTAGON
SINGAPORE 069534
TEL : 6389 6111 FAX : 6224 7175

DATE : 02/11/2018
PAGE : 1 OF 2

*Not Authorized
L1 Imp @ ?
Insurance After Point*

ACCIDENT REPAIR ON : SJA9164C
MODEL : TOYOTA COROLLA AXIO 1.5X
POLICY NO : 10555598
CHASSIS NO : NZE1416050484
YEAR OF MANUFACTURE : 2007
DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS
LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD
THIRD PARTY VEHICLE NO : GX8360Z

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID <i>RM ✓</i>	1		
2	REAR BOOTLID "LOGO" EMBLEM <i>RM ✓</i>	1		
3	REAR BOOTLID "AXIO" EMBLEM <i>RM ✓</i>	1		
4	REAR BOOTLID "X" EMBLEM <i>RM ✓</i>	1		
5	REAR BOOTLID OUTER GARNISH <i>RM 1000 ✓</i>	1		
6	REAR BOOTLID OUTER KEY LOCK <i>RM 5</i>	1		
7	REAR BOOTLID REVERSE CAMERA <i>RM X</i>	1		
8	REAR BOOTLID NUMBER PALTE WITH HOLDER <i>Red RM X ✓</i>	1		
9	REAR BOOTLID NUMBER PALTE LAMP LH <i>?</i>	1		
10	REAR BOOTLID NUMBER PALTE LAMP RH <i>?</i>	1		
11	REAR BOOTLID MECHANISM LOCK <i>RM ✓</i>	1		
12	REAR BOOTLID INNER TRIM BOARD <i>RM X</i>	1		
13	REAR BOOTLID HINGE LH <i>RM X</i>	1		
14	REAR BOOTLID HINGE RH <i>RM X</i>	1		
15	REAR BOOTLID WEATHERSTRIP <i>RM 50/50</i>	1		
16	REAR TAILLAMP LH <i>RM ✓</i>	1		
17	REAR TAILLAMP RH <i>?</i>	1		
18	REAR TAILLAMP LOWER BRACKET LH <i>?</i>	1		
19	REAR TAILLAMP LOWER BRACKET RH <i>?</i>	1		
20	REAR BUMPER <i>RM ✓</i>	1		
21	REAR BUMPER SIDE RETAINER LH <i>RM X</i>	1		
22	REAR BUMPER SIDE RETAINER RH <i>RM X</i>	1		
23	REAR BUMPER REVERSE SENSOR <i>?</i>	2		
24	REAR BUMPER INNER SIDE SHIELD LH <i>RM X</i>	1		
25	REAR BUMPER INNER SIDE SHIELD RH <i>RM X</i>	1		
26	REAR BUMPER IMPACT BRACKET LH <i>?</i>	1		
27	REAR BUMPER IMPACT BRACKET RH <i>?</i>	1		
28	REAR END PANEL <i>?</i>	1		
29	REAR END PANEL LOCK STRIKER <i>RM X</i>	1		
30	REAR END PANEL INNER TOP GARNISH <i>?</i>	1		
31	REAR SPARE TYRE PANEL <i>RM X</i>	1		
32	REAR SPARE TYRE PANEL INNER TOP CARD BOARD <i>RM X</i>	1		
33	REAR FENDER INNER TRIM BOARD LH <i>RM X</i>	1		
34	REAR FENDER INNER TRIM BOARD RH <i>RM X</i>	1		
SUB TOTAL				
LESS 25%				\$ -
PARTS TOTAL				\$ -

ACCIDENT REPAIR ON : SJA9164C
 MODEL : TOYOTA COROLLA AXIO 1.5X
 POLICY NO : 1055598
 CHASSIS NO : NZE1416050484
 YEAR OF MANUFACTURE : 2007
 DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS
 LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD
THIRD PARTY VEHICLE NO : GX8360Z

DATE : 02/11/2018
PAGE : 2 OF 2

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID OUTER GARNISH CLIPS <i>mc ✓</i>	4		
2	REAR BOOTLID INNER TRIM BOARD CLIPS <i>nn X</i>	10		
3	REAR TAILLAMP CLIPS LH <i>mc ✓</i>	3		
4	REAR TAILLAMP CLIPS RH <i>mc ✓</i>	3		
5	REAR BUMPER CLIPS <i>mc ✓</i>	10		
6	REAR BUMPER INNER SIDE SHIELD CLIPS LH <i>nn X</i>	3		
7	REAR BUMPER INNER SIDE SHIELD CLIPS RH <i>nn X</i>	3		
8	REAR END PANEL INNER TOP GARNISH CLIPS <i>nn ?</i>	4		
9	REAR FENDER INNER TRIM BOARD CLISP LH <i>nn X</i>	6		
10	REAR FENDER INNER TRIM BOARD CLISP RH <i>nn X</i>	6		
PARTS TOTAL			\$	-

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,200.00 ?
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 1,000.00 750
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00 ✓
4	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS. <i>nn</i>	\$ 120.00 X
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00 ?
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 100.00 200
LABOUR TOTAL		\$ 2,550.00

TOTAL PARTS & LABOUR	
GST 7%	\$ -
GRAND TOTAL	\$ -
ESTIMATE REPAIR DURATION	8 DAYS

YOURS SINCERELY,



ESTIMATOR : KIT
 TEL : 8405 4058
 FAX : 6269 2404
 EMAIL : karkit.ngai@bhauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

5 days