

INSURANCE

INS. CASE OWNER:

CC 6 / CTI1802 0018, Kpb3n2

LKK-  
IDAC:

Surveyor:

FSC

DOI:

ASSIGNMENT

(Fm)

Date / Time:

11/1/08

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GX 87602

Claim No.:

SWM182N5767102 ✓

Name of Insured:

TEREMY RENOVATION

Policy No.:

0MCRSN128761801

Insured Tel No.:

HP:

(Two)

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A.:

270/00/08

Place of Accident:

PIE

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

OHAR DOCK 48

OI GIA REPORT: YES / NO

( YES / NO )

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJA 91040



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

BH auto



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time		STAGE	DATE / PIC
20/11/08	Sprinkler - x	Non-Reporting 1st (1st):	
		Non-Reporting 1st (2nd):	
		Non-Reporting 1st (Final):	
		Notification 1st (if non-pickup):	
		Call OI:	26/12/11/08
		After call 1st to OI:	
26/12/08	File -> type mandale	Documentation Check List: Handler	Typist
27/3/19	DV sent	Notification 1st (if non-pickup):	
18/4/19	File -> show per to client	After call 1st to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: 26/12/08 Sent By: CAH

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$5 (days) Reduction: % Email  Call

FINAL SETTLEMENT Date/Time: 27/3/19 Confirm with: Reman Email  Call

Final Liability: % (Agreed / Assessed) BOLA S/N No.: 24

Repair Cost: WBSY \$5 3317.00

Loss of Rental (BORW/WH) \$5 747.00 (7 days) X#110

Loss of Use (LOU): \$5 - (5 x days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search \$5 2.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 4068.00 Global Sum \$5:

FINAL PAYMENT Date/Time: Confirm with: Email  Call

Payee 1: \$5 4068.00 Name 1: BH Auto Services Pte Ltd

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COMMENT

1) Claim status: Normal/Reject/Private Settle  
2) Report Format: 90  
3) Survey fee: \$250.00

ASSIGNMENT

From Date: 02-11-2018

Estimated Cost

OD  TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJA 9164A  
at Workshop: BH Auto  
of: Bik 1 Sin Ming Ind Est #01-115

Insured

Policy No:

Claims No:


Sum Insured: Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

11/27

Date: Person Contacted:

Vehicle: IN / OUT

Visit No: SJA 9164A<sup>C</sup> Yr Regn: 12 OF

Type:  M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Ario<sup>N</sup> C.C. 1496

Colour: M. Gold A/C: Insured / Std / NI / NA

Sp Reading: 216586 T/Radio: Insured / Std / NI / NA

Eng No:

C/No: N7E141 6050484

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim /  STD A/Rim or

Tyre Size: F: 185/70R14

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 30/11/18

Survey held at:

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

5/11 File pass to Catherine

US \$ 21W (Red # 5464.55 / 644)

Date/Time, File Pass to:  Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Site Insp

Interview

Tech Insp

Warrant

TOTAL

Report Format:

Lump Sum / I.B.I: \$

Add Fee:  Site Insp \$

Interview \$

Tech Insp \$

Warrant \$

Large empty box for calculations and totals.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18020018/Kpb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 05-11-2018	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GX 8360Z	Veh. Inspected	SJA 9164C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/11/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	30/10/2018	Inspection Date	02/11/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

- Private Property prices.....still up or down? Part II
- Public transport operators may increase fares by up to...
- Petrol price keeps increasing!

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Awesome May 2013 H-Benz C63 AMG Coupe At \$165800 On



Lowest Depreciation \$20k Still  
Negotiable: Up To 90% Loan  
Akrapovic Exhaust  
Roadlink Auto - Store All

**HIN LUNG AUTO**  
HoBee Group  
**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars  
30 years of car sale

Browse by Category

< Back ( 1 2 ) Next >

Sort by Date Posted 20 results/page

35 vehicles

Toyota Corolla axio

Advanced Search

	Make	Model	Price	Deprecation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Toyota	Corolla axio	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota	Corolla Axio 1.5A X (COE till 03/2022)	\$20,888	\$6,120 /yr	20-Apr-2007	1,496 cc	-	Sedan	Available
	Trade In All Available, Interested Please Call For Viewing. Viewing By Appointment Only.								
	Booki Auto & Marine								
	Posted: 01-Nov-2018 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota	Corolla Axio 1.5A X (COE till 11/2022)	\$24,800	\$6,110 /yr	23-Nov-2007	1,496 cc	126,000 km	Sedan	Available
	One Year In House Warranty! From \$2000 Onwards Drive Away, Able To Try High Loan, With Official Warranty Certificate For Peace Of Mind, Our Company Renew Cars Based On Car Condition Not On Ownership, ...								
	Carway								
	Posted: 01-Nov-2018 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota	Corolla Axio 1.5A X (New 5-yr COE)	\$27,800	\$5,560 /yr	31-Oct-2008	1,496 cc	-	Sedan	Available
	1 Year Comprehensive Warranty Inclusive! \$3K Down Payment! Accident Free Quality Pre Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. Vie...								
	Cosmo Automobiles								
	Posted: 01-Nov-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota	Corolla Axio 1.5A X (New 5-yr COE)	\$29,800	\$5,960 /yr	24-Oct-2008	1,496 cc	-	Sedan	Available
	\$0 Driveaway And \$0 Down Payment Available, No Worries About Down Payment, Bank And In House Loan Available, Low Interest Rate, Low Down Payment Or No Down Payment Available, High Trade In, Fast And Easy Ap...								
	Posted: 31-Oct-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota	Corolla Axio 1.5A X (New 5-yr COE)	\$26,800	\$5,360 /yr	24-Oct-2008	1,496 cc	106,000 km	Sedan	Available
	Low Mileage 106000km Done. Well Kept. Selling Cheap. Low Depreciation. 6 Months Engine/Gearbox Warranty. High Trade In. Bank Loan And In House Loan Available.								
	Posted: 31-Oct-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota	Corolla Axio 1.5A X (COE till 10/2023)	\$27,900	\$5,660 /yr	07-Oct-2008	1,496 cc	-	Sedan	Available
	Elegant Silver, Spacious Sedan, Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment. Flexible In-House Loan Packages Available.								
	Prime Motor & Leasing								
	Posted: 29-Oct-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								

Compare

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 1046G

### Vehicle Details

Vehicle No.: SJA9164C  
Vehicle to be Exported: No  
Intended Deregistration Date: 01 Nov 2018  
Vehicle Make: TOYOTA  
Vehicle Model: COROLLA AXIO 1.5X A  
Primary Colour: Beige  
Manufacturing Year: 2007  
Engine No.: 1NZC739269  
Chassis No.: NZE1416050484  
Maximum Power Output: 81.0 kW (108 bhp)  
Open Market Value: \$11,758.00  
Original Registration Date: 26 Dec 2007  
First Registration Date: 26 Dec 2007  
Transfer Count: 0  
Actual ARF Paid: \$12,934.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 30 Nov 2027  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
PQP Paid: \$41,994.00  
COE Rebate Amount: \$38,132.00  
**Total Rebate Amount: \$38,132.00**

The information contained herein is correct as at 01 Nov 2018

OK

KP

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT  
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
105 CECIL STREET  
#19-00 THE OCTAGON  
SINGAPORE 069534  
TEL : 6389 6111 FAX : 6224 7175

DATE : 02/11/2018  
PAGE : 1 OF 2

*NOT Without  
Running After Point*

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*6/11/18 @ 3100h*

ACCIDENT REPAIR ON : SJA9164C  
MODEL : TOYOTA COROLLA AXIO 1.5X  
POLICY NO : 10555598  
CHASSIS NO : NZE1416050484  
YEAR OF MANUFACTURE : 2007  
DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS  
LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD  
THIRD PARTY VEHICLE NO : GX8360Z

Acknowledged by Repairer  
Signature:  
Date:

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID	1	<i>164</i>	\$ 801.70
2	REAR BOOTLID "LOGO" EMBLEM	1	<i>164</i>	\$ 51.70
3	REAR BOOTLID "AXIO" EMBLEM	1	<i>164</i>	\$ 44.17
4	REAR BOOTLID "X" EMBLEM	1	<i>164</i>	\$ 39.80
5	REAR BOOTLID OUTER GARNISH	1	<i>mycom</i>	\$ 201.30
6	REAR BOOTLID OUTER KEY LOCK	1	<i>164</i>	\$ 141.60
7	REAR BOOTLID REVERSE CAMERA	1	<i>164</i>	\$ 380.00
8	REAR BOOTLID NUMBER PALTE WITH HOLDER	1		\$ <i>164</i> 65.00
9	REAR BOOTLID NUMBER PALTE LAMP LH	1		\$ <i>164</i> 58.70
10	REAR BOOTLID NUMBER PALTE LAMP RH	1		\$ <i>164</i> 58.70
11	REAR BOOTLID MECHANISM LOCK	1		\$ <i>164</i> 156.93
12	REAR BOOTLID INNER TRIM BOARD	1		\$ <i>164</i> 387.40
13	REAR BOOTLID HINGE LH	1		\$ <i>164</i> 87.54
14	REAR BOOTLID HINGE RH	1		\$ <i>164</i> 87.54
15	REAR BOOTLID WEATHERSTRIP	<i>72.8550</i>	<i>164</i>	\$ 185.30
16	REAR TAILLAMP LH	1	<i>164</i>	\$ 321.60
17	REAR TAILLAMP RH	1		\$ <i>164</i> 321.60
18	REAR TAILLAMP LOWER BRACKET LH	1		\$ <i>164</i> 87.40
19	REAR TAILLAMP LOWER BRACKET RH	1		\$ <i>164</i> 87.40
20	REAR BUMPER	1	<i>164</i>	\$ 522.60
21	REAR BUMPER SIDE RETAINER LH	1		\$ <i>164</i> 95.70
22	REAR BUMPER SIDE RETAINER RH	1		\$ <i>164</i> 95.70
23	REAR BUMPER REVERSE SENSOR	<i>164</i> 2	\$ 180.00	\$ 360.00
24	REAR BUMPER INNER SIDE SHIELD LH	1		\$ <i>164</i> 72.70
25	REAR BUMPER INNER SIDE SHIELD RH	1		\$ <i>164</i> 72.70
26	REAR BUMPER IMPACT BRACKET LH	1		\$ <i>164</i> 87.70
27	REAR BUMPER IMPACT BRACKET RH	1		\$ <i>164</i> 87.70
28	REAR END PANEL	1	<i>164</i>	\$ 677.30
29	REAR END PANEL LOCK STRIKER	1		\$ <i>164</i> 37.80
30	REAR END PANEL INNER TOP GARNISH	1		\$ <i>164</i> 187.35
31	REAR SPARE TYRE PANEL	1	<i>164</i>	\$ 775.60
32	REAR SPARE TYRE PANEL INNER TOP CARD BOARD	1	<i>164</i>	\$ 331.63
33	REAR FENDER INNER TRIM BOARD LH	1	<i>164</i>	\$ 395.70
34	REAR FENDER INNER TRIM BOARD RH	1	<i>164</i>	\$ 395.70
SUB TOTAL				\$ 7,761.26
LESS 25%				\$ (1,940.32)
PARTS TOTAL				\$ 5,820.95

*Handwritten checkmarks and notes on the right side of the table, including '4550' and '5080'.*

ACCIDENT REPAIR ON : SJA9164C  
 MODEL : TOYOTA COROLLA AXIO 1.5X  
 POLICY NO : 1055598  
 CHASSIS NO : NZE1416050484  
 YEAR OF MANUFACTURE : 2007  
 DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS  
 LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD  
 THIRD PARTY VEHICLE NO : GX8360Z

DATE : 02/11/2018  
 PAGE : 2 OF 2

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID OUTER GARNISH CLIPS <i>na</i>	4	\$ 3.20	\$ 12.80 ✓
2	REAR BOOTLID INNER TRIM BOARD CLIPS <i>na</i>	10	\$ 3.20	\$ 32.00 X
3	REAR TAILLAMP CLIPS LH <i>na</i>	3	\$ 4.20	\$ 12.60 ✓
4	REAR TAILLAMP CLIPS RH <i>na</i>	3	\$ 4.20	\$ 12.60 X
5	REAR BUMPER CLIPS <i>na</i>	10	\$ 3.90	\$ 39.00 ✓
6	REAR BUMPER INNER SIDE SHIELD CLIPS LH <i>na</i>	3	\$ 3.70	\$ 11.10 X
7	REAR BUMPER INNER SIDE SHIELD CLIPS RH <i>na</i>	3	\$ 3.70	\$ 11.10 X
8	REAR END PANEL INNER TOP GARNISH CLIPS <i>na</i>	4	\$ 4.20	\$ 16.80 X
9	REAR FENDER INNER TRIM BOARD CLISP LH <i>na</i>	6	\$ 3.80	\$ 22.80 X
10	REAR FENDER INNER TRIM BOARD CLISP RH <i>na</i>	6	\$ 3.80	\$ 22.80 X
PARTS TOTAL				\$ 193.60

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,200.00 <i>700</i>
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 1,000.00 <i>750</i>
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00 ✓
4	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS. <i>na</i>	\$ 120.00 X
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00 <i>60</i>
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS. TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 100.00 <i>20</i>
LABOUR TOTAL		\$ 2,550.00

TOTAL PARTS & LABOUR	\$ 8,564.55
GST 7%	\$ 599.52
<b>GRAND TOTAL</b>	<b>\$ 9,164.06</b>
ESTIMATE REPAIR DURATION	<del>8</del> <i>5</i> DAYS

YOURS SINCERELY,

ESTIMATOR : KIT  
 TEL : 8405 4058  
 FAX : 6269 2404  
 EMAIL : karkit.ngai@bhauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~start~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT  
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 105 CECIL STREET  
 #19-00 THE OCTAGON  
 SINGAPORE 069534  
 TEL : 6389 6111 FAX : 6224 7175

DATE : 02/11/2018  
 PAGE : 1 OF 2

*Not Authorized  
 L1 Sm & ?  
 Recovery After Point*

ACCIDENT REPAIR ON : SJA9164C  
 MODEL : TOYOTA COROLLA AXIO 1.5X  
 POLICY NO : 10555598  
 CHASSIS NO : NZE1416050484  
 YEAR OF MANUFACTURE : 2007  
 DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS  
 LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD  
 THIRD PARTY VEHICLE NO : GX8360Z

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID <i>RM ✓</i>	1		
2	REAR BOOTLID "LOGO" EMBLEM <i>RM ✓</i>	1		
3	REAR BOOTLID "AXIO" EMBLEM <i>RM ✓</i>	1		
4	REAR BOOTLID "X" EMBLEM <i>RM ✓</i>	1		
5	REAR BOOTLID OUTER GARNISH <i>RM 1 CRA ✓</i>	1		
6	REAR BOOTLID OUTER KEY LOCK <i>Sm x</i>	1		
7	REAR BOOTLID REVERSE CAMERA <i>Sm x</i>	1		
8	REAR BOOTLID NUMBER PALTE WITH HOLDER <i>Red Box ✓</i>	1		
9	REAR BOOTLID NUMBER PALTE LAMP LH <i>?</i>	1		
10	REAR BOOTLID NUMBER PALTE LAMP RH <i>?</i>	1		
11	REAR BOOTLID MECHANISM LOCK <i>RM ✓</i>	1		
12	REAR BOOTLID INNER TRIM BOARD <i>Sm x</i>	1		
13	REAR BOOTLID HINGE LH <i>R x</i>	1		
14	REAR BOOTLID HINGE RH <i>R x</i>	1		
15	REAR BOOTLID WEATHERSTRIP <i>RM 50/Sm</i>	1		
16	REAR TAILLAMP LH <i>CRA ✓</i>	1		
17	REAR TAILLAMP RH <i>?</i>	1		
18	REAR TAILLAMP LOWER BRACKET LH <i>?</i>	1		
19	REAR TAILLAMP LOWER BRACKET RH <i>?</i>	1		
20	REAR BUMPER <i>RM ✓</i>	1		
21	REAR BUMPER SIDE RETAINER LH <i>Sm x</i>	1		
22	REAR BUMPER SIDE RETAINER RH <i>Sm x</i>	1		
23	REAR BUMPER REVERSE SENSOR <i>?</i>	2		
24	REAR BUMPER INNER SIDE SHIELD LH <i>Sm x</i>	1		
25	REAR BUMPER INNER SIDE SHIELD RH <i>Sm x</i>	1		
26	REAR BUMPER IMPACT BRACKET LH <i>?</i>	1		
27	REAR BUMPER IMPACT BRACKET RH <i>?</i>	1		
28	REAR END PANEL <i>?</i>	1		
29	REAR END PANEL LOCK STRIKER <i>R x</i>	1		
30	REAR END PANEL INNER TOP GARNISH <i>?</i>	1		
31	REAR SPARE TYRE PANEL <i>R x</i>	1		
32	REAR SPARE TYRE PANEL INNER TOP CARD BOARD <i>Sm x</i>	1		
33	REAR FENDER INNER TRIM BOARD LH <i>Sm x</i>	1		
34	REAR FENDER INNER TRIM BOARD RH <i>Sm x</i>	1		
SUB TOTAL				
LESS 25%				\$ -
PARTS TOTAL				\$ -

**ACCIDENT REPAIR ON : SJA9164C**  
**MODEL : TOYOTA COROLLA AXIO 1.5X**  
**POLICY NO : 1055598**  
**CHASSIS NO : NZE1416050484**  
**YEAR OF MANUFACTURE : 2007**  
**DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS**  
**LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD**  
**THIRD PARTY VEHICLE NO : GX8360Z**

**DATE : 02/11/2018**  
**PAGE : 2 OF 2**

SPECIAL NETT ITEMS			QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID OUTER GARNISH CLIPS	NA ✓	4		
2	REAR BOOTLID INNER TRIM BOARD CLIPS	NA X	10		
3	REAR TAILLAMP CLIPS LH	NA ✓	3		
4	REAR TAILLAMP CLIPS RH	NA ?	3		
5	REAR BUMPER CLIPS	NA ✓	10		
6	REAR BUMPER INNER SIDE SHIELD CLIPS LH	NA X	3		
7	REAR BUMPER INNER SIDE SHIELD CLIPS RH	NA X	3		
8	REAR END PANEL INNER TOP GARNISH CLIPS	NA ?	4		
9	REAR FENDER INNER TRIM BOARD CLISP LH	NA X	6		
10	REAR FENDER INNER TRIM BOARD CLISP RH	NA X	6		
<b>PARTS TOTAL</b>					<b>\$ -</b>

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,200.00 ?
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 1,000.00 7500
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00 ✓
4	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	NA \$ 120.00 X ?
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00 ?
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 100.00 200
<b>LABOUR TOTAL</b>		<b>\$ 2,550.00</b>

<b>TOTAL PARTS &amp; LABOUR</b>	
<b>GST 7%</b>	\$ -
<b>GRAND TOTAL</b>	\$ -
<b>ESTIMATE REPAIR DURATION</b>	<b>8 DAYS</b>

YOURS SINCERELY,

  
 ESTIMATOR : KIT  
 TEL : 8405 4058  
 FAX : 6269 2404  
 EMAIL : karkit.ngai@bhauto.com.sg

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## Shu Pei (LKKAuto)

---

**From:** Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>  
**Sent:** Wednesday, 21 November 2018 10:52 AM  
**To:** Shu Pei (LKKAuto)  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving GX8360Z (OI : CTI - TBA) AND SJA9164C (TP : LKK REF - CC6/CTI18020018/Kpb3) on 30.10.2018  
**Attachments:** GX8360Z.PDF

### Without Prejudice

Dear Shu Pei,

Attached our insured's GIA report as per your request.

Thank you.

Regards,

### Ong Chin Kiat

Assistant Claims Executive  
Claims Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6174  
Fax (65) 6224 7174 / 6224 7478  
[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



### Disclaimer :

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd, except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]  
**Sent:** Tuesday, 20 November, 2018 7:11 PM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Cc:** Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

**Subject:** RE: Direct Settlement - Accident Involving GX8360Z (OI : CTI - TBA) AND SJA9164C (TP : LKK REF - CC6/CTI18020018/Kpb3) on 30.10.2018

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you

Best Regards,

Shu Pei | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAuto)

**Sent:** Monday, 5 November 2018 6:58 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com); Lucas Lee <[lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Direct Settlement - Accident Involving GX8360Z (OI : CTI - TBA) AND SJA9164C (TP : LKK REF - CC6/CTI18020018/Kpb3) on 30.10.2018

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SJA 9164C at M/s BH Auto Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Friday, 21 December 2018 12:10 PM  
**To:** 'BHAS - Jacelyn Loh'  
**Cc:** BHAS - Moo Wen Zheng; BHAS - Bernard Kee; BHAS - Chan Yun Shi; CS A Team; Admin A  
**Subject:** RE: PER REPAIR INSPECTION OUR VEHICLE - SJA9164A / YOUR VEHICLE - GX8360Z  
\*LKK REF: CC6/CTI18020018/Kpb3

### Without Prejudice

Hi Sirs/ Madam,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

**"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."**

**In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** BHAS - Jacelyn Loh <[jacelyn.loh@bhauto.com.sg](mailto:jacelyn.loh@bhauto.com.sg)>  
**Sent:** Friday, 21 December 2018 9:52 AM  
**To:** Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Bernard Kee

<bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>  
**Subject:** FW: PER REPAIR INSPECTION OUR VEHICLE - SJA9164A / YOUR VEHICLE - GX8360Z

Hi Sir / Madam,

Have your client make accident report?

PS: kindly advise me on liability on case. Thanks

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Wednesday, 12 December 2018 11:09 AM

**To:** 'Vic (LKKAuto)' <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; 'Joy Irene (LKKAuto)' <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>;  
chewht@lkkauto.com; 'Team A (admin-a@lkkauto.com)' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto)  
<[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** BHAS - Chan Yun Shi <[yunshi.chan@bhauto.com.sg](mailto:yunshi.chan@bhauto.com.sg)>; BHAS - Bernard Kee

<[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>; BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>

**Subject:** RE: PER REPAIR INSPECTION OUR VEHICLE - SJA9164A / YOUR VEHICLE - GX8360Z

Hi Sir / Madam,

Have your client make accident report?

PS: kindly advise me on liability on case. Thanks

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Thursday, 1 November 2018 3:30 PM

**To:** 'Team A (admin-a@lkkauto.com)' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; 'Admin-D (LKKAuto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** BHAS - Ngai Kar Kit <[karkit.ngai@bhauto.com.sg](mailto:karkit.ngai@bhauto.com.sg)>; BHAS - Moo Wen Zheng

<[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** RE: PER REPAIR INSPECTION OUR VEHICLE - SJA9164A / YOUR VEHICLE - GX8360Z

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently IN our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Thursday, 1 November 2018 3:29 PM

**To:** 'Team A ([admin-a@lkkauto.com](mailto:admin-a@lkkauto.com))' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** BHAS - Ngai Kar Kit <[karkit.ngai@bhauto.com.sg](mailto:karkit.ngai@bhauto.com.sg)>; BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** PER REPAIR INSPECTION OUR VEHICLE - SJA9164A / YOUR VEHICLE - GX8360Z

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 9 March 2019 2:26 PM  
**To:** BHAS - Bernard Kee  
**Cc:** BHAS - Chan Yun Shi; BHAS - Jacelyn Loh; BHAS - Moo Wen Zheng; Admin A  
**Subject:** Re: LOD FOR OUR VEHICLE SJA9164A / YOUR VEHICLE - GX8360Z \*LKK REF: CC6/CTI18020018/Kpb3

### Without Prejudice

Dear Sirs/Mdm,

Apologised for late response.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 3,317.00
2. Loss of Rental (7days x \$100.00) (w/GST)	\$ 749.00
3. LTA / GIA Search Fee	\$ 2.00
<b>Total</b>	<b>\$ 4,068.00</b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,  
**Hsiao Tong, Chew** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>  
**Sent:** Wednesday, 20 February 2019 11:52 AM  
**To:** Hsiao Tong (LKKAuto); BHAS - Bernard Kee; Admin A  
**Cc:** BHAS - Chan Yun Shi; BHAS - Jacelyn Loh; BHAS - Moo Wen Zheng  
**Subject:** RE: LOD FOR OUR VEHICLE SJA9164A / YOUR VEHICLE - GX8360Z \*LKK REF: CC6/CTI18020018/Kpb3

4

Dear Hsiao Tong,

Kindly refer to attached file is LOD for our vehicle.  
We had post out original copy document on 21/12/2018.

Please kindly acknowledge in reply and advice further course of action soonest.  
Awaiting for your favorable reply in due course.

## Hsiao Tong (LKKAuto)

---

**From:** BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>  
**Sent:** Monday, 11 March 2019 11:33 AM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** BHAS - Chan Yun Shi; BHAS - Jacelyn Loh; BHAS - Moo Wen Zheng; Admin A  
**Subject:** RE: LOD FOR OUR VEHICLE SJA9164A / YOUR VEHICLE - GX8360Z \*LKK REF: CC6/CTI18020018/Kpb3

Dear Hsiao Tong

We accept the offered.  
Please forward the DV to us ASAP , inorder we can closed up the case.  
Thank you

Best Regards,

*Bernard Kee*

### **BH AUTO SERVICES PTE LTD**

(W) +65-6559 8941 (F) +65-6269 2404 (M) +65 9747 8383

Bernard.kee@bhauto.com.sg <http://www.bhauto.com.sg>

---

**From:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Sent:** Saturday, 9 March 2019 2:26 PM  
**To:** BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>  
**Cc:** BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>; BHAS - Jacelyn Loh <Jacelyn.loh@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; Admin A <admin-a@lkkauto.com>  
**Subject:** Re: LOD FOR OUR VEHICLE SJA9164A / YOUR VEHICLE - GX8360Z \*LKK REF: CC6/CTI18020018/Kpb3

Without Prejudice

Dear Sirs/Mdm,

Apologised for late response.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 3,317.00
2. Loss of Rental (7days x \$100.00) (w/GST)	\$ 749.00
3. LTA / GIA Search Fee	\$ 2.00
<b>Total</b>	<b>\$ 4,068.00</b>

## Hsiao Tong (LKKAuto)

---

**From:** BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>  
**Sent:** Friday, 21 December 2018 1:49 PM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** BHAS - Moo Wen Zheng; BHAS - Bernard Kee; CS A Team; Admin A; BHAS - Jacelyn Loh  
**Subject:** LOD FOR OUR VEHICLE SJA9164A / YOUR VEHICLE - GX8360Z \*LKK REF: CC6/CTI18020018/Kpb3  
**Attachments:** LOD (2).pdf

Dear Hsiao Tong,

Kindly refer to attached file is LOD for our vehicle.  
We had post out original copy document by today.

Please kindly acknowledge in reply and advice further course of action soonest.  
Awaiting for your favorable reply in due course.

Thank you and have a nice day.



Thank You & Best Regards,

Yun Shi

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: [yunshi.chan@bhauto.com.sg](mailto:yunshi.chan@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Sent:** Friday, 21 December 2018 12:10 PM  
**To:** BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>  
**Cc:** BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: PER REPAIR INSPECTION OUR VEHICLE - SJA9164A / YOUR VEHICLE - GX8360Z \*LKK REF: CC6/CTI18020018/Kpb3

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Sunday, 6 January 2019 1:44 PM  
**To:** Claims Dept of CTI  
**Cc:** Admin A; 'Ong Chin Kiat'  
**Subject:** <Seek Mandate>Direct Settlement - Accident Involving GX8360Z (OI : CTI - TBA) AND SJA9164C (TP : LKK REF - CC6/CTI18020018/Kpb3) on 30.10.2018  
**Attachments:** LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos.pdf; TP LOD\_SJA9164C.pdf

Your ref : **TBA**  
Our ref : CC6/CTI18020018/Kpb3n2

Dear Sirs/Madam,

### **ACCIDENT INVOLVING GX 8360Z(OI) & SJA 9164C(TP) ON 30/10/2018**

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our driver's favour.  
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**BH AUTO SERVICES PTE LTD**" at **\$4,068.00(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 9,164.07	\$ 3,317.00
2. Loss of Rental (9days x \$180.00)(w/GST)	\$ 1,733.40	\$ 749.00(7days x \$100.00)(w/GST)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$10,899.47	<b><u>\$ 4,068.00</u></b>

\*\*05days recommendation for repair + 1PRS + 1Sunday = 7days.

Enclosed here with all the relevant documents for your perusal.

**For your approval please.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

## SATISFACTION CERTIFICATE / DISCHARGE VOUCHER

I, TAN JUI HWA hereby state that the repairs

to my Vehicle No : SJA9164C have been carried out to my entire satisfaction

and I am to agree that the discharge to the account of Messrs. **BH AUTO SERVICES PTE LTD**

for by the (Insurance) China Taiping Insurance (Singapore) Pte Ltd shall be in full discharge of all

claims under Vehicle No. GX8360Z with regard to the damages to my vehicle

as a result of accident which occurred on 30 / 10 / 2018 Time: 1630 Hrs

at ALONG PIE EXIT PAYA LEBAR RD.

Signature: 

Name: TAN JUI HWA

NRIC: S6811046G

Date: 8 / 11 / 18

Time: 1200 Hrs



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18020018/Kpb3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 23-04-2019



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 8360Z	Veh. Inspected	SJA 9164C
Policy No.	DMCVSN1748341801	Coverage (\$)	0.00
Claim No.	SNM18D05167/C02/0	Excess (\$)	0.00
Assign From		Assign Date	02/11/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	NZE1418050484	Colour	METALLIC GOLD
Odometer	216586	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	YOKOHAMA	9 mm
L/H Front Tyre	185/70 R14	YOKOHAMA	9 mm
R/H Rear Tyre	185/70 R14	YOKOHAMA	9 mm
L/H Rear Tyre	185/70 R14	YOKOHAMA	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	30/10/2018	Inspection Date	02/11/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 9164C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BOOTLID	BENT	801.70	801.70
1	REAR BOOTLID "LOGO" EMBLEM	NECESSARY	51.70	51.70
1	REAR BOOTLID "AXIO" EMBLEM	NECESSARY	44.17	44.17
1	REAR BOOTLID "X" EMBLEM	NECESSARY	39.80	39.80
1	REAR BOOTLID OUTER GARNISH	MTG CRACKED	201.30	201.30
1	REAR BOOTLID OUTER KEY LOCK	SERVICEABLE	141.60	-
1	REAR BOOTLID REVERSE CAMERA	SERVICEABLE	380.00	-
1	REAR BOOTLID NUMBER PLATE LAMP LH	SERVICEABLE	58.70	-
1	REAR BOOTLID NUMBER PLATE LAMP RH	SERVICEABLE	58.70	-
1	REAR BOOTLID MECHANISM LOCK	DENTED	156.93	156.93
1	REAR BOOTLID INNER TRIM BOARD	SERVICEABLE	387.40	-
1	REAR BOOTLID HINGE LH	TO REPAIR SEE LABOUR	87.54	-
1	REAR BOOTLID HINGE RH	TO REPAIR SEE LABOUR	87.54	-
1	REAR TAILLAMP LH	CRACKED	321.60	321.60
1	REAR TAILLAMP RH	SERVICEABLE	321.60	-
1	REAR TAILLAMP LOWER BRACKET LH	SERVICEABLE	87.40	-
1	REAR TAILLAMP LOWER BRACKET RH	SERVICEABLE	87.40	-
1	REAR BUMPER	BUCKLED	522.60	522.60
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	95.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	95.70	-
2	REAR BUMPER REVERSE SENSOR @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER INNER SIDE SHIELD LH	SERVICEABLE	72.70	-
1	REAR BUMPER INNER SIDE SHIELD RH	SERVICEABLE	72.70	-
1	REAR BUMPER IMPACT BRACKET LH	TO REPAIR SEE LABOUR	87.70	-
1	REAR BUMPER IMPACT BRACKET RH	TO REPAIR SEE LABOUR	87.70	-
1	REAR END PANEL	BENT	677.30	677.30
1	REAR END PANEL LOCK STRIKER	TO REPAIR SEE LABOUR	37.80	-

Report Ref No. CC6/CT118020018/Kpb3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	187.35	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	775.60	-
1	REAR SPARE TYRE PANEL INNER TOP CARD BOARD	SERVICEABLE	331.63	-
1	REAR FENDER INNER TRIM BOARD LH	SERVICEABLE	395.70	-
1	REAR FENDER INNER TRIM BOARD RH	SERVICEABLE	395.70	-
	LESS 25% DISCOUNT		-1,877.73	-704.27
			5,633.23	2,112.83
1	REAR BOOTLID NUMBER PLATE WITH HOLDER (SN)	DENTED	65.00	45.00
1	REAR BOOTLID WEATHERSTRIP (50%)(SN)	CUT	185.30	92.65
	LESS 25% DISCOUNT		-62.58	-
			187.72	137.65
	<b><u>SPECIAL NETT ITEMS</u></b>			
4	REAR BOOTLID OUTER GARNISH CLIPS @\$3.20 (SN)	NECESSARY	12.80	12.80
10	REAR BOOTLID INNER TRIM BOARD CLIPS @\$3.20 (SN)	NOT NECESSARY	32.00	-
3	REAR TAILLAMP CLIPS LH @\$4.20 (SN)	NECESSARY	12.60	12.60
3	REAR TAILLAMP CLIPS RH @\$4.20 (SN)	NOT NECESSARY	12.60	-
10	REAR BUMPER CLIPS @\$3.90 (SN)	NECESSARY	39.00	39.00
3	REAR BUMPER INNER SIDE SHIELD CLIPS LH @\$3.70 (SN)	NOT NECESSARY	11.10	-
3	REAR BUMPER INNER SIDE SHIELD CLIPS RH @\$3.70 (SN)	NOT NECESSARY	11.10	-
4	REAR END PANEL INNER TOP GARNISH CLIPS @\$4.20 (SN)	NOT NECESSARY	16.80	-
6	REAR FENDER INNER TRIM BOARD CLIPS LH @\$3.80 (SN)	NOT NECESSARY	22.80	-
6	REAR FENDER INNER TRIM BOARD CLIPS RH @\$3.80 (SN)	NOT NECESSARY	22.80	-
			193.60	64.40

Report Ref No. CC6/CT118020018/Kpb3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOTLID HINGE LH,REAR BOOTLID HINGE RH,REAR BUMPER IMPACT BRACKET LH,REAR BUMPER IMPACT BRACKET RH,REAR END PANEL LOCK STRIKER AND REAR SPARE TYRE PANEL.		1,200.00	700.00
	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		1,000.00	750.00
	REMOV AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.		50.00	50.00
	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	NOT NECESSARY	120.00	-
	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.		80.00	60.00
	DISCONNECT,CHECK,RESET AND DIAGNOSTIC ELLECTRICAL SYSTEM WIRING,HARNESS,WIRE SOCKETS AND ETC.REMOVE AND REINSTALL DAMAGED PARTS.TEST AND RECTIFY FOR PROPER FUNCTIONING.		100.00	20.00
			2,550.00	1,580.00
	<b>GRAND TOTAL</b>		<b>8,564.55</b>	<b>3,894.88</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,100.00</b>

Report Ref No. CC6/CT118020018/Kpb3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.