

22/11

KP

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
105 CECIL STREET
#19-00 THE OCTAGON
SINGAPORE 069534
TEL : 6389 6111 FAX : 6224 7175

DATE : 02/11/2018
PAGE : 1 OF 2

*Not Withheld
Recovery After Paint*

ACCIDENT REPAIR ON : SJA9164C
MODEL : TOYOTA COROLLA AXIO 1.5X
POLICY NO : 10555598
CHASSIS NO : NZE1416050484
YEAR OF MANUFACTURE : 2007
DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS
LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD
THIRD PARTY VEHICLE NO : GX8360Z

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

11/11/18 @ 3100h

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID	1	RM	\$ 801.70
2	REAR BOOTLID "LOGO" EMBLEM	1	RM	\$ 51.70
3	REAR BOOTLID "AXIO" EMBLEM	1	RM	\$ 44.17
4	REAR BOOTLID "X" EMBLEM	1	RM	\$ 39.80
5	REAR BOOTLID OUTER GARNISH	1	mycom	\$ 201.30
6	REAR BOOTLID OUTER KEY LOCK	1	RM	\$ 141.60
7	REAR BOOTLID REVERSE CAMERA	1	RM	\$ 380.00
8	REAR BOOTLID NUMBER PALTE WITH HOLDER	1	\$ RM	\$ 65.00
9	REAR BOOTLID NUMBER PALTE LAMP LH	1	\$ RM	\$ 58.70
10	REAR BOOTLID NUMBER PALTE LAMP RH	1	\$ RM	\$ 58.70
11	REAR BOOTLID MECHANISM LOCK	1	\$ RM	\$ 156.93
12	REAR BOOTLID INNER TRIM BOARD	1	\$ RM	\$ 387.40
13	REAR BOOTLID HINGE LH	1	\$ RM	\$ 87.54
14	REAR BOOTLID HINGE RH	1	\$ RM	\$ 87.54
15	REAR BOOTLID WEATHERSTRIP	1	RM	\$ 185.30
16	REAR TAILLAMP LH	1	CM	\$ 321.60
17	REAR TAILLAMP RH	1	\$ RM	\$ 321.60
18	REAR TAILLAMP LOWER BRACKET LH	1	\$ RM	\$ 87.40
19	REAR TAILLAMP LOWER BRACKET RH	1	\$ RM	\$ 87.40
20	REAR BUMPER	1	RM	\$ 522.60
21	REAR BUMPER SIDE RETAINER LH	1	\$ RM	\$ 95.70
22	REAR BUMPER SIDE RETAINER RH	1	\$ RM	\$ 95.70
23	REAR BUMPER REVERSE SENSOR	2	\$ 180.00	\$ 360.00
24	REAR BUMPER INNER SIDE SHIELD LH	1	\$ RM	\$ 72.70
25	REAR BUMPER INNER SIDE SHIELD RH	1	\$ RM	\$ 72.70
26	REAR BUMPER IMPACT BRACKET LH	1	\$ RM	\$ 87.70
27	REAR BUMPER IMPACT BRACKET RH	1	\$ RM	\$ 87.70
28	REAR END PANEL	1	RM	\$ 677.30
29	REAR END PANEL LOCK STRIKER	1	\$ RM	\$ 37.80
30	REAR END PANEL INNER TOP GARNISH	1	\$ RM	\$ 187.35
31	REAR SPARE TYRE PANEL	1	RM	\$ 775.60
32	REAR SPARE TYRE PANEL INNER TOP CARD BOARD	1	RM	\$ 331.63
33	REAR FENDER INNER TRIM BOARD LH	1	RM	\$ 395.70
34	REAR FENDER INNER TRIM BOARD RH	1	RM	\$ 395.70
SUB TOTAL				\$ 7,761.26
LESS 25%				\$ (1,940.32)
PARTS TOTAL				\$ 5,820.95

Handwritten checkmarks and notes on the right side of the table, including '455', '508', and 'X' marks next to various rows.

ACCIDENT REPAIR ON : SJA9164C
 MODEL : TOYOTA COROLLA AXIO 1.5X
 POLICY NO : 1055598
 CHASSIS NO : NZE1416050484
 YEAR OF MANUFACTURE : 2007
 DATE / TIME OF ACCIDENT : 30/10/2018@16:30HRS
 LOCATION : ALONG PIE EXIT PAYA LEBAR ROAD
 THIRD PARTY VEHICLE NO : GX8360Z

DATE : 02/11/2018
 PAGE : 2 OF 2

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR BOOTLID OUTER GARNISH CLIPS	4	\$ 3.20	\$ 12.80
2	REAR BOOTLID INNER TRIM BOARD CLIPS	10	\$ 3.20	\$ 32.00
3	REAR TAILLAMP CLIPS LH	3	\$ 4.20	\$ 12.60
4	REAR TAILLAMP CLIPS RH	3	\$ 4.20	\$ 12.60
5	REAR BUMPER CLIPS	10	\$ 3.90	\$ 39.00
6	REAR BUMPER INNER SIDE SHIELD CLIPS LH	3	\$ 3.70	\$ 11.10
7	REAR BUMPER INNER SIDE SHIELD CLIPS RH	3	\$ 3.70	\$ 11.10
8	REAR END PANEL INNER TOP GARNISH CLIPS	4	\$ 4.20	\$ 16.80
9	REAR FENDER INNER TRIM BOARD CLIP LH	6	\$ 3.80	\$ 22.80
10	REAR FENDER INNER TRIM BOARD CLIP RH	6	\$ 3.80	\$ 22.80
PARTS TOTAL				\$ 193.60

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,200.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 1,000.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00
4	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	\$ 120.00
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 100.00
LABOUR TOTAL		\$ 2,550.00

TOTAL PARTS & LABOUR	\$ 8,564.55
GST 7%	\$ 599.52
GRAND TOTAL	\$ 9,164.06
ESTIMATE REPAIR DURATION	5 DAYS

YOURS SINCERELY,

ESTIMATOR : KIT
 TEL : 8405 4058
 FAX : 6269 2404
 EMAIL : karkit.ngai@bhauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: