

CHINA

VEHICLE NO : SHC 1476T

DATE 2/11/2018 10:20

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 459.40
	Rear Bumper Reinforcement ?			\$ 294.80
	Rear Bumper Reinforcement Bracket (RH) ?			\$ 138.10
	Rear Bumper Centre Moulding Assy ✓			\$ 451.25
	Rear Bumper Cover Clips ✓			\$ 22.00 22.00
	SUB TOTAL			\$ 1,345.75
	LESS 20%			\$ 269.15
	DISCOUNTED TOTAL			\$ 1,076.60
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Bumper Number Plate ✓			\$ 35
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 250.00 200
	Wiring Charge			\$ 30.00 x
	Remove/Refix Reverse Sensor			\$ 120.00 30
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 2,012.30

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Applicable item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kahar (K)

2/11/18 11:00 hrs

2 By,

P/P

Rear Part p/lk

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.