



BAN HOCK HIN
Co., Pte Ltd

Not agree spare parts 50% only 1 item

Co.Reg.No: 187002200K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 33212

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

DATE : 02/11/2018
CLAIM NO. : 11208
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBK0493D
MAKE/MODEL : YAM / YBR125

Not Allowed
n/b
take the whole
2 by
5/11/18 1/2 8214.20

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	90.00 X
2	HEADLAMP ASSY P/N: 42005	REPLACE	1.00	\$147.00	147.00 X
3	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS	Supply/install	1.00	\$90.00	90.00 ✓
4	LAMP SIGNAL FRONT LH P/N: 43344	REPLACE	1.00	\$55.00	55.00 X
5	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	63.00 X
6	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$98.00	98.00 X
7	MUDGUARD REAR P/N: 45416	REPLACE	1.00	\$68.00	68.00 X
8	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	\$32.00	32.00 X
9	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00 X
10	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	\$16.00	16.00 ✓
11	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00 ✓
12	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00 ✓
13	VISOR P/N: 42004	REPLACE	1.00	\$68.00	68.00 ✓



P- 68
102
61.20
2.4.20



Address: No. 5, Duta Lane 4, Singapore 535470 Telephone: +65 (0)4 6923 Web: www.bhh.com.sg
Fax: (Main) +65 (0)4 7830 (Spares Dept) +65 (0)8 7530 (Insurance Dept) +65 (0)8 7964 (A/C parts) +65 (0)8 6769