

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9966Z**AAD1811-003***Not Authorized
L1 Lp @ 4500h*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 9966Z
VF1ABL15AUC273447
RENAULT
LATITUDE
1.11.2018
AIG

PART**LIST**

1 FENDER PANEL FRT LH
1 WHEELARCH FRT LH
1 FENDER BRACKET LOWER LH
1 FENDER INSULATOR LH
1 DOOR PANEL FRT LH
1 DOOR HINGE UPPER LH
1 DOOR HINGE LOWER LH
1 DOOR CHECK FRT LH
1 DOOR LOCK FRT LH
1 DOOR CATCH FRT LH
1 DOOR HANDLE OUTER FRT LH
1 DOOR HANDLE COVER FRT LH
1 DOOR HANDLE MODULE FRT LH
1 DOOR REGULATOR FRT LH
1 DOOR REGULATOR MOTOR FRT LH
1 DOOR REGULATOR GUIDE FRT LH
1 DOOR MIRROR ASSY LH

\$ 783.83 ✓
\$ 278.84 X
\$ 15.79 X
\$ 130.84 X
\$ 2,844.66 ✓
\$ 261.28
\$ 300.55
\$ 194.77
\$ 908.75
\$ 131.23
\$ 477.76
\$ 13.22
\$ 133.60
\$ 505.19
\$ 796.46
\$ 120.97
\$ 1,483.40 ✓

\$	9,381.15
10% \$	938.11
\$	8,443.03

Specical Nett

1 FRONT DOOR STICKER 'Trans-cab'
1 FRONT DOOR STICKER 'Chassis'
1 REAR DOOR STICKER '6555 3333'
1 DOOR CHECK BOLT
1 DOOR GUIDE SCREW

\$ 80.00 60sm
\$ 50.00 15sm
\$ 80.00 X
\$ 22.69 X
\$ 10.85 X

Trans-cab Auto Services Pte Ltd**AAD1811-003**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9966Z

1	DOOR HINGE BOLT	\$	SH 10.85	}
1	DOOR HINGE NUT RH	\$	SH 14.60	
1	DOOR CHECK BOLT	\$	SH 22.69	
1	DOOR CHECK NUT	\$	SH 3.75	
1	DOOR LOCK SCREW L70Y	\$	SH 6.12	
1	DOOR CATCH SCREW L70Y	\$	SH 10.06	
1	FRONT LEFT TYRE	\$	SH 330.00	
1	FRONT LEFT TYRE RIM	\$	SH 380.00	X

TOTAL \$ 1,021.63**TOTAL PARTS \$ 9,464.66****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	400l 3,000.00
Putty and spray painting of the affected portion.	\$	3,000.00 440l
To rust-proofing of the affected areas.	\$	170.00 60l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20l

Trans-cab Auto Services Pte Ltd**AAD1811-003**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9966Z

To transfer of front fender fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of front door fittings, attachment and
perform water seepage test.

\$ 380.00 *bol*

To transfer of Rear door fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X*

To pull and jack out chassis frame and correct it to
symmetrical position with the aid of hydraulic
pneumatic jack.

\$ *nn* 380.00 *X*

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *nn* 380.00 *X***TOTAL** \$ 9,770.00**Over All Total** \$ 19,234.66**LUMP SUM (REPAIR DAY)**~~10 DAYS~~*3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: