



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLU 1096 P

Parts	(a) Cost / List Price Items	\$	2,043.80
	Plus/Less 25%	\$	510.95
	<b>Total of Cost / List</b>	<b>\$</b>	<b>1,532.85</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	200.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>1,732.85</b>
<b>Labour</b>		<b>\$</b>	<b>1,370.00</b>
<b>Total</b>		<b>\$</b>	<b>3,102.85</b>

*Not Authorized*  
*Permy Bepair*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenrick  
Company : OKK  
Survey conducted on : 12/11/18 at \_\_\_\_\_

#### Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 02 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ \_\_\_\_\_
- (e) Signature of surveyor : Sc Date: 12/11/18



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLU 1096 P**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FUX03576899**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sm</i>	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		7
3	Rear bumper clip	10	\$40.00		7
4	Rear bumper side retainer LH <i>Sm</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Sm</i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		7
7	Rear bumper lower garnish centre <i>Del / Di /</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>Sm</i>	1	\$149.70		X
9	Rear bumper lower garnish RH <i>Sm</i>	1	\$149.70		X
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

