

HITACHI
 Inspire the Next

TP INSURER: AXA Insurance Pte Ltd (HQ)

Lee Shu Fang

 BLK 801C KEAT HONG CLOSE #12-41
 Singapore 683801

Claimant Insurer: Liberty Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	SI18V07874	Date of Loss:	27/10/2018
Vehicle Reg. No.:	SLQ6851P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LEE SHU FANG	Driver (Insured):	LEE SHU FANG
Make/Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Vehicle Reg. Date:	19/07/2017
Vehicle Colour:	BLACK		
Engine No:	P520454228	Chassis No:	JM6BN22A8H0161919
Odometer:	18762 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	PLEASE REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,580.00
+ GST 7.00% (S\$)	110.60
Nett Amount (S\$)	1,690.60

This claim is handled by: NG JIONG HOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align and replace damaged parts of affected area	New	300 150
2	Putty, blend and paint affected area	New	250 50 750.00
3	Check wiring, re-align headlamps and ensure proper function	New	X 80.00
Gross Labour Cost (\$\$)			1,580.00

Hitachi Capital Asia Pacific Pte. Ltd./SLQ6851P/30/10/2018 13:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul
Hp 90010068
23 days
P/P
08/11/18 @ 1225
Resurvey after repair

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Oct 2018)**Parts:** 143 MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/SLQ6851P/30/10/2018 13:18**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Fender LH <i>X not given</i> Repair	0.00	0.00	<i>inconsistent</i> F
2	1		*Front Bumper Repair	0.00	0.00	*- F

F=Franchise part.

Sub Total (\$)	0.00
+ Margin on L,N Items 20.00% (\$)	0.00
Total Parts (\$)	0.00

Hitachi Capital Asia Pacific Pte. Ltd/SLQ6851P/30/10/2018 13:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS