

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT56D (AXA)

Accident Date : 26-10-2018

Date : 02-11-2018

Our Ref : GBC169H / CHAN

21807

SKYWAVE PTE LTD
C/O ALAN'S UNITED AUTO PTE LTD
BLK 7 SIN MING IND.EST.SECTOR C
#01-76
SINGAPORE 575642

*Not Authorized
Puttying After Paint
4 days*

ESTIMATE COST OF REPAIR FOR NISSAN NV200 GBC169H

2 PCS	LH FRONT & REAR WHEEL HUB CAP @ \$80.00 SN	<i>nd/cmt</i>	\$160.00 SN	✓
1 PC	LH FRONT DOOR LOWER STICKER	<i>na</i>	\$28.00 SN	✓
1 SET	LH SLIDING DOOR LETTERING		\$200.00 SN	<i>1201</i>
	TO PANEL BEATING FRONT LH FENDER, LH DOOR, LH CENTRE PANEL, LH SLIDING DOOR, ALIGN AND ADJUST DAMAGED PARTS		\$500.00	<i>4001</i>
	TO PUTTY AND SPRAY DAMAGED REPAIR PARTS		\$1,200.00	<i>9001</i>
			<u>\$2,088.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Singapore Dollars Two Thousand Eighty Eight Only